

ASS. REC. BY: Sebastian
 REF: CS/MSG18001597 / Std3 n2
 ASSIGNMENT (Office)
 From Person: Merimen Mhd. Ashik of MSIG Date Time: 26/11/18 @ 10:27am
 Estimated Cost: Bill: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLK 4171M Insured: SKD 83394
 at Workshop with: World Auto Tel: 97588347
 of: No. 1 Kranji loop
 Policy No: 27264170 SVP Claim No: 5459 00
 Sum Insured: Excess: _____
 Make of Veh: D.O.A. 14/01/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS 'wp'
 Date/Time: 10:51am @ 26/11/18 Person Contacted: Mr. Daniel VEH: IN/OUT

Date/Time	Action/Instructions (✓) Estimate
	SLK 4171M - CC3 / LCR180001512 / wb3 D.O.A: 14/01/2018
	SKD 83394 - CC3 / LCR180001512 / wb3 D.O.A: 14/01/2018
30lt-	Revert preli via merimen.

Confirm lump sum \$1350/- 4 days (Red: 3504.50 : 72%)

REF: MS19

Signature

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GI A / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK 4171M Yr Regn: 16/1/17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 81436 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 12431217151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16 Giti

R: 11 Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/1/18. D.O.I. 16/1/18

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

RECEIVED 16 MAR 2018

Date/Time, File Pass to? : Preli. Report

1) 16/3 Typist : Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$) 1350/-

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) S + RS _____

: Interview (\$) Photos _____

: Tech. Invs (\$) Copies _____

: Weekend (\$) _____

Survey Fee:	200
Transportation:	10
TOTAL	
210	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018		26 Jan 2018 10:27 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Pressention Thomas , ID: S6967282E		
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201604597K		
Vehicle Reg. No.:	SLK4171M	Date of Loss:	14/01/2018 15:00 - :59
Claim Type:	TP / 545900	Policy/Cover Note No.:	27264170SVP (Comprehensive) Coverage: 12/01/2018 - 11/01/2019
Vehicle Reg. No. (Insured):	SKD8339U	Policy No. (Claimant):	
		Excess:	
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/01/2018]		
Driver/Custodian (Insured):	DE VASCONCELOS M LIZ PRESENTIN MARIA DA CONCEICAO (), NRIC: S6967283C, Tel: +6594504379		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001597/Std3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 8339U	Veh. Inspected	SLK 4171M
Policy No.	27264170SVP	Coverage (\$)	0.00
Claim No.	545900	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/01/2018	Inspection Date	26/01/2018
Survey held at	NO.1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Denise Tay (LKKAuto)

From: tgttan@worldauto.com.sg
Sent: Thursday, 15 March 2018 3:41 PM
To: Denise Tay (LKKAuto)
Subject: RE: SLK 4171M Our ref: TP/1786-18

Hi Denise

Confirmed herein at \$1,350 lump sum and 4 days of repairs.

Thanks n rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

-----Original Message-----

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 15 March 2018 3:21 PM
To: tgttan@worldauto.com.sg
Subject: RE: SLK 4171M Our ref: TP/1786-18

Dear Sophia,

Offer at \$1350/-, 4days

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: tgttan@worldauto.com.sg [mailto:tgttan@worldauto.com.sg]
Sent: Thursday, 15 March 2018 2:10 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: SLK 4171M Our ref: TP/1786-18

Hi Denise

There are no photographs taken.

Our Mr Kana has informed us that this case is settled on a lump sum basis.

We propose lump sum at \$1,700/4 days.

Kindly revert.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madl

Date: 30 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKD8339U	Accident Date	: 14/01/2018
TP Vehicle No	: SLK4171M	Assignment Date	: 26/01/2018
Make	: HONDA VEZEL	Est. Duration of Repair	: 4.00
Date of Inspection	: 26/01/2018		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,854.56
Revised Amount	:S\$	1,492.64
Check Items (Estimated)	:S\$	2,003.00
Total	:S\$	3,095.04

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

(Front Damages another accident → CR)

TP 50/60 MSIG
M

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 16/01/2018 10:12

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/01/2018 10:08
Date Of Accident	14/01/2018 15:00
Exact Location Of Accident	ALONG TANGLIN RD TOWARDS ORCHARD RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK4171M
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID-1.5 Z (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	TAN JOO KOON
NRIC No	S0086832I
Date Of Birth	16/07/1948
Occupation	OUTDOOR
Date Of Driving Pass	04/02/1970
Driving Experience	47 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD8339U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

On 14th Jan 2018 at about 1500 hrs, I was driving along Tanglin Road toward Orchard Road, whilst doing so, suddenly a car black in colour swerve in from the LEFT and swipe into the front RIGHT of my car. Heard a swiping sound and came to stop with the black car also stopping. Upon stopping, the Black Car SKD 83394 ended up in front of my car SKK 41714 still occupying the same lane one behind the other.

Came out of the car to inspect and saw my car front LEFT was damaged whilst the Black car had a dent on the RIGHT rear side of the car at the rear wheel location.

Superficially, damages doesn't seem severe. No one was injured.

That is all.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time




Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SGX CENTRE 2
 068807

Attention : Motor Claim Department
 Contact : 68277888

Estimate : ES201801

Date : 16/01/2018
 Vehicle Num. : SLK 4171M (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/01/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER ✓ cut		495.00
2.	1	FRONT BUMPER SIDE RETAINER L/H ? nn		75.00
3.	1	FRONT LOWER BUMPER ✓ cut		295.80
4.	1	FRONT FENDER WHEEL ARCH MOULDING LH ✓ TN		172.30
5.	1	FRONT FENDER LH ✓		580.00
6.	1	FRONT FENDER HYBRID EMBLEM ✓ NEC		84.60
7.	1	HEADLAMP LH ? nn		1,850.00
8.	1	HEADLAMP LOWER BRACKET LH ? nn		78.00
List Total S\$:				3,630.70
20.00% Discount S\$:				726.14
				2,904.56
SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP ✓ NEC		30.00
Special Nett Total S\$:				30.00
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				120.00 30.
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDE PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				800.00 400.
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS				1,000.00 400.
Labour Total S\$:				1,920.00

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for WORLD AUTO PTE LTD
 Signature:
 Date:

Sebastian.
 26/1/18.
 - Part by part repair.

E. & O.E. Total S\$: 4,854.56

- Question Mark Item Photo
 - Photo Before Paint
 90036121
 sebastianyeang@lkkauto.com

[Signature]
 30/1/18

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SGX CENTRE 2
 068807

Attention : Motor Claim Department
 Contact : 68277888

Estimate : ES201801

Date : 16/01/2018
 Vehicle Num. : SLK 4171M (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 14/01/2018
 Claim No. :
 Reference :
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS :		495.00
2.	1	FRONT BUMPER ✓ cut	? X MM	75.00
3.	1	FRONT BUMPER SIDE RETAINER LH		295.80
4.	1	FRONT LOWER BUMPER ✓ cut		172.30
5.	1	FRONT FENDER WHEEL ARCH MOULDING LH ✓ TN		680.00
6.	1	FRONT FENDER LH		84.60
7.	1	FRONT FENDER HYBRID EMBLEM ✓ NEC		1,850.00
8.	1	HEADLAMP LH		78.00
		HEADLAMP LOWER BRACKET LH ? - purchased X MM		
List Total S\$:				3,630.70
20.00% Discount S\$:				726.14
				2,904.56

1200.70

1.	1SET	SPECIAL FIT ITEMS :		30.00
		FRONT BUMPER CLIP ✓ NEC		30.00
Special Fit Total S\$:				30.00

LABOUR :			
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			120.00 30.
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS. INCLUDE PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS			800.00 400.
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS			1,000.00 400
Labour Total S\$:			1,920.00 830

LKK Auto Co hereby notifies the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts price must be confirmed
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental survey must be resurveyed and approval from Insurance Company

for WORLD AUTO PTE LTD
 Signature: _____
 Date: _____

Sebastian.
 20/1/18.
 - Part by part repair. SN 20 00
 E. & O.E. Total S\$: 4,854.56
 - Question Mark Item Photo
 - Photo Before Paint
 90036121
 sebastianyang@lkkauto.com

Handwritten calculations:
 \$1200.70
 240.14
 5960.56
 830
 1820.56

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001597/STD3N2

Date: 16/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27264170SVP
Claimant Vehicle No :	SLK4171M	Insured Vehicle No :	SKD8339U
Date of Loss:	14/01/2018	Nature of Claim:	TP
		Claim No:	545900

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK4171M	Engine No:	LEB5917163
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU31217151
Reg. Date:	16/01/2017 (Man. Year: 2016)	Odometer:	81436 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,934.56	868.16	2,066.40	70.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	830.00	1,090.00	56.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,854.56	1,698.16	3,156.40	65.02
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	4,854.56	1,350.00	3,504.56	72.19
+ GST 7.00/7.00% (S\$)	339.82	94.50	245.32	72.19
Nett Amount (S\$)	5,194.38	1,444.50	3,749.88	72.19

INSPECTION

Date of Assignment:	26/01/2018		
Date Inspected:	26/01/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK4171M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	495.00 FL	*495.00 FL
2	1		*FRONT BUMPER SIDE RETAINER L/H	Not Necessary	75.00 FL	*- FL
3	1		*FRONT LOWER BUMPER	Cut	295.80 FL	*295.80 FL
4	1		*FRONT FENDER WHEEL ARCH MOULDING LH	Torn	172.30 FL	*172.30 FL
5	1		*FRONT FENDER LH	Repair	580.00 FL	*- FL
6	1		*FRONT FENDER HYBRID EMBLEM	Necessary	84.60 FL	*84.60 FL
7	1		*HEADLAMP LH	Not Necessary	1,850.00 FL	*- FL
8	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	78.00 FL	*- FL
9	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,660.70	1,077.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	726.14	209.54
Total Parts (\$\$)	2,934.56	868.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRINGS CHECK AND RECTIFY WHERE NECESSARY	New	120.00	30.00
2	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDE PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	800.00	400.00
3	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS	New	1,000.00	400.00
Gross Labour Cost (S\$)			1,920.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >