

REF: cs/msg18001612/T1+d3n2

Munim

Taufik
Lionel Tan

ASSIGNMENT (Office)

MSIG

26/1/18 @ 9:24am

Estimated Cost:

B/L:

OD / TP / WS / TP RES / OD RES / EVA / DV / MV / CS

To Inspect Vehicle No:

SKT 2220H

Insured:

SKF 3331M

at Workshop no:

Mover Automotive

Tel:

6272 3892

of Blk 1008, Bkf Meriah Lane 3 # 01-04

Policy No: B28990449Mcy

Claim No:

547404

Sum Insured:

Excess:

Make of Veh:

D.O.A:

23/01/2018

(Client's Record)

CA / RLV / REP. / REV 24 HRS

up

H.O.D Endorsement:

Date/Time: 10:48am @ 26/1/18

Person Conducted:

Avriel

Vehicle: DMV

Date/Time	Action/Inspection	Remarks
	SKT 2220H - CC4 / III 17C06796 / R/pa3q2	D.O.A: 01/04/2017
	SKF 3331M - X	
6/2	Revert via menmen.	
	Taufik check price ok.	

Tanpin

MSIG

ASSIGNMENT

28/5/2015
2015 May.

Date 05/02/2018

Estimated Cost:

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: SKT 2220H
at Workshop: Mova Automotive
of Blk 1008, Bkt Meruh Lane 3 #01-04

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Damage Record:

Make of Van:

Policy Condition:

Remarks: The van had commenced its repair at the time of inspection.



Ball on Market Value:

ICAO Accident Report: Consistent? Yes or No

GIA PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP: 24 HRS wpr

Date: Person Contacted:

Vehicle IN / OUT
Tan Yu

Vehicle No: SKT 2220H

Type: M / C / Van / Lorry / Taxi / Prime Mover

Truck / Trailer:

Make:

Mayda 2

1496

Color:

Green

Insured: Std / Nil / NA

So Reading:

20295

Insured: Std / Nil / NA

Engine:

C No:

JM60J2HAA01100286

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt /

Brake: In order / Jammed / Leaked / Burnt /

Mod: Nil / STD / RIM /

Tyre Size:

205/50R16

BS / DUN / EXNOVA / FS / LIZA / MIC / QHTSU / RIR / SUMI

TOYO / YOKO or

Front:

R.Bal:

6

mm

Rear:

R.Bal:

6

L.Bal:

6

mm

L.Bal:

6

D.O.A:

D.O:

5/2/18 @ 230p

Survey by:

Mova BM

Des. of Damages: Frt / Rear / OS / NS / UIC / Roof top /

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time / Action / Instruction

lump sum \$2800 - 1/5 \$2800, 4 days - e-mail to Tan Yu.
(Red. 2070.28 : 42%)

RECEIVED 17 JUL 2018

Signature
17/7/2018

Case Time / File Pass /

HA Tan Yu

Case Time / File Report /



Prelim. Report

Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Visit:

Inspection:

Test:

Vehicle:

Surveys Fee:

Transportation:

Other:

Other:

Other:

Other:

Other:

Report Format:

Lump Sum

TP

2800

200
10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2018		26 Jan 2018 09:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BORNEO MOTORS (S) PTE LTD, Co. Reg. No.: 196700086Z		
Main Claimant:	Yong Soh Wah, ID: S8177311D		
Vehicle Reg. No.:	SKT2220H	Date of Loss:	23/01/2018 14:00 - :59
Claim Type:	TP / 547404	Policy/Cover Note No.:	B28990449MCY (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
Vehicle Reg. No. (Insured):	SKF3331M	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	Mova Automotive Pte Ltd (HQ) Block 1008 Bukit Merah Lane 3 #01-04/06/08/94, 159722 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/01/2018]		
Driver/Custodian (Insured):	LIAO QIANRONG, EDWIN (), NRIC: S8316964H, Tel: +6598323319		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001612/T1td3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 3331M	Veh. Inspected	SKT 2220H
Policy No.	B28990449MCY	Coverage (\$)	0.00
Claim No.	547404	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	26/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/01/2018	Inspection Date
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Denise Tay (LKKAUTO)

From: Jia Yu <jiayu@movac.com.sg>
Sent: Tuesday, 17 July 2018 11:35 AM
To: Taufikh (LKKAUTO)
Cc: Denise Tay (LKKAUTO)
Subject: RE: SKT2220H FINALIZATION

Hi Taufikh,

Okay. Confirmed at Lump Sum \$2800.00 with 4 repair days.
Thank You.

Best Regards,

Jiayu

Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Tuesday, 17 July 2018 10:34 AM
To: 'Jia Yu'
Cc: 'Denise Tay (LKKAUTO)'
Subject: RE: SKT2220H FINALIZATION

Hi Jia Yu,

Can close at lumpsum \$2800 , 4 days?

Regards
Taufikh
Lkk Auto

From: Jia Yu [mailto:jiayu@movac.com.sg]
Sent: Wednesday, 11 July 2018 2:03 PM
To: 'Denise Tay (LKKAUTO)'; 'Taufikh (LKK Auto)'
Subject: FW: SKT2220H FINALIZATION

Hi Denise/ Taufikh,

Able to Close the case at lump sum \$3000.00 with 4 repair days ?

Best Regards,

Jiayu

Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2018 14:44
Date Of Accident	23/01/2018 14:10
Exact Location Of Accident	PORTSDOWN AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT2220H
Insured/Policyholder	
Name Of Registered Owner	YONG SOH WAH
NRIC No	S8177311D
Email Address	SOHWAH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91144438
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA104878
Cover Note Number	

Driver

Name of Driver	YONG SOH WAH
NRIC No	S8177311D
Date Of Birth	06/11/1981
Occupation	INDOOR
Date Of Driving Pass	30/10/2004
Driving Experience	13 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91144438
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	SOHWAH@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/1/18

2.45 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SKT 2220H	ACCIDENT DATE & TIME: 23/1/2018 2:10pm
CONTACT NUMBER: 91144438	E-MAIL ADDRESS: sohwan@gmail.com
LOCATION: Portdown Ave	
<p>My stationary car (SKT 2220H) was waiting for traffic light at Portdown Ave junction to Commonwealth Ave to turn green before turning right. Car with plate number SKF 3331M which stopped behind my car suddenly moved forward and hit the back of my car (SKT 2220H) when traffic light has just turned green. Vehicles in front of me have yet to move off when my car was hit from the back.</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input checked="" type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 23/1/18 2:45pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/1/18

2.45pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

25/01/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1

Veh # :- SKT2220H

Veh Model :- MAZDA 2

Estimate# :- CK416962

Claim # :-

ACC. Date :- 23/01/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :				
1.	REAR BOOT	1	PC 965.70	965.70
2.	REAR BOOT LOGO	1	PC 62.00	62.00
3.	REAR BOOT EMBLEM "MAZDA2"	1	PC 59.60	59.60
4.	REAR BOOT EMBLEM "SKYACTIVE TECHNOLOGY"	1	PC 69.80	69.80
5.	REAR BOOT LOCK	1	PC 245.00	245.00
6.	REAR BUMPER	1	PC 865.00	865.00
7.	REAR NUMBER PLATE LAMP L+R	2	PC 65.00	130.00
8.	REAR BUMPER LOWER BRACKET L+R	2	PC 26.50	53.00
9.	REAR BUMPER RETAINER L+R	2	PC 38.00	76.00
10.	REAR KEYLESS SENSOR	1	PC 158.00	158.00
11.	REVERSE CAMERA	1	PC 835.00	835.00
12.	REAR BUMPER UNDERCOVER	1	PC 92.00	92.00
13.	REAR BUMPER CLIPS	10	PC 5.80	58.00
14.	REAR END PANEL - REPAIR	1	PC	

LIST TOTAL S\$

20% DISCOUNT S\$

2714.10 2564.10
-733.82

2171.28 2051.28
2.935.28

SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT	1	PC 40.00	40.00
2.	REVERSE SENSOR	1	PC 250.00	250.00
3.	REAR NUMBER PLATE	1	PC 45.00	45.00

SPECIAL NET TOTAL S\$

240. 335.00

LABOUR :

TO REPAIR REAR END PANEL. TO REMOVE AND
REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN
ALL AFFECTED AREAS

TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS

TO REMOVE & REFIX REAR WINDSCREEN GLASS

TO REMOVE & REFIX REAR BOOT MECHANISM,
WIPER MOTOR & CENTER LOCKING SYSTEM

TO REMOVE & REFIX REVERSE SENSOR & CHECK
WIRING

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

400 550.00
500 700.00
120 150.00
40 80.00
30 60.00
30 60.00
1120 1,600.00

Estimate

25/01/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1 130577
Veh # :- SKT2220H
Veh Model :- MAZDA 2
Estimate# :- CK416962
Claim # :-
ACC. Date :- 23/01/18
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S	
AMOUNT S\$	4,870.28
GST @ 7 %	340.92
AMOUNT DUE S\$	5,211.20

Signature

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanflh 9749 5749
wp
5/82/18
wp
lumpsum
Resurvey after repair
4 days
sure @ lkk auto com.

2171.28
2051.28
240
1120
3531.28
415428.00
4 days

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001612/T1TD3N2

Date: 18/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28990449MCY
Claimant Vehicle No :	SKT2220H	Insured Vehicle No :	SKF3331M
Date of Loss:	23/01/2018	Nature of Claim:	TP
		Claim No:	547404

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT2220H	Engine No:	HIDDEN
Make & Model:	MAZDA 2, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6DJ2HAA01100286
Reg. Date:	28/05/2015 (Man. Year: 2015)	Odometer:	20295 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50R16	Rear Tyre Size:	205/50R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,270.28	2,411.28	859.00	26.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,120.00	480.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,870.28	3,531.28	1,339.00	27.49
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,870.28	2,800.00	2,070.28	42.51
+ GST 7.00/7.00% (S\$)	340.92	196.00	144.92	42.51
Nett Amount (S\$)	5,211.20	2,996.00	2,215.20	42.51

INSPECTION

Date of Assignment: 26/01/2018

Date Inspected: 05/02/2018 Inspected At:

Mova Automotive Pte Ltd (HQ)
Block 1008 Bukit Merah Lane 3 #01-
04/06/08/94
Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2018)
Parts:	143	MAZDA 2 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT2220H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT	Bent	965.70 FL	*965.70 FL
2	1	*REAR BOOT LOGO	Necessary	62.00 FL	*62.00 FL
3	1	*REAR BOOT EMBLEM MAZDA2	Necessary	59.60 FL	*59.60 FL
4	1	*REAR BOOT EMBLEM SKYACTIVE TECHNOLOGY	Necessary	69.80 FL	*69.80 FL
5	1	*REAR BOOT LOCK	Not Necessary	245.00 FL	* FL
6	1	*REAR BUMPER	Deformed	865.00 FL	*865.00 FL
7	2	*REAR NUMBER PLATE LAMP L+R	Not Necessary	130.00 FL	* FL
8	2	*REAR BUMPER LOWER BRACKET L+R	Not Necessary	53.00 FL	* FL
9	2	*REAR BUMPER RETAINER L+R	Necessary	76.00 FL	*76.00 FL
10	1	*REAR KEYLESS SENSOR	Cracked	158.00 FL	*158.00 FL
11	1	*REVERSE CAMERA	Cracked	835.00 FL	*400.00 FL
12	1	*REAR BUMPER UNDERCOVER	Not Necessary	92.00 FL	* FL
13	10	*REAR BUMPER CLIPS	Necessary	58.00 FL	*58.00 FL
14	1	*REAR END PANEL (NPA)	Repair	0.00 FL	* FL
15	1	*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
16	1	*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
17	1	*REAR NUMBER PLATE	Not Necessary	45.00 FS	* FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,004.10	2,954.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	733.82	542.82
Total Parts (\$\$)	3,270.28	2,411.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR END PANEL.TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS	New	550.00	400.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	500.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO REMOVE & REFIX REAR BOOT MECHANISM.WIPER MOTOR & CENTER LOCKING SYSTEM	New	80.00	40.00
5	TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	New	60.00	30.00
6	TO RUST PROOF AFFECTED AREAS	New	60.00	30.00
Gross Labour Cost (\$\$)			1,600.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >