

INVOICE

ASS. REQ. BY

REF: CS3/AIG1800163/8d3ez

Special Instruction

ASSIGNMENT (Office)

From Person: Chin Lee Ying of AIG Date/Time: 25/11/18 @ 3:49pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD: ☒ TP / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC1851X Insured: SKU14484

at Workshop no: John Auto Services Tel: 8508 1258

at Blk E5, Woodlands Rd 395A Yew Tee Ind. Est.

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ Date: 23/01/2018  
(Client's Record)

CA REV: REP. / REV 24 HRS <sup>1wp</sup>

SLIP Follow-up

Date/Time: 8:58am @ 26/1/18 Person Checked: John

Vehicle ☒ IN ☐ OUT

Date/Time: \_\_\_\_\_ Action Inspection: ☒ ☐ \_\_\_\_\_

SLC1851X - X

SKU14484 - X

Summary

REF:

AIG

After 2pm

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLC 1851X Yr Regn: 31/12/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 520 c.c. 1995

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 138062 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W 134 NT 12070 CX 50614

Gen. Cond: Good / Bad / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 245/35 ZR19 Hand-lead

R: 275/30 ZR19 Arch-lead

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/1/18 D.O.I. 26/1/18

Survey held at John Auto Services

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)


Report Format : DAR

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

TOTAL

180
20
200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE SKU1448U AND SLC1851X ON 23/01/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 25/1/2018 3:49:55 PM  
Attachments:  Fax2CC9.tif

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



AMY LIM LAW PRACTICE

High Street Centre

1 North Bridge Road

#08-08

Singapore 179094

T: 9625 8742 / 9639 3110

F: 6491 5638

UEN: 53361230J

We do not accept service by fax

Our Ref: 2018.1061.PD.JAS /  
Your Ref: SKU1448U /

25 January 2018

AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)  
78 Shenton Way  
#08-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Department

BY FAX: (6835 7416) ONLY

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION**  
**CLAIMANT: TUTI HASLINDA BINTE MOHAMAD PADILAH /**  
**TRAFFIC ACCIDENT ON 23 JANUARY 2018 AT 15:50 HRS ALONG BKE**  
**TOWARDS WOODLANDS INVOLVING VEHICLES NO. SLC1851X & SKU1448U**

We are instructed by Tuti Haslinda Binte Mohamad Padilah to notify you of a road accident on 23 January 2018 at about 15:50 along BKE towards Woodlands involving our client's vehicle registration number SLC1851X and vehicle registration number SKU1448U driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: M/S John Auto Services  
Address: Block E5, Woodlands Road  
395A, Yew Tee Industrial Estate  
Singapore 677984  
Contact: John @ 8508 1258  
Email: khoman999@gmail.com /

Please liaise with the above workshop directly.

Yours faithfully



Esther Moey

Email: claims@esthermoey.com

encs

PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION

.....


**SINGAPORE  
POLICE FORCE**


T/20180124/2110

1 of 1

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800 7659999

Report No: T/20180124/2110

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made  
24/01/2018 17:32

Vide Report No.

Station Diary No  
98

**Informant's Particulars**

Name of Informant SUZALI BIN MOHAMAD			Address APT BLK 166B TECK WHYE CRESCENT #10-301 SINGAPORE 682105		
ID Type / ID No NRIC NO: S1750971C			Contact No Home/Office Mobile: 87211114		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 51	Date of Birth 08/05/1966	Type of Informant Driver		
Race Javanese			Language		Institution / School Name
Occupation OPERATION MANAGER			Driving Licence Information: Class: 3,4 Date of Expiry		

**General Information of the Accident**

Type of Accident	Injury Others	Drink Drive: No	Date/Time of Accident 23/01/2018 15:50	Type of Location Straight Road
Location Along Road 1 BUKIT TIMAH EXPRESSWAY BKE towards Woodlands				
Weather Drizzling		Road Surface: Wet		Road Speed Limit
Traffic Flow Dual Carriage Way		Traffic Control Not Controlled		Traffic Volume Moderate
Type of Collision Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKU1448U	Car				Slightly Damaged	0
SLC1851X	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved	No
No. of Pedestrians Injured	NIL
Use of Pedestrian Crossing	NA


**SINGAPORE  
POLICE FORCE**

Police Station Of Origin  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No 1800-7859999

1201501242110

2 of 3

Report No: 1201501242110

## CONTINUATION OF REPORT

<b>Driver</b>	
Name	YONG JONG SHYAN
Related Vehicle	SKU1448U (Car)
Hospital/Clinic	NIL
Date Treatment	NIL
No. of Days granted Medical Leave	NIL
<b>Driver</b>	
Name	SUZALI BIN MOHAMAD
Related Vehicle	SLC1851X (Car)
Hospital/Clinic	NATIONAL HEALTHCARE GROUP POLYCLINICS (CHOA CHU KANG)
Date Treatment	24/01/2018
No. of Days granted Medical Leave	03

**Brief Details.**

On 23/01/2018 about 1550hrs, I was driving along Bukit Timah Expressway towards Woodlands Road. There was a road work conducted at lane 1, hence, I changed lane to lane 2 and slowed down as the vehicles in front of me all slowed down. However, the vehicle behind of me did not slow down and hit the rear of my vehicle's rear.

The other driver and I got down our vehicle, exchanged particulars and decided to go for insurance claim. At that point of time, no one was injured.

However, on 24/01/2018 morning, I felt pain and stiffness at my left neck/shoulder and decided to consult a doctor. The doctor said that it could be due to muscle strained and gave me 3 days Medical Leave.

I have CCTV installed in my vehicle but it is not working.

**SINGAPORE  
POLICE FORCE**

Police Station Of Origin  
Choa Chu Kang N.P.C.  
20 Choa Chu Kang Street 12 #01-127  
SINGAPORE 680214  
Tel No. 1800 788888



172510012402110

1 of 5

Report No. 172510012402110

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474805 stating the report number as reference.

Signature Of Officer Recording The Report

Sgt 2 GOH JUN KWAN

Signature Of Informant

Signature Of Interpreter  
Not applicableDate/Time  
24/01/2018 17:32

Officer In Charge Of Case

TP: AEIT /

Staff Sgt WONG STEPHEN

Contact No: 65476423

Signature

Classification Of Case

Authentication Stamp  
#0168

Singapore Police Force

### Sketch Plan

### SKETCH PLAN

### IMPORTANT ROLE

1. The author is primarily concerned with the effects of the "new" on the "old."
2. The author is primarily concerned with the effects of the "new" on the "old."
3. The author is primarily concerned with the effects of the "new" on the "old."
4. The author is primarily concerned with the effects of the "new" on the "old."
5. The author is primarily concerned with the effects of the "new" on the "old."

Any file reports may be viewed in the [File Collection](#) category.

1. *Conduct the following activities with the students:*  
 1. *Read the story to the students.*  
 2. *Ask the students to read the story aloud.*  
 3. *Ask the students to write a paragraph about the story.*  
 4. *Ask the students to draw a picture of the story.*  
 5. *Ask the students to write a letter to the author.*  
 6. *Ask the students to write a poem about the story.*  
 7. *Ask the students to write a play about the story.*  
 8. *Ask the students to write a song about the story.*  
 9. *Ask the students to write a story about the story.*  
 10. *Ask the students to write a book about the story.*

6. Comment on the use of a data protection officer.

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840. 84

- [illegible]

1. *But...*

1945

1950

### Sketch Pinn #2

58434-51-1

### CLIMATE CHANGESTRATEGIES OF THE ACORN-FLY

The different aspects of the development of the  
 human mind, such as the development of the  
 language and the development of the  
 thought, are the main aspects of the

As I mentioned, due to the fact that the  
case is being handled by the same person who  
is also handling the other cases, it is not possible to  
have a separate case for each of the cases.

The owner of 5749 8th Ave. east of his car and  
 walked me to the rear door. When we arrived  
 at the rear door he found traffic coming  
 to check the damage done by the impact with the  
 football and took place of an emergency.

the best reports to make that report was made  
with the mother and then for the change of  
mother that's all

1961年12月

1. The first part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

2. The second part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

3. The third part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

4. The fourth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

5. The fifth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

6. The sixth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

7. The seventh part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

8. The eighth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

9. The ninth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

10. The tenth part of the document is a list of names and dates, which appears to be a roster or a list of participants. The names are written in a cursive script, and the dates are written in a more formal, printed style.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 24/01/2018 13:56                            |
| Date Of Accident           | 23/01/2018 15:50                            |
| Exact Location Of Accident | LANE 2 BKE > WOODLANDS NEAR BT PANJANG EXIT |
| Country/State of Loss      | SINGAPORE                                   |

### DETAILS OF OWN VEHICLE

|  |  |
|--|--|
| Vehicle Registration Number  | SLC1851X                                   |
| <b>Insured/Policyholder</b>  |  |
| Name Of Registered Owner   | TUTI HASLINDA BTE MOHD PADILAH             |
| NRIC No  | S7124883F                                  |
| Email Address  | NOEMAIL                                    |
| Mobile Phone No  | (LOCAL) +65-87495290                       |
| Alternative Phone No   | OFFICE-87495290                            |
| <b>Vehicle Particulars</b>   |  |
| Manufacturer   | BMW  |
| Model  | 520I-2.0 ABS AIRBAG 2WD XENON HEADLAMP (A) |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                                |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO   |
| If No, Please state action to be taken                                       | THIRD PARTY                                |
| Vehicle Category   | PRIVATE CAR                                |
| <b>Insurance Company</b>   |  |
| Name of Insurance Company  | NTUC INCOME INSURANCE CO-OPERATIVE LTD     |
| Type Of Coverage   | COMPREHENSIVE                              |
| Fleet Policy   | NO   |
| Policy Number  | 5091337428                                 |
| Cover Note Number  |  |
| <b>Driver</b>  |  |
| Name of Driver   | SUZALI BIN MOHAMAD                         |
| NRIC No  | S1750971C                                  |
| Date Of Birth  | 08/05/1966                                 |
| Occupation   | INDOOR                                     |
| Date Of Driving Pass   | 25/11/2016                                 |
| Driving Experience   | 1 YEAR AND 1 MONTH                         |
| Gender   | MALE                                       |
| Mobile Number  | (LOCAL) +65-87211114                       |
| Fax Number   |  |
| Contact Number   |  |
| Email Address  | NOEMAIL                                    |

|   |                                     |
|---|-------------------------------------|
| Address   | BLK 166B TECK WHYE CRESCENT #10-361 |
| Postcode  | 682166                              |
| Was driver an employee of the Insured's Company     | NO                                  |
| If No, Relationship of the Driver with the Insured  | SPOUSE                              |
| Vehicle Registration Number of Driver's Own Vehicle | -                                   |
|   | -                                   |
|   | -                                   |
| Insurance Company of Driver's Own Vehicle           | -                                   |
|   | -                                   |
|   | -                                   |

#### General Information of the Accident

|                    |                          |
|--------------------|--------------------------|
| Type Of Accident   | COLLISION - HEAD TO REAR |
| Weather Conditions | RAINING                  |
| Road Surface       | WET                      |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   |     |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                                    |
|-------------------------------------|------------------------------------|
| Vehicle Registration Number         | SKU1448U                           |
| Vehicle Make/Model/Colour           |                                    |
| Details Of Properties               |                                    |
| Vehicle Category                    | PRIVATE CAR                        |
| Name of Driver                      | YONG JONG SHYAN                    |
| NRIC/Passport Number                | S1530253D                          |
| Contact Number                      | 97732933                           |
| Address                             | BLK 551 CHOA CHU KANG ST 52 #06-57 |
| Postcode                            | 680551                             |
| Insurance Company Name              |                                    |
| Nature Of Damage                    |                                    |
| No. Of Passenger (Including Driver) |                                    |

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature

(If driver is not the policyholder)


Date & Time: 24/01/2018

1400 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/1/18 @ 1550 hrs I was travelling in my car SLC1851X on lane 2 at Bukit Timah Expressway (BKE) towards Woodlands during drizzling and heavy traffic as the lane 1 was partly closed due to roadwork.

As I was travelling due to the front traffic stop, I have to brake. After I brake and my car stopped suddenly a motor vehicle no. SKU1448U hit the rear of my car.

The driver of SKU1448U then came out of his car and signalled me to the road shoulder. I then move my car to the road shoulder to avoid traffic congestion, and to access the damage done to my car and we exchange particulars also took photo of our damage car.

We both agreed to make IDAC report and proceed with the insurance claim for the damage done to my car. That's all.

24/1/18

## DECLARATION

I/We declare the foregoing particulars are true and correct.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 1400 hrs

Reporting Centre Personnel's Signature  
Name:  
REC/THS:

(01)Bent (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched  
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

## MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (✓) (3)Check (✓)  
(4)Not Consistent (N/C)

### Rear Portion

| NAC  | INC    | Item                           | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate              |     |    |     |
| 1138 | 993627 | Rear Number Plate Base         |     |    |     |
| 1139 | 993630 | Rear Number Plate Garnish      |     |    |     |
| 1140 | 993632 | Rear Number Plate Lamp         |     |    |     |
| 1141 | 992958 | Rear Bumper                    | DD  | ✓  |     |
| 1142 | 993085 | Rear Bumper Upper              |     |    |     |
| 1143 | 993017 | Rear Bumper Lower <i>Cover</i> | CRA | ✓  |     |
| 1144 | 993054 | Rear Bumper Side               |     |    |     |
| 1145 | 993103 | Rear Bumper Tow Cover          | MIS | ✓  |     |
| 1146 | 992341 | Rear Bumper Clips              | NEC | ✓  |     |
| 1147 | 992976 | Rear Bumper Bracket            |     |    |     |
| 1148 | 993068 | Rear Bumper Side Retainer      | DS  | ✓  |     |
| 1149 | 993045 | Rear Bumper Reinforcement      | DD  | ✓  |     |
| 1150 | 992970 | Rear Bumper Beam               | DD  | ✓  |     |
| 1151 | 993077 | Rear Bumper Sponge             | CRA | ✓  |     |
| 1152 | 992999 | Rear Bumper Damper             |     |    |     |
| 1153 | 993040 | Rear Bumper Protector          |     |    |     |
| 1154 | 993036 | Rear Bumper Pad                |     |    |     |
| 1155 | 993026 | Rear Bumper Moulding           |     |    |     |
| 1156 | 993044 | Rear Bumper Reflector          |     |    |     |
| 1157 | 993023 | Rear Bumper Lower Spoiler      |     |    |     |
| 1158 | 994023 | Reverse Sensor                 | DM  | ✓  |     |
| 1159 | 993327 | Rear End Panel                 | DD  | ✓  |     |
| 1160 | 993339 | Rear End Panel Top Garnish     |     |    |     |
| 1161 | 993333 | Rear End Panel Inner Trim      |     |    |     |
| 1162 | 990333 | Boot Compartment Inner Trim    |     |    |     |
| 1163 | 993851 | Rear LH Taillamp               |     |    |     |
| 1164 | 993853 | Rear LH Taillamp Garnish       |     |    |     |
| 1165 | 993859 | Rear LH Taillamp Panel         |     |    |     |
| 1166 | 995116 | Rear RH Taillamp               |     |    |     |
| 1167 | 993853 | Rear RH Taillamp Garnish       |     |    |     |
| 1168 | 993859 | Rear RH Taillamp Panel         |     |    |     |
| 1169 | 993554 | Rear Apron Panel               |     |    |     |
| 1170 | 992895 | Bootlid                        | DD  | ✓  |     |
| 1171 | 991328 | Bootlid Emblem                 | NEC | ✓  |     |
| 1172 | 990356 | Bootlid Handle                 |     |    |     |
| 1173 | 995250 | Bootlid Moulding               |     |    |     |
| 1174 | 990376 | Bootlid Reflector              |     |    |     |
| 1175 | 995222 | Bootlid Lamp LH                |     |    |     |
| 1176 | 992899 | Bootlid Lamp RH                |     |    |     |
| 1177 | 995243 | Bootlid Lock                   |     |    |     |
| 1178 | 990377 | Bootlid Rubber                 | LMT | ✓  |     |
| 1179 | 990382 | Bootlid Hinge                  |     |    |     |
| 1180 | 993877 | Bootlid Spoiler                |     |    |     |
| 1181 | 994543 | Tailgate                       |     |    |     |
| 1182 | 991328 | Tailgate Emblem                |     |    |     |
| 1183 | 994643 | Tailgate Outer Handle          |     |    |     |
| 1184 | 994640 | Tailgate Moulding              |     |    |     |
| 1185 | 994545 | Tailgate Garnish               |     |    |     |
| 1186 | 994648 | Tailgate Reflector             |     |    |     |
| 1187 | 994549 | Tailgate Lamp                  |     |    |     |
| 1188 | 994646 | Tailgate Protector             |     |    |     |
| 1189 | 994676 | Tailgate Wiper Arm             |     |    |     |
| 1190 | 994677 | Tailgate Wiper Blade           |     |    |     |
| 1191 | 994679 | Tailgate Wiper Nozzle          |     |    |     |
| 1192 | 994555 | Tailgate Wiper Motor           |     |    |     |
| 1193 | 994602 | Tailgate Glass                 |     |    |     |
| 1194 | 994606 | Tailgate Glass Rubber          |     |    |     |
| 1195 | 994604 | Tailgate Glass Moulding        |     |    |     |
| 1196 | 994607 | Tailgate Glass Sealant         |     |    |     |
| 1197 | 994629 | Tailgate Lock                  |     |    |     |
| 1198 | 994651 | Tailgate Rubber                |     |    |     |
| 1199 | 994611 | Tailgate Hinge                 |     |    |     |
| 1200 | 994594 | Tailgate Damper                |     |    |     |
| 1201 | 994613 | Tailgate Inner Board           |     |    |     |

Vehicle No: *SLC 1851 X*

| NAC  | INC    | Item                           | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board               |     |    |     |
| 1203 | 994328 | Spare Tyre Panel               | DDR | ✓  |     |
| 1204 | 995065 | Spare Tyre                     |     |    |     |
| 1205 | 994326 | Spare Tyre Lock Screw          |     |    |     |
| 1206 | 993787 | Spare Tyre Cover               |     |    |     |
| 1207 | 995323 | Triangle Breakdown Sign        |     |    |     |
| 1208 | 990507 | CD Changer Assy                |     |    |     |
| 1209 | 990164 | Antenna                        |     |    |     |
| 1210 | 990534 | Centre Exhaust Pipe Assy       |     |    |     |
| 1211 | 990532 | Centre Exhaust Mounting        |     |    |     |
| 1212 | 993364 | Rear Exhaust Pipe              |     |    |     |
| 1213 | 993357 | Rear Exhaust Chrome Pipe       |     |    |     |
| 1214 | 993361 | Rear Exhaust Mounting          |     |    |     |
| 1215 | 993358 | Rear Exhaust Heat Shield       |     |    |     |
| 1216 | 995223 | Rear LH Chassis Member         |     |    |     |
| 1217 | 993165 | Rear RH Chassis Member         |     |    |     |
| 1218 | 993436 | Rear LH Fender                 |     |    |     |
| 1219 | 993449 | Rear LH Fender Protector       |     |    |     |
| 1220 | 993420 | Rear LH Fender Inner Panel     |     |    |     |
| 1221 | 993431 | Rear LH Fender Inner Trim      |     |    |     |
| 1222 | 993415 | Rear LH Fender Inner Garnish   |     |    |     |
| 1223 | 993425 | Rear LH Fender Inner Shield    |     |    |     |
| 1224 | 993621 | Rear LH Mudflap                |     |    |     |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |     |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |     |
| 1227 | 995065 | Rear LH Tyre                   |     |    |     |
| 1228 | 993456 | Rear RH Fender                 |     |    |     |
| 1229 | 993450 | Rear RH Fender Protector       |     |    |     |
| 1230 | 993420 | Rear RH Fender Inner Panel     |     |    |     |
| 1231 | 993431 | Rear RH Fender Inner Trim      |     |    |     |
| 1232 | 993415 | Rear RH Fender Inner Garnish   |     |    |     |
| 1233 | 993425 | Rear RH Fender Inner Shield    |     |    |     |
| 1234 | 993622 | Rear RH Mudflap                |     |    |     |
| 1235 | 993934 | Rear RH Wheel Rim              |     |    |     |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |     |
| 1237 | 995065 | Rear RH Tyre                   |     |    |     |
| 1238 | 995162 | Rear Fender Extension Panel LH |     |    |     |
| 1239 | 993401 | Rear Fender Extension Panel RH |     |    |     |
| 1240 | 993430 | Rear Fender Inner Top Garnish  |     |    |     |
| 1241 | 993673 | Rear Fender 1/4 Glass          |     |    |     |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber   |     |    |     |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant  |     |    |     |
| 1244 | 993949 | Rear Windscreen Glass          |     |    |     |
| 1245 | 993976 | Rear Windscreen Rubber         |     |    |     |
| 1246 | 993961 | Rear Windscreen Moulding       |     |    |     |
| 1247 | 993955 | Rear Windscreen Sealant        |     |    |     |
| 1248 | 994729 | Third Brake Light              |     |    |     |
| 1249 | 993385 | Rear Fender Air Grille         |     |    |     |
| 1250 | 992167 | Fuel Lid                       |     |    |     |
| 1251 | 992168 | Fuel Neck                      |     |    |     |
| 1252 | 992179 | Fuel Tank                      |     |    |     |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |     |
| 1254 | 992191 | Fuel Tank Float                |     |    |     |
| 1255 | 990247 | Sticker                        |     |    |     |

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |   |               |   |  |  |             |   |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 29 Mar 2018<br><a href="#">Edit Reg</a> |               | 25 Jan 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|             |                  |                      |                  |                 |
|-------------|------------------|----------------------|------------------|-----------------|
| <b>Main</b> | <b>Reference</b> | <b>Claim Details</b> | <b>Documents</b> | <b>Show All</b> |
|-------------|------------------|----------------------|------------------|-----------------|

|                                |   |  |
|--------------------------------|---|--|
| <b>CLAIM SUBFOLDER DETAILS</b> |   | [Created by adjuster]  |
| Insured:                       | Yong Jong Shyan, ID: S1530253D  |  |
| Main Claimant:                 | -   |  |
| Vehicle Reg. No.:              | SLC1851X  | Date of Loss: 23/01/2018 00:00 - :59<br>[96 Months and 23 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                    | TP / 3185201316SG   | Policy/Cover Note No.: (Comprehensive)   |
| Vehicle Reg. No. (Insured):    | SKU1448U  | Policy No. (Claimant):   |
|                                |   | Excess:  |
| Repairer:                      | - Not Applicable - (-)  |  |
| Handling Insurer:              | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]<br>Jaclyn-M.Kesaval@aig.com |  |
| Adjuster:                      | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 09/04/2018]       |  |
| Claimant's Solicitor:          | AMY LIM LAW PRACTICE  |  |

|  |                          |                                   |
|--|--------------------------|-----------------------------------|
| <b>ASSOCIATED MAIL RECEIVED</b>  | <a href="#">View All</a> | <a href="#">Compose Case Mail</a> |
| <ul style="list-style-type: none"> <li>AIG_SG (29/03/2018): Request To Upload TP GIA Report</li> </ul> |                          |                                   |

|                             |                          |                              |                                 |                          |         |             |              |            |       |
|-----------------------------|--------------------------|------------------------------|---------------------------------|--------------------------|---------|-------------|--------------|------------|-------|
| <b>ALL ASSOCIATED TASKS</b> | <a href="#">View All</a> | <a href="#">Search Tasks</a> | <a href="#">Create New Task</a> | <a href="#">Complete</a> |         |             |              |            |       |
| Due Date                    | Priority                 | Type                         | Task Group                      | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                 |                          |                              |                                 |                          |         |             |              |            |       |

## Claim Documents







































**\*SLC1851X (3185201316SG)**














































**[SKU1448U]**

**TP**

**Jan 23 2018 12:00AM**

**[Yong Jong Shyan]**

| Upload Documents |                 |                                   | Upload Photos |  | Compose New Letter |  | Upload Video |  | Upload Audio |  | View  |          | View in Browser                     |  |
|------------------|-----------------|-----------------------------------|---------------|--|--------------------|--|--------------|--|--------------|--|---|----------|-------------------------------------|--|
| Photos/Images    |                 |                                   |               |  |                    |  |              |  |              |  | 3 per page  |          | <input checked="" type="checkbox"/> |  |
| No               | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |               |  |                    |  |              |  |              |  | Thumbnail   | Print    |                                     |  |
| 1                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 2                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 3                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 4                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 5                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 6                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 7                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 8                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 9                | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 10               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |    | Load JPG | <input checked="" type="checkbox"/> |  |
| 11               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |   | Load JPG | <input checked="" type="checkbox"/> |  |
| 12               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 13               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 14               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 15               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 16               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 17               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 18               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 19               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 20               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 21               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 22               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 23               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 24               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 25               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 26               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 27               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 28               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 29               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 30               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 31               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 32               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 33               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 34               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 35               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 36               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 37               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |
| 38               | 02/04/18 17:28  | General View                      |               |  |                    |  |              |  |              |  |  | Load JPG | <input checked="" type="checkbox"/> |  |

| Photos/Images |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
|               |                 |                                   |  | <input checked="" type="checkbox"/> |
| 39            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 02/04/18 17:28  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG   | <input checked="" type="checkbox"/> |
| 56            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG  | <input checked="" type="checkbox"/> |
| 57            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 58            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 59            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 60            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 61            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 62            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 63            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 64            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 65            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 66            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 67            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 68            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 69            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 70            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 71            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 72            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 73            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 74            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 75            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 76            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 77            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 78            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 79            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 80            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 81            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 82            | 02/04/18 17:29  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 83            | 02/04/18 17:30  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 84            | 02/04/18 17:30  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 85            | 02/04/18 17:30  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 86            | 02/04/18 17:30  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |
| 87            | 02/04/18 17:30  | Photo After Spray                 |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |   | 3 per page |           | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|------------|-----------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |            | Thumbnail | Print                               |
| 88            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 89            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 90            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 91            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 92            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 93            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 94            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 95            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 96            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 97            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 98            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 99            | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 100           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 101           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 102           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 103           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 104           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| 105           | 02/04/18 17:30  | Photo After Spray                         | 1          | Load JPG  | <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page |           | <input checked="" type="checkbox"/> |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) |            | Thumbnail | Print                               |
| 1             | 29/03/18 11:53  | OI GIA Report                             | 1          | Load PDF  |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST  |  | Reset | Save | Print |
|--|--|-------|------|-------|
| There are no document checklists configured.   |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18001631/SD3E2

Date: 04/04/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLC1851X

Insured Vehicle No : SKU1448U

Date of Loss: 23/01/2018

Nature of Claim: TP

Claim No: 3185201316SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC1851X

Make &amp; Model: BMW 320I, 2.0 (A)

Engine No: A725I579N46B20BE

Reg. Date: 31/12/2009 (Man. Year: 2009)

Chassis No: WBANT12070CX30614

Colour: Black

Odometer: 138062 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/35Z R19

Rear Tyre Size: 275/30Z R19

Front Left Side: Habilead 6 mm

Rear Left Side: Achilles 6 mm

Front Right Side: Habilead 6 mm

Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 25/01/2018

Date Inspected: 26/01/2018

Inspected At:

JOHN AUTO SERVICES  
395A WOODLANDS ROAD  
SINGAPORE 677984

Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No.                | Qty | Part No. | Particulars                 | Condition | Repairer's | Amount |
|--------------------|-----|----------|-----------------------------|-----------|------------|--------|
| 1                  | 1   |          | *REAR BUMPER                | Dented    | 0.00 F     | *- F   |
| 2                  | 1   |          | *REAR BUMPER LOWER COVER    | Cracked   | 0.00 F     | *- F   |
| 3                  | 1   |          | *REAR BUMPER TOW COVER      | Missing   | 0.00 F     | *- F   |
| 4                  | 6   |          | *REAR BUMPER CLIPS          | Necessary | 0.00 F     | *- F   |
| 5                  | 2   |          | *REAR BUMPER BRACKET        | * Check   | 0.00 F     | *- F   |
| 6                  | 2   |          | *REAR BUMPER SIDE RETAINER  | Distorted | 0.00 F     | *- F   |
| 7                  | 1   |          | *REAR BUMPER REINFORCEMENT  | Dented    | 0.00 F     | *- F   |
| 8                  | 1   |          | *REAR BUMPER BEAM           | Dented    | 0.00 F     | *- F   |
| 9                  | 1   |          | *REAR BUMPER SPONGE         | Cracked   | 0.00 F     | *- F   |
| 10                 | 2   |          | *REVERSE SENSOR             | Damaged   | 0.00 F     | *- F   |
| 11                 | 1   |          | *REAR END PANEL             | Repair    | 0.00 F     | *- F   |
| 12                 | 1   |          | *REAR END PANEL TOP GARNISH | * Check   | 0.00 F     | *- F   |
| 13                 | 1   |          | *REAR RH TAILLAMP           | * Check   | 0.00 F     | *- F   |
| 14                 | 1   |          | *BOOTLID                    | Dented    | 0.00 F     | *- F   |
| 15                 | 1   |          | *BOOTLID EMBLEM             | Necessary | 0.00 F     | *- F   |
| 16                 | 1   |          | *BOOTLID LOCK               | * Check   | 0.00 F     | *- F   |
| 17                 | 1   |          | *BOOTLID RUBBER             | Cut       | 0.00 F     | *- F   |
| 18                 | 1   |          | *SPARE TYRE PANEL           | Repair    | 0.00 F     | *- F   |
| Total Parts (\$\$) |     |          |                             |           | 0.00       | 0.00   |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >