

Date In: 29/01/2018 09:58	Job description	Date & Time Completed	Done by
Ref No: NBA/mc1800166814	SAS e-illing		
Veh No: SV 98842	E-mail (with 3hrs, A/C 2hrs)		
D.O.A: 28/01/2018 12:45	1-Motor Claim Form	m/0979876	29/01/2018 14:21
☒ TP / Reporting Only	1-Motor W/O (w/lines 00 2hrs, TP 1hr)		
	1-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax/Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / OW:	Tel:	Fax:
TP Particulars	Yell No: —	INC () / Non-INC ()
Owner / Driver:	Tel:	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: ()	Date:	Time:
Insured/Driver Liability: ()	%(Note: BSL Status (WO): N: 0-20%; P: 21-79%; P: 80-100%)	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repeller.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () : Invoice: YES () / NO () : Towing Co: ()

Remarks:	INC Hotline: 5788 0016	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()			
2) QC Check / Post Repair Inspection ()			
3) Upload Resurvey Photo (Repair Cost > \$3000) ()			

Injury:

Date/Time	Action

Human Resources	Invoice Preparation/Chrgs	AM (S)	AM (P)
Driver/Owner:	1) AR: Accident Reporting (330)		
Contact No:	2) DA: Damage Assessment (3100) INC (330)		
Damaged Portion:	3) TP: Towing Fee 310/312		
	4) FT: Follow-Through Survey 3120		
	5) FT: Follow-Through Survey (Resurvey) 310		
	6) TR: Re-inspection 313		
	7) NI: 1440 DA + SMRT Survey 3160		
	8) NTUC Additional Services		
	Q11:		
	*NI: Courtesy Car / Tpl Allowance 31		
	*NI: Repair Coordination 310		
	*NI: Post Repair Inspection 313		
	*NI: BY / Collect Unsett Coordination 31		
	TE (NI) / TP (NI) against INC 320		
	9) NI: 1440 310/312		
	Invoice dated	Pax Charged	
	Issued by	Area Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 09:55
Date Of Accident	28/01/2018 12:45
Exact Location Of Accident	CHUA CHU KANG AVE 4 MSCP (BESIDE BLK 450)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV9884Z
Insured/Policyholder	
Name Of Registered Owner	CHIA KUOK WEI
NRIC No	S8426761I
Email Address	XIEGUOWEI1984@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98717166
Alternative Phone No	OTHERS-98717166

Vehicle Particulars

Manufacturer	SUZUKI
Model	LAPIN-658CC (A)
Exact Purpose for which vehicle was being used at time of accident	VISIT RELATIVE
Are you claiming under your own Insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097353800
Cover Note Number	

Driver

Name of Driver	CHIA KUOK WEI
NRIC No	S8426761I
Date Of Birth	11/08/1984
Occupation	INDOOR
Date Of Driving Pass	12/01/2010
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98717166
Fax Number	
Contact Number	OTHERS-98717166
Email Address	XIEGUOWEI1984@YAHOO.COM.SG

Address	BLK 113B MCNAIR ROAD #26-270
Postcode	323113
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JODINE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 29/01/18


Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/01/18 0935



Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: 

Diagram illustrating a car park layout. A car (SN 98842) is shown moving through a Gantry towards a wall and an upward arrow indicating the 2nd level. The area is labeled Multi-Storey Car Park.

I made a left turn into multi story car park and hit the car park wall with the front right of my car.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 29 Jan 18
0940

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Rashid Wani
NRIC/FIN No.:

Claim Handling

The premium on this policy has not been collected.

Accident MT/0979876

Policy No.	5097353800	Vehicle No.	SLV9884Z	GST Registration No.	
Policyholder Name	CHIA KUOK WEI			Policyholder NRIC	
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	
Contact No.(Mobile)	98717166	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Report Date

29/01/2018 14:15

Accident Report Within 24 hrs

Yes

Accident Type

Collided into Pro

Date of Accident

28/01/2018

Time of Accident hh:mm

12:45

Country of Accident

Singapore

Reporting Centre

Orange Force

ICM No.

Accident Location

CHUA CHU KANG AVE 4 HSCF (BESIDE BLK 450)

Benefits

Excess

GST Registered

No

GST Registration Date

GST Registration No.

GST Status Verified

Yes

Modification History

Policyholder Mailing Address

Address 1

BLK 113B #26-270

Address 2

MCNAIR ROAD

Address 3

Address 4

SINGAPORE 323113

Address Type

Singapore address

Post Code

Unit No.

26-270

Related Policy Number

5097353800

DI Driver Info

Driver Name

CHIA KUOK WEI

Driver Type

Main Driver

Unnamed driver Name

Driver NRIC

S84267611

Driver DOB

Register Date of Driver License

01/01/2010

Driver Age

33

Driving Experience

Contact No.(Mobile)

Contact No.(Office)

Contact No.(Home)

Address 1

BLK 113B #26-270

Address 2

MCNAIR ROAD

Address 3

Address 4

SINGAPORE 323113

Address Type

Singapore address

Post Code

Unit No.

26-270

Does he own a Singapore Registered car?

☒ Yes ☐ No

Driver Vehicle No.

SLV9884Z

Driver Insurer Company

Declaration

Breathalyser or Blood Test Reading?

0 mg

Any injury?

☒ Yes ☐ No

Modification History

Claim 001

New

Claim Type *	OD-MD	Injured Name	CHIA KUOK WEI	Insured NRIC	
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	
Email Address		DI Vehicle Number	SLV9884Z	TP Vehicle Number	
Claim Description	SLV9884Z / - ON 28 Jan 2018				Name of Preferred Workshop
Preferred Workshop Contact No.		Insured Liability *	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Income to assign workshop	GIA report	
Date Registered	29/01/2018 14:18	Claim Close Date		Date Received	
Report Taken By	ROSLE WAHAB				

☐ Print AK letter

Save Submit

Attachment

Accident No.	MT/0979876	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	29/01/2018 14:21
Path *		Category *	Confidential Urgency

Browse	Clear	Please Select	▼	N/A	▼	Normal
Browse	Clear	Please Select	▼	N/A	▼	Normal
Browse	Clear	Please Select	▼	N/A	▼	Normal
Browse	Clear	Please Select	▼	N/A	▼	Normal
Browse	Clear	Please Select	▼	N/A	▼	Normal
Browse	Clear	Please Select	▼	N/A	▼	Normal

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	De
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:21	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:20	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:19	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:19	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:19	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:19	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:19	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:18	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:18	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:18	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:18	Photos	Normal	Photo
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK IT MERAH)) on 29 Jan 2018 14:18	Photos	Normal	Photo

NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK
IT MERAH)) on 29 Jan 2018 14:18

SAS

Normal

SAS

NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUK
IT MERAH)) on 29 Jan 2018 14:18

NRIC/ Driving License

Normal

NRIC/ Driving

Video List

Uploaded By/Date

Folder Date

File Name



Source

Display in New Window

Scan and uploading

POLICE

RIP

JMS

11/1/17

ASSIGNMENT SHEET

By C.R.L. (nature of Accident):

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit ? ☐
- a) Motorist ☐ a) Pedestrian ☐
- b) Motorcycle ☐ b) Animal ☐
- c) Bicyclist ☐
- 3) Vehicle hit Road Side Object: ☐
- a) Gown Property ☐ b) Road Work Object ☐
- (e.g. signposts, busstop, etc)
- c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God: ☐
- a) Fallen Object ☐ b) Flood ☐
- c) Other ☐
- 6) Parked & Found Damaged: ☐
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case ☐
- a) Stolen ☐ b) Damage found ☐
- when recovered
- 8) Fire ☐
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

By Assessor- 1) Vehicle Information:

Veh No: SLV 9884Z Yr Bught: JAN 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / H/V
/ Truck / Trailer or

Make & Model: SUZUKI LAPIN 658S or 658

Colour: MINT Transmission Type: Auto / Manual

Eng/No: R06P2B7N38K Sp. Reading: 161 KM

C/No: HE33S185436

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NO / S/Rim / STD A/Rim or

Tyre Size: F 155/65 R14
R 155/65 R14

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bul: 6 mm L/Bul: 6 mm

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: 5 Vehicle in Idles: Yes / No

O.O.I. 29/01/2018 Time: 10:30

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle ☐ b. Motorcycle ☐ c. Bicyclist ☐ d. Pedestrian ☐
- e. Animal ☐ f. Gown Object ☐ g. Road Work Object ☐
- h. Private Property ☐ i. Drain ☐ j. Road Kerb/Cross Varga ☐
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐
- e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Time started

Time completed

SUSP

SUSP

2) When Vandalism Completed Date:

Confident (CON)

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Sealed (7) Deformed
(8) Shilled (9) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
(14) Unconfirmed (15) Not Working

MOTOR CAR (Frt)

ACTION (AC)

(1) Replace (2) Repair (3) Check (4) Not Consistent (NC)

Aug 2009

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991386	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		
1005	992341	Frt Bumper Clips	LMC		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	LMC		
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	?		
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991232	Frt Apron Panel	?		
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BS		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992753	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991034	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No

SLV 98942

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990139	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

Claim Handling

[Task Transfer](#) [Exit](#)

Accident MT/0979876

[IDS](#) [SAC](#) [SUB](#)

Policy No.	5097353800	Vehicle No.	SLV9884Z	GST Registration No.	
Policyholder Name	CHIA KUOK WEI			Policyholder NRIC	S84267611
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98717166	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	29/01/2018 14:15	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	28/01/2018	Time of Accident hh:mm	12:45	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	CHUA CHU KANG AVE 4 MSCP (BESIDE BLK 450)				

Benefits

Excess

Own damage Excess	600.00	Additional Excess	0.00	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 113B #26-270	Address 2	MCNAIR ROAD	Address 3	MCNAIR TOWERS
Address 4	SINGAPORE 323113	Address Type	Singapore address	Post Code	323113
Unit No.	26-270	Related Policy Number	5097353800		

OI Driver Info

Driver Name	CHIA KUOK WEI	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S84267611	Driver DOB	11/08/1964
Register Date of Driver License	01/01/2010	Driver Age	33	Driving Experience	8
Contact No.(Mobile)		Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 113B #26-270	Address 2	MCNAIR ROAD	Address 3	MCNAIR TOWERS
Address 4	SINGAPORE 323113	Address Type	Singapore address	Post Code	323113
Unit No.	26-270				
Does he own a Singapore Registered car?	☒ Yes ☐ No	Driver Vehicle No.	SLV9884Z	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☒ Yes ☐ No
Modification History			

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	CHIA KUOK WEI	Insured NRIC	S84267611
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	
Email Address		OI Vehicle Number	SLV9884Z	TP Vehicle Number	-
Claim Description	SLV9884Z / - ON 28 Jan 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Fully at Fault		
Requires Finalisation	Yes	Preferred Repair Option	income to assign workshop	GIA report	Received
Date Registered	29/01/2018 14:43	Claim Close Date		Date Received	29/01/2018 00:00
Report Taken By	ROSLL WAHAB	Workshop Repairer		Total Loss but Repaired	

[Print AK letter](#)
[Modification History](#)

Special Claim Creation Approval

Approval	Reason
Remarks	
damage assessment	Attachment

Vehicle Info

Vehicle Make *	SUZUKI	Vehicle Model	LAPIN	Engine Capacity	
Date of Registration *	25/01/2018	Class No.	HE3351BS436		
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	ROSLI WAHAB	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value (\$)		Scrape Value(\$)		Economical Repair Value(\$)	

NOTE:VEHICLE IS AT OPTIMA WERZ WARRANTY WORKSHOP(64721313)

Remark

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code
not					
Not Applicable	1	16000101	BUMPER (FRONT)	1	Replace
ABS	2	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Unconfirm
ABSORBER	3	16001303	BUMPER BRACKET (REAR LEFT)	1	Unconfirm
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	1	Replace
ACTUATOR	5	16005001	BUMPER REINFORCEMENT (FRONT)	3	Unconfirm
ADVERTISMENT STICKER	6	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
AIR BAG	7	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
AIR BLOWER	8	27100101	GRILLE (FRONT)	1	Unconfirm
AIR BOX	9	41300101	SUPPORT PANEL (FRONT)	1	Unconfirm
AIR CHAMBER BOX	10	27700102	HEAD LAMP (RIGHT)	1	Replace
AIR CLEANER	11	149001	BONNET	1	Replace
AIR COMPRESSOR	12	25400103	FENDER (FRONT RIGHT)	1	Replace
AIR CON	13	25400802	FENDER INNER PANEL (FRONT RIGHT)	1	Repair
AIR CON (VAN)	14	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm
AIR COOLER	15	25401602	FENDER WHEEL ARCH GARNISH (FRONT RIGHT)	1	Replace
AIR DISTRIBUTOR					
AIR FILTER					
AIR FLOW					
AIR GRILLE					
AIR HORN					
AIR INTAKE					
AIR RESONATOR BOX					

Save Submit

ACCIDENT STATEMENT

ACCIDENT DATE: 28/01/2018 (DD/MM/YYYY), TIME: 12:45 (HH:MM)

LOCATION: Choa Chu Kang Ave 4 Multi Storey Car Park (Beside Blk 450)

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SLV 9884 Z
 b) INSURANCE COMPANY: NTUC
 c) POLICY NUMBER: _____
 d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
 e) MAKE & MODEL: Suzuki Lapin
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE) COMMERCIAL / MOTORCYCLE
 h) PURPOSE OF USING AT ACCIDENT TIME: Visit relative
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- a) NAME: Chia Kuok Wei (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S84267611 CONTACT: 98717166
 c) ADDRESS: 113B McNair Road #26-270 Singapore 323113

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: Chia Kuok Wei (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S84267611 CONTACT: 98717166
 c) ADDRESS: 113B McNair Road #26-270 Singapore 323113

* d) DATE OF BIRTH: 11/08/1984 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS: 12 Jan 2010

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

a) VEHICLE NUMBER: _____ MODEL: _____

b) DRIVER'S NAME: _____

c) NRIC/FIN/PASSPORT: _____ CONTACT: _____

9. THIRD PARTY VEHICLE

d) VEHICLE NUMBER: _____ MODEL: _____

e) DRIVER'S NAME: _____

f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

email = xieguowei 1984@yahoo.com.sg

fax =

VIDEO

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S84267611



Name

CHIA KUOK WEI
(XIE GUOWEI)

谢国伟

Race

CHINESE

Date of birth

11-08-1984

Sex

M

Country of birth

SINGAPORE



S84267611

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S84267611

Name

CHIA KUOK WEI
(XIE GUOWEI)

Birth Date: 11 Aug 1984

Issue Date: 12 Jan 2010



4107886

NRIC No: S84267611



Date of issue

12-09-2007

APT B/LK 113B MCNAIR ROAD #28-270
SINGAPORE 323113

NRIC No: S84267611

Date: 08/08/2017

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 12 Jan 2010

NP 428A



eBaoTech

General Claim

Hello, NAC_BUKIT_MERAH_800676

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	25/01/2018 09:38						
Vehicle No. (For Motor)	SLV9884Z								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5097353800	CHIA KUOK WEI	584267611	GPC	drive CLASSIC	SLV9884Z	SLV9884Z	25/01/2018	24/01/2019
Continue									