

12/03/2002

ASS. REC. BY:

REF: CS/MSG18001687/ T1 qd3

n2

Special Instruction:

Surveyor

Meimen

Tehlich

ASSIGNMENT (Office)

From (Person):

jasmine lok

of

MSIG

Date/Time:

29/01/2018 @ 11:39am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EL776Y

Insured:

SKG 544E

at Workshop m/s

Munich Automobiles

Tel:

90515581

of

30 teban Gardens Crescent

Policy No:

S28979657SMA

Claim No:

546765

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/01/2018

2/2/18 @ 1:45pm; 23 Anderson Rd, 08-01

CA / REV / REP. / REV 24 HRS wp?

H.O.D. Endorsement:

Date/Time:

12:26pm @ 29/1/18

Person Contacted:

Mr. KOK

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

EL776Y-X

SKG 544E-X

02/2/18 @ 11:10am revised to Jasmine Lok via Meimen.

05/4/18 @ 1:37pm confirmed with Kok Ting final Rg &amp; 7451.99, 3 days by email.

(Red &amp; 3656.71, 33%)

Tanfer

MSIG

# ASSIGNMENT

Estim. Date: 2/2/18  
 Estimated Cost:  
 OD / TS / WS / TP RES / CD RES / EVA / INV / MY  
 To inspect Vehicle No: EL776 Y  
 at/Workshop No:  
 23 Anderson Rd #08-01, 259985  
 Insured:  
 Policy No:  
 Claims No:  
 Sum Insured: Excess:  
 (Client's Record)  
 Make of Van: 4.15pm - jeremy @ 98381291  
 Avalon.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Body or Market Value:  
 ICAC Accident Report: Consistent? Yes or No  
 G/A / PR Seen: Consistent? Yes or No  
 Est. Repairs: 3 days Res: Yes or No  
 LHM Sum: 3 Val: Yes or No

CA / REV / REP: 24 HRS <sup>lup</sup>  
 Date: Person Contacted: Vehicle IN / OUT

Vehicle: EL776 Y  
 Type: 0 Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover  
 Truck / Trailer  
 Make: BMW M3  
 Colour: Blue  
 Sp Reading: 70350  
 Eng No:  
 C No: WBSPM92000 E198188  
 Gen Cond: 0000 Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt  
 Brakes: In order / Jammed / Leaked / Burnt  
 Mod: Nil / 2 Rim / STD A/Rim  
 Tyre Size: R 225/50R17  
 R

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / QHTSU 017 / SUMI  
 TOYO / YOKO  
 Front: 6 Rear: 6  
 R Bal: 6 L Bal: 6  
 D/O A: 2/2/18 @ 6pm  
 Survey held at: Munich Auto  
 Des. of Damages: Front / Rear / O/S / N/S / U/O / Rooftop or  
 Front N/S  
 The U/O / Chassis frame / Body Structure affected due to collision

Signature  
 5/4/2018

RECEIVED 03 APR 2018

Date Time Release: 06/4/2018  
 Date Time Release of: 06/4/2018  
 Prell. Report: ☐  
 Final Report: ☐

Days Of Repair: 3  
 Resurvey No. of This:

Survey Fee:  
 Transport:

Add Fee: ☐ Grease: \$  
☐ Grease: \$  
☐ Grease: \$  
☐ Grease: \$

Report Format: MER-TP  
 Lump Sum: 7451.99

200
10
210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001687/T1qd3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 29-01-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 544E	Veh. Inspected	EL 776Y
Policy No.	S28979657SMA	Coverage (\$)	0.00
Claim No.	546765	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	29/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	17/01/2018	Inspection Date
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 07 Mar 2018

**Preliminary Advice**

Insured Vehicle No	: SKG544E	Accident Date	: 17/01/2018
TP Vehicle No	: EL776Y	Assignment Date	: 29/01/2018
Make	: BMW M3	Est. Duration of Repair	: 3.00
Date of Inspection	: 02/02/2018		
Inspection At	: MUNICH AUTOMOBILES PTE LTD (HQ) 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,108.70
Revised Amount	:S\$	5,220.25
Check Items (Estimated)	:S\$	2,478.45
Total	:S\$	7,698.70

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	17 Jan 2018		29 Jan 2018 11:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE KIM MOI, ID: S2501662I		
Main Claimant:	TAY KIAN ANN JEREMY, ID: S7416435H		
Vehicle Reg. No.:	EL776Y	Date of Loss:	17/01/2018 08:00 - :59
Claim Type:	TP / 546765	Policy/Cover Note No.:	S28979657SMA(COMP) (Comprehensive) Coverage: 26/07/2017 - 25/07/2018
Vehicle Reg. No. (Insured):	SKG544E	Policy No. (Claimant):	
		Excess:	
Repairer:	Munich Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent, 608927 West Coast - Tel: 6566-7666		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/01/2018]		
Driver/Custodian (Insured):	LIU WEI (), NRIC: G2290507X, Tel: +6591053714		
Adj Asg. Remarks:	ON WP		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 5 April 2018 1:37 PM  
**To:** 'Tan Kok Ting'; Taufikh (LKKAUTO)  
**Cc:** aaron.chuah@munichauto.com.sg; 'Chen Yanhang'; SUR  
**Subject:** RE: EL776Y / SKG544E D.O.A: 17/1/2018. Finalize

Dear Kok Ting,

Confirm final fig \$7,451.99 before GST and 3 repair days.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan Kok Ting [<mailto:kok.ting@munichauto.com.sg>]  
**Sent:** Tuesday, 6 March 2018 5:26 PM  
**To:** Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>  
**Cc:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; aaron.chuah@munichauto.com.sg; 'Chen Yanhang' <[yanhang.chen@munichauto.com.sg](mailto:yanhang.chen@munichauto.com.sg)>  
**Subject:** RE: EL776Y / SKG544E D.O.A: 17/1/2018. Finalize

Dear Taufikh ,

Attached is for finalize. Please let me know if I can provide additional information.  
Appreciate if we can complete the finalize by this week.

Best regards  
Kok ting

---

**From:** Taufikh (LKK Auto) [<mailto:taufikh@lkkauto.com>]  
**Sent:** Tuesday, February 06, 2018 5:17 PM  
**To:** 'Tan Kok Ting'  
**Cc:** 'Shiau Chan (LKKAUTO)'  
**Subject:** RE: EL776Y / SKG544E D.O.A: 17/1/2018

Hi Kok Ting,

Attached revised estimate.

Regards  
Taufikh  
Lkk Auto

---

**From:** Tan Kok Ting [<mailto:kok.ting@munichauto.com.sg>]  
**Sent:** Tuesday, 6 February 2018 11:53 AM  
**To:** 'Taufikh'  
**Cc:** 'Nivitha (LKK Auto)'  
**Subject:** RE: EL776Y / SKG544E D.O.A: 17/1/2018

## Shiau Chan (LKKAUTO)

---

**From:** Jasmine Lok Kheng Kwei <jasmine\_lok@sg.msig-asia.com>  
**Sent:** Monday, 29 January 2018 1:10 PM  
**To:** assignments  
**Cc:** SUR  
**Subject:** FW: Photographs of accident involving SKG544E Ref. M546765  
**Attachments:** car accident pic 1.jpg; car accident pic 2.jpg

Dear Taufikh,

We refer to the email below.

I have spoken to Tiffany and they provide the scene photos as shown above.

They mentioned that the damage is minor and to ensure damage consistency.

Please take note.

Thank you.

Have a nice day ahead.

**Jasmine Lok**

Executive, Claims Services (Motor)

Direct line +65 6594 2550 | Direct fax +65 6225 7402 | [jasmine\\_lok@sg.msig-asia.com](mailto:jasmine_lok@sg.msig-asia.com)



**MSIG Insurance (Singapore) Pte. Ltd.** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



A member of **MS&AD** INSURANCE GROUP

---

**From:** tiffanyng@adonis-beauty.com [mailto:tiffanyng@adonis-beauty.com]  
**Sent:** Monday, 29 January, 2018 10:57 AM  
**To:** Jasmine Lok Kheng Kwei <jasmine\_lok@sg.msig-asia.com>  
**Cc:** 'annlee' <annlee@adonis-beauty.com>  
**Subject:** Photographs of accident involving SKG544E Ref. 546765

Dear Jasmine

We refer to our tele-conversation earlier.

Attached please find the photographs taken during the accident. It was a very light bump. Hope this helps your surveyor.

As mentioned, we would like to have the breakdown of the claim as soon as you receive it.

Thank you for your kind assistance.

Kind regards,

Tiffany Ng (Ms.) | PA To CEO

ADONIS Body & Beauty Club

D: (+65) 67379854 | M: (+65) 90265549 | F: (+65) 63392059 | E: [Tiffanyng@adonis-beauty.com](mailto:Tiffanyng@adonis-beauty.com)

1 Pemimpin Drive #01-03, Singapore 576151 | [www.adonis-beauty.com](http://www.adonis-beauty.com)

*Our Mission: Commit and Care for woman body & beauty*

*Our Vision: A Drop We Care For Beautiful People*

*Our Product: ADONIS Skin Care And BB Body Care*

WeChat ID: AdonisSingapore | Facebook ID: [AdonisSingapore](#)

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately.

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/01/2018 15:10
Date Of Accident	17/01/2018 08:35
Exact Location Of Accident	CLAYMORE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EL776Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY KIAN ANN JEREMY
NRIC No	S7416435H
Email Address	JERRAHT@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98381291
Alternative Phone No	OFFICE-98381291

### Vehicle Particulars

Manufacturer	BMW
Model	M3-4.0 DCT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI17V13119

Cover Note Number

### Driver

Name of Driver	TAY KIAN ANN JEREMY
NRIC No	S7416435H
Date Of Birth	01/06/1974
Occupation	INDOOR
Date Of Driving Pass	20/01/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98381291
Fax Number	
Contact Number	OFFICE-98381291
Email Address	JERRAHT@YAHOO.COM

Address	20 ANDERSON ROAD #08-01
Postcode	259985
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to attached sketch plan

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER.
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG544E
Vehicle Make/Model/Colour	RANGE ROVER EVOQUE BLACK
Details Of Properties	REAR LEFT BUMPER
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### Sketch Plan




#### Describe Circumstances of the Accident

I was dropping off my child at school. The car in front of me reversed into me while I was waiting for it to move off. My car was stationary during that time. I have a car camera and can provide video evidence. The incident happened at 8:38am at Claymore Road.

Art: 9217VB119

#### Declaration

I/We declare the foregoing particulars are true in every respect.

 17/1/18  
1045am  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



# Munich Automobiles Pte Ltd

Company Reg No: 200910960R  
GST Reg No: 200910960  
30 Teban Gardens Crescent, Singapore 608927  
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **C0002**

Invoice Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

Customer Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

259985

259985

Email: jerraht@yahoo.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 53638	0	0		05/02/2018	12:53	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
EL776Y	E198188	E90 M3	09/09/2010		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damaged body parts and replace affected body parts		240.00	12.50		0.00	3,000.00 1800
2	GEN	Painting front bumper and bonnet		144.00	12.50		0.00	1,800.00 850
3	GEN	To Check electrical wiring system for proper function ability include parking assist sensors		96.00	12.50		0.00	1,200.00 600
4	GEN	To Re-programmed system and delete fault code after accident repair		96.00	12.50		0.00	1,200.00 600
5	SUN	Sundry items		80.00	1.00		0.00	80.00 20
Menu Subtotal:								7,280.00

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



# Munich Automobiles Pte Ltd

Company Reg No: 200910960R  
GST Reg No: 200910960  
30 Teban Gardens Crescent, Singapore 608927  
Tel: +65 65667666 Fax: +65 65659098



## ESTIMATE

Account No. **C0002**

Invoice Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

Customer Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

259985

259985

Email: jerraht@yahoo.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
W 53638	0	0		05/02/2018	12:53	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
EL776Y	E198188	E90 M3	09/09/2010		0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
6		A060976 Set of mount		1.00	66.50	EACH	0.00	66.50
7		Bumper cover front		1.00	1,283.75	EACH	0.00	1,283.75
8		A070812 Headlight le		1.00	2,188.35	EACH	0.00	2,188.35
9		A010652C Spray nozzl		2.00	145.05	EACH	0.00	290.10
Menu Subtotal:								3,828.70
10	NOTES			0.00	0.00		0.00	0.00

Third party claim against MSIG (SKG544E)  
-17/1/2018 0835hrs

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Menu Subtotal:

Tanfikh 97495749  
-wp  
\* Resurvey before paint  
3 days.

sure @ lkkauto.com  
tanfikh @ lkkauto.com

Acknowledged by Parts	3,828.70	V	Rate	Service/Goods	GST	Net	11,108.70
Signature: Surcharge	0.00	S	7.00	11108.70	777.61	G.S.T.	777.61
Date: Labour	7,280.00					Total	11,886.31
Sublet	0.00					Deposit	0.00
Menus	0.00					Owing	11,886.31

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



# Munich Automobiles Pte Ltd

Company Reg No: 200910960R  
GST Reg No: 200910960  
30 Teban Gardens Crescent, Singapore 608927  
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **M0006**

Invoice Name & Address:

MSIG Insurance Singapore Pte Ltd  
4 Shenton Way #21-01  
SGX Centre 2  
Singapore 068807  
Attn: Motor Claim Dept  
068807

Customer Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

259985

Email: jerraht@yahoo.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
B 53638	304	0	INS	06/03/2018	17:13	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
EL776Y	E198188	E90 M3	09/09/2010	26/02/2018	71295	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	GEN	Remove damaged body parts and replace affected body parts		144.00	12.50		0.00	1,800.00
2	GEN	Painting front bumper		68.00	12.50		0.00	850.00
3	GEN	To Check electrical wiring system for proper function ability include parking assist sensors		48.00	12.50		0.00	600.00
4	GEN	To Re-programmed system and delete fault code after accident repair		48.00	12.50		0.00	600.00
5	SUN	Sundry items		20.00	1.00		0.00	20.00
Menu Subtotal:								3,870.00

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.



# Munich Automobiles Pte Ltd

Company Reg No: 200910960R  
GST Reg No: 200910960  
30 Teban Gardens Crescent, Singapore 608927  
Tel: +65 65667666 Fax: +65 65659098



## ESTIMATE

Account No. **M0006**

Invoice Name & Address:

MSIG Insurance Singapore Pte Ltd  
4 Shenton Way #21-01  
SGX Centre 2  
Singapore 068807  
Attn: Motor Claim Dept  
068807

Customer Name & Address:

Mr Jeremy Tay Kian Ann  
23 Anderson Road  
08-01

259985

Email: jerraht@yahoo.com

Inv. Printed By: TKT Service Advisor: Tan Kok Ting

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
B 53638	304	0	INS	06/03/2018	17:13	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
EL776Y	E198188	E90 M3	09/09/2010	26/02/2018	71295	
Job Description						
Body repair						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
6		Bumper cover front w		1.00	1,315.90	EACH	5.00	1,250.11
7		Set of mount		1.00	66.50	EACH	5.00	63.18
8		Spray nozzle		1.00	145.05	EACH	5.00	137.80
Menu Subtotal:								1,451.09
9		Headlight left		1.00	2,243.05	EACH	5.00	2,130.90
Menu Subtotal:								2,130.90
10	NOTES	Third party claim against MSIG (SKG544E) -17/1/2018 0835hrs		0.00	0.00		0.00	0.00
Menu Subtotal:								0.00

Parts	3,581.99	V	Rate	Service/Goods	GST	Net	7,451.99
Surcharge	0.00	S	7.00	7451.99	521.64	G.S.T.	521.64
Labour	3,870.00					Total	7,973.63
Sublet	0.00					Deposit	0.00
Menus	0.00					Owing	7,973.63

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001687/T1QD3N2

Date: 06/04/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	S28979657SMA (COMP)	
Claimant Vehicle No :	EL776Y	Insured Vehicle No :	SKG544E	
Date of Loss:	17/01/2018	Nature of Claim:	TP	Claim No: 546765

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	EL776Y	Engine No:	20994686S65B40A
Make & Model:	BMW M3, 4.0 DCT (A)	Chassis No:	WBSPM92000E198188
Reg. Date:	09/09/2010 (Man. Year: 2010)	Odometer:	70350 km
Colour:	Blue		
Engine Capacity:	3999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,908.69	3,601.99	306.70	7.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	3,850.00	3,350.00	46.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>11,108.69</b>	<b>7,451.99</b>	<b>3,656.70</b>	<b>32.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>777.61</b>	<b>521.64</b>	<b>255.97</b>	<b>32.92</b>
<b>Nett Amount (S\$)</b>	<b>11,886.30</b>	<b>7,973.63</b>	<b>3,912.67</b>	<b>32.92</b>

## INSPECTION

Date of Assignment:	29/01/2018	
Date Inspected:	02/02/2018	Inspected At: Munich Automobiles Pte Ltd (HQ) 30 Teban Gardens Crescent Singapore 608927
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2018)
<b>Parts:</b> M1-COUPE	BMW M3 4.0 DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for EL776Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*A060976 SET OF MOUNT	Necessary	66.50 FS	*63.18 FS
2	1		*BUMPER COVER FRONT	Deformed	1,283.75 FS	*1,250.11 FS
3	1		*A070812 HEADLIGHT LE	Cut	2,188.34 FS	*2,130.90 FS
4	2		*A010652C SPRAY NOZZLE	Cracked (1pc only)	290.10 FS	*137.80 FS
5	1		*SUNDRY ITEMS	Necessary	80.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>3,908.69</b>	<b>3,601.99</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE DAMAGED BODY PARTS AND REPLACE AFFECTED BODY PARTS	New	3,000.00	1,800.00
2	PAINTING FRONT BUMPER AND BONNET	New	1,800.00	850.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDE PARKING ASSIST SENSORS	New	1,200.00	600.00
4	TO RE-PROGRAMMED SYSTEM AND DELETE FAULT CODE AFTER ACCIDENT REPAIR	New	1,200.00	600.00
Gross Labour Cost (S\$)			<b>7,200.00</b>	<b>3,850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >