





| EDIT                                                                                | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME       | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|-------------------------------------------------------------------------------------|-------|-------------------------|-----------------|------------|---------------|-------|-----------------|---------|
|  | 2     |                         | LABOUR CHARGE.  | 250        | 0             | 0     | Reviewing       |         |
|  | 3     |                         | SPRAY PAINTING. | 300        | 0             | 0     | Reviewing       |         |



Detailed Assessment

Inspection Date \*

02/02/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

255/35ZR20

Rear Tyre Size

255/35ZR20



FNOL INFORMATI... 10D BEDOK SOUTH AVENUE 2, 463010,  
Singapore

POST SURVEY INF ...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF ...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF ...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF ...

CATEGORY

Identification #

FNOL INFORMATI...

S1305644G

|                    |                           |                                  |
|--------------------|---------------------------|----------------------------------|
| CATEGORY           | Make                      | POST SURVEY INF...               |
| POLICY INFORMAT... | AUDI                      |                                  |
| ASSESSMENT INFO... | AUDI                      |                                  |
| CATEGORY           | Model                     | POST SURVEY INF...<br>mm/dd/yyyy |
| POLICY INFORMAT... | A6 AVANT 3.0 TFSI         |                                  |
| ASSESSMENT INFO... | A6 AVANT 3.0 TFSI QUATTRO |                                  |
| CATEGORY           | Type                      | POST SURVEY INF...               |
| POLICY INFORMAT... |                           | Occupation                       |
| ASSESSMENT INFO... |                           | Unknown                          |
| CATEGORY           | Type of Paint             | POST SURVEY INF...               |
| POLICY INFORMAT... |                           |                                  |
| ASSESSMENT INFO... |                           |                                  |
| CATEGORY           | Chassis No                | POST SURVEY INF...               |
| POLICY INFORMAT... | WAUZZZ4G5CN082501         |                                  |
| CATEGORY           | Driving Experience        |                                  |



Accelerated survey  
and authorize

Claim Handler

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

Additional Instructions

EXCESS NIL

| CREATED<br>USER | VERSION<br>DATE    | ESTIMATED<br>AMOUNT | APPROVED<br>AMOUNT | STATUS | SHARE | CLONE |
|-----------------|--------------------|---------------------|--------------------|--------|-------|-------|
| ANG<br>Yvonne   | 1/29/18<br>1:32 PM | 570                 | 570                | Open   | Share | Clone |



Accelerated survey  
and authorize

Claim Handler

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Document Type

Additional Instructions

EXCESS NIL

Document SubType

Upload Documents

| NAME                   | TYPE     | SUB-TYPE                                | AUTHOR                                  | DATE<br>UPLOADED    |
|------------------------|----------|-----------------------------------------|-----------------------------------------|---------------------|
| SBY358M.pdf            | Invoice  | Spare Part /<br>Accessories<br>Supplier | LOW Garnet                              | July 19,<br>2018    |
| RESURVEY<br>PHOTOS.pdf | Evidence | Photos                                  | LKK AUTO<br>CONSULTANTS PTE<br>LTD (OD) | March 31,<br>2018   |
| SURVEY<br>PHOTOS.pdf   | Evidence | Photos                                  | LKK AUTO<br>CONSULTANTS PTE<br>LTD (OD) | February 5,<br>2018 |