Tanjong REF: ATLG Ref: 18001742/71ks3

ASSIGNMENT

From Date 02.02.2018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKC 9633T

at Workshop m s Volkswagen

of 247 Alexandra Rd

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

11.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted.

Veh No: SKC 9633T Reg: 2011 Oct

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Scirocco CC: 1390

Colour: Black A/C: Insured / Std / Nil / NA

Sp Reading: 80723. T Radio: Insured / Std / Nil / NA

Eng No:

C No. WVWZZZ137CV009385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/40R18.

R: u/n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R.Bal.	6 mm	R.Bal.	6 mm
L.Bal.	6 mm	L.Bal.	6 mm
D.O.A.		D.O.I.	2/2/18 @ 1130

Survey held at VW Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date	Time	Action / Instruction

Date/Time File Pass to: [ ] : Preli. Report

[ ] : Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] Site Insp $

[ ] Interim $

[ ] Tech $

[ ] Assistance $

Report Format:

Lump Sum / LB $

Survey Fee

Transportation

Photo

Other