Surveyor: Tanjiln | REF: LPC

ASSIGNMENT

From: | Date: 06022018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 3688X

at Workshop m/s: Cycle & Carriage

of: 209 Pandan Garden

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Jun Ye

(Policy Condition) Morning

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SKR 3688X | Yr Regn: 2010 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Kia Cerato Forte | c.c 1591

Colour: Grey | A/C: Insured / Std / NI / NA

Sp.Reading: 86008 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAFW411MA5252349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / STRim / STD A/Rim or

Tyre Size: F: 215/45R17

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	6/2/18 @ 1215

Survey held at: C&C Pandan Garden

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time. File Pass to? 1)

Date/Time. File Return to? 2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation: ___$ + RS ___SI

Add Fee: ☐ Site Insp ($)

☐ Interview ($)

☐ Tech. Invs ($)

☐ Weekend ($)

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)