Surveyor: YML. REF: ALG h3 ~~HPLSTA~~

ASSIGNMENT

From: Date: 05022018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 1771A

at Workshop m/s Carcrafters

of 48 Toh Guan Rd East #05-155

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Faisal 1pm

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP 1771A Yr Regn: 06 Feb 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A6 c.c 1984

Colour Grey A/C Insured / Std / NI / NA

Sp.Reading 86735 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZZ4G9CN086986

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R19

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	05-02-18

Survey held at W/S 2:16pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp ($ ☐ Interview ($ ☐ Tech Invs ($ ☐ Weekend ($

Survey Fee

Transportation) ___$ - PS ___$)

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($