REF: II

82536

ASSIGNMENT

From: Date: 30012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 9638M

at Workshop m/s Volkswagen

of 247 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 1pm

Remark: The veh had commenced its repair at the time of inspection. owner waiting

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK9638M Yr Regn: 2013 SGP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Jetta 1.4 c.c 1390

Colour Red A/C: Insured / Std / NI / NA

Sp.Reading 75956 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVW2221626M0 35875

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 26/01/18 D.O.I. 30/01/18

Survey held at VOLKSWAGEN

Des. of Damages : Frt / ~~Rear~~ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip: Survey Fee:

Transportation:

Add Fee: ☐ Site Insp $ ☐ Interview $ ☐ Tech. Invs $ ☐ Weekend $

$ - R$ $

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: $