

Surveyor
Merimen

Ressul

ASSIGNMENT (Office)

From (Person):

Clarah Milah Yeo

of MSG

Date/Time 30/1/18 @ 9:52am

Estimate # Cost

Bill to

① / - / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 76617

Insured:

at Workshop m/s:

Performance

Tel:

91165700

of

303 Alexandra Road

Policy No:

29048377 SMP

Claim No:

547705

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 25/01/18

(Client's Record)

After 2pm.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

30/1/18 @ 10:25am

Person Contacted:

Mr. Han

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJP 76617-x

3/1/-

Revert via merimen

3/1/01-15:50pm authorise repair by Chen How

3/1/01-4:30pm email authorise to Han excess \$500-

Part by Part \$33531 (Red: 26911, 44%)

REF: 33644

REF: 33644

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJP 7661T
 at Workshop m/s: PERFORMANCE
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: 500
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Am

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 139k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJP 7661T Yr Regn: 2016 DBL
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W 318I SEDAN c.c. 1499
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp.Reading: 20273 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA8E36040NU32216
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/60R17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>25/01/18</u>	D.O.I. <u>30/01/18</u>
Survey held at <u>PERFORMANCE</u>	
Des. of Damages: Frt / <u>Rear</u> / O/S / N/S / U/C / Rooftop or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

1) 2415 Typist

Date/Time, File Return to?

2)

Report Format: CD

Lump Sum / (B): \$ 3353

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Weekend \$

Survey Fee:

Transportation

3-PS \$

Photos

Others

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2018		30 Jan 2018 09:52 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GOH TSUI LI JEAN, ID: S7043364H, Tel: +6591166231, Email: JEAN.YIPGOH@GMAIL.COM			[Created by insurer]
Vehicle Reg. No.:	SJP7661T	Date of Loss:	25/01/2018 06:00 - :59	
Claim Type:	OD / 547705	Policy/Cover Note No.:	29048377SMP (Comprehensive)	
		Excess:	Coverage: 23/12/2017 - 22/12/2018	
			S\$500.00	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]			
Driver/Custodian:	GOH TSUI LI JEAN (47 / Female), NRIC: S7043364H, Tel: +6591166231			
Adj Asg. Remarks:	Please arrange to survey this afternoon. Thanks. Pleas revert.			

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001778/R1td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 30-01-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SJP 7661T
Policy No.	29048377SMP	Coverage (\$)	0.00
Claim No.	547705	Excess (\$)	500.00
Assign From	MERIMEN (CLARAH MILAH YEO)	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	25/01/2018	Inspection Date	30/01/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 31 January 2018 4:30 PM
To: Han Kwan Yong
Cc: SUR
Subject: SJP7661T OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJP 7661T (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SJP7661T (547705)**

OD

Jan 25 2018 6:00AM

[GOH TSUI LI JEAN]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 31/01/2018 15:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$\$3290.50) - SJP7661T - Claim Handler: Clara Milah Yeo

Approved:3290.50.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2018 15:01
Date Of Accident	25/01/2018 06:50
Exact Location Of Accident	AYE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP7661T
Insured/Policyholder	
Name Of Registered Owner	GOH TSUI LI JEAN
NRIC No	S7043364H
Email Address	JEAN.YIPGOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91166231
Alternative Phone No	OFFICE-91166231

Vehicle Particulars

Manufacturer	BMW
Model	318i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	GOH TSUI LI JEAN
NRIC No	S7043364H
Date Of Birth	03/12/1970
Occupation	INDOOR
Date Of Driving Pass	07/05/2003
Driving Experience	14 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91166231
Fax Number	
Contact Number	OFFICE-91166231
Email Address	JEAN.YIPGOH@GMAIL.COM

Address	67 EASTWOOD ROAD
Postcode	486589
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
Policyholder's Signature


Date & Time:

25/1/18 1:15pm

X 
Driver's Signature
(If driver is not the policyholder)

Date & Time:

25/1/18 1:15pm


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN


Grid area for sketch plan.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

P/s refer to police report No. T/2018 0125/2050

DECLARATION


I/We declare the foregoing particulars are true in every respect.

X 

Policyholder's Signature

Date & Time:

25/1/18 1:15 pm

X 

Driver's Signature
(If driver is not the policyholder)

Date & Time:

25/1/18 1:15 pm



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180125/2050

1 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129658
Tel No: 1800-8729999

Report No. T/20180125/2050

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/01/2018 11:43		Vide Report No.:		Station Diary No.: 78	
Informant's Particulars					
Name of Informant: GOH TSUI LI JEAN			Address: 67 EASTWOOD ROAD SINGAPORE 486589		
ID Type / ID No.: NRIC NO / S7043364H			Contact No.: Home/Office:		Mobile: 91166231
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 47	Date of Birth: 03/12/1970	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: FINANCE MANAGER			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 25/01/2018 06:50	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY				
Towards Tuas				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJP7661T	Car				Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180125/2050

2 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180125/2050

CONTINUATION OF REPORT

Driver			
Name	GOH TSUI LI JEAN		ID No. S7043364H
Related Vehicle	NIL		Contact No. 91166231
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving my vehicle bearing registration plate number: SJP7661T along AYE towards Tuas. While driving, near to Portsdown exit, the car in front of me slowed down and I then slow down. At that material moment, I looked on to my rear view mirror and noticed a motorbike was coming at a very high speed towards my vehicle. I then felt an impact on the rear of my vehicle. I then checked my rear view mirror again and noticed a motorbike had just collided onto my vehicle. I then filtered to the road shoulder. After managed to park my car at the road shoulder, I went back to the accident scene however the motor bike was no longer there.

There is no in car video camera installed in my vehicle. I wish to inform that I did not managed to take down the motorbike registration plate number.



**SINGAPORE
POLICE FORCE**



T/20180125/2050

3 of 3

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180125/2050

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Sgt 3 SAIFULBAHRI BIN SHA'ARI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
25/01/2018 11:43

Officer In Charge Of Case:
TP / HRT /
SI KALESWARI PALANI
Contact No.: 65476902

Classification Of Case:

Authentication Stamp
NP168



SN 37

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3364H
Vehicle Details	
Vehicle No.:	SJP7661T
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318I SEDAN LED NAV
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	F2241448B38B15A
Chassis No.:	WBA8E36040NU32216
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,860.00
Original Registration Date:	23 Dec 2016
First Registration Date:	23 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$28,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2026
PARF Rebate Amount:	\$21,603.00
Intended COE Rebate Details	

COE Expiry Date:	22 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$41,109.00
Total Rebate Amount:	\$62,712.00

The information contained herein is correct as at 31 Jan 2018

OK

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45645
Date Estimated : 25/01/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Goh Tsui Li Jean
67 Eastwood Road

Singapore 486589

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP7661T	NU32216	23/12/2016	318iA/4Dr	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident

To respray rear bumper

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

850 1275.00

934 1,038.00

561 661.00

150 177.00

150 177.00

net 80.00

Total Labour 1: 3,408.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
GUIDE FOR BUMPER SIDE LH
REAR BUMPER PANEL PRIMED (LINES)
SET MOUNTING PDC/PMA SENSOR REAR
PLUG BLACK D=5MM
SENSOR WIRE FOR SMART OPENER TOP
SENSOR WIRE FOR SMART OPENER BOTTOM
RR BUMPER LH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTER
PDC SENSOR MINERALWEISS (A96)
(DG) ADHESIVE SET K6

QTY	PRIC	VALUE
1	64.50	64.50
1	31.30	31.30
1	422.30	422.30
1	55.65	55.65
1	1,073.45	1,073.45
1	62.50	62.50
10	0.90	9.00
1	42.10	42.10
1	40.50	40.50
1	34.35	34.35
2	4.95	9.90
2	368.80	737.60
1	53.05	53.05

VALUE

64.50

31.30

422.30

55.65

1,073.45

62.50

9.00

42.10

40.50

34.35

9.90

737.60

53.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45645
Date Estimated : 25/01/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP7661T	NU32216	23/12/2016	318iA/4Dr	0

Total Parts : 2,636.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 30/01/18 @ 1425 Excess S\$ 500Surveyor's Name Risul Sign _____Surveyor's Tel 90060068 Authorised Yes / ☒ REVERT

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Resurvey & paint

[Handwritten signature]
21/1/18

6044.20

Labour 1	:	3,408.00
Parts	:	2,636.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	423.09
Grand Total	:	6,467.29

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45645
Date Estimated : 25/01/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Goh Tsui Li Jean
67 Eastwood Road

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 486589

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SJP7661T	NU32216	23/12/2016	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dented areas caused by the accident	850.00		850.00
To respray rear bumper	934.00		934.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (LINES)	1,073.45	1.00		1,073.45
SET MOUNTING PDC/PMA SENSOR REAR	62.50	1.00		62.50
(DG) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,189.00
Total Labour & Parts :	3,353.00
Deduction for Excess :	500.00
Total Repair Costs less Excess:	2,853.00
GST @7%:	199.71
Grand Total :	3,052.71

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001778/R1TD3N2

Date: 24/05/2018

REFERENCE

Insured/Claimant:	GOH TSUI LI JEAN	Policy No:	29048377SMP	Claim No:	547705
Date of Loss:	25/01/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP7661T	Engine No:	F2241448B38B15A
Make & Model:	BMW 318i, 1.5 (A)	Chassis No:	WBA8E36040NU32216
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	20273 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60R17	Rear Tyre Size:	225/60R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,716.20	1,269.00	1,447.20	53.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,328.00	2,084.00	1,244.00	37.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,044.20	3,353.00	2,691.20	44.53
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	5,544.20	2,853.00	2,691.20	48.54
+ GST 7.00/7.00% (S\$)	388.09	199.71	188.38	48.54
Nett Amount (S\$)	5,932.29	3,052.71	2,879.58	48.54

INSPECTION

Date of Assignment:	30/01/2018	
Date Inspected:	30/01/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2018)
Parts: 143	BMW 318I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJP7661T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER BOTTOM REINFORCEMENT	Serviceable	64.50 FS	*- FS
2	1		*REAR BUMPER CENTRE GUIDE	Serviceable	31.30 FS	*- FS
3	1		*REAR BUMPER CARRIER (ECE)	Serviceable	422.30 FS	*- FS
4	1		*GUIDE FOR BUMPER SIDE LH	Serviceable	55.65 FS	*- FS
5	1		*REAR BUMPER PANEL PRIMED (LINES)	Torn	1,073.45 FS	*1,073.45 FS
6	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	62.50 FS	*62.50 FS
7	10		*PLUG BLACK D=5MM	Serviceable	9.00 FS	*- FS
8	1		*SENSOR WIRE FOR SMART OPENER TOP	Serviceable	42.10 FS	*- FS
9	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Serviceable	40.50 FS	*- FS
10	1		*RR BUMPER LH REFLECTOR	Serviceable	34.35 FS	*- FS
11	2		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	9.90 FS	*- FS
12	2		*PDC SENSOR MINERAL WEISS (A96)	Serviceable	737.60 FS	*- FS
13	1		*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
14	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	2,716.20 1,269.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	-
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			3,328.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >