

ASSIGNMENT (Office)

From (Person): Genid Poh of LPC Date/Time: 30/01/2018 @ 7:42am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIN 2773Y Insured: _____

at Workshop m/s: Mova Automotive Tel: 6272 3892

of Blk 1008, Blk Meruh Lane 3 #01-04

Policy No: Z1VP05013141 Claim No: 17/18/18/VP05/020353

Sum Insured: _____ Excess: -

Make of Veh: _____ (Client's Record) D.O.A. 26/01/2018

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 30/1/18 @ 9:24am Person Contacted: Nitha Vehicle: IN / OUT

Date/Time	Action/Instruction	Estimate
		<u>SIN 2773Y - COA / LPC18061784 / 1783</u>
<u>01/2/18 @</u>	<u>11.5am</u>	<u>varant to Genid Poh via Meimen.</u>
<u>01/17/18 @</u>	<u>12.37pm</u>	<u>Chew Beng Kee informed C/A via Meimen.</u>
<u>01/12/18 @</u>	<u>3.08pm</u>	<u>informed Nitha C/A on P/P basis & ex. & of by email.</u>
<u>02/3/18 @</u>	<u>4.32m</u>	<u>confirmed with Judgey final fig & 1216.50, 2 days.</u>
		<u>(Red & 146, 112)</u>

Tanjung

Lpc

31/01/18

SJN27733

2009 Feb

① 12745 TRBERS 12085 EWA


To Inspected by: SJN 27733
Mova Automotive
BIK 1008, Bkt Merah Laine 3 #01-04

0 Toyota Alhis 1598
Silva
108844

Sum Insured: Entres NIL
Denda Record: After lunch.

Engine: M20532EE (06124915)

Steering Wheel: Jammed
Brake: Jammed
Tire Size: 205/55R16



Remarks: The ven had commenced its repair at the time of inspection.

BS DUA EKNOVA 3 FS LIA MO C-TSU PP SUM
TOYO YOKO

Bar of Warer value: 20K
DAD Accident Room: Consistent? Yes or No
GUA PP Beer: Consistent? Yes or No
Est Repars: 2 days Yes Yes or No
Lum Sum: Yes or No

Engine: 6
P/Ba: 6
L/Ba: 6
D/C/A: 2/1/1/5 @ 6pm
Super repars: SJN Mova Bm.

SA ① PEP 24-HRS
Date: Person Contacted: Venue: N/CUT

Des of Damages: P/Ba ① NS UC P/Ba
The UC Chassis frame Body Structure (metal, plastic, etc)

[Signature]
2/3/2018

RECEIVED 2018

07/3/2018
Pre Receipt
Final Receipt

Days Of Repair: 2
Reserve No of Days

100 x 20% = 20
100 + 20 = 120
50

Add Fee: Pre Receipt
Final Receipt

16

MEK-7A
1216.50

186 + 10

196



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD	Ref : CS/LPC18001784/T1qd3
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555	Date : 30-01-2018
	Code : LPC2



1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJN 2773Y
Policy No. ZIVP05013141	Coverage (\$)	0.00
Claim No. 17/18/18/VP05/020353	Excess (\$)	0.00
Assign From MERIMEN (GERALD POH)	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 26/01/2018	Inspection Date
Survey held at MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Claim	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018 Sendback Est	29 Jan 2018 18:13 S\$1,362.50	30 Jan 2018 07:42 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHEONG HUN HENG , ID: S0347125Z, Tel: +6593240032, Email: DAISYTHE.HH@GMAIL.COM		
Vehicle Reg. No.:	SJN2773Y	Date of Loss:	26/01/2018 13:00 - :59
Claim Type:	OD / 17/18/18/VP05/020353	Policy/Cover Note No.:	Z17VP05013141 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/02/2018]		
Driver/Custodian:	CHEONG HUN HENG (69 / Female), NRIC: S0347125Z, Tel: +6593240032		
Adj Asg. Remarks:	SURVEY & REVERT.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 2 March 2018 4:32 PM
To: 'Jacelyn'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: FINALIZATION: SJN2773Y - OD/LONPAC - TOYOTA COROLLA ALTIS 1.6A (DOA: 26/01/2018)

Dear Jacelyn,

Confirm final fig \$1,216.50 before GST and 2 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jacelyn [<mailto:jacelyn@nova.com.sg>]
Sent: Friday, 23 February 2018 4:42 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: FINALIZATION: SJN2773Y - OD/LONPAC - TOYOTA COROLLA ALTIS 1.6A (DOA: 26/01/2018)

Dear Taufikh,

Please find the attached 'Marking Estimate', 'Before-Paint' & 'After-Paint' photographs for your reference.

We propose the finalize amount at Part-By-Part \$ 1,216.50. Kindly revert.

Thank you, have a nice day.

Best Regards,

Jacelyn Ooi

Estimator

9686-9275

Email: jacelyn@nova.com.sg

Mova Automotive Pte Ltd

From: nitha [<mailto:nitha@nova.com.sg>]
Sent: Thursday, 1 February 2018 3:55 PM
To: 'Jacelyn'
Subject: FW: VEHICLE SJN 2773Y (DOA: 26/01/2018)

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 1 February 2018 3:08 PM
To: nitha@moval.com.sg
Cc: SUR
Subject: VEHICLE SJN 2773Y (DOA: 26/01/2018)

Dear Nitha,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SJN 2773Y** at **repair cost on part by part basis. (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Jan 2018 18:04	Clim Veh Model Changed	(203311) TOYOTA COROLLA ALTIS 1.6 (A).	[R] Monitha Gunasekaran
2	29 Jan 2018 18:04	Clim Created	Reg No: SJN2773Y. Policy No: Z17VP05013141. Acct Date: 2018/01/26. Claim Type: OD. Insurer: Lonpac Insurance Bhd (HQ). Workshop: Mova Automotive Pte Ltd (Bukit Merah). Created from SAS:MMOV18013094	[R] Monitha Gunasekaran
3	29 Jan 2018 18:13	Clim Submitted	1362.50.	[R] Monitha Gunasekaran
4	30 Jan 2018 07:42	Clim Registration Modified	Excess: -> 0.00.	[I] Gerald Poh
5	30 Jan 2018 07:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY & REVERT.	[I] Gerald Poh
6	30 Jan 2018 07:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/08	[I] Gerald Poh
7	30 Jan 2018 07:42	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Gerald Poh
8	30 Jan 2018 09:00	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	30 Jan 2018 11:42	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
10	01 Feb 2018 11:53	Adj Rpt Initiated		[A] SHIAU CHAN
11	01 Feb 2018 11:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/08	[A] SHIAU CHAN
12	01 Feb 2018 11:55	Adj Mandate Request	Cur Req:1262.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	01 Feb 2018 12:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/08	[I] Chew Beng Kee
14	01 Feb 2018 12:33	Adj Mandate Set	Approved:1262.50.	[I] Chew Beng Kee

ACTIVITY

[30/01/2018 09:24] Nivitha Govindasamy:
Vehicle not in workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1708608	29/01/2018 18:04	Motor	Mova Automotive Pte Ltd (HQ)	Mova Automotive Pte Ltd (Bukit Merah)	SJN2773Y		xx.xx
1712588	01/02/2018 11:53	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJN2773Y		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 01 Feb 2018

Preliminary Advice

Vehicle No	: SJN2773Y	Accident Date	: 26/01/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: Z17VP05013141
Assignment Date	: 30/01/2018	Excess	: S\$0.00
Date of Inspection	: 31/01/2018	Est. Duration of Repair	: 2.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG,#07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,362.50
Revised Amount	:S\$	1,262.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,262.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	9,122.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,878.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 7125Z

Vehicle Details

Vehicle No.: SJN2773Y
 Vehicle to be Exported: No
 Intended De-registration Date: 01 Feb 2018
 Vehicle Make: TOYOTA
 Vehicle Model: COROLLA ALTIS 1.6 AUTO
 Primary Colour: Silver
 Manufacturing Year: 2008
 Engine No.: 3ZZ4816449
 Chassis No.: MR053ZEE106124915
 Maximum Power Output: 80.0 kW (107 bhp)
 Open Market Value: \$16,084.00
 Original Registration Date: 11 Feb 2009
 First Registration Date: 11 Feb 2009
 Transfer Count: 0
 Actual ARF Paid: \$16,084.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 10 Feb 2019
 PARF Rebate Amount: \$8,846.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2019
 COE Category: A - Car (1600cc & below)
 COE Period(Years): 10
 QP Paid: \$2,693.00
 COE Rebate Amount: \$276.00
Total Rebate Amount: \$9,122.00

The information contained herein is correct as at 01 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2018 16:27
Date Of Accident	26/01/2018 13:40
Exact Location Of Accident	KING'S ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN2773Y
Insured/Policyholder	
Name Of Registered Owner	CHEONG HUN HENG
NRIC No	S0347125Z
Email Address	DAISYTHE.HH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93240032
Alternative Phone No	OTHERS-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05013141
Cover Note Number	

Driver

Name of Driver	CHEONG HUN HENG
NRIC No	S0347125Z
Date Of Birth	25/10/1948
Occupation	INDOOR
Date Of Driving Pass	20/08/1976
Driving Experience	41 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93240032
Fax Number	
Contact Number	OTHERS-NOPHONE
EMail Address	DAISYTHE.HH@GMAIL.COM

Address 6 PANDAN VALLEY
#15-601

Postcode 597630

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : TEH HONG KIA
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

-

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR3688X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TAN YI JIE HAZEL

NRIC/Passport Number S8239472I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 26/1/18
4:25pm

Driver's Signature

(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

King's Road



A - SJN 2773Y
B - SKR 3688X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SJN 2773Y	ACCIDENT DATE & TIME: 26/1/18 1.40pm
CONTACT NUMBER: 93240032	E-MAIL ADDRESS: daisyteh.hh@gmail.com
LOCATION: King's Road	
<p>My car was stationary at King's Road with flickering light at the roadside. My husband was seated at the back seat. As he opened the rear door slightly a passing car a passing car must have hit against the door, as he heard the sound. The driver of the other vehicle stopped and we exchanged particulars. Photographs of the 2 cars were taken. There was no injury. The rear door of my car was slightly damaged and the ^{side mirror} rear of the other vehicle was damaged.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input checked="" type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Cherry Huntley
 Policyholder's Signature
 Date & Time: 26/1/18
 4.25pm

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Main Office : No. 22, Jaien Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: **Lonpac insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05013141	Date of Loss:	26/01/2018
Vehicle Reg. No.:	SJN2773Y	Driveable?	
Driver Age/Info:	69 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEONG HUN HENG	Contact No:	+6593240032
Driver:	CHEONG HUN HENG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	11/02/2009
Vehicle Colour:	GREY/SILVER	Chassis No:	MR053ZEE106124915
Engine No:	3ZZ4816449		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	-		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

Tan Guan 97495749
3/1/18 @ 6pm
Revert
Ex: NIL
Lumpsum after
Resurvey before repair
2 days
Sur @ LKKAUTO.COM

COST OF CLAIMS

	Amount
Parts	862.50
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	1,362.50
- Excess (S\$)	1.00
(S\$)	1,361.50
+ GST 7.00% (S\$)	95.31
Nett Amount (S\$)	1,456.81

This claim is handled by: **JACELYN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 29 Jan 2018)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN2773Y)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the **END OF ESTIMATES** marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH	0.00	0.00	bt ✓ *450.00 F
2	2		*REAR DOOR BLACK TAPE RH	0.00	40 0.00	neg ✓ *80.00 F
3	1		*REAR DOOR WEATHERSTRIP RH	0.00	0.00	cut ✓ *150.00 F
4	1		*REAR DOOR MOULDING RH	0.00	0.00	cut ✓ *45.00 F
5	1		*REAR DOOR MOULDING CHROME RH	0.00	0.00	cut ✓ *25.00 F
Sub Total (\$\$)						750.00
+ Margin on L,N Items 15.00% (\$\$)						112.50
Total Parts (\$\$)						862.50

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REPLACE NEW DOOR . TO TRANSFER ITEMS INTO NEW DOOR. TO ALIGN ALL CONNECTION.	New	200 250.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	200 250.00
Gross Labour Cost (\$)			500.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z17VP05013141	Date of Loss:	26/01/2018
Vehicle Reg. No.:	SJN2773Y	Driveable?	
Driver Age/Info:	69 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEONG HUN HENG	Contact No:	+6593240032
Driver:	CHEONG HUN HENG		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	11/02/2009
Vehicle Colour:	GREY/SILVER	Chassis No:	MR053ZEE106124915
Engine No:	3ZZ4816449		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	3		

PBP
 Tawfik 97495749
 3/1/18 @ 6pm
 Reverts Ex: NIL
 Lumpang affa
 Resurvey before repair
 02 days
 swr@uklands.com

Description of Accident/Loss -
 Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS	Amount
Parts	862.50
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	1,362.50
- Excess (S\$)	1.00
(S\$)	1,361.50
+ GST 7.00% (S\$)	95.31
Nett Amount (S\$)	1,456.81

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Part = \$ 816.50
 Lab = \$ 400.00
\$1216.50

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronized: 29 Jan 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJN2773Y)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH	0.00	0.00	450.00 450.00 F
2	1		*REAR DOOR BLACK TAPE RH	0.00	0.00	80.00 80.00 F 40
3	1		*REAR DOOR WEATHERSTRIP RH	0.00	0.00	150.00 150.00 F
4	1		*REAR DOOR MOULDING RH	0.00	0.00	45.00 45.00 F
5	1		*REAR DOOR MOULDING CHROME RH	0.00	0.00	25.00 25.00 F
				Sub Total (\$\$)		710.00 750.00
				+ Margin on L,N Items 15.00% (\$\$)		106.50 112.50
				Total Parts (\$\$)		816.50 862.50

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & REPLACE NEW DOOR . TO TRANSFER ITEMS INTO NEW DOOR. TO ALIGN ALL CONNECTION.	New	250.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	250.00
Gross Labour Cost (S\$)			500.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司
JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Dept Direct: 6305 9810

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001, #01-51 BUKIT MERAH LANE

710

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JACELYN

TAX INVOICE : AR201802-00767
DATE : 01/02/2018
CUSTOMER ID : MOV001
VEH REG. NO. : SJN2773Y
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T75923-02180/12060 ZZE141	REAR DR TAPE RH(12060)	PA PL2-J1-07A	1	40.00	40.00
2	T67871-02300/12530 ZZE141	RR DOOR RUBBER RH	PA PL1-A1-15P	1	150.00	150.00
3	T75741-02917/9 ALTIS-ZZE141	RR DR PROTECTOR RH 08"	PA PL2-K1-08M	1	45.00	45.00
4	T75797-02040 ZZE141	RR DOOR PROT MLDG RH	PA PL2-E1-08A	1	25.00	25.00

SUB-TOTAL : 260.00
ADD GST 7.00 % 18.20

E. & OE

TOTAL AMOUNT SGD : 278.20

[P] 01/02/2018 4:19:26PM

[E] 01/02/2018 4:14:45PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAN

This is computer generated document.
No signature is required.



AR201802-00767

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9638

Arrange By _____ Driver _____

Dept Direct: 6306 9810 Dept Direct: 6306 9811 Dept Direct: 6417 9792

Dept Direct: 6417 9794 Dept Direct: 6417 9795 Dept Direct: 6417 9796 Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

MOVA AUTOMOTIVE PTE LTD
BLK 1001 ,#01-51 BUKIT MERAH LANE

SINGAPORE 159419
TEL : 62723892/97185821 YONG FAX : 62708314/62643151
ATTN : JACELYN

TAX INVOICE . AR201802-00770
DATE : 01/02/2018
CUSTOMER ID : MOV001
VEH REG. NO. : SJN2773Y
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
1. T67003-12A20/02340 ALITS-Z/E141	RR DOOR RH	UJ	1	450.00	450.00
SUPPLIER					

SUB-TOTAL : 450.00
ADD GST 7.00 % 31.50

E. & O.E TOTAL AMOUNT SGD: 481.50

[P] 01/02/2018 4:19:33PM

[E] 01/02/2018 4:17:14PM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : HAN



Goods Received in Good Order

Signature / Co Stamp / Date

This is computer generated document.
No signature is required.

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2018 Sendback Est	29 Jan 2018 18:13 S\$1,362.50	30 Jan 2018 07:42 Edit Adj Rpt	S\$1,216.50 Edit Estimates	S\$1,216.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	CHEONG HUN HENG, ID: S0347125Z, Tel: +6593240032, Email: DAISYTHE.HH@GMAIL.COM		
Vehicle Reg. No.:	SJN2773Y	Date of Loss:	26/01/2018 13:00 - :59
Claim Type:	OD / 17/18/18/VP05/020353	Policy/Cover Note No.:	Z17VP05013141 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	LONPAC Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/02/2018]		
Driver/Custodian:	CHEONG HUN HENG (69 / Female), NRIC: S0347125Z, Tel: +6593240032		
Adj Asg. Remarks:	SURVEY & REVERT.		

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
• LONPAC_HQ (01/02/2018): Alert - Adj Mandate Approved (S\$1262.50) - SJN2773Y - Claim Handler: Gerald Poh	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN2773Y (17/18/18/VP05/020353)
OD
Jan 26 2018 1:00PM
[CHEONG HUN HENG]
Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail Print
1	29/01/18 18:13	Repalrer Estimates	<input checked="" type="checkbox"/> Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	01/02/18 11:54	Adjuster Immediate Advice	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	01/02/18 11:47	Odometer Reading	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	01/02/18 11:47	Chassis Number	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	01/02/18 11:47	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail Print
1	29/01/18 18:12	Certificate of Insurance	<input checked="" type="checkbox"/> Load PDF
2	29/01/18 18:12	Drivers Driving License	<input checked="" type="checkbox"/> Load TIF
3	29/01/18 18:12	E-filed GIA report	<input checked="" type="checkbox"/> Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	01/02/18 11:46	WORKSHOP ESTIMATE	<input checked="" type="checkbox"/> Load PDF
2	08/03/18 09:01	Parts Invoice	<input checked="" type="checkbox"/> Load PDF

Linked Accident Report Documents

			View View in Browser ▼
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail Print
1	26/01/18 17:05	Accident Statement	<input checked="" type="checkbox"/> Load HTM

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	26/01/18 17:05	Driving License		Load JPG	<input checked="" type="checkbox"/>
2	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	26/01/18 17:05	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	26/01/18 17:02	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<p>Show Remarks To: <input type="checkbox"/> Repairer <input checked="" type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18001784/T1QD3E2
Date: 08/03/2018

REFERENCE

Insured/Claimant: CHEONG HUN HENG **Policy No:** Z17VP05013141
Date of Loss: 26/01/2018 **Nature of Claim:** OD **Claim No:** 17/18/18/VP05/020353

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN2773Y**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) **Engine No:** 3ZZ4816449
Reg. Date: 11/02/2009 (Man. Year: 2008) **Chassis No:** MR053ZEE106124915
Colour: Silver **Odometer:** 108844 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$20,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 **Rear Tyre Size:** 205/55 R16
Front Left Side: Goodyear 6 mm **Rear Left Side:** Goodyear 6 mm
Front Right Side: Goodyear 6 mm **Rear Right Side:** Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	862.50	816.50	46.00	5.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	400.00	100.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,362.50	1,216.50	146.00	10.72
- Excess (S\$)	1.00	0.00	1.00	100.00
(S\$)	1,361.50	1,216.50	145.00	10.65
+ GST 7.00/7.00% (S\$)	95.31	85.16	10.15	10.65
Nett Amount (S\$)	1,456.81	1,301.66	155.15	10.65

INSPECTION

Date of Assignment: 30/01/2018 **Present Location:** Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected: 31/01/2018 **Inspected At:** BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 .
SINGAPORE 159722
Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN2773Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR DOOR RH (WCP)	Bent	450.00 F	*450.00 F	
2	1		*REAR DOOR BLACK TAPE RH (WCP)	Necessary-1pc only	80.00 F	*40.00 F	
3	1		*REAR DOOR WEATHERSTRIP RH (WCP)	Cut	150.00 F	*150.00 F	
4	1		*REAR DOOR MOULDING RH (WCP)	Cut	45.00 F	*45.00 F	
5	1		*REAR DOOR MOULDING CHROME RH (WCP)	Dented	25.00 F	*25.00 F	
					Sub Total (S\$)	750.00	710.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	112.50	106.50
					Total Parts (S\$)	862.50	816.50

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE NEW DOOR . TO TRANSFER ITEMS INTO NEW DOOR. TO ALIGN ALL CONNECTION.	New	250.00	200.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	250.00	200.00
Gross Labour Cost (\$)			500.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >