



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 VOLKSWAGEN JETTA 1.4 TSI SPORTS (SKA8759G)

Date of Loss

22 January 2018

Time of Loss

17.15

Loss Description

SKA8759G (INSD) C/W SHB1853T (TP)

Comment

Workshop Details

Total Rebate Amount

27758

Nett Loss Amount

\$11,242.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

23/07/2018



Days of work completion *

174



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKA8759G

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

11/04/2011



Mileage

146125

Age of Vehicle

6

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2011

ASSESSMENT INFO...

2010

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

JESSIE GOH

POST SURVEY INF...

CATEGORY	Make	
POLICY INFORMAT...	VOLKSWAGEN	
ASSESSMENT INFO...	VOLKSWAGEN	

CATEGORY	Model	
POLICY INFORMAT...	JETTA 1.4 TSI SPORTS	
ASSESSMENT INFO...	JETTA 1.4 TSI AT 1K23Q5 MX	

CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		

CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		

CATEGORY	Chassis No	
POLICY INFORMAT...	WVWZZZ1KZBM014785	

CATEGORY	Date of Birth	
FNOL INFORMATI...		
POST SURVEY INF...	dd/mm/yyyy	

CATEGORY	Age	
FNOL INFORMATI...	0	
POST SURVEY INF...		

CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		

CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		

CATEGORY	Driving Experience	
----------	--------------------	--

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... CAV216195

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S13495761

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/55R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/55R16

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/J BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			FRONT BUMPER			Repair	0	0	0	0	0	Deny
☐		2	1			BUMPER GUIDE PIECE LH			Serviceable	0	0	0	0	0	Deny
☐		3	1			BUMPER GUIDE PIECE RH			Serviceable	0	0	0	0	0	Deny
☐		4	1			BUMPER BRACKET LH			Serviceable	0	0	0	0	0	Deny
☐		5	1			BUMPER BRACKET RH			Serviceable	0	0	0	0	0	Deny
☐		6	1			LOWER SPOILER			Serviceable	0	0	0	0	0	Deny
☐		7	1			COOLING AIR GRILL LH			Serviceable	0	0	0	0	0	Deny
☐		8	1			FRONT BUMPER CHROME LH (WCP) (15%)			Damaged	78.2				78.2	Reviewing

Labour

Add

Approve

Deny

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐		1		TO REMOVE / REPLACE / REFIT & PANEL BEAT FOR FRONT BUMPER & OTHER AFFECTED AREAS	200	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		TO PUTTY & RESPRAY OF FRONT BUMPER	200	0	0	Reviewing		
		3		TO CHECK ACCIDENT AFFECTED WIRING SYSTEM & RECOVER	0	0	0	Deny		
		4		TO RECODE & DECODE ENGINE MANAGEMENT SYSTEM & FAULT CODE CLEARING AFTER REPAIR WORKS	0	0	0	Deny		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 2 DAYS	Reviewing		

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$478.20			Claim Amount	\$478.20			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$400.00	\$400.00
		Submit for Review