

ASS. REC. BY:

REF: CS3/AXA18001787/Gb52

Special Instruction:

Surveyor

GIR

ASSIGNMENT (Office)

Menimen

From (Person):

Ernest Tay

of

AXA

Date/Time:

30/1/18 @ 8:49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 1994S

Insured:

SHB 9926P

at Workshop m/s

Twincar Automotive

Tel:

68420051

of

Blk 2 Kaki Bukit # 01-17/18

Policy No:

P1680520

Claim No:

C0468884

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

R.O.D. Endorsement:

Date/Time:

9:27am @ 30/1/18

Person Contacted:

Mebody

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLC 1994S - NA/DA/18001650/r3

D.O.A.: 25/01/18

SHB 9926P - NA/DA/18001650/r3

D.O.A.: 25/01/18

Dismantle Part: 31.01.2018

After repair: 02.02.2018


21/03/18 5:29pm Email to Ernest Tay thru Menimen

PRS
XHL

AXA

ASSIGNMENT

Date: 30/01/18
 To: SLC 1994S
 Twincar Automotive
 BIK 2, kaki Bkt # 01-17/18
 Insured: _____
 Policy No: _____
 Demand: _____
 Sum Insured: _____ Excess: _____
 Claims Record: _____
 Make of Van: _____



Policy Condition:
 Remarks: The van had commenced its repair at the time of inspection.

Body or Marine Value: _____
 D.O.A. Accident Report: _____ Consistent? Yes or No
 D.O.A. P.D. Report: _____ Consistent? Yes or No
 Est. Repairs: _____ days Fee: Yes or No
 Sum Insured: _____ Rs. D.O.A. Yes or No
 D.O.A. REP / REP 24 HRS w/p
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

SLC1994S 20 Nov 2009
 Toyota Lexus RX450H 3456
 Black
 B55714
 JTJBC11A402015860
 Gen. Cond: Good Fair Poor Burnt
 Steering: Good Jammed Locked Burnt
 Brake: Good Jammed Locked Burnt
 Mod: N/A S/Rum STD
 Tyre Size: R 235/60 R18
 BS/DUN/EXNOVA BY PS/LZA/VIC/CHTL/PR/SLM
 TOYO/YOKO NEXEN
 Front: 6 Rear: 6
 LBA: 6
 D.O.A. 30-01-18
 Surveyed at: w/s Twincar 3pm
 Des of Damages: Front: Good OS NS L/O Roof/hood

The L.O. Chassis frame, Body Structure affected due to collision

RECEIVED 20 MAR 2018

Case File Fee: ☐ Prelim Report
☐ Final Report
 24032018

Days Of Report
 Resurvey No. of Time

Add Fee: ☐ Site Visit
☐ H.R. 1
☐ H.R. 2
☐ H.R. 3



Report Receipt
 24032018 PRS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA18001787/Gb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-01-2018



Code : AXA2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHB 9926P	Veh. Inspected	SLC 1994S
Policy No.	P1680520	Coverage (\$)	0.00
Claim No.	C0468884	Excess (\$)	0.00
Assign From	MERIMEN (ERNEST TAY)	Assign Date	30/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/01/2018	Inspection Date	30/01/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 08:49 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	LAU,KOK SENG, ID: S79020058		
Vehicle Reg. No.:	SLC1994S	Date of Loss:	25/01/2018 00:00 - :59
Claim Type:	TP / C0468884	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9926P	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/02/2018]		
Driver/Custodian (Insured):	LIM SOO HWEE (58 / Male), NRIC: S1356161C, Tel: +6581982768		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (30/01/2018): New TP Assignment - C0468884/P1680520

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Vehicle No.	SLC 1994S	Model / Make Lexus UX 450	
Date of Accident	25/1/18		
Time of Accident	17.30	HRS	
Location of Accident	PIE Toward Tuas Before CTE Exit		
Exact purpose use during accident	Private Use		
Name of Owner	Lau Kok Seng		
Telephone No.	H/P: 9798 9978	Home:	Office:
NRIC	S7902005B		
Address	11 Anchorvale Crescent #10-02 S(544649)		
Claim type	OD	(THIRD PARTY) REPORTING ONLY	
Insurance Company	Direct Asia		
Type of Coverage	(Comprehensive)	Third Party	Third Party / Fire / Theft
Policy No.	MT/00432241		
Name of Driver	(As Above) If No,		
NRIC	Any Passengers: Nil		
Date of birth	11/1/1979		
Occupation	Outdoor	/	Indoor
Driving License Pass Date	6 Jul 1998		
Gender	(Male) / Female		
Contact No.	H/P:	Home:	Office:
Address			
Driver have any own vehicle	(No)	If yes, Reg No.	
Relationship	Employee,	(If no, state Owner)	
Weather condition	(Clear)	Raining	Other
Road Surface	(Dry)	Wet	Other
Any Injuries	No,	(If Yes, Who?)	
Name And Contact No.			
Name And Contact No.			
Police Report	No,	(If Yes, Where?) Boon Teck NPP	
Vehicle B No.	SHB 9926P	Any Passengers: 1	
Name of Driver		Contact No.:	
Vehicle C No.		Any Passengers:	
Vehicle D No.		Any Passengers:	
Vehicle E no.		Any Passengers:	
Vehicle F No.		Any Passengers:	
Vehicle G No.		Any Passengers:	
Witness Name		Witness Contact:	
Accident Portion	Rear Portion		
Camera Recorder	(Yes) / No Not Working		
Email Address	garylau7979@gmail.com		
PARTICULAR WORKSHOP	Twincar Automotive Pte Ltd		
CONTACT NO.	6842 0051 / 6744 0510		
CONTACT PERSON	Amos		
FAX NO	6741 0510		
WORKSHOP Email ADDRESS	sales@n51.com.sg		


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

P1E Toward Tuas Before CTE Exit



A-SLC 1994S


B-SHB 9926P


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


As per police report no. 7/20180126/2064

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180126/2064

1 of 3

Police Station Of Origin:
Boon Teck NPP
207 Toa Payoh North #01-1231 SINGAPORE
310207
Tel No: 1800-2549999

Report No. T/20180126/2064

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/01/2018 12:37	Vide Report No.:	Station Diary No.: 9
--	------------------	-------------------------

Informant's Particulars

Name of Informant: LAU KOK SENG			Address: 11 ANCHORVALE CRESCENT #10-02 SINGAPORE 544649		
ID Type / ID No.: NRIC NO / S7902005B			Contact No.: Home/Office: Mobile: 97989978		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 11/01/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: MARKETING EXECUTIVE			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident

General Information of the Accident:				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/01/2018 17:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Towards Tuas before CTE (City) Exit - lane 1				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB9926P	Taxi	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red	Seriously Damaged	1
SLC1994S	Car	TOYOTA	LEXUS RX450H	Grey	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Boon Teck NPP
207 Toa Payoh North #01-1231 SINGAPORE
310207
Tel No: 1800-2549999

Report No. T/20180126/2064

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLC1994S	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MT/00432241	20/11/2017	19/11/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	LIM SOO HWEE		ID No.	S1356161C
Related Vehicle	SHB9926P (Taxi)		Contact No.	81982768
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	LAU KOK SENG		ID No.	S7902005B
Related Vehicle	SLC1994S (Car)		Contact No.	97989978
Hospital/Clinic	DOCTORS INC. MEDICAL GROUP		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	26/01/2018		Date Discharge	26/01/2018
No. of Days granted Medical Leave		03	Degree of Injury	Slight

Brief Details.

On 25/01/2018 at about 1750hrs, I was driving my car SLC1994S along Pan Island Expressway (PIE) towards Tuas. Before CTE(City) Exit, the traffic was heavy and I was along Lane 1 of the expressway. Vehicles at the front start slowing down and I followed, applied my brake and slowed down. At that moment, a taxi SHB9926P came from my rear hit to my vehicle. Both vehicles came to a stop and I came out to make a check. Afterwhich we took some photos at scene and the damages to the vehicle. We also exchange particulars and I continued my journey. The taxi was subsequently towed as there was smoke coming out from the front bonnet. Damages found on my rear portion, scratches, dents and cracks. The said taxi front side is damage and the bonnet cover was open and dented. On 26/01/2018 I visited the doctor and was given 3 days MC.



**SINGAPORE
POLICE FORCE**



T/20180126/2064

3 of 3

Police Station Of Origin:
Boon Teck NPP
207 Toa Payoh North #01-1231 SINGAPORE
310207
Tel No: 1800-2549999

Report No. T/20180126/2064

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
E /
Sgt 2 MUHAMMAD ZULHAFFIZ BIN MOHD ZIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sgt 2 YEO KIA HUAT
Contact No.: 65476325

Authentication Stamp
NP168

SN 062

SIGNATURE

Signature Of Informant:

Date/Time:
26/01/2018 12:37

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2005B
Vehicle Details	
Vehicle No.:	SLC1994S
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS RX450H
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	2GRJ166835
Chassis No.:	JTJBC11A402015860
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$69,509.00
Original Registration Date:	20 Nov 2009
First Registration Date:	20 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$41,706.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2019
PARF Rebate Amount:	\$22,938.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,510.00
COE Rebate Amount:	\$3,517.00
Total Rebate Amount:	\$26,455.00

The information contained herein is correct as at 31 Jan 2018

OK

▶ Lexus RX450h Used Vehicle List (4 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Lexus RX450h Hybrid (Petrol-Electric)	\$51,800	\$16,540 /yr	16-Dec-2009	3,456 cc	-	Presto Expat Motoring Services Pte Ltd	Available
Power-Packed With A 3.5L Engine, The RX450h Gives You Responsive Rides While Providing Fuel Economy With Its Hybrid Build. Spaciously Built Cabin Allows For Comfortable Drives Everywhere. This Unit Pr...							
Office No. - 67327737 Lionel - 85117181							
Lexus RX450h Hybrid (Petrol-Electric)	\$48,888	\$17,260 /yr	17-Sep-2009	3,456 cc	120,000 km	Mr Benz Traders	Available
CHEAPEST In The Market! Brand New Paintwork And Brand New Leather Upholstery. Stain-Resistant Leather Seats! Like New Car! Car Serviced Regularly. Excellent Condition, View To Appreciate.							
Office No. - 63461282 Bernard Foong - 96609891 Wee - 92240044 K C - 86616867 Richard - 97711650							
Lexus RX450h Hybrid (Petrol-Electric)	\$47,800	\$19,140 /yr	30-Jun-2009	3,456 cc	104,000 km	Car Lingual	Available
Well Maintained By Meticulous Owner, Excellent Condition, Beautiful Paintwork. Lexus Flagship Model. Powerful And Efficient Luxury SUV. Please Feel Free To Call Our Friendly Sales Consultants Now For ...							
Lexus RX450h Hybrid (Petrol-Electric)	\$46,500	\$18,430 /yr	18-Jun-2009	3,456 cc	65,100 km		Available
Luxury SUV In Excellent Condition. Low Mileage - Just Over 65,000 Km! Great Value With New Batteries And Tires. Ideal For COE Renewal. Accident Free. Shelter Parked Director's Car. Contact Owner Now. ...							
Office No. - - Johnson - 92985145							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

View Sent Message

This mail is associated with :

***SLC1994S (C0468884)**

[SHB9926P]

TP

LAU,KOK SENG

Jan 25 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

Twincar Automotive Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 24/03/2018 17:29 PM.
To AXA_ErnestTay
CC AXA_SG
Subject Pre-repair Inspection

Dear Ernest,

Refer to your assignment on 30.01.2018 at 8.49AM.

Please be informed that we have inspected the vehicle SLC 1994S on 30.01.2018 at 4.26PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		30 Jan 2018 08:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	LAU,KOK SENG, ID: S7902005B		
Vehicle Reg. No.:	SLC1994S	Date of Loss:	25/01/2018 00:00 - :59
Claim Type:	TP / C0468884	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9926P	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/02/2018]		
Driver/Custodian (Insured):	LIM SOO HWEE (58 / Male), NRIC: S1356161C, Tel: +6581982768		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (30/01/2018): New TP Assignment - C0468884/P1680520

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC1994S (C0468884)**
[SHB9926P]
TP
LAU,KOK SENG
Jan 25 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Twincar Automotive Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#) ▼

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	29/01/18 08:59	GIA SHB9926P INSD_ABS	Load PDF	
2	29/01/18 08:59	GIA SLC1994S TP_ABS	Load PDF	
3	29/01/18 08:59	EMAIL_ABS	Load PDF	
4	29/01/18 08:59	WORKSHOP_ABS	Load PDF	
5	29/01/18 09:02	LIST OF SURVEY_ABS	Load PDF	
6	29/01/18 11:31	Email from TP - Reject our Surveyor Listing	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/18 17:28	LKKPhotosIn6-1	Load PDF	
2	24/03/18 17:28	LKKPhotosIn6-2	Load PDF	
3	24/03/18 17:28	LKKPhotosIn6-3	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA18001787/GBS2
Date: 27/03/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No : SLC1994S **Insured Vehicle No :** SHB9926P
 Date of Loss: 25/01/2018 Nature of Claim: TP Claim No: C0468884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC1994S**
 Make & Model: LEXUS RX450H, 3.5 (A) Engine No: 2GRJ166835
 Reg. Date: 20/11/2009 (Man. Year: 2009) Chassis No: JTJBC11A402015860
 Colour: Black Odometer: 135714 km
 Engine Capacity: 3456 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2018
 Date Inspected: 30/01/2018 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/27/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2018)
Parts:	M1-SUV	LEXUS RX450H 3.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC1994S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >