

Range 2 days

ASS. REC. BY:

REF: CS3/CTI18001791/Wd3sz

Special Instruction:

Surveyor:
Meimien

Wilson

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time:

29/1/18 @ 4:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G4120Y

Insured:

SGD 1198C

at Workshop m/s

Hong Motor Service

Tel:

6282 2052

of

Blk 5035, AMK Ind. Prk 2 (off Ave 3) # 01-365

Policy No:

DMPCSN1439361705

Claim No:

SNM18D00508C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

9:17am @ 30/1/18

Person Contacted:

Ah Huat

Vehicle:

IN OUT

Date/Time	Action/Instruction (X) Estimate
	G4120Y - X
	SGD 1198C - X

Wilson

ASSIGNMENT

From: Date 30/1/2018
 Estimated Cost:
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV
 To inspect Vehicle No: GY 120 Y
 at Workshop mis: Hong Motor Service
 of BK 5035, AMK Ind Park 2
 Insured: # 01-365
 Policy No:
 Claims No:
 Sum Insured: Excess
 (Client's Record)
 Make of Veh:

Veh No: GY 120 Y Vr Reg: 2/12/2004
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Lit. cc 2184
 Colour: Silver AC Insured / Std / NI / NA
 Sp. Reading: T. Radio Insured / Std / NI / NA
 Eng No:
 C/No: CR42 5018747
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value:
 IDAO Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted Vehicle: IN / OUT

N/S	O/S

Tyre Size: F: 165 R13C
 R: 165 R13C
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wentlake (F)
Dura Grip (R)
 Front
 R/Bal: 4 mm R/Bal: 4 mm
 L/Bal: 4 mm L/Bal: 4 mm
 D.O.A. DOJ: 30/1/2018
 Survey held at: As Above
 Des. of Damages: Frt / Res / O/S / N/S / U/C / Roof top or
 The U/C / Chassis frame / Body Structure affected due to collision

30/1/18 Van Over Turn
Mileage Not Recorded - Battery Flat
Accident Report Not Given
Range \$15,000 - \$18000
(18 Days of Repair)

RECEIVED 25 APR 2018

Date/Time File Pass to: ☐ : Preli. Report Days Of Repair: 18
☐ : Final Report Resurvey No. of Trip: 1
 Date/Time File Return to:
 Add Fee: ☐ Site Insp IS
☐ Interview IS
☐ Tech Insp IS
☐ Weekend IS
 Report Format: PR2
 Lump Sum / I.B.I: IS
 Survey Fee
 Transcon
 Price
 Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		29 Jan 2018 16:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant: **PDT ENTERPRISE PTE LTD,** Co. Reg. No.: 200400348N

Vehicle Reg. No.: **GY120Y** Date of Loss: 22/01/2018 00:00 - :59

Claim Type: **TP / SNM18D00508C02** Policy/Cover Note No.: DMPCSN1439361705

Vehicle Reg. No. (Insured): **SGD1198C** Policy No. (Claimant):

Excess: S\$0.00

Repairer: **Hong Motor Service (HQ)** Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538, 569538 Ang Mo Kio - Tel: 62822052

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Joel Goh**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Final Rpt** due 07/02/2018]

Adj Asg. Remarks: NO EST, CASE W/O SJE.

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter

→ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/H1/1812201/st
Your Reference : SGD 1198C

Date : 29th January 2018

BY FAX & EMAIL: 6224-7478 &
claimsdept@sg.cntaiping.com ONLY

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 22/01/2018 INVOLVING VEHICLE NOS. GY 120Y AND SGD 1198C ALONG KPE TOWARDS TPE BEFORE PAYA LEBAR EXIT.

We are instructed by PDT ENTERPRISE PTE LTD (owners of motor vehicle no. GY 120Y) and/or HONG MOTOR SERVICE (the motor workshop for GY 120Y) to notify you of a road traffic accident on 22/01/2018 at about 1505 hours along KPE TOWARDS TPE BEFORE PAYA LEBAR EXIT involving our client's vehicle registration number [GY 120Y] and [SGD 1198C] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO - (Branch Office)

Encl

c.c. 1) FONG CHEE WAH

(Vehicle : SGD 1198C)

- 2) **NAME OF WORKSHOP : HONG MOTOR SERVICE**
Blk 5035 Ang Mo Kio Industrial Park 2
#01-365
Singapore 569538
Telephone : 6282-2052 (Ah Huat)

(Vehicle : GY 120Y)

Fax : 6556-2934

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Please reply to our Branch Office for this matter

→ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sg

Our Reference : MN/IG/H1/1812201/st
Your Reference : SGD 1198C

Date : 29th January 2018

BY FAX & EMAIL: 6224-7478 &
claimsdept@sg.cntaiping.com ONLY

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 22/01/2018 INVOLVING VEHICLE NOS. GY 120Y AND SGD 1198C ALONG KPE TOWARDS TPE BEFORE PAYA LEBAR EXIT.

We are instructed by PDT ENTERPRISE PTE LTD (owners of motor vehicle no. GY 120Y) and/or HONG MOTOR SERVICE (the motor workshop for GY 120Y) to notify you of a road traffic accident on 22/01/2018 at about 1505 hours along KPE TOWARDS TPE BEFORE PAYA LEBAR EXIT involving our client's vehicle registration number [GY 120Y] and [SGD 1198C] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO - (Branch Office)

Encl
c.c. 1) FONG CHEE WAH

(Vehicle : SGD 1198C)

- 2) **NAME OF WORKSHOP : HONG MOTOR SERVICE** (Vehicle : GY 120Y)
Blk 5035 Ang Mo Kio Industrial Park 2
#01-365
Singapore 569538
Telephone : 6282-2052 (Ah Huat)

Fax : 6556-2934

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2018 16:46
Date Of Accident	22/01/2018 15:05
Exact Location Of Accident	KPE TOWARDS TPE BEFORE PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY120Y
Insured/Policyholder	
Name Of Registered Owner	PDT ENTERPRISE PTE LTD
Co Reg No	200400348N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91708024
Vehicle Particulars	
Manufacturer	TOYOTA
Model	LITEACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5090242091
Cover Note Number	
Driver	
Name of Driver	KOH LIAN BOON
NRIC No	S6871517B
Date Of Birth	02/07/1968
Occupation	OUTDOOR
Date Of Driving Pass	02/12/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91708024
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 626 PASIR RIS DRIVE 3
#04-306

Postcode 510626

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

Details of Witness 1

Name HEIKAL

Phone Number 93873844

Email Address NA

Details of Witness 2

Name COLIN

Phone Number 96666869

Email Address NA

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number NA

Vehicle Make/Model/Colour MERCEDES BENZ

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KOH LIAN BOON

Approximate Age

49

Injuries Sustain

KNEE

Injured person in which vehicle?

GY120Y

Were seat-belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 626 PASIR RIS DRIVE 3
#04-306

Postcode

510626


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report T/20180123/2023.

I wish to state that those goods in my vehicle was damage due to this incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

GRAM: SketchPlanForm_V3

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180123/2023

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

1 of 3

Report No. T/20180123/2023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/01/2018 11:00		Vide Report No.:		Station Diary No.: 41	
Informant's Particulars					
Name of Informant: KOH LIAN BOON			Address: APT BLK 626 PASIR RIS DRIVE 3 #04-306 SINGAPORE 510626		
ID Type / ID No.: NRIC NO / S6871517B			Contact No.:		Mobile: 91708024
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 02/07/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Company director			Driving Licence Information: Class: 3.		Date of Expiry:

General Information of the Accident					
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/01/2018 15:05	Type of Location: Straight Road	
Location: Along Road 1 KALLANG PAYA LEBAR EXPRESSWAY KPE towards TPE before Paya Lebar Exit					
Weather: Covered Tunnel		Road Surface: Dry		Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No	

Details of Vehicle Involved					
Vehicle No:	Type:	Make:	Model:	Condition:	No of Passenger:
GY120Y	Van			Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180123/2023

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3

Report No. T/20180123/2023

CONTINUATION OF REPORT

Driver			
Name	KOH LIAN BOON	ID No.	S6871517B
Related Vehicle	GY120Y (Van)	Contact No.	91708024
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/01/2018 at about 1507hrs, I drove my company's vehicle GY120Y along KPE towards TPE. As I was driving along the 2nd lane before the Paya Lebar exit, another car on the 1st lane beside me swerved towards my lane. I attempted to avoid a collision with the car and it caused my van to swerve out of control. My van eventually toppled, spun around and hit the side wall of the KPE tunnel. The accident caused a concrete piece to break. My Van suffered major damages to its body frame, and the preliminary assessment by the workshop is that the repair cost would be too big and it is better to scrap the vehicle. I suffered slight injury to my knee but does not require any medical attention. I will self medicate to let it heal. The ambulance attended to me after the accident but I refused to be conveyed. Police attended to me vide incident G/20180122/0131.

I was approached by two witnesses. Heikal HP:93873844 and Colin HP:96666869. Heikal had provided me with his in-vehicle camera recordings of the accident. I would be able to submit the video for investigation purposes if required.



**SINGAPORE
POLICE FORCE**



T/20180123/2023

3 of 3

Report No. T/20180123/2023

Police Station Of Origin:

Pasir Ris N.P.C

1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457

Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt MUHAMMAD DZARIF BIN
MOHAMMAD HAKIM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

23/01/2018 11:00

Officer In Charge Of Case:

TP / GIT /

Sgt 2 MARIAH BINTE ZAKARIAH

Contact No.: 65476433

SINGAPORE
POLICE FORCE

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0348N
Vehicle Details	
Vehicle No.:	GY120Y
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE SDR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C4004523
Chassis No.:	CR425010747
Maximum Power Output:	-
Open Market Value:	\$18,669.00
Original Registration Date:	02 Dec 2004
First Registration Date:	02 Dec 2004
Transfer Count:	1
Actual ARF Paid:	\$934.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,133.00
COE Rebate Amount:	\$8,796.00
Total Rebate Amount:	\$8,796.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 31 Jan 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		29 Jan 2018 16:57 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	PDT ENTERPRISE PTE LTD , Co. Reg. No.: 200400348N		
Vehicle Reg. No.:	GY120Y	Date of Loss:	22/01/2018 00:00 - :59 [157 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00508C02	Policy/Cover Note No.:	DMPCSN1439361705
Vehicle Reg. No. (Insured):	SGD1198C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hong Motor Service (HQ) Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538, 569538 Ang Mo Kio - Tel: 62822052		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 07/02/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GY120Y (SNM18D00508C02)**
[SGD1198C]

TP
PDT ENTERPRISE PTE LTD
Jan 22 2018 12:00AM

[-]
Hong Motor Service

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	25/04/18 11:01	General View		Load PDF	
2	25/04/18 11:01	Photographs of Damaged Parts		Load PDF	

Documentation

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	29/01/18 16:57	PRS		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18001791/WD3S2
 Date: 30/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1439361705
 Claimant Vehicle No: GY120Y Insured Vehicle No: SGD1198C
 Date of Loss: 22/01/2018 Nature of Claim: TP Claim No: SNM18D00508C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GY120Y Engine No: 3C4004523
 Make & Model: TOYOTA LITEACE, 1.5 (A) Chassis No: CR425010747
 Reg. Date: 02/12/2004 (Man. Year: 2004) Odometer: 0 km
 Colour: Silver
 Engine Capacity: 2184 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165 R13C Rear Tyre Size: 165 R13C
 Front Left Side: West Lake 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: West Lake 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/01/2018
 Date Inspected: 30/01/2018 Inspected At: Hong Motor Service (HQ)
 365 Singapore 569538
 Singapore 569538
 Estimated Period of Repair: 18.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/30/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000.00 - \$18,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Apr 2018)

Parts: N/A TOYOTA LITEACE 1.5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GY120Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >