

INS. CASE OWNER:

Spacey

CC 4 / ASM1800

1795, Plea 352

LKK:  
IDAC:

SMASPT  
27871

Surveyor:

Amk

DOI:

30-6-18

Date / Time:

30/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

CLJ9931J

Claim No.:

S8m0081L

Name of Insured:

CHEO TIONG ANGE @ Lee Ting Hong

Policy No.:

P1882326

Insured Tel No.:

HP:

97540522

Make / Model:

Bmw 640I

Excess Sec II :SS

D.O.A.:

28/01/2018

Place of Accident:

Orange Grove Rd

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC6053Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
7/2	Non-Reporting ltr (1st):	
Amk	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	<b>Documentation Check List:</b> Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR: TP:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 2/1/18 Sent By: Amk

FINALIZATION Date/Time: 4/8 Confirm with: GARY Confirm by: Amk

Repair Cost: 48 S\$2,100 ( 3 days) Reduction: 48 % Email  Call

FINAL SETTLEMENT Date/Time: 25.7.18 Confirm with: GARY Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL If NO or B 28, Ass. Lia:

Repair Cost: 01/67 S\$2,247.00 01 HIT STATIONARY TP

Loss of Rental (LOR): S\$ 363.04 ( 4 days) x 90.76

Loss of Use (LOU): S\$ - (\$ x days)

Loss of Income (LOI): S\$ 140.00 (\$40 x 4 days)

LOR only  LOU only  LOR + LOU  LOR + LOI  (Tick only one)

GIA/LTA Search S\$ 7.45  
Medical: S\$ -  
Disbursement: S\$ - (e.g. Tow/ Independent)  
Legal Cost S\$ -  
Total: S\$ 2,717.49 Global Sum S\$:  
FINAL PAYMENT Date/Time: 25.7.18 Confirm with: GARY Email  Call


Payee 1: S\$ 2,717.49 Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD  
Payee 2: (Strike if N.A.) S\$ Name 2:  
Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT  
3/8/18

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop mis: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: 3 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Veh No: **SHC 6053Y** Regn: **10ZY 2018**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T  Prime Mover /  
 Truck / Trailer or  
 Make: **KIA optima** CC: **168**  
 Colour: **silver** A/C:  Ins'd / Std / NI / NA  
 Sp Reading: **30217** T.Race:  Ins'd / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C.No: **KNA6M414ME5X63902**  
 Gen Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / SiRim /  D A/Rim or  
 Tyre Size F: **205 / 65 R16**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Achilles**  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R.Bal: 7 mm R.Bal: 7 mm  
 L.Bal: 7 mm L.Bal: 7 mm  
 D.O.A: 28/1/8 D.O.I: 30/1/8  
 Survey held at: Premis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**ob Frnt**  
 The U/C / Chassis frame / Body Structure affected due to collision.

**AXA**

45: → 2,100 (RED: → 1,926.90 48%)

Date/Time File Pass to?  : Preli. Report  
 : Final Report  
 Date/Time File Return to?

Days Of Repair:  
 Resurvey No. of Trip:

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Add Fee:  Site Insp \$ \_\_\_\_\_  
 Inter. insp \$ \_\_\_\_\_  
 Tech. insp \$ \_\_\_\_\_  
 Other \$ \_\_\_\_\_

Report Format:  
 Lump Sum / I.B.I.:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18001795/K1ea3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 30-01-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLJ 9931J	Veh. Inspected	SHC 6053Y
Policy No.		Coverage (\$)	0.00
Claim No.	S8M0081L	Excess (\$)	0.00
Assign From		Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/01/2018	Inspection Date	30/01/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

30-Jan-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6053 Y

1 pc	Front bumper	<i>Robert</i>	\$	531.00
1 pc	Front bumper emblem	<i>uc</i>	\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00	<i>uc</i>	\$	16.00
1 pc	Front o/s wheel cover	<i>Robert</i>	\$	116.00
1 pc	Front o/s fender	<i>X repair</i>	\$	384.00
1 pc	Front o/s fender inner shield	<i>X repair</i>	\$	120.00
1 pc	o/s mirror assy	<i>Robert</i>	\$	590.00
			\$	1,801.00
			Less 10%	\$ 180.10
			\$	1,620.90

### S/NETT

1 set	Front o/s fender inner shield clips	<i>X repair</i>	\$	28.00
1 set	Front bumper clips	<i>uc</i>	\$	48.00
1 pc	Front o/s fender sticker	<i>X repair</i>	\$	30.00
1 set	o/s door sticker	<i>uc</i>	\$	100.00

### Sundry

To check wheel alignment

*uc* \$ ~~50.00~~ 20  
\$ ~~80.00~~ 60

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ *X repair*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, o/s windscreen pillar

\$ ~~700.00~~ <sup>500</sup> ~~400~~

To putty and spray painting on front bumper, front o/s fender, o/s side mirror, front o/s door, o/s windscreen pillar

\$ ~~1,000.00~~ <sup>690</sup> ~~390~~

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ 50

\$ 4,036.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*12/2/18*  
*Robert* *45 \$2100 / 3 Reps*

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Final price survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Kalvin LKK*  
*30/1/18 1545h*  
*3 Reps.*  
*4/5*  
*After Repair photo*

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

30-Jan-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6053 Y

1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00 ✓	\$	16.00
1 pc	Front o/s wheel cover ✓	\$	116.00
1 pc	Front o/s fender X <i>14.00</i>	\$	384.00
1 pc	Front o/s fender inner shield X	\$	120.00
1 pc	o/s mirror assy ✓	\$	590.00
		\$	<u>1,801.00</u>
	Less 10%	\$	180.10
		\$	<u>1,620.90</u>

### S/NETT

1 set	Front o/s fender inner shield clips X	\$	28.00
1 set	Front bumper clips ✓	\$	48.00
1 pc	Front o/s fender sticker X	\$	30.00
1 set	o/s door sticker ✓	\$	100.00

Sundry \$ ~~50.00~~ *20*

To check wheel alignment \$ ~~80.00~~ *60*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ ~~180.00~~ *X*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, o/s windscreen pillar \$ ~~700.00~~ *500*

To putty and spray painting on front bumper, front o/s fender, o/s side mirror, front o/s door, o/s windscreen pillar \$ ~~1,000.00~~ *690*

To apply rustproofing on the repaired and replaced panels. \$ ~~200.00~~ *50*

\$ 4,036.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

*Kalvin LKK*  
*30/1/18 1545h*  
*3 Days.*  
*4/5*  
*After Repair photo*



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M0081L

Our ref: CC4/ASM18001795/K1ea3

Date: 31.01.2018

The Motor Claims Department  
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 6053Y**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.01.2018 at the premises of M/s Premier Automotive Services Pte Ltd - Changi and have the following to report:-

Workshop Estimate Amount	: S\$	4,036.90
Revised Estimate Amount	: S\$	2,743.30
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 12 March 2018 11:34 AM  
**To:** 'Gary Shi'  
**Cc:** AccReport; Vic (LKKAuto)  
**Subject:** RE: LOD / Accident involving SHC6053Y & SLJ9931J on 28.01.18 (AXA case)  
**Attachments:** OI SKETCH PLAN.pdf

Without Prejudice

Hi Gary,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client swerved out from stationary position and collided our insured vehicle which driving straight. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of **video footage/witness statement/scene photos**(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Gary Shi [<mailto:gary.shi@premiertaxi.com>]  
**Sent:** Friday, 23 February 2018 3:48 PM  
**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Cc:** AccReport <[AccReport@Premier-Corp.net](mailto:AccReport@Premier-Corp.net)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** LOD / Accident involving SHC6053Y & SLJ9931J on 28.01.18 (AXA case)

WITHOUT PREJUDICE

Dear Asher & Vic,

Your Ref: SLJ9931J

Our Ref: SHC6053Y/GS

Date of accident: 28/01/2018



## MANDATE REQUEST FOR S8M0081L

*Stationary*

Type

📌 Question

Message

Liability: Insured hit stationary TP (OI was charged for inconsiderate Driving. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$2,247.00 (w/GST) Loss of Rental: \$363.04 (4days x \$90.76) Loss of Income: \$160.00 (4days x \$40) LTA: \$7.45 Total: \$2,777.49

Reply

<< **Re:MANDATE REQUEST FOR S8M0081L**

Type

 Information

Message

Pls proceed

Reply

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLJ 9931J (Insd veh)	Model:	KIA OPTIMA 1.7(A) DIESEL
	SHC 6053Y (TP veh)		
Date of Accident:	28/01/2018		

Global Sum Settlement	:	[ ] Yes	[ X ] No		
Repair Estimate	:			\$ 4,319.48	
Final Repair Cost	:			\$ 2,247.00	
Loss of Token Sum	:			\$ 160.00	4 days at \$40.00 per day
Rental (if any)	:			\$ 363.04	4 days
LTA / GIA Search Fee	:			\$ 7.45	

Others: : \$

: \$  
Final Settlement Sum : \$ 2,777.49

Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_  
 BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks  
 \_\_\_\_\_  
 \_\_\_\_\_

Payment Instruction: Payee's Breakdown		
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	: \$ 2,777.49

NUR SHAQILAH BTE ABDOL  
WAHAB

03/08/2018  
Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## Service Request Details

Claim	S8M0081L
Reference	CC4/ASM18001795/KI1ea9s2ate
Request Date	January 28, 2018
Due Date	January 30, 2018
Vendor Name	September 28, 2018
Type of Loss	LKK AUTO CONSULTANTS PTE Loss LTD (TP)
Services	Third Party Vehicle Damage

### Vehicle Information

Incident Vehicle SHC6053Y  
 Registration # TPVD KIA  
 Make Model OPTIMA-1.7 D (A)  
 Service Address

### Actions

Next Step: Finish the work  
 Complete Work  
 More

### Contact/Insured

Primary Contact/Insured: CHEO TIONG HENG @ LEE TIONG HENG  
 11 LADY HILL ROAD, 258678, Singapore  
 62657824  
 tiongheng.cheo@cprint.com.sg

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 18, 2018
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 16, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 16, 2018
TP PIR.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	March 28, 2018
TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	January 31, 2018
Preliminary Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 31, 2018
EMAIL.msg	Letters and Correspondence	Workshop	KADRI Mateen	January 30, 2018

**SERVICE REQUESTS**

**MESSAGES**

**CLAIMS**



## Service Request Details

Claim	S8M0081L
Reference	CC4/ASM18001795/KI1008342ate 
Request Date	January 28, 2018
Due Date	January 30, 2018
Vendor Name	September 28, 2018
Type of Loss	LKK AUTO CONSULTANTS PTE Loss LTD (TP)
Services	Third Party Vehicle Services Damage

### Vehicle Information

Incident Vehicle SHC6053Y  
 Registration # TPVD KIA  
 Make Model OPTIMA-1.7 D (A)  
 Service Address

### Actions

Next Step

### Primary Contact/Insured

CHEO TIONG HENG @ LEE TIONG HENG  
 11 LADY HILL ROAD, 258678, Singapore  
 62657824  
 tiongheng.cheo@cprint.com.sg



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration#  
SHC6053Y

Registration State

SINGAPORE

Mileage

302117

Purchase Date

mm/dd/yyyy

Registration Date \*

07/10/2014

Age of Vehicle

3

## Driver Details

CATEGORY Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2013

CATEGORY Driver Name

FNOL INFORMATI... TAN HIAN THORN

CATEGORY Make

POST SURVEY INF...

CATEGORY Engine No

POLICY INFORMAT...

ASSESSMENT INFO... D4FDDH308315

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1685 cc

CATEGORY Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT...

ASSESSMENT INFO... 0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY Address



-  SERVICE REQUESTS
- MESSAGES
- CLAIMS

 **Assessment Details**

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary

Front left side

ACHILLES 7mm

Front right side

ACHILLES 7mm

Rear left side

ACHILLES 7mm

Rear right side

ACHILLES 7mm

SERVICE REQUESTS    MESSAGES    CLAIMS

### Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary    Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART
<input type="checkbox"/>	1	1			FRONT BUMPER			Deformed	531		10		477.9	Reve
<input type="checkbox"/>	2	1			FRONT BUMPER EMBLEM			Necessary	44		10		39.6	Reve
<input type="checkbox"/>	3	1			FRONT BUMPER O/S SIDE RETAINER			Cracked	16		10		14.4	Reve
<input type="checkbox"/>	4	1			FRONT O/S WHEEL COVER			Damaged	116		10		104.4	Reve
<input type="checkbox"/>	5	1			FRONT O/S FENDER			Repair	0		10		0	Reve
<input type="checkbox"/>	6	1			FRONT O/S FENDER INNER SHIELD			Serviceable	0		10		0	Reve
<input type="checkbox"/>	7	1			O/S MIRROR ASSY			Damaged	590		10		531	Reve

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R

SERVICE REQUESTS    MESSAGES    CLAIMS

## << Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary

EDIT    SR NO    NAME    ACTION    AMOUNT    COMMENT    REMOVE

1    DAYS OF REPAIR    Reviewing    3   

2    SET FRONT O/S FENDER INNER SHIELD CLIPS    Reviewing    0    NOT NECESSARY   

3    SET FRONT BUMPER CLIPS    Reviewing    48    NECESSARY

SERVICE REQUESTS    MESSAGES    CLAIMS



## Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary    Claim Amount    \$2,635.30    Claim Amount    \$2,635.30

CATEGORY    ESTIMATE    REVISED AMOUNT

Labour    \$1,300.00    \$1,300.00

Miscellaneous    \$168.00    \$168.00

Spare Parts    \$1,167.30    \$1,167.30

Submit for Review

SERVICE REQUESTS    MESSAGES    CLAIMS

## Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	FINAL LUMP SUM	Reviewing	2100		
--	---	----------------	-----------	------	--	--