

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	4	FRONT O/S FENDER STICKER	Reviewing	0	NOT NECESSARY	
	5	SET O/S DOOR STICKER	Reviewing	100	NECESSARY	
	6	SUNDRY	Reviewing	20	NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
	1		TO CHECK WHEEL ALIGNMENT.	60	0	0	Reviewing		
	2		TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	0	0	0	Reviewing		
	3		TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT BUMPER, O/S FRONT BUMPER, O/S WINDSCREEN PILLAR.	500	0	0	Reviewing		
	4		TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER, O/S SIDE MIRROR, FRONT O/S DOOR, O/S WINDSCREEN PILLAR.	690	0	0	Reviewing		
	5		TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	50	0	0	Reviewing		

Detailed Assessment

Inspection Date *

01/30/2018



Condition of Vehicle at time of survey

General condition

Fair

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/65R16

Rear Tyre Size

205/65R16

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

FNOL INFORMATION... BLK 471F #05-20U, 323471, Singapore

POST SURVEY INF ...

CATEGORY Address type

FNOL INFORMATION... Personal Correspondence

POST SURVEY INF ...

CATEGORY Gender

FNOL INFORMATION... Male

POST SURVEY INF ...

CATEGORY Marital status

FNOL INFORMATION... Unknown

POST SURVEY INF ...

CATEGORY Identification #

FNOL INFORMATION... 50018150A

POST SURVEY INF ...

POLICY INFORMAT... TPVD KIA

ASSESSMENT INFO...

KIA

CATEGORY

Model

POLICY INFORMAT... OPTIMA-1.7 D (A)

ASSESSMENT INFO...

OPTIMA 1.7(A) DIESEL

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

KNAGM414ME5463902

CATEGORY

Date of Birth

FNOL INFORMATI...

September 18, 1951

POST SURVEY INF...

m/m/dd/yyyy



CATEGORY

Age

FNOL INFORMATI...

66

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Pending verification -
Direct Settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents
Assessment Metrics Notes

Additional Instructions

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	5/16/18 5:44 PM	2100	2100	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>
KADRI Mateen	1/30/18 10:14 AM	2635.3	2635.3	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

Pending verification -
Direct Settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Documents

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Accident Statement	Reports & Statement		Merimen	
--------------------	---------------------	--	---------	--

Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 18, 2018
-----------------------------------	---------------------	--------	-----------------------------------	--------------

LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 18, 2018
------------------------	---------------------	--------	-----------------------------------	--------------