

REF: CS/MSG18001799 / Uvd3 ⁰² Special Instructions

TO: BY: Marcus ASSIGNMENT (Office) Date/Time: 30/1/18 @ 12:00pm
 FROM: Merimen MSIG Bill to: _____

Estimated Cost: _____ Insured: SGF 225D
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS Tel: 6395 7877

To Inspect Vehicle No: SLN1609Y
 at Workshop m/s: Trans Eurokars

of: 5 ubi close, 408605 Claim No: 545088
 Policy No: 80415334 AVW Excess: _____

Sum Insured: _____ D.O.A. 21/12/2017
 Make of Veh: _____ H.O.D. Endorsement: _____
 (Client's Record)

CA / REV / REP. / REV 24 HRS ^{1wp} Person Contacted: Vion Vehicle: IN / OUT
 Date/Time: 12:25pm @ 30/1/18

Date/Time	Action/Instruction (✓) Estimate
	<u>SLN1609Y-X</u>
	<u>SGF 225D-X</u>
<u>11/04/18</u>	<u>@ 14:10 p.m. revised to Irene Tan Gek Ing via merimen.</u>

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

MSIC/
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLN16084

at Workshop m/s Treas. Ender

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

CA / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN16084 Yr Regn: 417

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mazda 6 c.c. 1998

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 16125 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YM6GL1071H0109602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 21/12/18

Survey held at

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 10/4/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/5/18 confirmed final by 2873.10 with Catherine.
(Red 3599.29, 55%)

COR Sen

14/05/18

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

14/5 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

200

Transportation:

10

Photos

Others

TOTAL

210

Report Format: merimen

Lump Sum / I.B.I. (\$) 2873.10




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001799/Uvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 30-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGF 225D	Veh. Inspected	SLN 1609Y	
Policy No.	80415334AVW	Coverage (\$)	0.00	
Claim No.	545088	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/12/2017	Inspection Date		
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		30 Jan 2018 12:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CHRIS LOW YEN LIN, ID: S1655485E		[Created by insurer]
Main Claimant:	SUMARLEKI BIN AMJAH, ID: S7121161D		
Vehicle Reg. No.:	SLN1609Y	Date of Loss:	21/12/2017 14:00 - :59
Claim Type:	TP / 545088	Policy/Cover Note No.:	80415334AVW (Comprehensive)
Vehicle Reg. No. (Insured):	SGF225D	Policy No. (Claimant):	Coverage: 06/10/2017 - 05/10/2018
		Excess:	S\$500.00
Repairer:	Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/01/2018]		
Driver/Custodian (Insured):	TAN HIEW-KEN (), NRIC: S1707557H, Tel: +6594550385		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Thursday, 10 May 2018 10:53 AM
To: Veron Chen (LKKAUTO)
Cc: SUR
Subject: FW: SLN1609Y - FINALIZATION OF COR
Attachments: 1913_001.pdf; IMG_4312.JPG; IMG_4310.JPG; IMG_4311.JPG

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Thursday, 10 May, 2018 10:40 AM
To: Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; vion.lim@eurokars.com.sg
Subject: SLN1609Y - FINALIZATION OF COR

Dear Marcus

Our COR computation is attached for your agreement.

COR: \$2873.10 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <mazdacanon@mazda.com.sg>
Sent: Thursday, May 10, 2018 10:22 AM
To: Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>
Subject: Attached Image

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1161D
Vehicle Details	
Vehicle No.:	SLN1609Y
Vehicle to be Exported:	No
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	PE20858394
Chassis No.:	JM6GL1071H0109602
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$20,399.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$20,559.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$15,419.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,501.00
COE Rebate Amount:	\$48,810.00
Total Rebate Amount:	\$64,229.00

The information contained herein is correct as at 10 Apr 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 11 Apr 2018

Preliminary Advice

Insured Vehicle No	: SGF225D	Accident Date	: 21/12/2017
TP Vehicle No	: SLN1609Y	Assignment Date	: 30/01/2018
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 3 days
Date of Inspection	: 10/04/2018		
Inspection At	: Trans Eurokars Pte Ltd NO. 5 UBI-CLOSE, SINGAPORE Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,472.39
Revised Amount	:S\$	2,873.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,873.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 15:07
Date Of Accident	21/12/2017 14:10
Exact Location Of Accident	GRANGE ROAD IN FRONT OF TANGLIN MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1609Y
Insured/Policyholder	
Name Of Registered Owner	SUMARLEKI BIN AMJAH
NRIC No	S7121161D
Email Address	LEKI98@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91545871
Alternative Phone No	OTHERS-91545871

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6 2.0L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700004633
Cover Note Number	

Driver

Name of Driver	SUMARLEKI BIN AMJAH
NRIC No	S7121161D
Date Of Birth	26/06/1971
Occupation	INDOOR
Date Of Driving Pass	16/05/1998
Driving Experience	19 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91545871
Fax Number	
Contact Number	OTHERS-91545871
Email Address	LEKI98@HOTMAIL.COM

Address	26 WILBY ROAD #06-23
Postcode	276308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	SLL4194S - -
Insurance Company of Driver's Own Vehicle	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGF225D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HIEW KEN
NRIC/Passport Number	S1707557H
Contact Number	94550385
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


22/1/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Catherine Chua
NRIC/FIN No.: S14492514

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG GRANGE ROAD ON 21 DECEMBER 2017 WHEN THE CAR BELONGING TO ME HIT MY REAR WHEN I BRAKED DUE TO SLOW TRAFFIC.

WE GOT OFF THE CARS AND INSPECTED OUR RESPECTIVE CARS. IT WAS EVIDENT THAT MY REAR BUMPER WAS HIT AND SUFFERED DAMAGES - SLIGHT DENT & SCRATCHES. WE MOVED TO THE SIDE OF CUSCADDEN ROAD TO DISCUSS THE MATTER. THE OTHER PARTY ACKNOWLEDGED HIS FAULT AND SUGGESTED PRIVATE SETTLEMENT. SUBSEQUENTLY I REPORTED THIS INCIDENT TO MY INSURANCE AND FILED AN ONLINE CLAIM. A POLICE REPORT WAS ALSO MADE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

24/1/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Catherine Chua

NRIC/FIN No.: S1449251H

NOTICE OF COMPLIANCE Pg. 1

Annex D

NOTICE OF REPORTING

This is to confirm that SUMARLEKI BIN AMJAH, NRIC/FIN S7121161D, has reported to the Police a non-injury traffic accident which occurred at GRANGE ROAD, in front of Tanglin Mall

on 21/12/17 at 2:10 am/pm involving the following vehicles:

1) SLN 1609Y

2) SGF 225D

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SSGT TOFOZS Henry

Date: 21/12/17 Time: 3:55 pm.

S/D Ref: 148

Police Post/Unit :



BT Merah East Neighbourhood
Police Centre
501 New Bridge Road
POLICE Cantonment Complex
Singapore 088763
Tel: 1800-279999

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

Not Affected
Take photo separately
3 day
10/4/18

MSIG INSURANCE SINGAPORE P/L		NAME : Mr Sumarleki Bin Amjah	WIP : 58328
4 SHENTON WAY #21-01		ADDRESS : 26 Wilby Road	EXCESS :
SGX CENTRE 2		#06-23 The Tassarina	DATE: 24-Jan-18
SINGAPORE 068807		Singapore 276308	
ATTN. :	MOTOR CLAIMS	TEL : 91545871	
FAX :			

VEH NO :	SLN1609Y	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6GL1071H0109602	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6 2L	DATE REG.:	25-Apr-17	POLICY NO. :	

NATURE OF WORKS

Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	MGJR9-50-221ABB	20/2e	\$ 1,172.80
2	RETAINER(LHS), REAR BUMPER	1	MGJR9-50-2J1	17	\$ 39.00
3	RETAINER(RHS), REAR BUMPER	1	MGJR9-50-2H1	17	\$ 39.00
4	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	17	\$ 5.10
5	REFLECTOR LHS	1	MD350-51-5L0E	17	\$ 50.40
6	REFLECTOR RHS	1	MD350-51-5M0E	17	\$ 50.40
7	COVER(LHS), TOWING	1	MG4YL-50-EL1 64	17	\$ 23.70
8	COVER(RHS), TOWING	1	MG4YL-50-EK1 64	17	\$ 23.70
9	REAR REINFORCEMENT	1	MGHK1-50-260	R	\$ 512.60
10	FASTENER, REAR BUMPER	6	MB45A-56-146A	21	\$ 16.80
11	GROMMET, REAR BUMPER	4	MH260-50-841	21	\$ 11.20
12	GROMMET, REAR BUMPER	1	M9991-00-501	21	\$ 2.80
13	GASKET(LHS), TAILLAMP	1	MGHK1-51-163	21	\$ 27.70
14	GASKET(RHS), TAILLAMP	1	MGHK1-51-153	21	\$ 27.70
15	FASTENER, TAILLAMP	2	MKD53-51-146B	17	\$ 7.80
16	FASTENER, TAILLAMP	2	MGHP9-51-146	17	\$ 6.60
17	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	17	\$ 29.80
TOTAL PARTS					\$ 2,047.10
LESS 10%					\$ 204.71
TOTAL PARTS COST					\$ 1,842.39

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,500.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	150	\$ 630.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	Net 30	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 4,630.00
TOTAL PARTS	\$ -	\$ 1,842.39
TOTAL	\$ -	\$ 6,472.39
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

 Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



MSIG INSURANCE SINGAPORE P/L 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Sumarleki Bin Amjah ADDRESS: 26 Wilby Road #06-23 The Tassarina Singapore 276308 TEL: 91545871	WIP: 58328 EXCESS: DATE: 24-Jan-18
VEH NO:	SLN1609Y	DATE IN:	CONTACT PERSON: VION 6395 7877
CHASSIS NO:	JM6GL1071H0109602	MILEAGE:	TYPE OF CLAIM: THIRD PARTY CLAIM
MODEL:	MAZDA6 2L	DATE REG.: 25-Apr-17	POLICY NO.:

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MGJR9-50-221ABB	\$ 1,172.80	\$ 1,172.80
2	1	MGJR9-50-2J1		\$ 39.00
3	1	MGJR9-50-2H1		\$ 39.00
4	1	MKD53-50-251		\$ 5.10
5	1	MD350-51-5L0E		\$ 50.40
6	1	MD350-51-5M0E		\$ 50.40
7	1	MG4YL-50-EL1 64		\$ 23.70
8	1	MG4YL-50-EK1 64		\$ 23.70
9	1	MGHK1-50-260		\$ 512.60
10	6	MB45A-56-146A	\$ 16.80	\$ 16.80
11	4	MH260-50-841	\$ 11.20	\$ 11.20
12	1	M9991-00-501	\$ 2.80	\$ 2.80
13	1	MGHK1-51-163	\$ 27.70	\$ 27.70
14	1	MGHK1-51-153	\$ 27.70	\$ 27.70
15	2	MKD53-51-146B		\$ 7.80
16	2	MGHP9-51-146		\$ 6.60
17	2	MGJ6A-51-14Y		\$ 29.80
TOTAL PARTS			\$ 1,259.00	\$ 2,047.10
LESS 10%			\$ 125.90	\$ 204.71
TOTAL PARTS COST			\$ 1,133.10	\$ 1,842.39

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 630.00	\$ 1,500.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	\$ 150.00	\$ 630.00

4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR			\$ 1,740.00	\$ 4,630.00
TOTAL PARTS			\$ 1,133.10	\$ 1,842.39
TOTAL			\$ 2,873.10	\$ 6,472.39
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 2,873.10	
GST 7%			\$ 201.12	\$ -
GRAND TOTAL			\$ 3,074.22	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001799/UVD3N2

Date: 15/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80415334AVW
Claimant Vehicle No :	SLN1609Y	Insured Vehicle No :	SGF225D
Date of Loss:	21/12/2017	Nature of Claim:	TP
		Claim No:	545088

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1609Y	Engine No:	PE20858394
Make & Model:	MAZDA MAZDA5, 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A)	Chassis No:	JM6GL1071H0109602
Reg. Date:	25/04/2017 (Man. Year: 2016)	Odometer:	16125 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,942.39	1,163.10	779.29	40.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	1,710.00	2,820.00	62.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,472.39	2,873.10	3,599.29	55.61
+ GST 7.00/7.00% (\$\$)	453.07	201.12	251.95	55.61
Nett Amount (\$\$)	6,925.46	3,074.22	3,851.24	55.61

INSPECTION

Date of Assignment:	30/01/2018	Inspected At:	Trans Eurokars Pte Ltd
Date Inspected:	10/04/2018		NO. 5 UBI CLOSE, SINGAPORE
			Singapore 408605
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2018)
Parts:	M1-SUV	MAZDA MAZDA5 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN1609Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,172.80 FL	*1,172.80 FL
2	1		*RETAINER (LHS),REAR BUMPER	Not Necessary	39.00 FL	*- FL
3	1		*RETAINER (RHS),REAR BUMPER	Not Necessary	39.00 FL	*- FL
4	1		*BRACKET CENTER,REAR BUMPER	Not Necessary	5.10 FL	*- FL
5	1		*REFLECTOR LHS	Not Necessary	50.40 FL	*- FL
6	1		*REFLECTOR RHS	Not Necessary	50.40 FL	*- FL
7	1		*COVER (LHS),TOWING	Not Necessary	23.70 FL	*- FL
8	1		*COVER (RHS),TOWING	Not Necessary	23.70 FL	*- FL
9	1		*REAR REINFORCEMENT	Repair	512.60 FL	*- FL
10	6		*FASTENER,REAR BUMPER	Necessary	16.80 FL	*16.80 FL
11	4		*GROMMET,REAR BUMPER	Necessary	11.20 FL	*11.20 FL
12	1		*GROMMET,REAR BUMPER	Necessary	2.80 FL	*2.80 FL
13	1		*GASKET (LHS),TAILLAMP	Necessary	27.70 FL	*27.70 FL
14	1		*GASKET (RHS),TAILLAMP	Necessary	27.70 FL	*27.70 FL
15	2		*FASTENER,TAILLAMP	Not Necessary	7.80 FL	*- FL
16	2		*FASTENER,TAILLAMP	Not Necessary	6.60 FL	*- FL
17	2		*GROMMET,TAILLAMP	Not Necessary	29.80 FL	*- FL
18	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,147.10	1,289.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	204.71	125.90
Total Parts (\$\$)	1,942.39	1,163.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,800.00	660.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,500.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	630.00	150.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
Gross Labour Cost (\$\$)			4,530.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >