

stacy

CCF AGM  
AXA1800

1802, Webb

Surveyor:

marcus

DOI:

ASSIGNMENT

17/1/18

Date / Time:

30/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJM 4362A

Name of Insured:

TAM SING YI TERENCE

Insured Tel No.:

HP:

91138559

Excess Sec II :SS

D.O.A:

28/01/18

Is driver the owner?

(YES/NO)

Nature of Accident:

Claim No.:

S8M0081H / 27865

Policy No.:

64088034

Make / Model:

SUBARU

Place of Accident:

UPP TRINSON KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability:

%

Final ? Yes/No

SLR 7164C



INSRS:

WSP:

Tel:

Liability:

RMKS:

pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
31/1/18	SLR 7164C-X	Non-Reporting ltr (1st):	
31/1/18	SJM 4362A	Non-Reporting ltr (2nd):	
	# Smartclaim	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
31/1/18 @ 10:38	CAUSED OI CONTRIBUTED ACCIDENT. OI INTENTION THAT THE ACCIDENT HAPPEN BEFORE THE SMALL MERCHANT LAKE. INFORM TP CHAN AGREE TO SETTLE AT POST AND ANSWER ABOUT NCD RATE.	Call OI:	Done 31/1/18
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

RECEIVED 31 OCT 2018

<b>PRELIMINARY ADVICE</b>		Date/Time:	Sent By:
<b>FINALIZATION</b>		Date/Time: 25.6.18	Confirm with: PT
Repair Cost:	45 SS 800	( 3 days) Reduction:	59 %
<b>FINAL SETTLEMENT</b>		Date/Time: 09.10.18	Confirm with: PT
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	PH
Repair Cost:	SS 856.00	DI (AT INFO) P (PNE)	
Loss of Rental (LOR):	SS 164.90	( 2 days) x 84.95	
Loss of Use (LOU):	SS -	(5 x days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	SS 7.44		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost:	SS -		
Total:	SS 1,033.34	Global Sum SS:	
<b>FINAL PAYMENT</b>		Date/Time: 09.10.18	Confirm with: PT
Payee 1:	SS 1,033.34	Name 1:	PEGASUS ENGINEERING & TRADING PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT  
31/10/18

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TT
- 3) Survey fee: 350

REF: ASM

## ASSIGNMENT

Date 13/2/18

Estim / Cost

OO (H) / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No: SLR 7164C

at Workshop no: Pegasus

of 51 Deft Lane 10

Insured SUN 4362A

Policy No

Claims No

Sum Insured Excess

(Client's Record) 2pm @ owner waiting

Make of Van

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.



Est. or Market Value

IC Accident Report Consistent? : Yes or No

IC PR Seen Consistent? : Yes or No

Est. Repairs 2 days Res. Yes or No

Lump Sum 20 5 3 Val. Yes or No

CA / REV / REP. / 24 HRS <sup>hwp</sup>

77006

Date Person Contacted

Vehicle IN / OUT

Date / Time Action / Instruction

45:4860 (RED: 1,143.04 59%)

Date/Time File Pass to:

☐ : Prelim. Report☐ : Final Report

Date/Time File Return to:

Report Format:

Lump Sum / LB / HS

Days Of Repair:

Resurvey No. of Trip

Survey Fee

Transfer Fee

Add Fee:

☐ Site Insp 4☐ Trip Insp 4☐ Trip Insp 4☐ Resurvey 4

SLR 7164C P 17

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer

Make Honda verel Hybrid 1496

Colour Silver

So Reading 38511

Engine

CNC RU 31.222716

Gen. Cond. Good / Fair / Poor / Burnt

Steering Inspected / Jammed / Leaked / Burnt or

Brake Inspected / Jammed / Leaked / Burnt or

Mod. Nil / S/Run / STD A/Rum or

Tyre Size F 215/60R16

R

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI

TOTU / YOKO or

Front 6 Rear 6

R.Bal 6 L.Bal 6

D.O.A. 2 6/1/18 D.O. 13/2/18

Survey held at

Des. of Damages Fr / Rear / OS / NS / UC / Roof/Hop or

0/5 H.

The UC / Chassis frame / Body Structure affected due to collision



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18001802/eb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 30-01-2018		
		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJU 4362A	Veh. Inspected	SLR 7164C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	26/01/2018	Inspection Date		
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

From :  
PEGASUS ENGINEERING & TRADING PTE LTD  
C/O 51 DEFU LANE 10  
539216  
Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

Customer :  
GRAB RENTALS PTE LTD  
18 SIN MING LANE  
#01-08 MIDVIEW CITY  
SINGAPORE 573960  
Attn :  
Tel :  
Fax :  
*13/1/18 @ 1300h*  
*To arrange repair*

Quotation No : QO18/01-1246	Quotation Date : 27/01/2018	Terms : 30 DAYS
Vehicle No : SLR7164C	Chassis No : RU31222716	Third Party Insurer :
Model : VEZEL	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SJU4362A, DATE OF ACCIDENT: 26.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	O/S FRONT FENDER	1	580.0000	580.00
2	FRONT FENDER INNER LINER	1	130.0000	130.00
3	FRONT FENDER INNER LINER CLIPS	6	3.9000	23.40
4	FRONT FENDER HYBRID BADGE	1	62.9000	62.90
5	O/S FRONT FENDER WHEEL ARC GARNISH	1	195.0000	195.00
6	MARK UP 15% (ITEM 1-5)	1	-198.2600	-198.26
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	50.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	450.0000	450.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	650.0000	650.00

*1/5 of 800*  
*not allowed*  
*13/2/18*

*tel: 62583561*  
*take photo before painting*  
*13/2/18*

*2 days repair*

*2 days*

*Work sum \$800.00*

*2 days repair*

*Work sum \$800.00 (continued)*

*198.26*  
*70*  
*2206.74*  
*820.00*  
*1026.74*  
*20%*  
*5821.06*

Sub Total 1,943.04  
GST(7.00%) 136.01  
Total (SGD) 2,079.05

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

*on 25/06/18*

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

**From :**  
PEGASUS ENGINEERING & TRADING PTE LTD  
C/O 51 DEFU LANE 10  
539216  
Officer in Charge : ALVIN LOW WAI LUN  
Tel :  
Email :

**Customer :**  
GRAB RENTALS PTE LTD  
18 SIN MING LANE  
#01-08 MIDVIEW CITY  
SINGAPORE 573960  
Attn :  
Tel :  
Fax :  
*AKK Mann*  
*13/1/18 @ 1300h*

Quotation No : QO18/01-1246	Quotation Date : 27/01/2018	Terms : 30 DAYS
Vehicle No : SLR7164C	Chassis No : RU31222716	Third Party Insurer :
Model : VEZEL	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SJU4362A, DATE OF ACCIDENT: 26.01.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	O/S FRONT FENDER	1	580.0000	580.00
2	FRONT FENDER INNER LINER	1	130.0000	130.00
3	FRONT FENDER INNER LINER CLIPS	6	3.9000	23.40
4	FRONT FENDER HYBRID BADGE	1	62.9000	62.90
5	O/S FRONT FENDER WHEEL ARC GARNISH	1	195.0000	195.00
6	<del>MARK UP 15% (ITEM 1-5)</del>	1	-198.2600	-198.26
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	50.0000	50.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	450.0000	450.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	650.0000	650.00

*Not Approved*  
*HL*

*211:62583561*  
*Take photo before painting.*  
*13/2/18*  
*2 day.*

*257.9*  
*202*  
*206.32*  
*1026.32*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Sub Total 1,943.04  
GST(7.00%) 136.01  
Total (SGD) 2,079.05

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLR7164C

Vehicle to be Exported: Yes

Intended De-registration Date: 27 Jan 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: LEBS922729

Chassis No.: RU31222716

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$27,061.00

Original Registration Date: 25 Aug 2017

First Registration Date: 25 Aug 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Aug 2027

PARF Rebate Amount: \$3,750.00

### Intended COE Rebate Details

COE Expiry Date: 24 Aug 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,001.00

COE Rebate Amount: \$40,000.00

**Total Rebate Amount: \$43,750.00**

5/26/2018



## MANDATE REQUEST FOR S8M0081H

Type

Question

Message

Liability: Insured cut into third party lane and collided with third party vehicle (Refer to third party video). Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$856.00 (w/GST) Loss of Rental: \$169.90 (2days x \$84.95) GIA Search: \$2.00 Total: \$1,033.39 Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (02/08/2018)

Reply



## Re:MANDATE REQUEST FOR S8M0081H

Type

🔗 Question

Message

pls proceed

Reply



**GREAT AMERICAN INSURANCE COMPANY**

UEN: T15FC00298 GST REG. NO.: M90370081T  
3 TEMASEK AVENUE, #16-01 CENTENNIAL TOWER  
SINGAPORE 039190  
TEL: +65 6804 6000  
FAX: +65 6235 2616

**MOTOR COVER NOTE: MTGRAB20172171**

The Insured mentioned in this Covernote, having proposed for insurance in respect of the Motor Vehicle described, is hereby HELD COVERED under the terms of the Insurer's usual form of Motor Policy applicable thereto for the period mentioned unless the cover be terminated by the Insurer by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium payable for such insurance will be charged for the time the Company has been on risk.

The Insurer	: GREAT AMERICAN INSURANCE COMPANY
The Insured	: Grab Rentals Pte. Ltd.
Insured Nric/Passport No/ Roc	: 201617200G
Policy Coverage	: Comprehensive
Make And Description Of Vehicle	: Honda Vezel 1.5 X Hybrid
Vehicle Registration No.	
Year Of Manufacture	: 2017
Engine No.	: LEB5922729
Chassis No.	: RU31222716
Engine Capacity/ Tonnage/ Seater	: 1496 cc
Hire Purchase	: Malayan Banking Berhad
Value (S\$)	: Market Value of Insured Vehicle at Time of Loss
Period Of Insurance	: From 02/08/2017 to 01/08/2018
Excess (S\$)	: All Claims Excess - S\$2,000.00 Windscreen Excess - S\$100.00
Great American Authorised Workshop	: Authorised Workshop

I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 189) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA)

Note: This Cover Note is only valid for 60 days from the date of issuance unless replaced by the Certificate of Insurance issued by the Company.

For and on behalf of Great American Insurance Company

Great American Insurance Company  
Authorised Signatory

Date of Issue : 01/08/2017

Intermediary : Citrine Systems (S) Pte Ltd (Grab Leasing)

MTR/COVERNOTE/V02/16



## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Wednesday, 31 January 2018 2:09 PM  
**To:** 'YELLOWMONK@HOTMAIL.COM'  
**Subject:** ACCIDENT INVOLVING SJU 4362A AND SLR 7164C ALONG UPPER THOMSON ROAD ON 26/01/2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

31 JAN 2018

**TAM SING YI TERENCE**

Dear Sir/ Mdm

**OUR REF : CC4/ASM18001802/eb3**

**YOUR REF : SJU 4362A**

**ACCIDENT INVOLVING SJU 4362A AND SLR 7164C ALONG UPPER THOMSON ROAD ON 26/01/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s PEGASUS ENGINEERING & TRADING PTE LTD acting on behalf of the owner of SLR 7164C against your motor insurance policy.

Based on the accident report and accident scenario, we are of the opinion that liability may be equally shared between both parties due to conflicting versions without any concrete evidences to support each version.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

## AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: OWNER OF VEHICLE NUMBER SLR7164 C

ACCIDENT INVOLVING SJU4362A

ALONG/AT Upper Thomson Road ON 26.01.2018

We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident,

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name : Grab Rentals Pte Ltd

Co Reg No : 2016172006

Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960

Contact : 6655 0005

Date : 04-07-2018

Signature



Owner



redefining / insurance

CLAIM REF : SBM0081H  
INSURED : TAM SING YI TERENCE

DISCHARGE VOUCHER

We/I GRAB RENTALS PTE LTD, NRIC NO. 201617200G hereby agree to accept the sum of dollars [ONE THOUSAND THIRTY THREE AND CENTS THIRTY NINE ONLY.] [S\$1,033.39] paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their insured or the driver of motor vehicle no. [SJU 4362A] as a result of an accident along [UPPER THOMSON ROAD] on [26/01/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/ rider/ pillion/ insurer of motor vehicle no. [SLR 7164C].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said insurer, owner and/or driver of vehicle no. [SJU 4362A] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SJU 4362A].

Dated this 23 day of October 2018

Claimant's Signature

NRIC no./ Company Stamp

Occupation/ Business

Address

Telephone No.

Witness's Name

Witness's Signature

Witness's NRIC No.

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)  
8 Shenton Way, #24-01 AXA Tower, Singapore 068811  
Customer Centre #B1-01  
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Vehicle Model : Honda Vezel 1.5 Hybrid X (A)  
Vehicle No : SLR7164C  
Chassis No : RU31222716

GST / ROC Company No : 201101753C

Third Party Insurer : AXA  
Insured's Veh No : SJU4362A  
Date of accident : 26.01.2018

Tax Invoice No : IV18/06-1083  
Invoice Date : 25.06.2018

Pages : 1 of 1

DESCRIPTION	AMOUNT
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR.	\$ 800.00
Sub Total	\$ 800.00
GST (7.00%)	\$ 56.00
Total	\$ 856.00

Cheques should be made payable to **PEGASUS ENGINEERING & TRADING PTE LTD**

**PEGASUS ENGINEERING & TRADING PTE LTD**

  
Authorized Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846  
Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216  
E-mail : claims@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd  
No. 51 Defu Lane 10  
Singapore 539216

Mailing Address  
18 Sin Ming Lane,  
#01-08 Midview City,  
Singapore 573960  
Co. No. 201617200G

To whom it may concern,

**Re: Vehicle Rental Rates for Loss of Rental Claims.**

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66.95
03	Nissan Qashqai 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	<b>\$84.95</b>
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee  
Grab Rental Pte Ltd



## Enquire Vehicle &amp; Owner Information ( Vehicle No. SJU4362A As At 26 Jan 2018 / 19:15:00 )

## Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: SLR7164C

## Current Owner Details

Owner ID Type: Singapore NRIC  
Owner ID: S7815830A  
Owner Name: TAM SING YI, TERENCE (TAN CHENGYI)  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 16  
Registered Street Name: ANG MO KIO AVENUE 2  
Registered Unit No.: # 16 - 26  
Registered Building Name: -  
Registered Postal Code: 567699

## Current Vehicle Details

Vehicle No.: SJU4362A  
Make Description/Model: SUBARU / SUBARU FORESTER 2.0XT  
Insurance Company Name: AXA INSURANCE PTE LTD

# Thank you



Lee Ming Hui Kelvin has successfully logged out.  
Your last login date and time was 29 Jan 2018, 09:59:04.  
To return to ONE.MOTORING, please click [here](#)  
For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner</u> <u>ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SJU4362A	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	29 Jan 2018 / 09:59:57

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJU 4362A (Insd veh)	Model:	HONDA VEZEL HYBRID
	SLR 7164C (TP veh)		(A)
Date of Accident:	26/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	2,079.05
Final Repair Cost	:	\$	856.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	169.90 2 days
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	1,033.39

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	PEGASUS ENGINEERING & TRADING PTE LTD	:	\$ 1,033.39

\_\_\_\_\_  
JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
07/11/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18001802/Ueb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 07-11-2018		
		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJU 4362A	Veh. Inspected	SLR 7164C	
Policy No.	GA088034	Coverage (\$)	0.00	
Claim No.	S8M0081H	Excess (\$)	0.00	
Assign From		Assign Date	30/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31222716	Colour	SILVER	
Odometer	38511	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/01/2018	Inspection Date	13/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 7164C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	O/S FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	580.00	-
1	FRONT FENDER INNER LINER (CONSISTENT)	NOT NECESSARY	130.00	-
6	FRONT FENDER INNER LINER CLIPS @\$3.90 (CONSISTENT)	NOT NECESSARY	23.40	-
1	FRONT FENDER HYBRID BADGE (CONSISTENT)	NECESSARY	62.90	62.90
1	O/S FRONT FENDER WHEEL ARC GARNISH (CONSISTENT)	CUT	195.00	195.00
	LESS 20% DISCOUNT		-198.26	-51.58
			793.04	206.32
	<b>LABOUR</b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER .		450.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		650.00	500.00
			1,150.00	820.00
<b>GRAND TOTAL</b>			<b>1,943.04</b>	<b>1,026.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>800.00</b>

Report Ref No. CC4/ASM18001802/Ueb3q2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.