

22/03/2003

ASS. REC. BY:

REF: CS/EG18001814/Ktd3er

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of EGI

Date/Time: 30/1/18 @ 2:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB7970Z

Insured: XD7971X

at Workshop m/s Trans-Cab

Tel: 6213 0993

of 2 AMK Street 63

Policy No:

Claim No: DSMCH1800187

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 2:57pm @ 30/1/18

Person Contacted: Jiong how

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHB7970Z - NA1A1G17013338/r3

D.O.A: 08/07/2017

XD7971X - X

11Qty 8450d (Red: 19099.63; 80%)

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 30 January 2018 2:48 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XD7971X / TP : SHB7970Z/LKK / DOA : 26/01/2018 (DSMCH1800187)
Attachments: XD7971X - SAS.pdf; SHB7970Z - SAS.pdf; SHB7970Z - ESTIMATE.pdf

Dear Ashley,

Please assist to conduct these surveys:-

NO	VEH TO BE SURVEY	W/SHOP NAME	PERSON TO CONTACT	OUR REF	OIC	REMARKS
1	SHB 7970Z	TRANS-CAB SERVICES PTE LTD @ 2 ANG MO KIO STREET 63	NG JOING HOW @ 6213 0993 / 6213 0998	XD7971X	ROHAINI	DOA: 26/01/2018 WP

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001814/Ktd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 30-01-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7971X	Veh. Inspected	SHB 7970Z
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCH1800187	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/01/2018	Inspection Date	30/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB7970Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Jan 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1461770K
Chassis No.:	KL1LA69RJBB123953
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,971.00
Original Registration Date:	29 Jan 2013
First Registration Date:	29 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$13,971.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2021
PARF Rebate Amount:	\$9,779.00
Intended COE Rebate Details	

COE Expiry Date:	28 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$22,704.00
Total Rebate Amount:	\$32,483.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GI&A Records Management Centre established by the General Insurance Association of Singapore (GI&A) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 17:52
Date Of Accident	26/01/2018 18:25
Exact Location Of Accident	PEIRCE ROAD TOWARDS HOLLAND RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7970Z
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	MAH MENG CHYE
NRIC No	S1817153H
Date Of Birth	12/05/1967
Occupation	OUTDOOR
Date Of Driving Pass	04/08/1987
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97298512
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 20 EUNOS CRESCENT #05-2965
Postcode	400020
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT: T/20180127/2045 & T/20180129/2134

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7971X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANG
NRIC/Passport Number	
Contact Number	90804050
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MAH MENG CHYE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB7970Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to police report -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180127/2045

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

1 of 4

Report No. T/20180127/2045

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/01/2018 11:17		Vide Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: MAH MENG CHYE			Address: APT BLK 20 EUNOS CRESCENT #05-2965 SINGAPORE 400020		
ID Type / ID No.: NRIC NO / S1817153H			Contact No.:		Mobile: 97298512
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 50	Date of Birth: 12/05/1967	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/01/2018 18:25	Type of Location: T-Junction
Location: Along Road 1 PEIRCE ROAD				
At the traffic light junction				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD7970Z	Taxi			Red	Slightly Damaged	0
XD7971X	Lorry				No Damage	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180127/2045

2 of 4

Report No. T/20180127/2045

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

CONTINUATION OF REPORT

Driver			
Name	MAH MENG CHYE	ID No.	S1817153H
Related Vehicle	SHD7970Z (Taxi)	Contact No.	97298512
Hospital/Clinic	C&K FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/01/2018	Date Discharge	27/01/2018
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Driver			
Name	ANG	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/01/2018 at about 1825hrs, I was driving along Peirce Road after dropping my passengers off at Dempsey. I came to a stop behind a stationary car at a red light junction.

Suddenly, I felt an impact from my rear and realized that a lorry had hit onto my vehicle.

Both myself and the lorry driver alighted from our vehicles and took photos. We exchanged particulars however I wish to inform that I am not sure where I had placed the slip of paper.

As we did not want to block the traffic, I continued on with my journey. After a while, I drove home and rest.

On 27/01/2018, I woke up and felt pain on my neck and my back. I was also feeling giddy. I then decided to visit the doctor. I visited C&K Family Clinic Pte Ltd and was given 7 days of Medical Leave from dates 27/01/2018 to 02/02/2018.

I then called my operator who then informed me to come down to the office on Monday to lodge an accident report as they are closed for the weekend.

I do not have any in vehicle camera in my taxi.



**SINGAPORE
POLICE FORCE**



T/20180127/2045

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

3 of 4

Report No. T/20180127/2045

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180127/2045

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

4 of 4
Report No. T/20180127/2045

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 NUR AMERA KHAIRYANI BINTE ALI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 27/01/2018 11:17
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE



**SINGAPORE
POLICE FORCE**



T/20180129/2134

1 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20180129/2134

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/01/2018 18:31	Vide Report No.: T/20180127/2045	Station Diary No.: 149
--	-------------------------------------	---------------------------

Informant's Particulars			
Name of Informant: MAH MENG CHYE		Address: APT BLK 20 EUNOS CRESCENT #05-2965 SINGAPORE 400020	
ID Type / ID No.: NRIC NO / S1817153H		Contact No.: Home/Office: Mobile: 97298512	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 12/05/1967	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/01/2018 18:25	Type of Location: T-Junction
Location: Along Road 1 PEIRCE ROAD AT TRAFFIC LIGHT JUNCTION, TOWARDS HOLLAND ROAD				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHB7970Z	Car					0
XD7971X	Lorry					0



**SINGAPORE
POLICE FORCE**



T/20180129/2134

2 of 3

Report No. T/20180129/2134

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

CONTINUATION OF REPORT

Brief Details.

Ref: T/20180127/2045, I wished to state that the correct vehicle number for my vehicle should be SHB7970Z and not as stated. The correct location of incident should be Along Peirce Road towards Holland Road.



**SINGAPORE
POLICE FORCE**



T/20180129/2134

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

3 of 3
Report No. T/20180129/2134

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Staff Sgt LGH ZHIMING
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414

Signature Of Informant:
Date/Time: 29/01/2018 18:31
Classification Of Case:

Authentication Stamp
NP168

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7970Z - ERGO

AAD1801-318

Not Assessed

1/15/18 @ 4500

Vehicle No.:	SHB7970Z - JHOW
Chassis No.:	KL1LA69RJBB123953
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	26.01.2018
Third Party Insurer :	ERGO

PART		LIST
1	1 Rear Bumper	\$ <i>R</i> 1,202.00 ✓
2	1 Rear Bumper Beam	\$ <i>R</i> 239.94 ✗
3	1 Rear Bumper Centre Absorber	\$ <i>Sn</i> 260.00 ✗
4	1 Rear Bumper Side Retainer RH	\$ <i>Sn</i> 68.76 ✗
5	1 Rear Bumper Side Retainer LH	\$ <i>DR</i> 68.76 ✓
6	1 Rear Bumper Reflectors RH	\$ <i>Sn</i> 119.74 ✗
7	1 Rear Bumper Reflectors LH	\$ <i>Sn</i> 119.74 ✗
8	1 Rear Bumper Tow Hook Cover	\$ <i>Sn</i> 93.00 ✗
9	1 Rear Luggage Floor Panel	\$ <i>R</i> 973.00 ✗
10	1 Rear Luggage Floor Panel Insulator	\$ <i>Sn</i> 63.50 ✗
11	1 Rear Luggage Floor Panel Trim Board	\$ <i>Sn</i> 378.00 ✗
12	1 Rear End Panel Outer	\$ <i>R</i> 623.76 ✓
13	1 Rear End Panel Inner Trim	\$ <i>DR</i> 263.84 ✓
14	1 Bootlid	\$ <i>R</i> 973.00 ✓
15	1 Bootlid inner trim board	\$ <i>Sn</i> 400.00 ✗
16	1 Bootlid Weatherstrip	\$ <i>DR/DR</i> 344.28 <i>50/50</i>
17	1 Bootlid Lock - Top	\$ <i>DR</i> 466.56 ✓
18	1 Bootlid 'CHEVROLET' Badge	\$ <i>DR</i> 120.62 ✓
19	1 Bootlid Logo	\$ <i>DR</i> 138.84 ✓
20	1 Bootlid 'EPICA LT' Badge	\$ <i>DR</i> 119.84 ✓
21	1 Bootlid Reflector Centre	\$ <i>Sn</i> 217.97
22	1 Bootlid Reflector RH	\$ <i>Sn</i> 128.40
23	1 Bootlid Reflector LH	\$ <i>Sn</i> 128.40
24	1 Bootlid Hinge RH	\$ <i>R</i> 120.00
25	1 Bootlid Hinge LH	\$ <i>R</i> 120.00
26	1 Rear Tail Lamp RH	\$ <i>Sn</i> 479.30
27	1 Rear Tail Lamp Panel RH	\$ <i>R</i> 359.00
28	1 Rear Tail Lamp LH	\$ <i>Sn</i> 479.30
29	1 Rear Tail Lamp Panel LH	\$ <i>R</i> 359.00
30	1 Rear Exhaust Box (Muffler A-EXH,RR)	\$ <i>R</i> 1,110.00

172-1450

DR/DR 344.28 50/50

} ✗

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-318

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7970Z - ERGO

31	1	Rear Fender RH	\$	<i>R</i> 1,145.00	X
32	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44	X
33	1	Rear Fender LH	\$	<i>R</i> 1,145.00	X
34	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44	X

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Special Nett

1	1Set	Licence Plate With Holder	\$	<i>Sn</i> 60.00	X
2	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00	X
3	1Set	Rear Bumper Parking Sensor	\$	<i>Redshon</i> 300.00	✓
4	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00	✓
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00	X
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00	X
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00	X
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nn</i> 30.00	✓
9	1	Rear Boot Sticker '6555-3333'	\$	<i>nn</i> 30.00	✓
10	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00	X
11	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00	X
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00	X
13	1	Spare Tyre	\$	<i>Sn</i> 180.00	X
14	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74	X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,389.63

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,050.00 *600*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *600*

Putty And Spray Painting Of The Affected Portion.

\$ 4,200.00 *600*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-318

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7970Z - ERGO

To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	<i>601</i>
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	X
To transfer of boot fittings and conduct water seepage test.	\$	170.00	<i>601</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
	\$	10,210.00	
TOTAL	\$	23,599.63	

Repair Days*15 Days**5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001814/Ktd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 19-09-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7971X	Veh. Inspected	SHB 7970Z
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCH1800187	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB123953	Colour	WHITE / RED
Odometer	441061	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	8 mm
L/H Front Tyre	195/65 R15	GITI	8 mm
R/H Rear Tyre	195/65 R15	FALKEN	8 mm
L/H Rear Tyre	195/65 R15	CREMAX	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/01/2018	Inspection Date	30/01/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7970Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK - TOP	DENTED	466.56	466.56
1	BOOTLID 'CHEVROLET' BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID 'EPICALT' BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-

Report Ref No. CS/EG18001814/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH, RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,332.12	-397.72
			11,989.03	3,579.50
1	BOOTLID WEATHERSTRIP (50%) (SN)	DISTORTED / CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14
	SPECIAL NETT ITEMS			
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED / SHORTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,090.74	404.00

Report Ref No. CS/EG18001814/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM, REAR LUGGAGE FLOOR PANEL, BOOTLID HINGE RH, BOOTLID HINGE LH, REAR TAIL LAMP PANEL RH, REAR TAIL LAMP PANEL LH, REAR EXHAUST BOX (MUFFLER A-EXH, RR), REAR FENDER RH AND REAR FENDER LH.		4,050.00	600.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	600.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			10,210.00	1,460.00
	GRAND TOTAL		23,599.62	5,615.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CS/EG18001814/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.