

ASS. REC. BY:

REF: CS/ASM18001817 (1/1/vb 02) Special Instruction:

## ASSIGNMENT (Office)

From (Person): smart claim Kitty Teo of ASM Date/Time: 30012018 5:12pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 1479L Insured: \_\_\_\_\_

at Workshop m/s SMART Tel: 9826 7051

of Blk 176 Sin Ming Driv #D4-16

Policy No: \_\_\_\_\_ Claim No: S8MD0798

Sum Insured: \_\_\_\_\_ Excess: \$600.00

Make of Veh: \_\_\_\_\_ D.O.A. 13.012018

(Client's Record)

CA / REV / REP. / REV 24 HRS 31.01.2018 H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 30012018 5:29pm Person Contacted: Mr. Long Vehicle IN/OUT


Date/Time	Action/Instruction ( ✓ ) Estimate
	<u>GBB 1479L -x</u>
<u>1/2/18</u>	<u>Ma said max repair cost \$10k</u>
<u>1/2/18</u>	<u>Revert by SMART claim</u>
<u>5/2/18</u>	<u>Recd authorise repair by SMART claim</u>
<u>5/2/18</u>	<u>Informed Rajan c/A on LS repair, ex \$600 by email</u>

REF:

ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop mis: WEGA SMRT  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GBB147PL Yr Regn: AUG 2008  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: TOYOTA ARIES CC: 2982  
 Colour: SILVER A/C: Insured / Std / NI / NA  
 Sp. Reading: - T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFH502A80002990K  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size F: 195/80/R15  
 R: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: ~~113K~~ 113K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or B.F.  
 Front R/Bal. 8 mm Rear R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 13/11/2018 D.O.T. 3/11/2018 @ 11am  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
NS BODY / OS BODY / FRT  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>dua</u>
<u>23/5/18</u>	<u>LS \$10,000 confirmed by email (Red 11,920, 5419)</u>
<u>15/6/18</u>	<u>@ 258pm Call Rajan no answer</u>
<u>6/7/18</u>	<u>@ 4pm Call Rajan no answer</u>

RECEIVED 28 AUG 2018

Date/Time File Pass to?  : Prel. Report  
 : Final Report

Days Of Repair: 12  
 Resurvey No. of Trip: 1

Date/Time File Return to?  
27/8- typist

Add Fee:  Site Insp \$  
 Interview \$  
 Tech Invs \$  
 Weekend \$

Survey Fee:	<u>300</u>
Transportation	
Photo	
Other	
<b>Total</b>	<b>300</b>

Report Format: SMART claim  
 Lump Sum / I.B.h \$ 10,000p



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18001817/M1vb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 30-01-2018	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBB 1479L
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00798	Excess (\$)	600.00
Assign From	SMART CLAIM (KITTY TEO)	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/01/2018	Inspection Date	31/01/2018
Survey held at	WEGA - 176 SIN MING DRIVE #04-16		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 5 February 2018 9:47 AM  
**To:** 'Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'  
**Cc:** Leong Chee Kwong; SUR  
**Subject:** RE: GBB 1479L-DOA: 13/1/2018

Dear Rajan,

As instructed by our client AXA , please proceed to repair the insured vehicle **GBB 1479L on Lump Sum basis (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:theagarajan@smrt.com.sg]  
**Sent:** Friday, 2 February 2018 9:45 AM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** Leong Chee Kwong <cheekwongwega@gmail.com>  
**Subject:** RE: GBB 1479L-DOA: 13/1/2018

Hi veron

Pls see the attachment

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)

**From:** Leong Chee Kwong [mailto:cheekwongwega@gmail.com]  
**Sent:** Friday, 2 February, 2018 9:33 AM

**To:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[theagarajan@smrt.com.sg](mailto:theagarajan@smrt.com.sg)>

**Subject:** Fwd: GBB 1479L-DOA: 13/1/2018

Hi Rajan,

GBB 1479L-DOA: 13/1/2018

Pls signature and send back to Veron Chen (LKK)

----- Forwarded message -----

From: **Veron Chen (LKKAuto)** <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

Date: Thu, Feb 1, 2018 at 2:24 PM

Subject: GBB 1479L-DOA: 13/1/2018

To: "[cheekwongwega@gmail.com](mailto:cheekwongwega@gmail.com)" <[cheekwongwega@gmail.com](mailto:cheekwongwega@gmail.com)>

Cc: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

Dear Mr Leong,

Please refer attached.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thanks & Regards

*Chee Kwong*

Wega Engineering Pte Ltd

Office: 64521493

## ⏪ Re:RE: Re:RE: Re:IA SUBMITTED - Please revert

Type

🔔 Question

Message

Hi Veron, Please proceed to authorise at lump sum. Thanks.

Reply

 **IA SUBMITTED**

Type

 Question

Message

Dear Kitty, Please be informed that IA submitted. We have Not authorise repair. Kindly let us have your approval please. Repairer's Estimate (Gross) : S\$21,920.00 Revised Estimate Amount : S\$8,680.00 "Check" Items Amount : S\$1,250.00 Total : S\$9,930.00 Market Value : S\$13,000.00 COE/PARF Rebate : S\$632.00  
Nett Value : S\$12,368.00

[Reply](#)



Your ref: S8M00798  
Our ref: CS/ASM18001817/M1vb

Date :1/2/2018

The Motor Claims Department  
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. GBB 1479L**


We thank you for your instruction on 30/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/1/2018 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: S\$21,920.00
Revised Estimate Amount	: S\$8,680.00
"Check" Items Amount	: S\$1,250.00
Total	: S\$9,930.00
Market Value	: S\$13,000.00
COE/PARF Rebate	: S\$632.00
Nett Value	: S\$12,368.00

Description of Damage:

The vehicle sustained damages at the n/s body,o/s body and front portion



Survey date and time: 31/1/2018 at 11am

We have Not authorise repair.

No of days: 12 days

Yours faithfully,  
**MA CHIN FOOK**  
**Automotive Apprasier**

## ◀ Service Request Details

Claim

S8M00798

Reference

None 

Loss Date

January 13, 2018

Request Date

January 30, 2018

Due Date

February 6, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

GBB1479L

Make

TOYOTA HIACE MANUAL

### Service Address

---

60 WOODLANDS, , ,

### Primary Contact/Insured

---

HORIZON AUTOMOTIVE PTE. LTD.  
14 BENOI ROAD, 629887, Singapore, Singapore  
92311006 -JEROME  
jeromechou@horizon-automotive.com

### Claim Handler

---

Kitty TEO  
6568804602  
kitty.teo@axa.com.sg

Additional Instructions  
EXCESS \$600

[Messages](#)

[Invoices](#)

[History](#)

[Documents](#)

[Assessment](#)

[Metrics](#)

[Notes](#)

[New Message](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6371K
Vehicle Details	
Vehicle No.:	GBB1479L
Vehicle to be Exported:	No
Intended De-registration Date:	01 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1853340
Chassis No.:	JTFHT02P800029905
Maximum Power Output:	-
Open Market Value:	\$24,647.00
Original Registration Date:	12 Aug 2008
First Registration Date:	12 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$1,233.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2018
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$12,002.00
COE Rebate Amount:	\$632.00
<b>Total Rebate Amount:</b>	<b>\$632.00</b>

The information contained herein is correct as at 01 Feb 2018

OK

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	GBB1479L
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	HIACE MANUAL
Chassis No. :	JTFHT02P800029905
Propellant :	Diesel
Engine No. :	1KD1853340
Engine Capacity :	2982 cc
Maximum Power Output :	-
Maximum Laden Weight :	2800 kg
Unladen Weight :	1800 kg
Year Of Manufacture :	2008
Original Registration Date :	12 Aug 2008
Lifespan Expiry Date :	11 Aug 2028
COE Category :	C - Goods Vehicle & Bus
Quota Premium :	\$12,002.00
COE Expiry Date :	11 Aug 2018
Road Tax Expiry Date :	11 Aug 2018
Inspection Due Date :	11 Aug 2018
Intended Transfer Date :	31 Jan 2018
CO2 Emission :	-

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	23/01/2018 09:25
Date Of Accident	13/01/2018 09:45
Exact Location Of Accident	BKE (WOODLANDS) AFTER PIE(TUAS)
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB1479L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	HORIZON AUTOMOTIVE PTE LTD
Co Reg No	201216371K
Email Address	JEROMECHOU@HORIZON-AUTOMOTIVE.COM 92511006
Mobile Phone No	
Alternative Phone No	OFFICE-64530100
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1810877
Cover Note Number	
<b>Driver</b>	
Name of Driver	SAZLINDA BTE HASHIM
NRIC No	S7416536B
Date Of Birth	27/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	11/01/2005
Driving Experience	13 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87480774
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 110 JURONG EAST ST 13 #04-302
Postcode	600110
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	DRIZZING
Road Surface	WET

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG WEST NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO POLICE REPORT

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	SAZLINDA BTE HASHIM
------	---------------------

Approximate Age

Injuries Sustain

BACK, TUMMY, CHEST, RIGHT LEG

Injured person in which vehicle?

GBB1479L

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**



I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed,
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



  
 Policyholder's Signature  
 Date & Time: 22/1/18 5:12pm


  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 22/1/18 12:10hrs



  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.

Sketch Plan Pg. 2

SKETCH PLAN

Accident Date: 13<sup>th</sup> January 2018 Time: 9.4 am Location: BKE ~~road~~ (Woodlands) after PIR  
My Vehicle A: G8B1479L Vehicle B: \_\_\_\_\_ Vehicle C/Others: \_\_\_\_\_

(Tues)

Unable to provide sketch.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 13<sup>th</sup> Jan 2018 at 0947 Hrs I skidded my van and out of control. Weather was ~~the~~ <sup>very</sup> drizzling and wet road I couldn't remember and recall ~~what~~ <sup>how</sup> it exactly happen coz is too fast and sudden. my steering wheel turning ~~and~~ <sup>over</sup> to the other side of the lane and landed myself at the verge drain. when I regained conscious suddenly I saw there a vehicle in front of me landed in the drain.


Claim OD / TP at Ah Lim Motor     Claim OD / TP at other workshop     Reporting Only


Remarks : Please forward a copy of my efile accident report to  
My workshop : \_\_\_\_\_  
Email Address : jeanne.chan@horizon-automotive.com  
& Myself : \_\_\_\_\_  
Email Address : isanyongtee@horizon-automotive.com  
Note : Please take note that your insurer have **14 days timeframe** for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect

  
Policyholder's Signature  
Date & Time 22/1/18 5:10pm

  
Driver's Signature (if driver is not the policyholder)  
Date & Time 22/1/18 5:10pm

  
Witnessed by Reporting Centre  
Personnel

Accident Photo



Accident Photo



Accident Photo





Char.

### SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Commercial  
Reg. No. : GBB1479L  
Make / Model : TOYOTA HIACE  
Chassic No : JTFHT02P800029905  
Name of Driver : SAZLINDA BTE.HASHIM

Ref. No. : \_\_\_\_\_  
Reg. Date : \_\_\_\_\_  
Mileage : \_\_\_\_\_  
Rental/Replacement Vehicle : Yes / No

Date/Time of Accider : 13/01/18 0945

Surveyer is Required ? YES

If Yes, VICOM / LKK / AIS / Others MSIG : AXA

Vehicle is Towed Back ? YES Date / Time : \_\_\_\_\_


Accident reporting date : 23/1/2018 0925

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :

176 Sin Ming Drive, Sin Ming Autocare, #04-13,16, S(575721)

The damages on the vehicle are as indicated in the following diagram



Signed : \_\_\_\_\_ Date : \_\_\_\_\_

Accident Repair Job Card Nr : \_\_\_\_\_ Date Prepared : \_\_\_\_\_

Summary of Repair Estimates Repair Complete : \_\_\_\_\_

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges :	\$	<u>4,930.00</u>	\$	<u>-</u>
Total Spray Painting Charges	\$	<u>2,800.00</u>	\$	<u>-</u>
Total Material Charges :	\$	<u>13,140.00</u>	\$	<u>-</u>
Other Charges :	\$	<u>150.00</u>	\$	<u>-</u>
<b>TOTAL</b> :	\$	<u>21,020.00</u>	\$	<u>-</u>

21,920

Lump Sum Repair, if any : \_\_\_\_\_

No. of Repair Days : [ 21 ] days [ ] days

Signature : Prepared by: \_\_\_\_\_

Adjusted by: \_\_\_\_\_

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	
To top up a/c gas	\$ <del>150.00</del> 100	
to check wiring & system function	\$ <del>100.00</del> 60.	
To transfer door mechanisam	\$ <del>300.00</del> 180.	
To remove & refix a/c condenser , radiator fan assy	\$ <del>300.00</del> 180	
To remove & refix exhaust system	\$ <del>200.00</del> 120.	
To remove & refix reverse sensor	\$ <del>80.00</del> 60.	
To cutting welding knocking accident area front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender ,front door pillar 2nd layer rh & lh	\$ <del>3,800.00</del> 1500.	
<b>Total Labour</b>	\$4,930.00	\$0.00

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	
To respray front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender ,front door pillar 2nd layer rh & lh side door floor panel	\$ <del>2,800.00</del> 1600	
<b>Total Spray Painting &amp; Panel Beating</b>	\$2,800.00	\$0.00

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	
TOWING FEE	\$ <del>150.00</del> 120.	
<b>Total Other Costs</b>	\$150.00	\$0.00

Part 4 - Spare Parts / Material Usage

Ref No.:

To be completed by Service Advisor, ARC							Not given (X)
Part Number	Parts Description	Qty	COST Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Repair (R) Replace (/)
	FRONT BUMPER	1	\$ 220.00	✓	not def		
	FRONT BUMPER BRACKET LH	1	\$ 80.00	✓	dis		
	FRONT BUMPER BRACKET RH	1	\$ 80.00	✓	dis		
	FRONT BUMPER TOW HOCK COVER LH	1	\$ 10.00	✓	dis		
	FRONT BUMPER TOW HOCK COVER RH	1	\$ 10.00	✓	dis		
	FRONT BUMPER FOG LAMP LH	1	\$ 80.00	X	acc		
	FRONT BUMPER FOG LAMP RH	1	\$ 80.00	X	acc		
	FRONT BONNET HINGE LH	1	\$ 40.00	X	R		
	FRONT BONNET HINGE RH	1	\$ 40.00	X	R		
	FRONT BONNET	1	\$ 280.00	X	R		
	FRONT DOOR LH	1	\$ 650.00	✓	dt		
	FRONT DOOR RH	1	\$ 650.00	X	Repair		
	FRONT DOOR PILLAR LH	1	\$ 330.00	✓	dt		
	FRONT DOOR PILLAR 2ND LAYER	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE LOWER LH	1	\$ 55.00	X	R		
	FRONT DOOR CHECK LH	1	\$ 85.00	X	svc		
	FRONT DOOR PILLAR RH	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER RH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR STEP COVER LH		\$ 95.00	✓	dis		
	FRONT DOOR STEP COVER RH		\$ 95.00	✓	dis		
	FRONT DOOR STEP PANAL RH		\$ 125.00	✓	not		
	LH SIDE DOOR		\$ 750.00	✓	dt		
	RH SIDE DOOR		\$ 750.00	✓	dt		



Part Number	Parts Description	Qty	cost price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace(/)	Not given (X) Repair (R) Replace(/)
	AIR COND SUCTION HOSE	1	\$ 210.00	—	WA		
	AIR COND DISCHARGE HOSE	1	\$ 195.00	—	WA		
	AIR FILTER BOX ASSY	1	\$ 340.00	—	dis		
	REAR BUMPER	1	\$ 230.00	—	det		
	REAR BUMPER BRACKET LH	1	\$ 45.00	—	ur		
	REAR BUMPER BRACKET RH	1	\$ 45.00	—	ur		
	REVERSE SENSOR	1	\$ 180.00	—	SWA		
	REAR FENDER RH	1	\$ 1,200.00	X	R		
	FRONT EXHAUSE PIPE	1	\$ 2,600.00	—	WA		
	REAR EXHAUST PIPE	1	\$ 495.00	X	R		
	NUMBER PLATE <i>FRONT</i>	1	\$ 30.00	—	dis		
	DOOR COMPANY STICKER	2	\$ <del>100.00</del>	20%	ur		
TOTAL MATERIALS			\$ 14,040.00		\$ -		

Surveyor Remark:

Veron Chen (LKKAuto)

---

Nelson

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
<theagarajan@smrt.com.sg>  
**Sent:** Wednesday, 28 March 2018 9:55 AM  
**To:** SUR  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Subject:** GBB1479L TO FINALISE  
**Attachments:** 1479.pdf

Hi

Hereby I attached the surveyor marked copy for finalised pls go thru and give a reply ASAP.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: Theagarajan@smrt.com.sg



Chia

### SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Commercial

Reg No : GBB1479L Ref No : \_\_\_\_\_

Make / Model : TOYOTA HIACE Reg Date : \_\_\_\_\_

Chassis No : JTFHT02P800029905 Mileage : \_\_\_\_\_

Name of Driver : SAZLINDA BTE HASHIM Rental/Replacement Vehicle : Yes / No

Date/Time of Accident : 13/01/18 0945

Surveyor is Required ? YES

If Yes, VICOM / LKK / AIS / Others MSIG : AXA

Vehicle is Towed Back ? YES Date / Time : \_\_\_\_\_

Accident reporting date : 23/1/2018 0925

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any

176 Sin Ming Drive, Sin Ming Autocare, #04-13, 16, S(575721)

The damages on the vehicle are as indicated in the following diagram



Signed \_\_\_\_\_ Date \_\_\_\_\_

Accident Repair Job Card No: \_\_\_\_\_ Date Prepared: \_\_\_\_\_

Summary of Repair Estimates Repair Complete: \_\_\_\_\_

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	\$ <u>4,930.00</u>	\$ _____
Total Spray Painting Charges	\$ <u>2,800.00</u>	\$ _____
Total Material Charges	\$ <u>13,140.00</u>	\$ _____
Other Charges	\$ <u>150.00</u>	\$ _____
<b>TOTAL</b>	<b>\$ <u>21,020.00</u></b>	<b>\$ _____</b>

Lump Sum Repair, if any: \_\_\_\_\_

No. of Repair Days : [ 21 ] days [ \_\_\_\_\_ ] days

Signature: Prepared by  Adjusted by

QN No \_\_\_\_\_ Invoice No \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed \_\_\_\_\_ Date \_\_\_\_\_

## Part 1 - Labour Works

Job Scope	Quotation from ARC	
To top up a/c gas	\$ <del>150.00</del>	100
to check wiring & system function	\$ <del>100.00</del>	60
To transfer door mechanism	\$ <del>300.00</del>	180
To remove & refix a/c condenser , radiator fan assy	\$ <del>300.00</del>	180
To remove & refix exhaust system	\$ <del>200.00</del>	120
To remove & refix reverse sensor	\$ <del>80.00</del>	60
To cutting welding knocking accident area front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender , front door pillar 2nd layer rh & lh	\$ <del>3,800.00</del>	1,500
<b>Total Labour</b>	\$4,930.00	\$0.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray front bumper , front bonnet , front door lh & rh , front door pillar lh & rh , side door lh & rh , support panel , radiator lower support panel , rear rh fender , front door pillar 2nd layer rh & lh side door floor panel	\$ <del>2,800.00</del>	1,600
<b>Total Spray Painting &amp; Panel Beating</b>	\$2,800.00	\$0.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	
TOWING FEE	\$ <del>150.00</del>	120
<b>Total Other Costs</b>	\$150.00	\$0.00

11190.40

13988  
2797.60

3920

Part 4 - Spare Parts / Material Usage

Ref No

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	COST Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (✓)	Not given (X) Repair (R) Replace (✓)
	FRONT BUMPER	1	\$ 220.00	✓	not def		
	FRONT BUMPER BRACKET LH	1	\$ 80.00	✓	dis		
	FRONT BUMPER BRACKET RH	1	\$ 80.00	✓	dis		
	FRONT BUMPER TOW HOOK COVER LH	1	\$ 10.00	✓	dis		
	FRONT BUMPER TOW HOOK COVER RH	1	\$ 10.00	✓	dis		
	FRONT BUMPER FOG LAMP LH	1	\$ 80.00	X	acc		
	FRONT BUMPER FOG LAMP RH	1	\$ 80.00	X	acc		
	FRONT BONNET HINGE LH	1	\$ 40.00	X	R		
	FRONT BONNET HINGE RH	1	\$ 40.00	X	R		
	FRONT BONNET	1	\$ 280.00	X	R		
	FRONT DOOR LH	1	\$ 650.00	✓	dt		
	FRONT DOOR RH	1	\$ 650.00	X	Repair		
	FRONT DOOR PILLAR LH	1	\$ 330.00	✓	dt		
	FRONT DOOR PILLAR 2ND LAYER	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	✓	R		
	FRONT DOOR HINGE LOWER LH	1	\$ 55.00	X	R		
	FRONT DOOR CHECK LH	1	\$ 85.00	X	src		
	FRONT DOOR PILLAR RH	1	\$ 290.00	X	R		
	FRONT DOOR HINGE UPPER RH	1	\$ 55.00	X	R		
	FRONT DOOR HINGE UPPER LH	1	\$ 55.00	X	R		
	FRONT DOOR STEP COVER LH		\$ 95.00	✓	dis		
	FRONT DOOR STEP COVER RH		\$ 95.00	✓	dis		
	FRONT DOOR STEP PANEL RH		\$ 126.00	✓	not		
	LH SIDE DOOR		\$ 750.00	✓	dt		
	RH SIDE DOOR		\$ 750.00	✓	dt		



Part Number	Parts Description	Qty	cost price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	AIR COND SUCTION HOSE	1	\$ 210.00		wa		
	AIR COND DISCHARGE HOSE	1	\$ 195.00		wa		
	AIR FILTER BOX ASSY	1	\$ 340.00		dis		
	REAR BUMPER	1	\$ 230.00		det		
	REAR BUMPER BRACKET LH	1	\$ 45.00		nc		
	REAR BUMPER BRACKET RH	1	\$ 45.00		nc		
	REVERSE SENSOR	1	\$ 180.00		shwa		
	REAR FENDER RH	1	\$ 1,200.00		R		
	FRONT EXHAUSE PIPE	1	\$ 2,600.00		wa		
	REAR EXHAUST PIPE	1	\$ 495.00		X R		
	NUMBER PLATE <i>FRONTA</i>	1	\$ 30.00		dis		
	DOOR COMPANY STICKER	2	\$ <del>100.00</del>		30 nc		
TOTAL MATERIALS			\$ 14,040.00		\$		

Surveyor Remark:

*MAX 10K  
CONG*

*12XPS  
2017  
10.068*

## Veron Chen (LKKAuto)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
<theagarajan@smrt.com.sg>  
**Sent:** Wednesday, 23 May 2018 12:12 PM  
**To:** Veron Chen (LKKAuto); SUR  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Subject:** GBB1479L TO FINALISE  
**Attachments:** 1479DV.pdf; 1479FRB1.pdf

Hi Veron

Please see the attachment of the DV and FRB to proceed for the payment.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: Theagarajan@smrt.com.sg

---

**From:** Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]  
**Sent:** Wednesday, 2 May, 2018 5:33 PM  
**To:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <theagarajan@smrt.com.sg>; SUR <sur@lkkauto.com>  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TanSohChern@smrt.com.sg>; Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <PehEngHock@smrt.com.sg>  
**Subject:** RE: GBB1479L TO FINALISE

Dear Rajan,

Offer Lump Sum \$10,000 before excess \$600.

Kindly confirmed.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:theagarajan@smrt.com.sg]  
**Sent:** Friday, 13 April 2018 3:38 PM  
**To:** SUR <sur@lkkauto.com>  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TanSohChern@smrt.com.sg>; Peh Eng Hock (Auto

Svcs/Ext Biz Svcs/AR & SC/ARC) <PehEngHock@smrt.com.sg>

**Subject:** FW: GBB1479L TO FINALISE

Hi Ma

Its already 2 weeks didn.t hear from you. Pls try to finalise ASAP.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Sent:** Wednesday, 28 March, 2018 9:55 AM  
**To:** [sur@lkkauto.com](mailto:sur@lkkauto.com)  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[TanSohChern@smrt.com.sg](mailto:TanSohChern@smrt.com.sg)>  
**Subject:** GBB1479L TO FINALISE

Hi

Hereby I attached the surveyor marked copy for finalised pls go thru and give a reply ASAP.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179402  
Tel: 65 63311000 Fax: 65 63340247

### Tax Invoice

Customer Code: 3000505

Accident Repair Customer (Upper Bukit Timah)  
AXA INSURANCE  
Block Unit 24-01  
AXA TOWER  
8 SHENTON WAY  
SINGAPORE 068811

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : EV180500478  
Date : 23.05.2018  
Vehicle No. : GBB1479L  
Your Ref No. : UBT/JAN2018/005  
Our Ref No. : 21003220  
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount
<b>Others</b>					
REPAIR COST AS APPRVED BY SURVEYOR	1.00	\$9000.00	0.00	\$ 0.00	\$ 9000.00

TOTAL BEFORE GST	\$	9,000.00
ADD GST @ 07 %	\$	630.00
GRAND TOTAL	\$	9,630.00

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Computer generated  
no signature requires

\_\_\_\_\_  
Authorised Signature  
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

### Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : EV180500476  
Date : 23.05.2018  
Vehicle No. : GBB1479L  
Your Ref No. : UBT/JAN2018/005  
Our Ref No. : 21003099  
Terms : 30 Days

Customer Code: 3000505

Accident Repair Customer (Upper Bukit Timah)  
AXA INSURANCE  
Block Unit 24-01  
AXA TOWER  
8 SHENTON WAY  
SINGAPORE 068811

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount,
<b>Others</b>					
REPAIR COST AS APPROVED BY SURVEYOR	1.00	\$1000.00	0.00	\$ 0.00	\$ 1000.00
TOTAL					\$ 1,000.00
EXCESS PAYMENT					-\$ 600.00
TOTAL BEFORE GST					\$ 400.00
ADD GST @ 07 %					\$ 28.00
GRAND TOTAL					\$ 428.00

N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Computer generated  
no signature requires

Authorized Signature  
for SMRT Automotive Services Pte Ltd

## Veron Chen (LKKAuto)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <theagarajan@smrt.com.sg>  
**Sent:** Thursday, 31 May 2018 2:06 PM  
**To:** Veron Chen (LKKAuto)  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Subject:** FW: GBB1479L TO FINALISE  
**Attachments:** 1479.pdf

Hi Veron

Please see the attachment of the DV and FRB to proceed for the payment.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)

---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Wednesday, 2 May, 2018 5:33 PM  
**To:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <theagarajan@smrt.com.sg>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[TanSohChern@smrt.com.sg](mailto:TanSohChern@smrt.com.sg)>; Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[PehEngHock@smrt.com.sg](mailto:PehEngHock@smrt.com.sg)>  
**Subject:** RE: GBB1479L TO FINALISE

Dear Rajan,

Offer Lump Sum \$10,000 before excess \$600.

Kindly confirmed.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [<mailto:theagarajan@smrt.com.sg>]  
**Sent:** Friday, 13 April 2018 3:38 PM

**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[TanSohChern@smrt.com.sg](mailto:TanSohChern@smrt.com.sg)>; Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[PehEngHock@smrt.com.sg](mailto:PehEngHock@smrt.com.sg)>

**Subject:** FW: GBB1479L TO FINALISE

Hi Ma

Its already 2 weeks didn.t hear from you. Pls try to finalise ASAP.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)

---

**From:** Theagarajan Annamalai (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

**Sent:** Wednesday, 28 March, 2018 9:55 AM

**To:** [sur@lkkauto.com](mailto:sur@lkkauto.com)

**Cc:** Susan Tan Soh Chern (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[TanSohChern@smrt.com.sg](mailto:TanSohChern@smrt.com.sg)>

**Subject:** GBB1479L TO FINALISE

Hi

Hereby I attached the surveyor marked copy for finalised pls go thru and give a reply ASAP.

Thanks and Regards,  
A.Theagarajan (Rajan)  
Mobile: 8647 5507  
DID/ FAX: 6469 1234  
Email: [Theagarajan@smrt.com.sg](mailto:Theagarajan@smrt.com.sg)



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

### Tax Invoice

Customer Code: 3000505

Accident Repair Customer (Upper Bukit Timah)  
AXA INSURANCE  
Block Unit 24-01  
AXA TOWER  
8 SHENTON WAY  
SINGAPORE 068811

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : EV180500684  
Date : 31.05.2018  
Vehicle No. : GBB1479L  
Your Ref No. : UBT/JAN2018/005  
Our Ref No. : 21004799  
Terms : 30 Days

Description	Qty	Unit Cost	Add %	(Discount) Amount	Amount,
<b>Others</b>					
REPAIR COST AS APPROVED BY SURVEYOR	1.00	\$10000.00	0.00	\$ 0.00	\$ 10000.00

TOTAL	\$ 10,000.00
EXCESS PAYMENT	-\$ 600.00
TOTAL BEFORE GST	\$ 9,400.00
ADD GST @ 07 %	\$ 658.00
GRAND TOTAL	\$ 10,058.00


N.B. Payment by cheque should be crossed and made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Computer generated  
no signature requires

\_\_\_\_\_  
Authorised Signature  
for SMRT Automotive Services Pte Ltd

## SATISFACTION FORM

I, HORIZON AUTOMOTIVE PTE LTD, hereby acknowledge having received from SMRT Automotive Services Pte Ltd my vehicle bearing registration number GBB 1479L which has been repaired to my satisfaction and acceptance. And I agree that the payment of the account for such repairs to SMRT Automotive Services Pte Ltd. shall be in full discharge of all claims under policy number VFX/P1810877 in respect of the damage caused in the accident which occurred on BKE CWOODLANDS) AFTER PIE (TUMS)

  
8865546B  
Signature, NRIC No. & Date



  
Co. Stamp (If applicable)