

ASS. REC BY:

REF: CS/SMO18001857/Mad3

Surveyor

## ASSIGNMENT (Office)

From (Person) Grace Teo

of SMO

Date/Time 30/1/18 @ 4:23pm

Estimated Cost:

Bill to:

OD  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 496K

Insured:

SLQ 5700K

at Workshop in/:

SG 98 Motor

Tel:

64524898

of Blk 4001 #01-21, AMK Ind. Park I

Policy No:

Claim No:

CMTD18 00474 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 26/01/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

4:50pm @ 30/1/18

Person Contacted:

Rose

Vehicle IN  OUT

Date/Time

Action/Instruction ( → Estimate

FBM 496K-x

SLQ 5700K-x

07/2/18 @ 3:08pm Informed Thelma, we are pending for estimate from repairer.

29/1/18 @ 4:01pm Revised to Thelma by email.

Ls \$1500, 3 days (Fed \$1686, 53%)

125  
Resul

SMO

4951C

ASSIGNMENT

Make: \_\_\_\_\_ Date: 2/2/18

Estimated Cost: \_\_\_\_\_

QC:  WS / TP RES / CD RES / EVA / INV / MV

To: FBM 496K  
SG 98 Motor  
AMK

at: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Excess: \_\_\_\_\_

Client Record: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

Policy Condition: Ilam

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \_\_\_\_\_

ICAO Accident Report Consistent? Yes or No


GA - RR Exam Consistent? Yes or No

Est. Report days Res: Yes or No

Lim Surv: % Eva: Yes or No

CA / REV / REP / 24 HRS 1up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_



Year: FBM 496K Year: 2017 Jan

Type Motor: CB 400SF Equ / Ven / Long / Tall / Prime Mover

Truck / Trailer: \_\_\_\_\_

Make: Honda CB 400SF 399

Color: Red/white Insured / Std / N / NA

So. Rating: 6284 T-Rate / Insured / Std / N / NA

Eng No: \_\_\_\_\_

Chassis: NC 42-1503449

Gen. Cond: Good Fair / Poor / Burnt

Steering: Wonder / Jammed / Leaked / Burnt or

Brake: Wonder / Jammed / Leaked / Burnt or

Mod: Nil SRim / STD A-Rim or

Tyre Size: F: 120/60ZR17  
R: 160/60ZR17

BS / DUN / EXNOVA / GY / PS / LGA / MID / OHTSU / PIR / SUMI

TOYO / YOKO or Bridgestone

Front	Pass
R Se: <u>2</u>	R Se: <u>2</u>
L Se: <u>2</u>	L Se: <u>2</u>

D/OA: 26/1/2018 / 2/2/2018

Surveyed at: Ilam

Des. of Damages: Fr: \_\_\_\_\_ Rear: OS / N/S / U/C / Rooftop or

The U/C / Chassis/frame / Body Structure is/affected due to collect

2/2/18 Question which will send to Remy!

RECEIVED 30 JAN 2019

*[Signature]*  
29/1/2019

Days of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Cost of Repair: 200

Final Report:  Prelim Report:

Add Fee:  Mileage:

Report Format: TA

Write Sum: 1500

200

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18001857/R1qd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 31-01-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 5700K	Veh. Inspected	FBM 496K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800474/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	31/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/01/2018	Inspection Date	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 30 January 2018 4:23 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Sg Motor; Sg Motor; Choo, Thelma; Henry, Irene James  
**Subject:** CMTD1800474/THE - ACCIDENT INVLG SLQ5700Z & FBM496K ON 26.01.18  
**Attachments:** FBM 496K-PRI.PDF

Our Reference: CMTD1800474/THE

Dear LKK AUTO CONSULTANTS/ Mohd Rasul,

Please make arrangement to conduct the survey for FBM496K.

Please be informed that Thelma Choo the handler of this case

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Sg Motor [mailto:sgmotor2000@yahoo.com.sg]

**Sent:** Tuesday, January 30, 2018 2:32 PM

**To:** Teo, Grace

**Cc:** Sg Motor; Choo, Thelma; Henry, Irene James

**Subject:** Re: CMTD1800474/THE - ACCIDENT INVLG SLQ5700Z & FBM496K ON 26.01.18

Dear Grace

Please appoint LKK Auto Consultants Pte Ltd (Rasul) for the Pre Repair Inspection.

Thank You

Regards

Linda

**SG 98 Motor Pte Ltd**

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

On Tuesday, 30 January 2018, 1:39:51 PM GMT+8, Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference : CMTD1800474/THE

Your Reference: FBM496K

**Without Prejudice**

Date: 30<sup>TH</sup> January 2018

**Attention:**

**M/S SG 98 MOTOR PTE LTD**

Dear Linda/ Rose,

**ACCIDENT INVOLVING SLQ5700Z & FBM496K ON 26.01.18**

We refer to your Notice of Accident dated 30/01/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

### Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Sg Motor [<mailto:sgmotor2000@yahoo.com.sg>]  
**Sent:** Tuesday, January 30, 2018 12:45 PM  
**To:** Claims - Motor Survey  
**Cc:** Sg Motor  
**Subject:** Please arrange PRI For bike FBM 496K

Attn : Motor Claims Dept

Dear Sir/Madam

Please arrange PRI For bike FBM 496K as per attached.

Thank You

Regards

Linda

**SG 98 Motor Pte Ltd**

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

---

Date : 29 January 2018

Sompo Insurance Singapore Pte Ltd  
50 Raffles Place  
#05-01/06 Singapore Land Tower  
SINGAPORE 048623

Attn : Motor Claims Dept  
Fax : 6221 3147 / 62266318  
Email: motorsurvey@sompo.com.sg

Dear Sir/Mdm,

## PRE-REPAIR INSPECTION

Accident between FBM 496K and SLQ 5700Z accident on 26 January 2018 at 1730hrs  
Location: Tuas Avenue 5 beside Bok Seng Company

- 1) We hereby give you NOTICE that we are claiming against your insured motor Vehicle No : SLQ 5700Z damages to our client's Motor Vehicle No: FBM 496K
- 2) Plse provide a list of surveyors and their respective company name.
- 3) Kindly let us know if you wish to conduct a pre-repair inspection only after 11.30am at Blk 4001 Ang Mo Kio Industrial Park 1 #01-21 Singapore 569622.  
(Tel : 6452 4898, HP : 9171 1655)
- 4) If we do not hear from you within the next two (2) working days, we shall advise our clients to proceed with their own inspection and repairs.

Hope you are able to assist us on the above matter soonest.

Yours faithfully



Rose  
SG 98 Motor Pte Ltd  
Tel : 6452 4898



## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 29 January 2019 4:01 PM  
**To:** 'Choo, Thelma'  
**Cc:** SUR; 'Henry, Irene James'  
**Subject:** CMTD1800474/THE - ACCIDENT INVLG SLQ 5700Z & FBM 496K ON 26.01.18  
**Attachments:** CSSMO18001857R1qd3.pdf

Dear Thelma,

Enclosed herewith preliminary advice of FBM 496K.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1800474/THE

Date: 29<sup>th</sup> August 2018

Our Ref: CS/SMO18001857/R1qd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. FBM 496K.**

We thank you for the instruction on 30/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/02/2018 at the premises of M/s SG 98 MOTOR and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,186.00</u>
Revised Estimate Amount	: <u>S\$ 1,500.00 (Lump Sum)</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:  
The vehicle sustained damages at the o/s portion.



Comments/ Present Status:  
Damages consistent.  
Days of repair: 3 days.  
We have not authorized repair.

Yours faithfully

Rasul  
Automobile Assessor

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 7 February 2018 3:08 PM  
**To:** 'Teo, Grace'; assignments; 'Choo, Thelma'  
**Cc:** SUR; 'Henry, Irene James'  
**Subject:** RE: CMTD1800474/THE - ACCIDENT INVLG SLQ5700Z & FBM496K ON 26.01.18

Dear Thelma,

Please be informed that we have inspected the vehicle FBM 496K on 02/02/2018.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 30 January 2018 4:54 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; 'Choo, Thelma' <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** RE: CMTD1800474/THE - ACCIDENT INVLG SLQ5700Z & FBM496K ON 26.01.18

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Tuesday, 30 January 2018 4:23 PM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Sg Motor <[sgmotor2000@yahoo.com.sg](mailto:sgmotor2000@yahoo.com.sg)>; Sg Motor <[sg\\_motor\\_enterprise@yahoo.com.sg](mailto:sg_motor_enterprise@yahoo.com.sg)>; Choo, Thelma <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** CMTD1800474/THE - ACCIDENT INVLG SLQ5700Z & FBM496K ON 26.01.18

Our Reference: CMTD1800474/THE

Dear LKK AUTO CONSULTANTS/ Mohd Rasul,

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/01/2018 14:37
Date Of Accident	26/01/2018 17:30
Exact Location Of Accident	ALONG TUAS AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM496K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOO SOON HENG
NRIC No	S1624951C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96838273
Alternative Phone No	OTHERS-96838273

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF-399CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1968543
Cover Note Number	05/07/2017 - 04/07/2018

### Driver

Name of Driver	LOO SOON HENG
NRIC No	S1624951C
Date Of Birth	23/01/1963
Occupation	INDOOR
Date Of Driving Pass	23/03/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96838273
Fax Number	
Contact Number	OTHERS-96838273
EMail Address	NOEMAIL

Address	BLK 546 CHOA CHU KANG ST 52 #05-20
Postcode	680546
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KALLANG NEIGHBOURHOOD POLICE POST
Police Station Address	<b>ROAD:</b> BLK 105 TOWNER ROAD #01-400 , <b>POSTCODE:</b> 321105 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-2996999 - <b>FAX NO:</b> 63912397
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLQ5700Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:


\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre for Road Accidents' Signature  
Name:  
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 26/1/18 Time: 12:30 Location: Along Tuas Ave 5  
 My Vehicle A: from garage Vehicle B: SL23P2 Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to the police report*

Claim OD/TP at Ah Lim Motor  Claim OD/TP at other workshop  Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :  
 Email address :  
 & myself :  
 Email address :

Note: Please take note that your Insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own Insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]  
 Policyholder's Signature  
 Date & Time:

[Signature]  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

[Signature]  
 Reporting Officer's Signature  
 Name:  
 NRIC/PIN No.:



ah lim motor.com.sg







Police Station Of Origin:  
Kallang NPP  
105 Towner Road #01-400 SINGAPORE  
321105  
Tel No: 1800-2996999

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	LOO SOON HENG	ID No.	S1624951C
Related Vehicle	FBM496K	Contact No.	96838273
Hospital/Clinic	CHONG'S CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	27/01/2018	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	NIL

**Brief Details.**

On 26/01/2018 at about 1730hrs, I was riding my motorbike along Tuas Avenue 5. During then there was a car beside me on the same lane. A vehicle (SLQ5700Z) which came out from Bok Seng company suddenly appeared and in order to prevent from getting hit, as such I swirl to my right side and fell onto the floor. During then, the driver of SLQ5700Z (HP:81830824) came out of the vehicle and asked if I were okay and required any assistance. We also managed to exchange our phone numbers.

No Traffic police or ambulance were at scene. I wish to state that my exhaust pipe is dent and both my hand handle and brake handle is bent.

On 27/01/2018, I woke up and I felt pain on the lower back. As such I went to consult a doctor and was given MC from 27/01/2018 to 31/01/2018.



**SINGAPORE  
POLICE FORCE**



T/20180127/2103

Police Station Of Origin:  
Kallang NPP  
105 Towner Road #01-400 SINGAPORE  
321105  
Tel No: 1800-2996999

3 of 3




Report No. T/20180127/2103

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: A / Sgt 2 DOWSON TAN SOO HAO 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 27/01/2018 15:49
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:
Authentication Stamp NP168  Signature: 	SN I

SUMAN CHAN

fax on 24/9/18 @ 15:24

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 28 February 2018

To : LKK

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBM 496K

ACCIDENT DATE: 26 January 2018

By Fax: 6256-4315

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Rep	Qty	Quotation \$
---------------------	-----	--------------

1 Exhaust Pipe	1	1,100.00 PA
2 Mirror <del>Left</del> <i>Right</i>	1	190.00 SCR
3 Handle Bar	1	160 250.00 <del>PA</del>
4 Balancer <i>RH</i>	1 set	50 250.00 SCR
5 Rear Tail Fairing	1	300.00 repair
6 Rear Pillar Footrest RH	1	50 150.00 SCR

Sub-Total 2,240.00 *1530*  
 Less 10% 224.00 *10%*  
 Sub-Total 2,016.00 *1377*


### Nett items

1 Remove & repress fork assy, top up fork oil	250.00 X 17
2 Remove & replace necessary parts, align & etc	320.00 <i>250</i>
3 Putty & respray paint & touch up	250.00 <i>100</i>
4 Rear Box	350.00 <i>180 net</i>

Sub-Total 1,170.00  
 Nett Total 3,186.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you.



*Quoted amount 24/9*

*Repair*  
*Hp 90010068*  
*3 days*  
*02/02/18 @ 12:20*  
*4/8*

*1377.00*  
*530.00*  


---

*1907*  
*206*  
*1525.60*  


---

*42-1,500*  


---

*3 days*

SG 98 MOTOR PTE LTD



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18001857/R1qd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 30-01-2019	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLQ 5700Z	Veh. Inspected	FBM 496K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800474/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/01/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400SF	c.c	399
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NC421803449	Colour	RED / WHITE
Odometer	6284	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/60Z R17	BRIDGESTONE	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60Z R17	BRIDGESTONE	2 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/01/2018	Inspection Date	02/02/2018
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 496K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	EXHAUST PIPE	BENT	1,100.00	1,100.00
1	MIRROR RIGHT	SCRATCHED	190.00	170.00
1	HANDLE BAR	BENT	250.00	160.00
1	SET BALANCER RH	SCRATCHED	250.00	50.00
1	REAR TAIL FAIRING	TO REPAIR SEE LABOUR	300.00	-
1	REAR PILLAR FOOTREST RH	SCRATCHED	150.00	50.00
	LESS 10% DISCOUNT		-224.00	-153.00
			2,016.00	1,377.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BOX (SN)	NECESSARY	350.00	180.00
			350.00	180.00
<b><u>LABOUR</u></b>				
	REMOVE & REPRESS FORK ASSY, TOP UP FORK OIL.	NOT NECESSARY	250.00	-
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC. INCLUSIVE OF THE REPAIR OF REAR TAIL FAIRING.		320.00	250.00
	PUTTY & RESPRAY PAINT & TOUCH UP.		250.00	100.00
			820.00	350.00
<b>GRAND TOTAL</b>			<b>3,186.00</b>	<b>1,907.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/SMO18001857/R1qd3e2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.