



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2006 HONDA ACCORD 2.0 (SGL3802L)

Date of Loss

26 January 2018

Time of Loss

18.20

Loss Description

SGL3802L (INSD) HIT SLR4432Z (TP) INTO REAR

Comment

Workshop Details

Total Rebate Amount

20476

Nett Loss Amount

\$5,524.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

29/04/2018



Days of work completion *

87



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SGL3802L

Registration State

SINGAPORE

Mileage

367910

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2006

ASSESSMENT INFO...

2006

Purchase Date

dd/mm/yyyy



Registration Date *

13/09/2006



Age of Vehicle

11

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

ONG SU KWANG JAMES

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... ACCORD 2.0

ASSESSMENT INFO... ACCORD 2.0 A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... CL73202398

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 9 July 1982

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 35

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... K20A6042832

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 14

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 264A PUNGGOL WAY, 821264,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S8274521A

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

900

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

205/55R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

205/55R16

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Save

Assessment Details

General & Workshop Details															
Vehicle & Driver Details															
Vehicle Condition															
Taxes & Ratio															
Parts & Labour															
Miscellaneous															
Summary															
Parts															
AddApproveDeny															
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
		1	1			BONNET			Serviceable	0	0	0	0	0	Deny
		2	1			FRONT GRILLE			Damaged	145				145	Review
		3	1			FRONT GRILLE LOGO			Damaged	15				15	Review
		4	1			FRONT GRILLE MOULDING TOP			Serviceable	0	0	0	0	0	Deny
		5	1			FRONT GRILLE MOULDING CENTER			Damaged	110				110	Review
		6	1			FRONT GRILLE LOWER			Damaged	55				55	Review
		7	1			FRONT HEADLAMP RH			Cracked	440				440	Review
		8	1			FRONT HEADLAMP LH			Cracked	440				440	Review
		9	1			FRONT BUMPER			Damaged	550				550	Review
		10	10			FRONT BUMPER CLIPS			Necessary	1				10	Review
		11	1			FRONT BUMPER SIDE RETAINER RH			Bent	12				12	Review
		12	1			FRONT BUMPER SIDE RETAINER LH			Bent	12				12	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			HEADLAMP LOWER BRACKET RH			Serviceable	0	0	0	0	0	Deny
		14	1			HEADLAMP LOWER BRACKET LH			Serviceable	0	0	0	0	0	Deny
		15	1			FRONT BUMPER REINFORCEMENT			Damaged	145				145	Review
		16	1			A/C CONDENSOR			Serviceable	0	0	0	0	0	Deny
		17	1			FRONT FENDER RH			Serviceable	0	0	0	0	0	Deny
		18	1			FRONT FENDER LH			Serviceable	0	0	0	0	0	Deny
		19	1			FRONT SUPPORT PANEL			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMARKS
		1		LABOUR TO FACILIATE REPAIR	300	0	0	Reviewing		1
		2		LABOUR TO SPRAY PAINT AFFECTED AREAS	400	0	0	Reviewing		1
		3		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	20	0	0	Reviewing		1
		4		TO REMOVE & REFIT AIRCON CONDENSOR INCLUDING TOP US AIRCON GAS	0	0	0	Deny		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	COOLANT	Deny	0	NOT NECESSARY	
		2	FRONT NUMBER PLATE & HOLDER	Reviewing	35	BENT	
		3	DAYS OF REPAIR : 4 DAYS	Reviewing			

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount \$1,789.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$950.00	\$720.00
Spare Parts	\$2,194.00	\$1,934.00
Miscellaneous	\$70.00	\$35.00
Excess	-\$900.00	-\$900.00