

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.01.2018

REPAIR ESTIMATE

Time: 10:17:24

Page: 1/2

TS

Ag Asia - 45
LKK - Calvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305111974
 REGN NO : SH 7829M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.02.2014
 DATE/TIME IN : 30.01.2018 07:45
 ACCIDENT DATE : 29.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	X repair
0002 04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	49.00	20.00	39.20	?
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	X
0004 04-01-0101-0627-A	BUMPER PROTECTOR MAT	1	50.00	200	50.00	—
0005 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	X
0006 04-01-0103-0851-G	REAR BUMPER REFLECTOR LH	1	32.00	20.00	25.60	X

SUB-TOTAL : 795.28

JOB NATURE

0000 L	PANEL BEATING	280.00	100
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	180

SUB-TOTAL : 480.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.01.2018

Time: 10:17:24

Page: 2/2

REPAIR ESTIMATE

Agasia - 45
LKK - Calvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305111974
REGN NO : SH 7829M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.02.2014
DATE/TIME IN : 30.01.2018 07:45
ACCIDENT DATE : 29.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,275.28

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Calvin LKK
30/1/18 1030 hrs.
2 Digs
4/5
After Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplemental claim(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: