

TO APPLY COPY OF STATEMENT OF SKU 5331 X

INS. CASE OWNER: Satika | CC 61AIG18001903 UKB3 ^{rk} | LKK: | IDAC:

Surveyor: Marcus | DOI: 05/02/18 | Date / Time: 31/01/18
Registered in Meritem: 31/01/18

Pre-assign / CCU / FTE

 Insured Vehicle No.: QJK 8224S | Claim No.: 75362959956
Name of Insured: ORANGE LEASING PTE LTD | Policy No.:
Insured Tel No.: | HP: | Make / Model: HYUNDAI AVANTE
Excess Sec II :\$5 | D.O.A: 15/01/18 | Place of Accident: BROADELL TOWARDS SERANGOON
Is driver the owner? (YES NO) | Nature of Accident:
If NO, Driver Name / Age: TAN ROCK HOAG | OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No.: 97121990 (V/L: YES / NO) | Insured Liability: % | Final ? Yes / No

XD 9476X → → → →

 INSR: WSP: V4x Auto | Tel: | Liability: | RMKS:
 INSR: WSP: | Tel: | Liability: | RMKS:
 INSR: WSP: | Tel: | Liability: | RMKS:
 INSR: WSP: | Tel: | Liability: | RMKS:

Date/Time	STAGE	DATE / PIC
03/02/18 (Zaini)	Non-Reporting lr (1st): Non-Reporting lr (2nd): Non-Reporting lr (Final): Notification lr (if non-pickup): Call OI: After call lr to OI:	
23/02/18 @ 4.00pm	Documentation Check List: Handler Typist Notification lr (if non-pickup): After call lr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form: Post-Repair Photos: Others:	
06/03/2018		
11/3/18		

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>415</u>	\$5 <u>3,850</u>	(<u>3</u> days) Reduction: <u>60</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>50</u> - (Agreed / Assessed) BOLA S/N No. : <u>19</u>		
Repair Cost:	\$5		
Loss of Rental (LOR):	\$5 (<u>1</u> days)		
Loss of Use (LOU):	\$5 (<u>5</u> x days)		
Loss of Income (LOI):	\$5 (<u>5</u> x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> (Tick only one)			
GIA/LTA Search:	\$5		
Medical:	\$5		
Disbursement:	\$5 (e.g. Tow/ Independent)		
Legal Cost:	\$5		
Total:	\$5	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5	Name 1:	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

COPY SENT 5/8/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP
3) Survey fee: 1250 72W



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18001903/Uks3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 31-01-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJK 8224S	Veh. Inspected	XD 9476X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/01/2018	Inspection Date	05/02/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7586H
Vehicle Details	
Vehicle No.:	XD9476X
Vehicle to be Exported:	No
Intended De-registration Date:	05 Feb 2018
Vehicle Make:	SCANIA
Vehicle Model:	P360LA4X2MSZ
Primary Colour:	Multi-Colour
Manufacturing Year:	2014
Engine No.:	6805020
Chassis No.:	YS2P4X20005345398
Maximum Power Output:	-
Open Market Value:	\$102,579.00
Original Registration Date:	11 Sep 2014
First Registration Date:	11 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$5,129.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Sep 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$52,390.00
COE Rebate Amount:	\$34,562.00
Total Rebate Amount:	\$34,562.00

The information contained herein is correct as at 05 Feb 2018

OK

M/S AIG ASIA PACIFIC INS PTE LTD
 CHARTIS BUILDING
 78 SHENTON WAY #08-16
 SINGAPORE 079120

Vfix Auto Service Pte Ltd
 60 Kaki Bukit Ave 6
 Ark@KB Singapore 417892
 Email: vfixauto@gmail.com
 Tel: 64489268 Fax: 64452368

*Not Affected
 new
 el/v18
 take photo after repair
 1/5 → 3850
 3dy.*

ESTIMATE
 DATE : 30/01/2018
 ACC DATE : 15/01/2018
 REF NO. : VFIX-TP20180408
 POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO XD9476X SCANIA

DESCRIPTION	AMOUNT S\$
1 2 FRONT BUMPER R+L <i>20/moqad</i>	1,049.00 2,098.00 ✓
2 2 FRONT BUMPER END GARNISH R+L <i>cut</i>	172.00 344.00 ✓
3 1 SIDE LAMP LH <i>340</i>	345.20 ✓
4 1 EXHUAST MUFFLER COVER <i>2</i>	988.20 ✓
5 1 FUEL TANK <i>2</i>	1,850.00 ✓
6 1 ADBLUE TANK <i>gran 6 780</i>	985.00 ✓
7 1 FUEL TANK BELT <i>2m</i>	322.00 ✓
8 1 FUEL TANK BELT RUBBER <i>new</i>	98.00 ✓
9 1 LADDER STEP <i>2</i>	650.00 ✓
	<u>7,680.40</u>
	LESS 10%
	<u>6,912.36</u>

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten,repair member replace new parts refit align into position with all necessary components attachmets	<i>600</i>	1,200.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	<i>400</i>	1,000.00
3 To remove,replace fuel tank with necessary components/attachments	<i>60</i>	200.00
4 To remove,replace adblue tank with necessary components/attachments	<i>100</i>	200.00
		<u>\$ 2,600.00</u>

GRAND TOTAL : \$ 9,512.36

SINGAPORE DOLLARS : NINE THOUSAND FIVE HUNDRED TWENTY & CENTS
 THIRTY SIX ONLY

4832.98

Vfix Auto Service Pte Ltd



I hereby acknowledge the Reparer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature: _____
 Date: _____

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 1 August 2019 2:37 PM
To: Syed-Yusoff, Saliha
Subject: RE: [2nd reminder] 7536295999SG-003

Dear Ms. Saliha,

Kindly be informed that the Third party workshop repairer informed that the claimant is yet to send in the vehicle for repair.

In view of the above, we will proceed to temporary close the file and submit WP to your office.

If there is any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: Wednesday, 31 July 2019 10:02 AM
To: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: [2nd reminder] 7536295999SG-003

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

Thank You.

Best Regards,
Asher Sng | Case Handler

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jan 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	ORANGE LEASING PTE LTD , Co. Reg. No.: 201622533W								
Main Claimant:	KL LOGISTICS PTE LTD , Co. Reg. No.: 201307586H								
Vehicle Reg. No.:	XD9476X	Date of Loss:	15/01/2018 00:00 - :59 [40 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7536295999SG	Policy/Cover Note No.:	0999994948 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJK8224S	Policy No. (Claimant):	DMCSHQ17000052						
		Excess:							
Repairer:	Vfix Auto Service Pte Ltd - Kaki Bukit (HQ) 60 KAKI BUKIT AVE 6, ARK@KB, 417892 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/02/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD9476X (7536295999SG)
[SJK8224S]

TP

KL LOGISTICS PTE LTD
Jan 15 2018 12:00AM
[ORANGE LEASING PTE LTD]
Vfix Auto Service Pte Ltd - Kaki Bukit

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Video												1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print			
1	01/02/18 17:27	Video - Accident from SKU5331X						Load MP4					
Assessment Reports												1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print			
1	01/02/18 11:09	Accident Statement <small>From: SC - Reg. No: SJK8224S, Claimant: ORANGE LEASING PTE LTD</small>						Load HTM					
Photos/Images												3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print			
1	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
2	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
3	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
4	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
5	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
6	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
7	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
8	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
9	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
10	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
11	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
12	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
13	05/02/18 18:33	General View						Load JPG		<input checked="" type="checkbox"/>			
14	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
15	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
16	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
17	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
18	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
19	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
20	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
21	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
22	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
23	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
24	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
25	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
26	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
27	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
28	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
29	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			
30	05/02/18 18:34	General View						Load JPG		<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (5G)	Thumbnail	Print
31	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
32	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
33	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
34	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
35	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
36	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
37	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
38	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
39	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
40	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
41	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
42	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
43	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
44	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
45	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
46	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
47	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
48	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
49	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
50	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
51	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
52	05/02/18 18:34	Chassis Number		Load JPG <input checked="" type="checkbox"/>
53	05/02/18 18:34	General View		Load JPG <input checked="" type="checkbox"/>
54	05/02/18 18:34	Odometer Reading		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 15:15	NOTIFICATION FROM WORKSHOP		Load PDF
2	31/01/18 17:18	TP GIA REPORT		Load PDF
3	07/02/18 10:18	TP ESTIMATE- MARKED		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18001903/UKB3Q2
Date: 06/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994948
Claimant Vehicle No : XD9476X	Insured Vehicle No :	SJK8224S
Date of Loss: 15/01/2018	Nature of Claim: TP	Claim No: 7536295999SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD9476X	Engine No:	6805020
Make & Model:	SCANIA P360LA, 12.7 D 4X2 MSZ (M)	Chassis No:	YS2P4X20005345398
Reg. Date:	11/09/2014 (Man. Year: 2014)	Odometer:	179617 km
Colour:	White		
Engine Capacity:	12742 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,912.36	3,772.98	3,139.38	45.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,060.00	1,540.00	59.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,512.36	4,832.98	4,679.38	49.19
Approved Total (Overridden) (S\$)		3,850.00		
	(S\$)	9,512.36	3,850.00	5,662.36
	+ GST 7.00/7.00% (S\$)	665.87	269.50	396.37
	Nett Amount (S\$)	10,178.23	4,119.50	6,058.73
	Global Sum Settlement (S\$)		0.00	

INSPECTION

Date of Assignment:	05/02/2018	
Date Inspected:	05/02/2018 Inspected At:	Vfix Auto Service Pte Ltd - Kaki Bukit (HQ) 60 KAKI BUKIT AVE 6, ARK@KB Singapore 417892
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER R+L	Dented / Warped	2,098.00 FL	*2,098.00 FL
2	2		*FRONT BUMPER END GARNISH R+L	Cut	344.00 FL	*344.00 FL
3	1		*SIDE LAMP LH	Broken	345.20 FL	*345.20 FL
4	1		*EXHAUST MUFFLER COVER	Repair	988.20 FL	*- FL
5	1		*FUEL TANK	Repair	1,850.00 FL	*- FL
6	1		*ADBLUE TANK	Grazed	985.00 FL	*985.00 FL
7	1		*FUEL TANK BELT	Twisted	322.00 FL	*322.00 FL
8	1		*FUEL TANK BELT RUBBER	Necessary	98.00 FL	*98.00 FL
9	1		*LADDER STEP	Repair	650.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,680.40	4,192.20
- List Item Discount on L Items 10.00/10.00% (S\$)	768.04	419.22
Total Parts (S\$)	6,912.36	3,772.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN ,REPAIR MEMBER REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	1,200.00	600.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	400.00
3	TO REMOVE,REPLACE FUEL TANK WITH NECESSARY COMPONENTS /ATTACHMENTS	New	200.00	60.00
4	TO REMOVE,REPLACE ADBLUE TANK WITH NECESSARY COMPONENTS /ATTACHMENTS	New	200.00	0.00
Gross Labour Cost (S\$)			2,600.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >