

15/5/2010

INS. CASE OWNER:

Bernard

CC6 /AIG1800

1934, U h6302

LKK:

IDAC:

Surveyor:

MARLUS

DOI:

31/1/18


Date / Time:

21/1/18

Registered in Merimen:

21/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEA 8399L

Claim No.:

4224442354

Name of Insured:

Sheila KWOK Wai Yee

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$S

D.O.A:

12/1/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLS 7527J

INSRS:
WSP:
Tel:
Liability:
RMKS:

persons

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
6/2/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
23/04/18	Notification ltr (if non-pickup):	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☒
	Release Voucher:	☐
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

6/2/18
VIC
07102118 @ 5:30PM
NO OI LIA. SENT WIT 21 LETTER.
FINALISED.
W/ KSHR. 9 POINT TO OI. OI COMPLETED
ACCIDENT DETAILS. ONLY SMALL TOUCH, NO
DAMAGE TO TP VEHICLE. OI WILL DO
REPORT SOON.
23/04/18
NO OI GIA REPORT IN YET.
OI GIA REPORT IN.
OI REPORTED NO INCIDENT.
23/04/18
TP LOU IN BY EMAIL.
EMAIL LIABILITY UNCLEAR
03/05/18
TP VIDEO IN. V DRIVE VIC/SLS7527S
FORWARDED TP VIDEO TO AIG CBB
TO CALL OI.
14/06/18
SUBMIT WP REPORT PLUS HM REPORT
NO CONTRIBUTION

PRELIMINARY ADVICE	Date/Time:	Sent By:
	1/2/2018	LSP
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: PIP	\$S 901.50	(2 days) Reduction: 67 %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	\$S —	
Loss of Rental (LOR):	\$S —	(days)
Loss of Use (LOU):	\$S —	(\$ x days)
Loss of Income (LOI):	\$S —	(\$ x days)
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]
GIA/LTA Search	\$S —	
Medical:	\$S —	
Disbursement:	\$S —	(e.g. Tow/ Independent)
Legal Cost	\$S —	
Total:	\$S	Global Sum \$S:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S —	Name 1: —
Payee 2: (Strike if N.A.)	\$S —	Name 2: —
Payee 3: (Strike if N.A.)	\$S —	Name 3: —

NO SETTLEMENT
WP REPORT / TP PEG CANDIDATE
COPY SENT
16/4/2019

REF: ALH

ASSIGNMENT

From: Date: 31.01.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL5 7527J

at Workshop mis: Pegasus

of: 51 Dehu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GL / PR Seen: Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SL5 7527J (Regn) 10 17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Toyota prius Hybrid 1798

Colour: Silver A.C. Insured / Std / NI / NA

Sp. Reading: 36103 T. Radio: Insured / Std / NI / NA

Eng No:

C.No: JTDKB3FU00357173

Genl Cond: Good / Fair / Poor / Burnt

Steering: Interfer / Jammed / Leaked / Burnt or

Brake: Interfer / Jammed / Leaked / Burnt or

Mod: Nil / Std A/Rim or

Tyre Size: F: 205 / 60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or westlake

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 17/1/18

D.O.I: 31/1/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to:

☐: Prel. Report

Days Of Repair:

1:

☐: Final Report

Resurvey No. of Trip:

Date/Time File Return to:

Survey Fee:

2:

Add Fee:

☐ Site Insp: \$

Transporter:

☐ Interfer: \$

Fuel 3+50 \$

☐ Techn. Insp: \$

Photo:

☐ Weighing: \$

Others:

Report Format:

Lump Sum / I.B. / H.S.

P/LP \$901.50

CRAB: \$1,867.10 / 67%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18001934/Uhb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 31-01-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 8399L	Veh. Inspected	SLS 7527J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/01/2018	Inspection Date	31/01/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : <i>LLK marks.</i> Tel : Fax : <i>31-01. 1666.</i>
---	---

Quotation No : QO18/01-1220	Quotation Date : 25/01/2018	Terms : 30 DAYS
Vehicle No : SLS7527J	Chassis No : JTDKB3FU003571775	Third Party Insurer :
Model : PRIUS	Date of Accident :	
Remarks : TP INSURER : AIG , INSURED'S VEHICLE NO : SKA8399L , DATE OF ACCIDENT : 17-01-2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER UPPER <i>✓</i>	1	423.9000 <i>✓</i>	423.90
2	REAR BUMPER LOWER <i>de</i>	1	552.0000 <i>✓</i>	552.00
3	REAR BUMPER TOW COVER <i>11</i>	1	55.0000 <i>X</i>	55.00
4	REAR BUMPER REINFORCEMENT <i>✓</i>	1	318.3000 <i>✓</i>	318.30
5	REAR BUMPER ABSORBER FOAM <i>✓</i>	1	<i>X</i>	.
6	REAR BUMPER CLIPS <i>✓</i>	10	5.0000 <i>✓</i>	50.00 <i>✓</i>
7	REAR BUMPER SIDE RETAINER <i>11</i>	2	112.7000 <i>X</i>	225.40 <i>1624.6</i>
8	LESS 25% ITEM (1-7)	1	-406.0000	-406.00 <i>1218.40</i>
9	REAR BUMPER PARKING SENSOR	1 <i>sn</i>	280.0000 <i>✓</i>	280.00
10	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000 <i>50</i>	120.00
11	PANEL BEATING, KNOCKING AND STRAIGHTEN THE REAR END PANEL PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	550.0000 <i>200</i>	550.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	600.0000 <i>200</i>	600.00

*NOT Affect
Luk*

take photo after repair

2 day.

31/1/18

7/1/18 901.50

P-602

481.50

901.50

Sub Total
GST(7.00%)
Total (SGD)

2,768.00 *45*
193.80
2,962.40

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/01-1220	Quotation Date : 25/01/2018	Terms : 30 DAYS
Vehicle No : SLS7527J	Chassis No : JTDKB3FU003571775	Third Party Insurer :
Model : PRIUS	Date of Accident :	
Remarks : TP INSURER : AIG , INSURED'S VEHICLE NO : SKA8399L , DATE OF ACCIDENT : 17-01-2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER UPPER	1	423.9000	423.90
2	REAR BUMPER LOWER	1	552.0000	552.00
3	REAR BUMPER TOW COVER	1	55.0000	55.00
4	REAR BUMPER REINFORCEMENT	1	318.3000	318.30
5	REAR BUMPER ABSORBER FOAM	1		
6	REAR BUMPER CLIPS	10	5.0000	50.00
7	REAR BUMPER SIDE RETAINER	2	112.7000	225.40
8	LESS 25% ITEM (1-7)	1	406.0000	-406.00
9	REAR BUMPER PARKING SENSOR	1	280.0000	280.00
10	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00
11	PANEL BEATING, KNOCKING AND STRAIGHTEN THE REAR END PANEL PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	550.0000	550.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	600.0000	600.00

*not added
back*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*take photo after repair
2 day.
31/1/18
P/P \$1*

Sub Total	2,768.60
GST(7.00%)	193.80
Total (SGD)	2,962.40

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216
 Date:

Vic (LKKAuto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Friday, 14 June, 2019 3:10 PM
To: Vic (LKKAuto)
Cc: Admin A
Subject: RE: Your Ref: 4222949323SG_ACCIDENT INVOLVING VEHICLES SKA 8399L (OI) AND SLS 7527J (TP) ON 17/01/2018 LKK REF CC6/AIG18001934/Uhb3

Dear Vic,

Please submit report and billing for our closure.

Thanks.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Ler, Bernard-JQ
Sent: 25 April 2019 11:42
To: 'Vic (LKKAuto)' <vicalpeh@lkkauto.com>
Cc: 'Bryan Ang (LKKAuto)' <bryanang@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'Naz (LKKAuto)' <Naz@lkkauto.com>
Subject: RE: Your Ref: 4222949323SG_ACCIDENT INVOLVING VEHICLES SKA 8399L (OI) AND SLS 7527J (TP) ON 17/01/2018 LKK REF CC6/AIG18001934/Uhb3
Importance: High

Dear Vic,

Kindly advise on the below urgently.

Thanks.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Ler, Bernard-JQ

Sent: 18 April 2019 15:10

To: 'Vic (LKKAUTO)' <vicalpeh@lkkauto.com>

Cc: 'Bryan Ang (LKKAUTO)' <bryanang@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'Naz (LKKAUTO)' <Naz@lkkauto.com>

Subject: RE: Your Ref: 4222949323SG_ACCIDENT INVOLVING VEHICLES SKA 8399L (OI) AND SLS 7527J (TP) ON 17/01/2018 LKK REF CC6/AIG18001934/Uhb3

Dear Vic,

Kindly advise whether insured has been cleared. Also, please assist to upload survey report into Merimen for our perusal.

Thanks.

Best Regards,

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Ler, Bernard-JQ

Sent: 15 April 2019 09:37

To: Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Cc: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Naz (LKKAUTO) <Naz@lkkauto.com>

Subject: RE: Your Ref: 4222949323SG_ACCIDENT INVOLVING VEHICLES SKA 8399L (OI) AND SLS 7527J (TP) ON 17/01/2018 LKK REF CC6/AIG18001934/Uhb3

Dear Vic,

I will write to them on this matter.

Thanks.

Best Regards,

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18001934/Uhb3

06TH Feb 2018

Sheila Kwok Wai Yee
2 Fifth Avenue #02-11
SINGAPORE 268800

Dear Sirs,

**ACCIDENT INVOLVING SKA 8399L AND SLS 7527J ON 17.01.2018 ALONG AT KPE
TOWARDS SIMS AVENUE**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Jan 2018 Edit Reg		31 Jan 2018 00:00 Edit Adj Rpt	S\$901.50 Edit Estimates	S\$901.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Sheila Kwok Wai Yee , ID: S7248711G									
Main Claimant: GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G									
Vehicle Reg. No.:	SLS7527J	Date of Loss:	17/01/2018 09:00 - :59 [3 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4222949323SG	Policy/Cover Note No.:	2100248610-07 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKA8399L	Policy No. (Claimant):							
		Excess:							
Repairer: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: Great American Insurance Company (HQ) - Tel: 6804 6047									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/02/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (01/02/2018): No OI GIA Report - AIG_SG (01/02/2018): Request for TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS7527J (4222949323SG)
[SKA8399L]**

TP

GRAB RENTALS PTE LTD

Jan 17 2018 9:05AM

[Sheila Kwok Wai Yee]

Pegasus Engineering & Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video				
			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/05/18 12:00	Video - Accident	 Load MP4	
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	23/04/18 14:05	Accident Statement From: SC - Reg. No: SKA8399L, Claimant: SHEILA KWOK WAI YEE	 Load HTM	
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 20:11	Odometer Reading	 Load JPG	☒
2	31/01/18 20:11	General View	 Load JPG	☒
3	31/01/18 20:11	Chassis Number	 Load JPG	☒
4	31/01/18 20:11	General View	 Load JPG	☒
5	31/01/18 20:11	General View	 Load JPG	☒
6	31/01/18 20:11	General View	 Load JPG	☒
7	31/01/18 20:11	General View	 Load JPG	☒
8	31/01/18 20:11	General View	 Load JPG	☒
9	31/01/18 20:11	General View	 Load JPG	☒
10	31/01/18 20:11	General View	 Load JPG	☒
11	31/01/18 20:11	General View	 Load JPG	☒
12	31/01/18 20:11	General View	 Load JPG	☒
13	31/01/18 20:11	General View	 Load JPG	☒
14	31/01/18 20:11	General View	 Load JPG	☒
15	31/01/18 20:11	General View	 Load JPG	☒
16	31/01/18 20:11	General View	 Load JPG	☒
17	31/01/18 20:11	General View	 Load JPG	☒
18	31/01/18 20:11	General View	 Load JPG	☒
19	06/03/18 19:38	Reinspection Photo	 Load JPG	☒
20	06/03/18 19:38	Reinspection Photo	 Load JPG	☒
21	06/03/18 19:38	Reinspection Photo	 Load JPG	☒
Documentation				
			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 16:22	TP ESTIMATE- MARKED	 Load PDF	
2	01/02/18 16:22	TP GIA REPORT	 Load PDF	
3	06/02/18 11:24	Non reporting letter	 Load PDF	
4	23/04/18 15:25	OI DRIVING LICENCE STATUS	 Load PDF	
5	15/04/19 09:18	EMAIL FROM TP	 Load PDF	
6	25/06/19 16:24	INVESTIGATION REPORT	 Load PDF	

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
7	25/06/19 16:35	EMAIL	 Load PDF	
8	25/06/19 16:46	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18001934/UHB3S2
Date: 25/06/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100248610-07
Claimant Vehicle No :	SLS7527J	Insured Vehicle No :	SKA8399L
Date of Loss:	17/01/2018	Nature of Claim:	TP
		Claim No:	4222949323SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7527J	Engine No:	2ZRS092192
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU003571775
Reg. Date:	03/10/2017 (Man. Year: 2017)	Odometer:	36103 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,498.45	451.50	1,046.95	69.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	450.00	820.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,768.45	901.50	1,866.95	67.44
+ GST 7.00/7.00% (S\$)	193.79	63.11	130.68	67.43
Nett Amount (S\$)	2,962.24	964.61	1,997.63	67.44

INSPECTION

Date of Assignment:	31/01/2018	
Date Inspected:	31/01/2018	Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Repair	423.90 FL	*- FL
2	1		*REAR BUMPER LOWER	Deformed	552.00 FL	*552.00 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	55.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	318.30 FL	*- FL
5	1		*REAR BUMPER ABSORBER FOAM (NPA)	Not fitted	0.00 FL	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	225.40 FL	*- FL
8	1		*REAR BUMPER PARKING SENSOR	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,904.60	602.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	406.15	150.50
Total Parts (\$\$)	1,498.45	451.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE REAR END PANEL PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	550.00	200.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	200.00
Gross Labour Cost (\$\$)			1,270.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >