

Surveyor

## ASSIGNMENT (Office)

From (Person): Kelvyn Ngian of GAI Date/Time: 31/1/18 @ 3.29pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 9111C Insured: SJA 1019Sat Workshop m/s: United Sq Automobile Tel: 9007 7556of 53 Ubi Ave 1 #01-56

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 25/01/2018

(Client's Record) \_\_\_\_\_ 01/02/2018

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: \_\_\_\_\_Date/Time: 4.19pm @ 31/1/18 Person Contacted: Sean Vehicle: IN/OUT

Date/Time	Action/Instruction ( X ) Estimate	
	SKD 9111C - NA/EQ11800/634/r3	D.O.A.: 25/01/2018
	SJA 1019S - NA/EQ11800/634/r3	D.O.A.: 25/01/2018
	Dismantle Part: 07.02.2018	

REF: GAI

ASSIGNMENT

Report Date: 1/2/18  
 Estimated Cost:  
 CD: ☒ NS / ☐ PR / RES / ☐ CD / RES / EVA / INV / MY  
 To inspect Vehicle ID: SKD 911C  
 At Workshop: United SG Automobile  
 at: 53 Ubi Ave # 01-56  
 Insured:  
 Policy No:  
 Claim No:  
 Sum Insured: Excess:  
 Clients Record:  
 Make of Ven:



Policy Condition:  
 Remark: The veh had commenced its repair at the time of inspection.  
 Body or Market Value:  
 QAO Accident Report: Consistent? Yes or No  
 Q14 / PR Seen: Consistent? Yes or No  
 Est. Repairs: days Res: Yes or No  
 Sum Sur: \$ B Val: Yes or No  
 CA / REV / REP / 24 HRS <sup>1up</sup>  
 Date: Person Contacted: Vehicle IN / OUT

Ref: SKD 911C / Rep: <sup>No</sup> Available  
 Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover  
 Truck / Trailer:  
 Make: BMW 335 <sup>No</sup> Available  
 Color: Black  
 AC: Insured / Std / Nil / NA  
 AC: Insured / Std / Nil / NA  
 Eng No:  
 CNO: WBA WBT2220 P054981  
 Gen Con: ☒ Good / ☐ Bad / ☐ Poor / ☐ Burnt  
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt / ☐ ☐  
 Brakes: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt / ☐ ☐  
 Mod: Nil ☒ S Rim / ☐ STD A Rim / ☐ ☐  
 Tyre Size: R: 245 / 40 R18  
 R: 265 / 35 R18  
 BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / RIR / SUM /  
 TOYO / YOKO or: Bridgestone  
 Front: Rear:  
 R Bal: 2 mm R Bal: 2 --  
 L Bal: 2 mm L Bal: 2 --  
 D/OA: D/O: 1/2/2018  
 Survey held at: AS Above 3:32pm  
 Des of Damages: Frt / Rear / OS / NS / LIC / Roofed or:  
 Right Frt  
 The LIC / Chassis frame / Body Structure affected due to collision.

Date Time Action Instruction  
 1/2/2018 No Accident report Given

Range \$3900 - \$4900

3 Days Repair

RECEIVED 11 APR 2018

\* Co - M/LA Sbl Aff

*[Signature]*  
 9/10/2018

Date Time File Passed:  
 10.04.2018  
 : ☐ Prel. Report  
 : ☐ Final Report

Days Of Repair:  
 Resurvey No. of Trip:

Survey Fee:  
 Theft/Conceal:  
 Pull:  
 Drag:  
 Towing:  
 Other:

Add Fee:  
☐ Stamped \$  
☐ Night \$  
☐ Tech \$  
☐ Rep \$

Report Format: PRS  
 Vehicle Sur: 181

## Nivitha (LKK Auto)

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Wednesday, 31 January 2018 3:29 PM  
**To:** assignments  
**Subject:** FW: PRS Notice for SKD 9111C Insd -SJA1019S  
**Attachments:** 20180129162152317.pdf; SJA1019S.pdf; SKD9111C.pdf

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]  
**Sent:** Wednesday, 31 January 2018 3:23 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** FW: PRS Notice for SKD 9111C Insd -SJA1019S

Hi team

Please conduct TP survey

Thanks  
Kelvyna

---

**From:** Jerone [<mailto:jerone@chiaarul.com>]  
**Sent:** Tuesday, January 30, 2018 10:07 AM  
**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>  
**Subject:** RE: PRS Notice for SKD 9111C Insd -SJA1019S

O/Ref: SKD 9111C (Jr)  
Y/Ref: SJA1019S

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Kelvyna,

We thank you for your email below.

Kindly be informed that our client is not agreeable to your list of surveyors and we hereby propose the following:

<b><u>Name of Surveyor</u></b>	<b><u>Company</u></b>
Winson Goh	WG Appraisal Services

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

**Mr. Jerone Lee**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Ngian, Kelvyna [<mailto:Kelvyna.Ngian@sg.gaig.com>]

**Sent:** Monday, 29 January, 2018 6:47 PM

**To:** Jerone <[jerone@chiaarul.com](mailto:jerone@chiaarul.com)>

**Subject:** RE: PRS Notice for SKD 9111C Insd -SJA1019S

WITHOUT PREJUDICE

Dear Jerone

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Please confirm on SJE

Thanks

Kelvyna

---

**From:** Jerone [<mailto:jerone@chiaarul.com>]

**Sent:** Monday, January 29, 2018 4:28 PM

**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; Tan, Angela <[Angela.Tan@sg.gaig.com](mailto:Angela.Tan@sg.gaig.com)>

**Subject:** PRS Notice for SKD 9111C

O/Ref: SKD 9111C (Jr)

Y/Ref: TBA

Dear Madam,

We refer to the above mater.

Kindly find enclosed herewith the PRS Notice for your attention.

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

**Mr. Jerone Lee**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

**CHIA S ARUL LLC**  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S

Our Ref : SKD 9111C (Jr)

Your Ref : TBA

29 January 2018

**GREAT AMERICAN INSURANCE COMPANY**

**BY EMAIL ONLY**

3 Temasek Avenue  
#16 – 01, Centennial Tower  
Singapore 039190

Dear Sir,

**RE: PROPERTY DAMAGE CLAIM**  
**CLAIMANT : GOH JUN LIN**  
**ACCIDENT INVOLVING SKD 9111C & SJA 1019S ALONG CTE TOWARDS SLE**  
**BEFORE BRADDELL ROAD ON 25 JANUARY 2018**

1. We act for GOH JUN LIN, the owner of motor vehicle no. SKD 9111C, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SJA 1019S for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s United SG Automobile Pte Ltd at 53 Ubi Avenue 1 #01 – 56 Paya Ubi Industrial Park Singapore 408934 and kindly arrange with Sean Lian at 9007 7556.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to [jerone@chiaarul.com](mailto:jerone@chiaarul.com).

Yours faithfully,

**MR ARULCHELVAN S**  
cc: Client (By Email)

**Enquire Vehicle & Owner Information ( Vehicle No. SJA1019S As At 25 Jan 2018 / 23:10:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: SKD9111C

**Current Owner Details**

Owner ID Type: Singapore NRIC  
Owner ID: S1017635B  
Owner Name: CHOW KOK CHEE  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 115  
Registered Street Name: BISHAN STREET 12  
Registered Unit No.: # 06 - 76  
Registered Building Name: -  
Registered Postal Code: 570115

**Current Vehicle Details**

Vehicle No.: SJA1019S  
Make Description/Model: MERCEDES BENZ / E 200CGI  
Insurance Company Name: GREAT AMERICAN INSURANCE COMPANY



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWERS SINGAPORE 039190		Ref: CS3/GAI18001943/Wd3s2 Date: 16-04-2018 Code: GAI	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SJA 1019S	Veh. Inspected	SKD 9111C
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000561	Excess (\$)	0.00
Assign From	KELVYNA NGIAN	Assign Date	31/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	BMW 335	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBAWB72020P054981	Colour	BLACK
Odometer	211152 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/40R18	BRIDGESTONE	2 mm
L/H Front Tyre	245/40R18	BRIDGESTONE	2 mm
R/H Rear Tyre	265/35R18	BRIDGESTONE	2 mm
L/H Rear Tyre	265/35R18	BRIDGESTONE	2 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
<b>5. General Information</b>			
Accident Date	25/01/2018	Inspect Date / Time	01/02/2018 ( 03:32 PM )
Survey held at	UNITED SG AUTOMOBILE - 53 UBI AVE 1 #01-56		
Repairer	-		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900- \$4,900			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/GAI18001943/Wd3s2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K. LAU CPT (RET)

BEng (Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.