

Survivor:

Meimien

GQ

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time: 31/1/18 @ 3:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GT1797P

Insured:

SKF 7995 X

at Workshop m/s

Ethicarz

Tel:

6381 4404

of

56 Loyang way # 04-04

Policy No:

27728588QMY

Claim No:

548208

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

01/02/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

4:32pm @ 31/1/18

Person Contacted:

Sheila

Vehicle IN/OUT

Date/Time

Action/Instruction (→ Estimate

GT1797P-X

SKF7995-X

Sent poli thru meimien

Confirm Ls \$5900, 8 days (Red: 828,746.37, 83%)

1000

MSIG

ASSIGNMENT

Date 1/2/2018

671797P

03 Aug 2000

Estimated Cost:

CO (TP) WS / TP RES / CO RES / EVA / INV / MV

To inspect Vehicle No GT 1797P
at Workshop or at Ethicarz

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Vehicle:

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.

O	
N.S	O/S
O	

Balance Market Value:

DAC Accident Report Consistent? Yes or No

GIA / PF Seen Consistent? Yes or No

Est. Repair 8 days Res: Yes or No

Lum Sum 20 % G Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Type: M Car / M Cycle / Bus / Van / L / T / Taxi / Prime Mover

Truck / Trailer:

Make Nissan cabstar No 3153

Color orange A.C. Insured: Std. Nil / NA

So. Reading 554072 T. Rep: Insured: Std. Nil / NA

Eng No:

C.No. JN1SF 4F 23 E 0841377

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake In Order / Jammed / Leaked / Burnt or

Mod. O / S / Rim / STD A / Rim or

Tyre Size R 185 R14 (NEUTON)
R 155 R12 (condor)

BS / DUN / EXNOVA / GY / RS / LIZA / MIC / QHTSU / PIR / SUMI

TOYO / YOKO or

Front

R.Bal 5 mm R.Bal 5

L.Bal 5 mm L.Bal 5

D.O.A. D.O.I. 01-02-18

Survey held at W/S 12pm

Des. of Damages O / S / N.S / U.C / Roof top or

The U.C. / Chassis frame Body Structure affected due to collision

Date Time Action Instruction

RECEIVED 24 AUG 2018

Date Time File Passed?

☐ Prel. Report
☒ Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Date Time File Return?

Add Fee:

See Insur: \$
Insur: \$
Rep: \$
Att: \$

Transportation

Report Format:

tr

Lum Sum: 5900

350
10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001947/Grd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 31-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKF 7995X	Veh. Inspected	GT 1797P	
Policy No.	27728588QMY	Coverage (\$)	0.00	
Claim No.	548208	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	31/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018	Inspection Date		
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018		31 Jan 2018 15:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MOHD KHAIR BIN MOHD NOOR, ID: S1750853I			[Created by insurer]
Main Claimant:	M/S FRIENDLY PAINTS & TRADING, Co. Reg. No.: -			
Vehicle Reg. No.:	GT1797P	Date of Loss:	29/01/2018 00:00 - :59	
Claim Type:	TP / 548208	Policy/Cover Note No.:	27728588QMY	
Vehicle Reg. No. (Insured):	SKF7995X	Policy No. (Claimant):	Coverage: 03/07/2017 - 02/07/2018	
		Excess:		
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2018]			
Adj Asg. Remarks:	W/s wld like Mr Marcus Chua to survey the vehicle.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

View All	Search Tasks	Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 02 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKF7995X	Accident Date	: 29/01/2018
TP Vehicle No	: GT1797P	Assignment Date	: 31/01/2018
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 8.00
Date of Inspection	: 01/02/2018		
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,430.00 (Labour only)
Revised Amount	:S\$	2,230.00 (Labour only)
Check Items (Estimated)	:S\$	1,250.00
Total	:S\$	3,480.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 11:22
Date Of Accident	29/01/2018 18:00
Exact Location Of Accident	WOODLANDS AVE 2 TWDS WOODLANDS AVE 1 CROSS JCT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GT1797P
Insured/Policyholder	
Name Of Registered Owner	FRIENDLY PAINTS & TRADING
Co Reg No	53201001M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64498133

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-2.0 (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	VCB/P1573818
Cover Note Number	

Driver

Name of Driver	MUTHU ANBARASAN
Passport No/FIN	G7566834T
Date Of Birth	24/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	13/11/2013
Driving Experience	4 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82536344
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 10 KAKI BUKIT AVE 4, SINGAPORE 415874

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name WOODLANDS WEST NPC

Police Station Address ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKF7995X

Vehicle Make/Model/Colour CHEVROLET ORLANDO 1.8 AT ABS AIRBAG 2WD 5DR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBB2618X
Vehicle Make/Model/Colour MITSUBISHI FB70BB1SRDEA
Details Of Properties
Vehicle Category GOODS VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBF5180A
Vehicle Make/Model/Colour TOYOTA HIACE DX 3.0 M
Details Of Properties
Vehicle Category GOODS VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUTHU ANBARASAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? GT1797P
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Shah
NIC/TIN No: 8204257M

Sketch Plan #2

SKETCH PLAN

WOODLANDS AVE 2 TOWARDS ADMIRALTY RD

VEH A - GT 1797 P
 VEH B - SKF 795 X
 VEH C - LBB 2168 X
 VEH D - GEF 5780 A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Person's Signature
 Name: Staine
 SPS/PA No: 82045701

QSR/2010/01/01/01/01/01

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1001M
Vehicle Details	
Vehicle No.:	GT1797P
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	QD32125471
Chassis No.:	JN1SF4F23Z0841377
Maximum Power Output:	-
Open Market Value:	\$22,879.00
Original Registration Date:	03 Aug 2000
First Registration Date:	03 Aug 2000
Transfer Count:	2
Actual ARF Paid:	\$1,144.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$25,292.00
COE Rebate Amount:	\$12,646.00
Total Rebate Amount:	\$12,646.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Feb 2018

OK



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GT1797P

NISSAN LORRY

554072

JN1SF4F23Z0-841377

ATTN:					
QTY	DESCRIPTION - PARTS			PRICE	
1	FRONT WINDSCREEN MOULDING / MC.	10%	184.96	184.46	
1	FRONT PANEL / Bmc	20%	1883.6	1457.4	
1	FRONT PANEL TOP COVER / GRL.	10%	625.72	430.8	
1	FRONT PANEL SIDE MIRROR ASSY X NN		2.96		
1	FRONT GRILLE ASSY / CFA	20%	469.43	346.6	
1	FRONT GRILLE LOGO (NISSAN) / MC.	20%	75.6	45.3	
2	FRONT QUARTER PANEL X NN		428.9		
2	HEADLAMP LH+RH / CFA	10%	417.6 X 2PCS	701	
10	HEADLAMP CLIPS X NN		10X0PCS		
1	FRONT BUMPER / MC.	20%	841.7	675.4	
1	FRONT BUMPER GRILLE X		NN		
2	FRONT BUMPER FOG LAMP COVER LH+RH X		46.8 X 2PCS	46.80 X 2PCS	
2	FRONT BUMPER RETAINER X		NN	NN	
2	FRONT BUMPER BRACKET X	NN	704.6	NN	
1	FRONT BUMPER GRILLE X		NIL	NN	
1	INNER PANEL X		NIL	NN	
1	AIR CON CONDENSER X		517.9		
1	AIR CON FAN ASSY X		620		
1	RADIATOR X		756.20		
1	AIR CON BLOWER X		1987.4		
1	COOLING COIL X		2481.3		
1	TAILGATE / BT.	10%	1679.64	1399.7	
2	TAILGATE LOCK X		39.1 39.1		
2	TAILGATE HINGE X	NN	546 546		
1	TAILGATE CANOPY SET X		NIL		
2	TAILLAMP / CFA.	10%	178.4 X 2PCS	291	
2	TAILLAMP HOLDER / BT.	130-32 20%	65.16 X 2PCS	105	
2	SIDE GATE X NN		2600 X 2.		

3384.26
10 1/2 3045.83

1	END PANEL X Repair.	848.6.
2	CHASSIS MEMBER X Repair.	232.80.
1	TOW HOOK X NN	103.4.
1	REAR CARPLATE MOUNTING X / BT	208
	lower member / BT.	1135.8
1	SPARE TYRE BRACKET X NN	288.6
1	SPARE TYRE / cut.	646
		646

60
317.3
60(SN)

QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	FRONT WINDSCREEN SEALANT /	50 150
1	FRONT PANEL STICKER- NIPPON PAINT /	2 500
1	FRONT PANEL STICKER- NISSAN /	2 250
1	TAILGATE STICKER- 70KM /	10 80
1	TAILGATE STICKER- 5PAX /	10 80
1	TAILGATE STICKER- NIPPON PAINT /	2 500

NEC

80
20
80
80
250
310

QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT	600 1500
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT	500 1300
1	TO RUST PROOF ACCIDENT AFFECTED FRONT	60 150
1	TO RNR ACCIDENT AFFECTED REAR	400 2600
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED REAR	400 1500
1	TO RUST PROOF ACCIDENT AFFECTED REAR	NN X 150
1	TO RNR FRONT WINDSCREEN	100 250
1	TO RNR DASHBOARD ASSY	X 400
1	TO RNR AIR CON CONDENSER AND REFILL GAS	NN X 200
1	TO RNR RADIATOR	NN X 200
1	TO CHECK WATER SEEPAGE	X 120
1	TO ALIGN CHASSIS REAR	100 500

37126.17

2160

8 Days.

Unsprung Repair / After repair photos. 7386.62

Emo Giay - 82880282

01/2/18.

20% 5550

5900

SUPPLEMENTARY FOR
G171797P.

1.	END PANEL TOP BOARD.	X N N	2000
1.	REAR CARPLATE	BT	80
1.	REAR CARPLATE HOLDER.	X N N	400

Gino Giff

02/2/18

PARTS TOTAL = \$9420.87.

LESS 10% = (\$942.087).

PARTS TOTAL = \$8478.78.

SPECIAL NET = \$1,360.

LABOUR TOTAL = \$2,160.

REPAIR COST = \$11,998.78.

LESS 20% = (\$2,399.756).

REPAIR COST = \$9,600 L/S



Ethicarz Pte. Ltd, 56 Loyang Way, Singapore (508775) #04-04
 Loyang Enterprise Building, Email: johnong@ethicarz.sg
 Tel: 63844404, FAX: 63840444

VECHICLE NUM:	GT1797P
MAKE & MODEL:	NISSAN LORRY
MILEAGE:	554072
TYRE:	
CHASSIS NUM:	JN1SF4F23Z0-841377

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1	FRONT WINDSCREEN MOULDING / acc.	
1	FRONT PANEL / Bnc	
1	FRONT PANEL TOP COVER / GRL.	
1	FRONT PANEL SIDE MIRROR ASSY X	
1	FRONT GRILLE ASSY / CFA	
1	FRONT GRILLE LOGO (NISSAN) / acc.	
2	FRONT QUARTER PANEL X	
2	HEADLAMP LH+RH ?	
10	HEADLAMP CLIPS ?	10X0PCS
1	FRONT BUMPER / de.	
1	FRONT BUMPER GRILLE X	
2	FRONT BUMPER FOG LAMP COVER LH+RH X	
2	FRONT BUMPER RETAINER X	
2	FRONT BUMPER BRACKET X	
1	FRONT BUMPER GRILLE X	
1	INNER PANEL X	
1	AIR CON CONDENSER X	
1	AIR CON FAN ASSSY X	
1	RADIATOR X	
1	AIR CON BLOWER X	
1	COOLING COIL X	
1	TAILGATE / BT.	
2	TAILGATE LOCK X	
2	TAILGATE HINGE X	
1	TAILGATE CANOPY SET X	
2	TAILLAMP / CFA.	
2	TAILLAMP HOLDER / BT.	
2	SIDE GATE L	

1	END PANEL X Repair.	
2	CHASSIS MEMBER X Repair.	
1	TOW HOOK X	
1	REAR CARPLATE MOUNTING X	
	lower member / BT.	
1	SPARE TYRE BRACKET ?	
1	SPARE TYRE / Cut.	
QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	FRONT WINDSCREEN SEALANT /	50 150
1	FRONT PANEL STICKER- NIPPON PAINT /	? 500
1	FRONT PANEL STICKER- NISSAN /	? 250
1	TAILGATE STICKER- 70KM /	10 80
1	TAILGATE STICKER- 5PAX /	10 80
1	TAILGATE STICKER- NIPPON PAINT /	? 500
		1560
QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT	600. 1500
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT	500. 1300
1	TO RUST PROOF ACCIDENT AFFECTED FRONT	60. 150
1	TO RNR ACCIDENT AFFECTED REAR	400. 2600
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED REAR	400. 1500
1	TO RUST PROOF ACCIDENT AFFECTED REAR	X 150
1	TO RNR FRONT WINDSCREEN	100. 250
1	TO RNR DASHBOARD ASSY	X 400
1	TO RNR AIR CON CONDENSER AND REFILL GAS	X 200
1	TO RNR RADIATOR	X 200
1	TO CHECK WATER SEEPAGE	X 120
1	TO REALIGN CHASSIS REAR	100. 500
		10430

8 Days.

Unpenn Repair / After repair photo

Eno Qiao - 8288 0282

01/2/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal notice (if any) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018		31 Jan 2018 15:20 Edit Adj Rpt	S\$5,900.00 Edit Estimates	S\$5,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHD KHAIR BIN MOHD NOOR , ID: S1750853I		
Main Claimant:	M/S FRIENDLY PAINTS & TRADING , Co. Reg. No.: -		
Vehicle Reg. No.:	GT1797P	Date of Loss:	29/01/2018 00:00 - :59 [209 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 548208	Policy/Cover Note No.:	27728588QMY Coverage: 03/07/2017 - 02/07/2018
Vehicle Reg. No. (Insured):	SKF7995X	Policy No. (Claimant):	
		Excess:	
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 02/03/2018]		
Adj Asg. Remarks:	W/s wld like Mr Marcus Chua to survey the vehicle.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GT1797P (548208)**

[SKF7995X]

TP

M/S FRIENDLY PAINTS & TRADING

Jan 29 2018 12:00AM

[MOHD KHAIR BIN MOHD NOOR]

Ethicarz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Assessment Reports

1 per page



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:20	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 14:22	General View	Load JPG	
2	02/02/18 14:22	General View	Load JPG	
3	02/02/18 14:22	General View	Load JPG	
4	02/02/18 14:22	General View	Load JPG	
5	02/02/18 14:22	General View	Load JPG	
6	02/02/18 14:22	General View	Load JPG	
7	02/02/18 14:22	General View	Load JPG	
8	02/02/18 14:22	General View	Load JPG	
9	02/02/18 14:22	General View	Load JPG	
10	02/02/18 14:22	General View	Load JPG	
11	02/02/18 14:22	General View	Load JPG	
12	02/02/18 14:22	General View	Load JPG	
13	02/02/18 14:22	General View	Load JPG	
14	02/02/18 14:22	General View	Load JPG	
15	02/02/18 14:22	General View	Load JPG	
16	02/02/18 14:22	General View	Load JPG	
17	02/02/18 14:22	General View	Load JPG	
18	02/02/18 14:22	General View	Load JPG	
19	02/02/18 14:22	General View	Load JPG	
20	02/02/18 14:22	General View	Load JPG	
21	02/02/18 14:22	General View	Load JPG	
22	02/02/18 14:22	General View	Load JPG	
23	02/02/18 14:22	General View	Load JPG	
24	02/02/18 14:22	General View	Load JPG	
25	02/02/18 14:22	General View	Load JPG	
26	02/02/18 14:22	General View	Load JPG	
27	02/02/18 14:22	General View	Load JPG	
28	02/02/18 14:22	General View	Load JPG	
29	02/02/18 14:22	General View	Load JPG	
30	02/02/18 14:22	General View	Load JPG	
31	02/02/18 14:22	General View	Load JPG	
32	02/02/18 14:22	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	02/02/18 14:22	General View	 Load JPG	☒
34	02/02/18 14:22	General View	 Load JPG	☒
35	02/02/18 14:22	General View	 Load JPG	☒
36	02/02/18 14:22	General View	 Load JPG	☒
37	02/02/18 14:22	General View	 Load JPG	☒
38	02/02/18 14:22	General View	 Load JPG	☒
39	02/02/18 14:22	General View	 Load JPG	☒
40	02/02/18 14:22	General View	 Load JPG	☒
41	02/02/18 14:22	General View	 Load JPG	☒
42	02/02/18 14:22	General View	 Load JPG	☒
43	02/02/18 14:22	General View	 Load JPG	☒
44	02/02/18 14:22	General View	 Load JPG	☒
45	02/02/18 14:22	General View	 Load JPG	☒
46	02/02/18 14:22	General View	 Load JPG	☒
47	02/02/18 14:22	General View	 Load JPG	☒
48	02/02/18 14:22	General View	 Load JPG	☒
49	02/02/18 14:22	General View	 Load JPG	☒
50	02/02/18 14:22	General View	 Load JPG	☒
51	02/02/18 14:22	General View	 Load JPG	☒
52	02/02/18 14:22	General View	 Load JPG	☒
53	02/02/18 14:22	General View	 Load JPG	☒
54	02/02/18 14:22	General View	 Load JPG	☒
55	02/02/18 14:22	General View	 Load JPG	☒
56	02/02/18 14:22	General View	 Load JPG	☒
57	02/02/18 14:22	General View	 Load JPG	☒
58	02/02/18 14:22	General View	 Load JPG	☒
59	02/02/18 14:22	General View	 Load JPG	☒
60	02/02/18 14:22	General View	 Load JPG	☒
61	02/02/18 14:22	General View	 Load JPG	☒
62	02/02/18 14:22	General View	 Load JPG	☒
63	02/02/18 14:22	General View	 Load JPG	☒
64	02/02/18 14:22	General View	 Load JPG	☒
65	02/02/18 14:22	General View	 Load JPG	☒
66	02/02/18 14:22	General View	 Load JPG	☒
67	02/02/18 14:22	General View	 Load JPG	☒
68	02/02/18 14:22	General View	 Load JPG	☒
69	02/02/18 14:22	General View	 Load JPG	☒
70	02/02/18 14:22	General View	 Load JPG	☒
71	02/02/18 14:22	General View	 Load JPG	☒
72	02/02/18 14:22	General View	 Load JPG	☒
73	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
74	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
75	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
76	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
77	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
78	23/08/18 17:42	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	MSIG Insurance (Singapore) Pte, Ltd. (HQ)		Thumbnail Print
1	31/01/18 14:18	PRI Memo		Load PDF
2	31/01/18 14:18	Email frm TP - PRI		Load PDF
3	31/01/18 14:18	GT1797P GIA Rpt		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001947/GRD3S2

Date: 27/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27728588QMY

Claimant Vehicle No: GT1797P

Insured Vehicle No: SKF7995X

Date of Loss: 29/01/2018

Nature of Claim: TP

Claim No: 548208

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GT1797P

Make & Model: NISSAN CABSTAR, 3.2 D (M)

Engine No: QD32125471

Reg. Date: 03/08/2000 (Man. Year: 2000)

Chassis No: JN1SF4F23Z0841377

Colour: Orange

Odometer: 554072 km

Engine Capacity: 3153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185R14

Rear Tyre Size: 155R12

Front Left Side: Neuton 5 mm

Rear Left Side: Condor 5 mm

Front Right Side: Neuton 5 mm

Rear Right Side: Condor 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,256.17	5,236.62	23,019.55	81.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,870.00	2,160.00	6,710.00	75.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,126.17	7,396.62	29,729.55	80.08
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	37,126.17	5,900.00	31,226.17	84.11
+ GST 7.00/7.00% (S\$)	2,598.83	413.00	2,185.83	84.11
Nett Amount (S\$)	39,725.00	6,313.00	33,412.00	84.11

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 01/02/2018 Inspected At:

Ethicarz Pte Ltd (HQ)
56 LOYANG WAY #04-04 LOYANG ENTERPRISE
BUILDING
Singapore 508775

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Aug 2018)	
Parts:	N/A	NISSAN CABSTAR 3.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GT1797P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Buckled	1,883.60 F	*1,457.40 FL
2	1		*FRONT GRILLE ASSY	Cracked	469.43 F	*346.60 FL
3	1		*FRONT GRILLE LOGO (NISSAN)	Necessary	75.60 F	*45.30 FL
4	1		*FRONT BUMPER	Deformed	841.70 F	*675.40 FL
5	2		*TAILLAMP HOLDER	Bent	130.32 F	*105.00 FL
6	1		*FRONT WINDSCREEN MOULDING	Necessary	184.46 F	*184.46 FN
7	1		*FRONT PANEL TOP COVER	Scratched	625.72 F	*430.80 FN
8	1		*TAILGATE	Bent	1,679.64 F	*1,399.70 FN
9	2		*TAILLAMP	Cracked	356.80 F	*291.00 FN
10	1		*REAR CARPLATE MOUNTING	Bent	268.00 F	*60.00 FN
11	1		*LOWER MEMBER	Bent	1,135.80 F	*317.30 FN
12	1		*FRONT PANEL SIDE MIRROR ASSY	Not Necessary	296.00 FS	*-FS
13	2		*FRONT QUARTER PANEL	Not Necessary	428.90 FS	*-FS
14	10		*HEADLAMP CLIPS (NPA)	Not Necessary	0.00 FS	*-FS
15	1		*FRONT BUMPER GRILLE (NPA)	Not Necessary	0.00 FS	*-FS
16	2		*FRONT BUMPER FOG LAMP COVER LH & RH	Not Necessary	93.60 FS	*-FS
17	2		*FRONT BUMPER RETAINER (NPA)	Not Necessary	0.00 FS	*-FS
18	2		*FRONT BUMPER BRACKET	Not Necessary	704.60 FS	*-FS
19	1		*FRONT BUMPER GRILLE (NPA)	Not Necessary	0.00 FS	*-FS
20	1		*INNER PANEL (NPA)	Not Necessary	0.00 FS	*-FS
21	1		*AIR CON CONDENSER	Not Necessary	517.90 FS	*-FS
22	1		*AIR CON FAN ASSY	Not Necessary	620.00 FS	*-FS
23	1		*RADIATOR	Not Necessary	756.20 FS	*-FS
24	1		*AIR CON BLOWER	Not Necessary	1,987.40 FS	*-FS
25	1		*COOLING COIL	Not Necessary	2,421.30 FS	*-FS
26	2		*TAILGATE LOCK	Not Necessary	39.10 FS	*-FS
27	2		*TAILGATE HINGE	Not Necessary	546.00 FS	*-FS
28	1		*TAILGATE CANOPY SET (NPA)	Not Necessary	0.00 FS	*-FS
29	2		*SIDE GATE	Not Necessary	5,200.00 FS	*-FS
30	1		*END PANEL	Repair	848.60 FS	*-FS
31	2		*CHASSIS MEMBER	Repair	232.30 FS	*-FS
32	1		*TOW HOOK	Not Necessary	103.40 FS	*-FS
33	1		*SPARE TYRE BRACKET	Not Necessary	288.60 FS	*-FS
34	1		*SPARE TYRE	Cut	646.00 FS	*60.00 FS
35	1		*FRONT WINDSCREEN SEALANT	Necessary	150.00 FS	*50.00 FS
36	1		*FRONT PANEL STICKER-NIPPON PAINT	Necessary	500.00 FS	*80.00 FS
37	1		*FRONT PANEL STICKER-NISSAN	Necessary	250.00 FS	*20.00 FS
38	1		*TAIL GATE STICKER-70KM	Necessary	80.00 FS	*10.00 FS
39	1		*TAIL GATE STICKER-5PAX	Necessary	80.00 FS	*10.00 FS
40	1		*TAIL GATE STICKER-NIPPON PAINT	Necessary	500.00 FS	*80.00 FS
41	2		*HEADLAMP LH & RH	Cracked	835.20 F	*701.00 FN
42	1		*END PANEL TOP BOARD	Not Necessary	2,000.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR CARPLATE	Bent	80.00 FS	*40.00 FS
44	1		*REAR CARPLATE HOLDER	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett, L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$\$)					28,256.17	6,363.96
- List Item Discount on L Items 0.00/30.00% (\$\$)					0.00	788.91
- Nett Item Discount on N Items 0.00/10.00% (\$\$)					0.00	338.43
Total Parts (\$\$)					28,256.17	5,236.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT AFFECTED FRONT	New	1,500.00	600.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT	New	1,300.00	500.00
3	TO RUST PROOF ACCIDENT AFFECTED FRONT	New	150.00	60.00
4	TO RNR ACCIDENT AFFECTED REAR	New	2,600.00	400.00
5	TO PUTTY AND RESPRAY ACCIDENT AFFECTED REAR	New	1,500.00	400.00
6	TO RUST PROOF ACCIDENT AFFECTED REAR	New	150.00	-
7	TO RNR FRONT WINDSCREEN	New	250.00	100.00
8	TO RNR DASHBOARD ASSY	New	400.00	-
9	TO RNR AIR CON CONDENSER AND REFILL GAS	New	200.00	-
10	TO RNR RADIATOR	New	200.00	-
11	TO CHECK WATER SEEPAGE	New	120.00	-
12	TO REALIGN CHASSIS REAR	New	500.00	100.00
Gross Labour Cost (\$\$)			8,870.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >