

8/2/2018

ISSUED

ASS. REC. BY:

REF: CS/MSG/18001948/D 1039

Special Instructions:

Surveyor:
Menmen

MA

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSIG

Date/Time:

31/1/18 @ 1:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDM 2002R

Insured:

SKU 5623D

at Workshop m/s

Service @ Interview

Tel:

64814849

of

10, AMK Autopoint # 01-07/11/16

Policy No:

A28866680QMX

Claim No:

547630

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

21/01/2018

CA / REV / REP. / REV 24 HRS

lwp

01/02/2018

H.O.D. Endorsement:

Date/Time:

4:43pm @ 31/1/18

Person Contacted:

Kelvin

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDM 2002R-X

SKU 5623D-X

07/2/18 @

4:23pm revised to Katherine Wong via Menmen.

07/4/18 @

2:03pm confirmed with Kelvin LS \$4000, 4 days.

LRad \$5662.80, 54%.

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. _____

at Workshop this SERVICE @ DRIVER VIEW

of _____

Insured _____

Policy No. _____

Claims No. _____


Sum Insured _____ Excess _____

(Client's Record)

Make of Van _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value:		Consistent? : Yes or No
ODAC Accident Report:		Consistent? : Yes or No
GLA / PR Seen:		Consistent? : Yes or No
Est. Repairs:	4 days	Res.: Yes or No
Leak Summary:	3 Val	Yes or No

CA / REV / REP / 24 HRS

Date	Person Contacted
------	------------------

Vehicle IN / OUT

Form No. SDM/2002R Date APR 2017
 Type MC / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make BMW 3 528i Year 1997
 Colour WHITE AC Insured / Std / Nil / NA
 Sp. Reading 69978 T. Radio Insured / Std / Nil / NA
 Eng. No.
 C.No. WBA5A52050D285152
 Gen. Cond. G / Good / Fair / Poor / Burnt
 Steering G / Order / Jammed / Leaked / Burnt or
 Brake G / Order / Jammed / Leaked / Burnt or
 Model Nil / Rim / STD A/Rim or
 Tyre Size: F. 255/35/R20
 R. 285/30/R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or PIR
 Front: 8 Rear: 8
 R.Bal. mm L.Bal. mm R.Bal. mm L.Bal. mm
 D.O.A. 24/12/18 D.O.I. 1/2/2018
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

The UIC Channel frame Body Structure is made of aluminum.

Date / Time	Action / Instruction
-------------	----------------------

Ma, Check parts prices

RECEIVED 0-7 SEP 2018

CaseTime File Path: ☐ : Prel. Report

02/19/2014 Final Report

2002年12月15日

Days Of Repair:

Resurvey No. of Trip

2000

Fact & Format

Jump Sum / ☒ 18

Add Fee:

[illegible]

WFL-TP

4000



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001948/M1qd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 31-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKU 5623D	Veh. Inspected	SDM 2002R
Policy No.	A28866680QMX	Coverage (\$)	0.00
Claim No.	547630	Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	31/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/01/2018	Inspection Date	
Survey held at	SERVICE @ RIVERVIEW PTE LTD BLK 10 AMK AUTOPOINT ANG MO KIO INDUSTRIAL PARK 2A #04-11 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2018		31 Jan 2018 13:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN KOK PING, ID: S1762556Z, Tel: +6596551188, Email: NOEMAIL		
Main Claimant:	KANG SIEW TING, ID: S7114514Z		
Vehicle Reg. No.:	SDM2002R	Date of Loss:	24/01/2018 15:00 - :59
Claim Type:	TP / 547630	Policy/Cover Note No.:	A28866680QMX (Comprehensive) Coverage: 17/12/2017 - 16/12/2018
Vehicle Reg. No. (Insured):	SKU5623D	Policy No. (Claimant):	
		Excess:	
Repairer:	Service@riverview Pte Ltd (HQ) 10 ANG MO KIO AUTOPOINT #04-07/11/16 ANG MO KIO IND. PARK 2A, 568047 Singapore City - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2018]		
Driver/Custodian (Insured):	TAN KOK PING (51 / Male), NRIC: S1762556Z, Tel: +6596551188		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Kelvin <riverview@singnet.com.sg>
Sent: Friday, 7 September 2018 2:03 PM
To: Shiau Chan (LKKAuto)
Subject: Re: FINALISE OF VEHICLE SDM 2002R (DOA: 24/01/2018)

OK CONFIRM

From: [Shiau Chan \(LKKAuto\)](#)
Sent: Friday, September 07, 2018 1:15 PM
To: riverview@singnet.com.sg
Subject: FINALISE OF VEHICLE SDM 2002R (DOA: 24/01/2018)

Dear Kelvin,

WITHOUT PREJUDICE

Offer Lump Sum \$4,000.00 and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 02 Feb 2018

Preliminary Advice

Insured Vehicle No	: SKU5623D	Accident Date	: 24/01/2018
TP Vehicle No	: SDM2002R	Assignment Date	: 31/01/2018
Make	: BMW 530I	Est. Duration of Repair	: 4.00
Date of Inspection	: 01/02/2018		
Inspection At	: SERVICE@RIVERVIEW PTE LTD (HQ) 10 ANG MO KIO AUTOPOINT #04-07/11/16 ANG MO KIO IND. PARK 2A SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,662.80
Revised Amount	:S\$	6,174.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,174.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4514Z
Vehicle Details	
Vehicle No.:	SDM2002R
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	B.M.W.
Vehicle Model:	528I AT D/AB SR LED NAV
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	B5040708N20B20A
Chassis No.:	WBA5A52050D285152
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$53,614.00
Original Registration Date:	08 Apr 2014
First Registration Date:	08 Apr 2014
Transfer Count:	0
Actual ARF Paid:	\$63,506.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2024
PARF Rebate Amount:	\$47,629.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$82,900.00
COE Rebate Amount:	\$51,236.00
Total Rebate Amount:	\$98,865.00

The information contained herein is correct as at 02 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2018 16:47
Date Of Accident	24/01/2018 15:15
Exact Location Of Accident	OUTSIDE SERANGOON GARDEN OCBC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDM2002R
Insured/Policyholder	
Name Of Registered Owner	KANG SIEW TING
NRIC No	S7114514Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91913936
Alternative Phone No	OTHERS-91913936

Vehicle Particulars

Manufacturer	BMW
Model	528i AT D/AB SR LED NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN816785
Cover Note Number	08/04/2017 - 07/04/2018

Driver

Name of Driver	GOH HENG BUN
NRIC No	S7531491D
Date Of Birth	22/10/1975
Occupation	INDOOR
Date Of Driving Pass	02/05/1996
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91913936
Fax Number	
Contact Number	OTHERS-91913936
Email Address	RINAKST195@HOTMAIL.COM

Address	BLK 419 HOUGANG AVE 8 #03-936
Postcode	530419
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU5623D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Date of accident: 24.1.18 Time: 3:50pm Location: Outside Serangoon garden OCBC
 My Vehicle A: SDM2002R Vehicle B: SKL5623D Vehicle C: _____
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the 24.1.18 at about 3:50pm, vehicle SDM2002R was parked stationary in the carpark lot outside OCBC bank at serangoon garden. I was standing and waiting outside the bank beside my car. I saw vehicle SKL5623D trying to park in the empty lot behind my car. While trying to park his car, vehicle SKL5623D hit onto my stationary park car SDM2002R in the rear portion, causing damages to my car. There were no passengers in my car at the time of the accident.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Servic @ Riverview Pte Ltd

Email address: Riverview @ singnet.com.sg

& myself: Riverview @ singnet.com.sg

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre/Insurer's Signature
Name:
NRIC/FIN No.:



SERVICE @ RIVERVIEW PTE LTD

10, Ang Mo Kio Autopoint #04-11

Ang Mo Kio Industrial Park 2A

Singapore 568047

Tel : 6481 9810 / 64814849 Fax : 6481 6256

Email : riverview@singnet.com.sg

Buss.reg.No : 200910700K

Lump Sum repair

Can 20%

SDM 2002R

Part

BMW 528i

List Price \$

BMW Can 5%

Boot lid (repair/spray paint) 1470¹² X Repair

Boot lid BMW Badge \$188.60 ✓ new

Boot lid emblem 22 \$198.00 55 ✓ new

Rear Bumper ✓ def \$11435.00

Rear Bumper PDC sensor 25 x 4 2PC \$730 ✓ short

Rear Bumper Chrome LH \$161 ✓ 215

Rear Bumper Chrome centre \$181 ✓ new

Rear Bumper Chrome RH \$161 ✓ new

Rear Bumper reinforcement beam \$768 ✓ RT 696.00

Boot lid lock actuator \$520 ✓ bt

Boot lid remote sensor trim board ✓ 31575 dis X ~~102.45~~

Boot lid remote sensor x over \$275

Boot lid remote sensor dips (left) over X.

Boot lid lock actuator x over

Rear end panel centre trim \$249.45 dis 83.50

Rear end panel (repair/spray paint) x repair 920k

Not Authorised
4 weeks
US Run

2/2/18

Pg 1

SERVICE @ RIVERVIEW PTE LTD

10, Ang Mo Kio Autopoint #04-11

Ang Mo Kio Industrial Park 2A

Singapore 568047

Tel : 6481 9810 / 64814849 Fax : 6481 6256

Email : riverview@singnet.com.sg

Buss.reg.No : 200910700K

Lemp Sum repair
less 20%.

SDM2002R

BMW 528I

Labour charges

- 1) To Renew damaged parts & repair accident area. 700
600k
- 2) To spray paint Bootlid, Rear Bumper and ~~700~~
Rear end panel 700k
- 3) To check with BMW computer, clear fault code
and set to specifications. 700
180k
- 4) To carry out anti Rust treatment at 120k
the accident area 60k

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2018		31 Jan 2018 13:38 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN KOK PING , ID: S1762556Z, Tel: +6596551188, Email: NOEMAIL								
Main Claimant:	KANG SIEW TING , ID: S7114514Z								
Vehicle Reg. No.:	SDM2002R	Date of Loss:	24/01/2018 15:00 - :59 [45 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 547630	Policy/Cover Note No.:	A28866680QMX (Comprehensive) Coverage: 17/12/2017 - 16/12/2018						
Vehicle Reg. No. (Insured):	SKU5623D	Policy No. (Claimant):							
		Excess:							
Repairer:	Service@riverview Pte Ltd (HQ) 10 ANG MO KIO AUTOPOINT #04-07/11/16 ANG MO KIO IND. PARK 2A, 568047 Singapore City - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 02/03/2018]								
Driver/Custodian (Insured):	TAN KOK PING (51 / Male), NRIC: S1762556Z, Tel: +6596551188								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDM2002R (547630)
[SKU5623D]

TP

KANG SIEW TING

Jan 24 2018 3:00PM

[TAN KOK PING]

Service@riverview Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	31/01/18 10:01	Accident Statement From: SC - Reg. No: SKU5623D, Claimant: TAN KOK PING		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	02/02/18 16:23	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	07/09/18 14:23	General View		Load JPG ☒
2	07/09/18 14:23	General View		Load JPG ☒
3	07/09/18 14:23	General View		Load JPG ☒
4	07/09/18 14:23	General View		Load JPG ☒
5	07/09/18 14:23	General View		Load JPG ☒
6	07/09/18 14:23	General View		Load JPG ☒
7	07/09/18 14:23	General View		Load JPG ☒
8	07/09/18 14:23	General View		Load JPG ☒
9	07/09/18 14:23	General View		Load JPG ☒
10	07/09/18 14:23	General View		Load JPG ☒
11	07/09/18 14:23	General View		Load JPG ☒
12	07/09/18 14:23	General View		Load JPG ☒
13	07/09/18 14:23	General View		Load JPG ☒
14	07/09/18 14:23	General View		Load JPG ☒
15	07/09/18 14:23	Odometer Reading		Load JPG ☒
16	07/09/18 14:23	General View		Load JPG ☒
17	07/09/18 14:23	Chassis Number		Load JPG ☒
18	07/09/18 14:23	Reinspection Photo		Load JPG ☒
19	07/09/18 14:23	Reinspection Photo		Load JPG ☒
20	07/09/18 14:23	Reinspection Photo		Load JPG ☒
21	07/09/18 14:23	Reinspection Photo		Load JPG ☒
22	07/09/18 14:23	Reinspection Photo		Load JPG ☒
23	07/09/18 14:23	Reinspection Photo		Load JPG ☒
24	07/09/18 14:23	Reinspection Photo		Load JPG ☒
25	07/09/18 14:23	Reinspection Photo		Load JPG ☒
26	07/09/18 14:23	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	31/01/18 10:01	SDM2002R E FILE REPORT From: SC - Reg. No: SKU5623D, Claimant: TAN KOK PING		Load PDF
2	31/01/18 10:02	TP PRI Request		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001948/QD3Q2

Date: 10/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28866680QMX

Claimant Vehicle No: SDM2002R

Insured Vehicle No: SKU5623D

Date of Loss: 24/01/2018

Nature of Claim: TP

Claim No: 547630

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDM2002R

Make & Model: BMW 530i, 2.0 LED NAV (A)

Reg. Date: 08/04/2014 (Man. Year: 2013)

Colour: White

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B5040708N20B20A

Chassis No: WBA5A52050D285152

Odometer: 69978 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R20

Rear Tyre Size: 285/30 R20

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,072.80	3,792.19	4,280.61	53.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,540.00	780.00	33.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,392.80	5,332.19	5,060.61	48.69
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,392.80	4,000.00	6,392.80	61.51

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 01/02/2018 Inspected At:

Service@riverview Pte Ltd (HQ)
10 ANG MO KIO AUTOPOINT #04-
07/11/16 ANG MO KIO IND. PARK 2A
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2018)
Parts: 143	BMW 530i 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDM2002R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (REPAIR/SPRAY PAINT)	Repair	1,470.00 F	*- FL
2	1		*BOOTLID BMW BADGE	Necessary	88.60 F	*88.60 FL
3	1		*BOOTLID EMBLEM 22	Necessary	98.00 F	*55.00 FL
4	1		*REAR BUMPER	Deformed	1,435.00 F	*1,435.00 FL
5	4		*REAR BUMPER PDC SENSOR	Shorted (2 PCS ONLY)	1,460.00 F	*730.00 FL
6	1		*REAR BUMPER CHROME LH	Distorted	161.00 F	*161.00 FL
7	1		*REAR BUMPER CHROME CENTRE	Necessary	181.00 F	*181.00 FL
8	1		*REAR BUMPER CHROME RH	Necessary	161.00 F	*161.00 FL
9	1		*REAR BUMPER REINFORCEMENT BEAM	Bent	768.00 F	*696.00 FL
10	1		*BOOTLID LOCK ACTUATOR	Bent	520.00 F	*520.00 FL
11	1		*BOOTLID REMOVE SENSOR TRIM BOARD	Distorted	315.75 F	*102.45 FL
12	1		*BOOTLID REMOVE SENSOR	Serviceable	275.00 F	*- FL
13	1		*SET BOOTLID REMOVE SENSOR CLIPS (NPA)	Serviceable	0.00 F	*- FL
14	1		*BOOTLID LOCK ACTUATOR (NPA)	Serviceable	0.00 F	*- FL
15	1		*REAR END PANEL CENTRE TRIM	Distorted	219.45 F	*83.50 FL
16	1		*REAR END PANEL (REPAIR/SPRAY PAINT)	Repair	920.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,072.80	4,213.55
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	421.36

Total Parts (\$\$)	8,072.80	3,792.19
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & REPAIR ACCIDENT AREA	New	900.00	600.00
2	TO SPRAY PAINT BOOTLID ,REAR BUMPER AND REAR END PANEL	New	1,000.00	700.00
3	TO CHECK WITH BMW COMPUTER ,CLEAR FAULT CODE AND SET TO SPEAFICATIONS	New	300.00	180.00
4	TO CARRY OUT ANTI RUST TREATMENT OF THE ACCIDENT AREA	New	120.00	60.00
Gross Labour Cost (S\$)			2,320.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >