

Survivor:

Menmen

From (Person):

Taufik
Chong Boon Sen

ASSIGNMENT (Office)

of CTI

Date/Time: 3/1/18 @ 1:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBB 3359L

Insured:

SLR 344X

at Workshop m/s:

Southern Motor

Tel:

627 30369

of BIK 1006, Bkt Merah Leine 2 # 01-10

Policy No:

DMHCSN1752961700

Claim No:

SNM18D00576C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/12/2017

01/02/18

CA / REV / REP. / REV 24 HRS ¹wp

H.O.D. Endorsement:

Date/Time:

4:35pm @ 3/1/18

Person Contacted:

Ah Huat

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒) Estimate

FBB 3359L - NBA/GAI18000123/Y

D.O.A.: 14/12/2017

SLR 344X - NBA/GAI18000123/Y

D.O.A.: 14/12/2017

14/5/18

@ 4:53pm Ah Huat will arrange for resurvey.

12/7/18

@ 5:27pm Ah Huat said TP pay his own repair cost

Taufik

REP: CTI

cor 2026 Sep.

2007 March

ASSIGNMENT

From: Date: 05/02/18

Estimated Cost:

CD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: FBB 3359L

at Worked on: Southern Motor

of Bk1006, Bkf Meruh Lane 2 # 01-10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

Make of Veh:

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market Value:

IDAQ Accident Report Consistent? : Yes or No

G/A / PR / Seen Consistent? : Yes or No

Est. Repairs days Res: Yes or No

Sum Sur: \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{wp}

Date: Person Contacted:

Vehicle IN / OUT

Page: 1 Type: M/Gar / M/Car / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Transport

Make:

Honda CR400

CC: 399

Colour:

Black

4-Dr

Insured / Std / NI / NA

So Reading:

-

T Read: Insured / Std / NI / NA

Eng No:

C/N:

JH2NC39926M20049

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt /

Brake: In order / Jammed / Leaked / Burnt /

Mod: NI / R / STD A / Rim /

Tyre Size:

R

120 / 60 R17

R

160 / 60 R17

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU /

TOYO / YOKO /

Front:

Rear:

R/Bal:

5

R/Bal:

5

L/Bal:

L/Bal:

D/OA:

D/OA:

5/2/18 @ 1400

Surveyed at:

Southern Motor

Des. of Damages:

Front

Rear

OIS

NS

UIC

Roof top

or

The UIC / Chassis frame / Body Structure affected due to

Date Time Action Instruction

Battery weak

RECEIVED 13 JUL 2018

Date Time File Received

☐ Prelim. Report
☐ Final Report

Days Of Repair:

6

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

Food & Accommodation:

Other:

Total:

Remarks:

Signature:

Date:

Report Format:

Letter Sum (B/E):

Add Fee:

☐ Site Insp: \$
☐ Machine: \$
☐ Tech. Insp: \$
☐ Rep. Fee: \$

220

typist

Survey Department Check List (Case Handler)

Reference No. : CS/CTI 1800 1951 Tivd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 13/7/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18001951/T1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-01-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 344X	Veh. Inspected	FBB 3359L
Policy No.	DMHCSN1752961700	Coverage (\$)	0.00
Claim No.	SNM18D00576C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	31/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/12/2017	Inspection Date
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018		31 Jan 2018 13:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GANESAN S/O SALVAKUMAR, ID: S9203920Z		
Vehicle Reg. No.:	FBB3359L	Date of Loss:	14/12/2017 00:00 - :59
Claim Type:	TP / SNM18D00576C02	Policy/Cover Note No.:	DMHCSN1752961700
Vehicle Reg. No. (Insured):	SLR344X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/02/2018]		
Adj Asg. Remarks:	EST \$10,036.20, ASSIGN MOHD RASUL AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 18:59
Date Of Accident	14/12/2017 02:15
Exact Location Of Accident	AYE TOWARDS TUAS BEFORE AXIT 2A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBB3359L
Insured/Policyholder	
Name Of Registered Owner	GANESAN S/O SALVAKUMAR
NRIC No	S9203920Z
Email Address	GANESANSALVAKUMAR26@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-88699532
Alternative Phone No	OTHERS-88699532

Vehicle Particulars

Manufacturer	HONDA
Model	CB400-399CC
Exact Purpose for which vehicle was being used at time of accident	AFTER NIGHT WORK GOING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MOMVM000000309-00-001
Cover Note Number	

Driver

Name of Driver	GANESAN S/O SALVAKUMAR
NRIC No	S9203920Z
Date Of Birth	26/01/1992
Occupation	INDOOR
Date Of Driving Pass	22/06/2016
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88699532
Fax Number	
Contact Number	OTHERS-88699532
Email Address	GANESANSALVAKUMAR26@HOTMAIL.COM

Address	BLK 64 TELOK BLANGAH DRIVE
	#07-196
Postcode	100064
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TELOK BLANGAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 51 TELOK BLANGAH DRIVE , POSTCODE: 100051 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2729999 - FAX NO: 63772526
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20171216/2153

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR344X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #1600
Springleaf Tower
Singapore 079909

Tel 63896111
Fax 62447175

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	GANESAN S/O SALVAKUMAR
Approximate Age	
Injuries Sustain	SERIOUS INJURY
Injured person in which vehicle?	FBB3359L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	


SKETCH PLAN

IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 2/1/2018
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

 08/01/2018
Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten text across the lined area: "P/S REFER TO POLICE REPORT 7/2017/216/2153". The text is written diagonally across the lines.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

9 21/1/2018
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

08/01/2018
Reporting Centre Personnel's Signature
Name: ROSE WONG
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20171216/2153

1 of 3

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

Report No. T/20171216/2153

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/12/2017 21:42		Vide Report No.: A/20171214/0021		Station Diary No.: 23	
Informant's Particulars					
Name of Informant: GANESAN S/O SALVAKUMAR			Address: APT BLK 64 TELOK BLANGAH DRIVE #07-196 SINGAPORE 100064		
ID Type / ID No.: NRIC NO / S9203920Z			Contact No.: Home/Office:		Mobile: 88699532
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 26/01/1992	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: ENGINEERING OFFICER			Driving Licence Information: Class: 2B,2A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 14/12/2017 02:15	Type of Location: Bend
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE towards Tuas before exit 2A.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBB3359L	Motorcycle	HONDA	CB400	Grey	Totally Damaged	0
SLR344X	Car				Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBB3359L	GREAT AMERICAN INSURANCE COMPANY	MT2016TR00273	17/09/2016	20/12/2017



**SINGAPORE
POLICE FORCE**



T/20171216/2153

2 of 3

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

Report No. T/20171216/2153

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	GANESAN S/O SALVAKUMAR	ID No.	S9203920Z
Related Vehicle	FBB3359L (Motorcycle)	Contact No.	88699532
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A Date of Expiry: NIL
Date Treatment	14/12/2017	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Serious

Brief Details.

On 14/12/2017 at about 0215 hrs, I was riding along AYE towards Tuas along Keppel Flyover. When I was approaching the end of the flyover before the bend, I saw construction work happening along the split road but towards Tuas. As I was heading towards Telok Blangah Road, I decided to keep left.

I did my checks and when there were no cars, I then moved to the extreme left lane. I was travelling at 60km/h as there were speed stripes. I suddenly felt a hard push against the back of my bike and I skidded. When I hit the floor, I immediately pushed away the bike. When I came to a stop, the bike was quite a distance away from me. The car that hit me from behind also came to a stop. The car is a black Toyota Corolla Axis bearing registration number SLR 344 X. As a result of the collision, I suffered abrasions to both my elbows, both of my hands and wrists, both my knees, my right ankle and my right shoulder blade. I also suffered from 3 broken tooth.

After the collision, I stood up and walked towards the driver. I shouted at the driver to come out and subsequently he came out. He came and hugged me and said "bro, I bring you to Vivocity. We settle privately". When he hugged me, I could smell alcohol coming from his breath. I felt giddy thus I told him to give me some space. I then walked towards the side of the road and sat down on the road. The construction worker then told me to not sit on the road and it was dangerous. I then stood up and walked towards the chevron near the construction site. While I was walking, the driver was still trying to persuade me to settle the matter privately. I then called the police and the ambulance for assistance. I wish to inform that the driver continuously tried to persuade me to settle the matter privately the entire time.

The ambulance came and subsequently conveyed me to Singapore General Hospital. I subsequently got a 5 day MC from the incident.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999



T/20171216/2153

3 of 3

Report No. T/20171216/2153

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 BRANDON CHUA

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /

Contact No.:

Signature Of Informant:

Date/Time:
16/12/2017 21:42

Classification Of Case:



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3920Z
Vehicle Details	
Vehicle No.:	FBB3359L
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	NC23E3100526
Chassis No.:	JH2NC39926M200497
Maximum Power Output:	-
Open Market Value:	\$6,408.00
Original Registration Date:	10 Mar 2007
First Registration Date:	10 Mar 2007
Transfer Count:	6
Actual ARF Paid:	\$962.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2026
COE Category:	D - Motorcycle
COE Period(Years):	10



南方摩哆 SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 29th January 2018

Motor Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #16-00
Springleaf Tower
Singapore 079908

Dear Sirs,

Re: Cost of repair to Honda CB400SF 1992 - 7BB 3359 L

1 pc of meter complete	38	950.00 cna ✓
" Head lamp		220.00 ca ✓
" Meter bracket		65.00 bt ✓
" Lamp stay		110.00 bt ✓
" Head lamp bracket		90.00 bt ✓
" Front signal		65.00 cna ✓
" Front mudguard		165.00 cut ✓
" Radiator		530.00 ?
" Throttle cable		110.00 cut ✓
" Handle bar		95.00 bt ✓
" Top brake pump		255.00 cut ✓
1 set of Mirror		130.00 cut ✓
1 pc of engine guard		110.00 dol ✓
" Footrest bracket RH		280.00 cna ✓
" Front exhaust pipe		85.00 bt ✓
" Rear exhaust pipe		65.00 dd ✓
" Fuel tank		250.00 dd ✓
" Tank cover		290.00 cna ✓
" Rear absorber		1,050.00 cna ✓
" Rear tyre mudguard		15.00 dl ✓

Sub Total 7,173.00

Yours faithfully,
SOUTHERN MOTOR

Tel 6389 6111
Fax 6224 7174



南方摩哆 SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Honda CR400SF 1pc 18 - FBB 33192

Date: 28th January 2018

Motor Claims

China Tai'ping Insurance (Singapore) Pte Ltd

Sub Total: S\$ 7,173.00

1 pc of	Rear mudguard	90.00 de
"	Rear boss	480.00 m/s
"	Rear bracket	180.00 am
2 pcs of	Rear signal	120.00 am
1 pc of	Rear swing arm	1,400.00 ?
"	Rear rim	850.00 am
"	Rear fork	350.00 bro
"	Rear rim bearing	500.00 ne
		<hr/>
		10,380.00
		<hr/>
		1,038.80
		<hr/>
		9,341.20

Tax 10%

Nett

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Transport
Jack body
Rear No. plate
Jack fork
Labour

30.00 ✓
120.00 100
12.00 65 ✓
85.00 60
350.00 280

S\$ 10,036.20

Yours faithfully,
SOUTHERN MOTOR

12/2/18

Tanjin 97495745
- wp'

5/2/18 @ 1410.

Lympson
Resurvey After repair.
Colony.

sur @ lkkauto.com.

Tel 63496111

Fax 62347175

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018		31 Jan 2018 13:23 Edit Adj Rpt	S\$8,103.20 Edit Estimates	S\$8,103.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -			
Main Claimant:	GANESAN S/O SALVAKUMAR , ID: S9203920Z			
Vehicle Reg. No.:	FB3359L	Date of Loss:	14/12/2017 00:00 - :59 [129 Months and 4 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM18D00576C02	Policy/Cover Note No.:	DMHCSN1752961700	
Vehicle Reg. No. (Insured):	SLR344X	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/02/2018]			
Adj Asg. Remarks:	EST \$10,036.20, ASSIGN MOHD RASUL AS SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



































Claim Documents






























***FBB3359L (SNM18D00576C02)**
[SLR344X]







TP
GANESAN S/O SALVAKUMAR
Dec 14 2017 12:00AM
[-]
Southern Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
59	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
60	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
61	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
62	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
63	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
64	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
65	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
66	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
67	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
68	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
69	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
70	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
71	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
72	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
73	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
74	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
75	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
76	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
77	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
78	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
79	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
80	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
81	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
82	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
83	06/02/18 12:52	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images				<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
85	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
86	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
87	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
88	06/02/18 12:52	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/18 13:22	REPAIR EST	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118001951/T1VD3S2

Date: 18/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1752961700

Claimant Vehicle No: FBB3359L Insured Vehicle No: SLR344X

Date of Loss: 14/12/2017 Nature of Claim: TP Claim No: SNM18D00576C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBB3359L

Make & Model: HONDA CB400, 399cc Engine No: NC23E3100526

Reg. Date: 10/03/2007 (Man. Year: 2006) Chassis No: JH2NC39926M200497

Colour: Black Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60R17 Rear Tyre Size: 160/60R17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,361.20	7,633.20	1,728.00	18.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	675.00	470.00	205.00	30.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,036.20	8,103.20	1,933.00	19.26
+ GST 7.00/7.00% (S\$)	702.53	567.22	135.31	19.26
Nett Amount (S\$)	10,738.73	8,670.42	2,068.31	19.26

INSPECTION

Date of Assignment: 31/01/2018

Date Inspected: 05/02/2018 Inspected At: Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2, #01-10
Singapore 159762

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS \$51,728.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jul 2018)	
Parts:	N/A	HONDA CB400 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB3359L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDGUARD	Deformed	90.00 FL	*90.00 FL
2	1		*REAR BOX	Missing	480.00 FL	*480.00 FL
3	1		*BOX BRACKET	Cracked	180.00 FL	*180.00 FL
4	2		*REAR SIGNAL	Cracked	130.00 FL	*130.00 FL
5	1		*REAR SWING ARM	*Check	1,400.00 FL	*- FL
6	1		*REAR RIM	Cracked	850.00 FL	*850.00 FL
7	1		*REAR FOOTREST	Broken	35.00 FL	*35.00 FL
8	1		*REAR RIM BEARING	Necessary	50.00 FL	*50.00 FL
9	1		*REAR NO. PLATE	Bent	12.00 FS	*12.00 FS
10	1		*METER COMPLETE	Cracked	950.00 FL	*950.00 FL
11	1		*HEAD LAMP	Cracked	320.00 FL	*320.00 FL
12	1		*METER BRACKET	Bent	65.00 FL	*65.00 FL
13	1		*LAMP STAY	Bent	110.00 FL	*110.00 FL
14	1		*HEAD LAMP BRACKET	Bent	90.00 FL	*90.00 FL
15	1		*FRONT SIGNAL	Cracked	65.00 FL	*65.00 FL
16	1		*FRONT MUDGUARD	Cut	165.00 FL	*165.00 FL
17	1		*RADIATOR	*Check	520.00 FL	*- FL
18	1		*THROTTLE CABLE	Cut	110.00 FL	*110.00 FL
19	1		*HANDLE BAR	Bent	98.00 FL	*98.00 FL
20	1		*TOP BRAKE PUMP	Cut	285.00 FL	*285.00 FL
21	1		*SET MIRROR	Cut	130.00 FL	*130.00 FL
22	1		*ENGINE GUARD	Dented	110.00 FL	*110.00 FL
23	1		*FOOTREST BRACKET RH	Cracked	280.00 FL	*280.00 FL
24	1		*FRONT EXHAUST PIPE	Bent	950.00 FL	*950.00 FL
25	1		*REAR EXHAUST PIPE	Dented	650.00 FL	*650.00 FL
26	1		*FUEL TANK	Dented	850.00 FL	*850.00 FL
27	1		*FORK COVER	Cracked	290.00 FL	*290.00 FL
28	1		*REAR ABSORBER	Cracked	1,050.00 FL	*1,050.00 FL
29	1		*REAR TYRE MUDGUARD	Deformed	85.00 FL	*85.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,400.00	8,480.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,038.80	846.80
Total Parts (\$\$)	9,361.20	7,633.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT.	New	30.00	30.00
2	JACK BODY.	New	180.00	100.00
3	JACK FORK.	New	85.00	60.00
4	LABOUR.	New	380.00	280.00
Gross Labour Cost (S\$)			675.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >