

ASS. REC. BY

REF CS/MSG18002030/Kvd321

Field Information

Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person)

Chris Fina Wong

MSIG

Date/Time 01/02/18 @ 11:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJT 5558B

Insured:

FX 9567A

at Workshop n/s

NGS Trading

Tel

6481 5727

of BIK 10, AMK Ind. Prk 2A # 02-01

Policy No

MSD/VMT/17-359717

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/01/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time: 1:50pm @ 1/2/18

Person Contacted:

Evelyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJT 5558B - X

FX 9567A - X

2/2/18

Send preli revised by merimen

10/5/18

@ 5:03pm Ah Siong said vehicle will send in for repair next week

25/5/18

Kenneth said RS

ASS. REC. BY:

REF: *W6-1*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *\$35k*

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: *10* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SKT 3558B*Yr Regn: *08, 0.9*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Odyssey*c.c. *2354*Colour: *M-L Blue*

A/C

Insured / Std / NI / NA

Sp. Reading: *177859*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JHMRB 385090200367*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orMod: Nil / S/Rim / *STD A/Rim* orTyre Size: F: *215/55R17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal: *8* mmR/Bal: *6* mmL/Bal: *8* mmL/Bal: *6* mmD.O.A: *27/1/18*D.O.A: *1/2/18*

Survey held at _____

Des. of Damages: *Acc N/S* / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*2/2 File pass to Catherine**25/5/18 Confirmed RS \$3200 (Red 3298.08, 50%)*

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: *3*Resurvey No. of Trip: *1*

Survey Fee

Transportation

S - RS - SI

Photos

Others

TOTAL

1)

Date/Time, File Return to?

☐

: Final Report

25/5- typist

Report Format:

*merimen*Lump Sum / I.B.I. (\$) *RS \$3200*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

*200**10**20*

Survey Department Check List (Case Handler)

Reference No.: CS | MSG 1800 2030 | Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 25/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002030/Kvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FX 9567A	Veh. Inspected	SJT 5558B
Policy No.	MSD/VMT/17-359717	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/01/2018	Inspection Date	01/02/2018
Survey held at	NGS TRADING BLK 10 AMK IND PK 2A #02-01 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	01 Feb 2018		01 Feb 2018 11:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD HUSSEIN MARICAN BIN ASN MARICAN, ID: S92215221		
Main Claimant:	SZE CHONG SOON, ID: S2563054H		
Vehicle Reg. No.:	SJT5558B	Date of Loss:	27/01/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/17-359717
Vehicle Reg. No. (Insured):	FX9567A	Policy No. (Claimant):	Coverage: 24/02/2017 - 23/02/2018
		Excess:	
Repairer:	NGS TRADING (HQ) Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64815727		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/02/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 02 Feb 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: FX9567A	Accident Date	: 27/01/2018
TP Vehicle No	: SJT5558B	Assignment Date	: 01/02/2018
Make	: KAWASAKI KRR ZX150 M	Est. Duration of Repair	: 3.00
Date of Inspection	: 01/02/2018		
Inspection At	: NGS TRADING (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,378.08
Revised Amount	:S\$	2,751.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,751.04
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3054H
Vehicle Details	
Vehicle No.:	SJT5558B
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4L AT SR
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	K24Z21300372
Chassis No.:	JHMRB38509C200367
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$34,119.00
Original Registration Date:	05 Aug 2009
First Registration Date:	05 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$34,119.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Aug 2019
PARF Rebate Amount:	\$18,765.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2019
COE Category:	B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$18,501.00
COE Rebate Amount:	\$2,785.00
Total Rebate Amount:	\$21,550.00

The information contained herein is correct as at 02 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/01/2018 11:12
Date Of Accident 27/01/2018 19:30
Exact Location Of Accident ALONG PUNGGOL ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJT5558B
Insured/Policyholder
Name Of Registered Owner SZE CHONG SOON
NRIC No S2563054H
Email Address CSSZE55@GMAIL.COM
Mobile Phone No (LOCAL) +65-83863088
Alternative Phone No OFFICE-62837787

Vehicle Particulars

Manufacturer HONDA
Model ODYSSEY
Exact Purpose for which vehicle was being used at time of accident GOING HOME
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5092894020
Cover Note Number

Driver

Name of Driver SZE CHONG SOON
NRIC No S2563054H
Date Of Birth 27/05/1955
Occupation INDOOR
Date Of Driving Pass 27/06/1981
Driving Experience 36 YEARS AND 7 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-83863088
Fax Number
Contact Number OFFICE-62837787
Email Address CSSZE55@GMAIL.COM

Address	BLK 27 #01-14 UPPER SERANGOON VIEW
Postcode	534045
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED ACCIDENT SKETCHPLANS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FX9567A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD HUSSEIN MARICAN BIN ASNAN MARICAN
NRIC/Passport Number	S92215221
Contact Number	85152125
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and by the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The title and contents of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigations.
6. The report will be forwarded by the Insurers of the C&A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report as the insurer and to copies of the report being made available as aforesaid.
8. Covered under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my work unit and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or pursuant by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have received vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in responding to any enquiries by me;
 - (iv) administering my claims (including the making of cash/cheque/loan, statement, invoices, reports or replies to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of correspondence and/or for
- (b) conveying with applicable law to administering, processing, handling and/or dealing with my claim (collectively the "Purposes")
- (c) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (d) my Personal Information may/are be disclosed by or to the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be shed outside of Singapore, for one or more of the above Purposes
- (e) my Personal Information will also be collected and used to compile claim history for the purpose of fraud detection, investigation and management in present and all future claims
- (f) the information be collected under (c) above may be stored / disclosed:
 - (i) to all insurers and/or any other third parties that would be necessary, investigating, conducting or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law, or court orders.


Policyholder's Signature
Date & Time: 30/01/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: SUREN MOON
GIA-C-100000

Sketch Plan #2

SKETCH PLAN

Refer to attached description

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG PONGOL ROAD AND STOPPED AT THE TRAFFIC JUNCTION (ALONG RIVERVALE DRIVE) ALL OF A SUDDEN I HEARD A ENGINE BEHIND MY CAR. I CAME OUT AND SAW A MOTORCYCLIST ON THE ROAD. HE GOT UP AND WE EXCHANGE CONTACT AND PARTICULARS OF DRIVING LICENCE. HE ALSO PUSHED HIS MOTORCYCLE TO THE SIDE OF THE ROAD. I ALSO PARKED MY CAR TO THE SIDE OF THE ROAD TO AVOID TRAFFIC JAM AT THE TRAFFIC JUNCTION.

DECLARATION

We declare the foregoing particulars are true in every respect.



Police Officer's Signature

Date & Time: 30/01/2018 11:25

2018/01/30 11:25

Driver's Signature

(If driver is not the police officer)

Date & Time:



30/01/2018 11:25


Reporting Crime Forwarder's Signature

Name: A. B. M. M. M.

1801/2018

Sketch Plan #3

Along Pungnet Road



NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.: 51106300L

QUOTATION

No. : QT-09292

MSIG INS (S) PTE LTD
MOTOR CLAIMS DEPT
16 RAFFLES QUAY
#24-01 HONG LEONG BLDG
SINGAPORE 048581

Not Authorized
1/1 Sur & 1
Resurvey After Pain
3 days

Your Ref. :
Our Ref :
C. C. :
Date : 01-02-2018
Page : 1 of 2

TEL : 6880 9644

FAX : 6225 6571

Description	Qty	U/ Price S\$	Amount S\$
-------------	-----	-----------------	---------------

ACCIDENT ON 27/01/2018 @19:30HRS ALONG PUNGGOL ROAD

INVOLVING SJT5558B & FX9567A CLAIMS AGAINST FX9567A

REPLACEMENT PART:

REAR BOOT LID
REAR BUMPER
REAR RETAINER LH, REAR BUMPER
REAR BOOT LAMP LH
REAR BUMPER REFLECTOR
TAILLAMP LH ASSY
EXHAUST
TOW COVER
EXHAUST HANGER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RL	983.30	983.30 X
Bu	815.90	815.90 L
Sw	48.00	48.00 X
CRH	442.10	442.10 L
CRH	162.50	162.50 L
CRH	478.70	478.70 L
R ₁	0.00	0.00 -
hiv	48.00	48.00 -
Tn	38.20	76.40 L

SubTotal

3,054.90

Less 20%

-610.98

2444.92

REAR BOOT LOGO 'ODYSSEY' S.NETT

1 82.00 82.00 X

REVERSE SENSOR S.NETT

1 280.00 280.00 X

PARKING CAMERA S.NETT

1 380.00 380.00 X

CLIPS S.NETT

8 4.00 32.00 L

TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT.

1 1,200.00 1,200.00

STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL.
REPLACE DAMAGED PARTS. REFIT INTO POSITION.

REMOVE/REPLACE EXHAUST REALIGN INTO POSITION

TRANSFER REAR BOOT MECHANISM

1 150.00 150.00 X

SPRAY PAINTING ON REAR BOOT LID, REAR BUMPER, REAR FENDER LH,
REAR END PANEL & ECT.

1 1,200.00 1,200.00

CHECK WIRING/LIGHT PROPER FUNCTION

1 50.00 50.00

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.: 51106300L

QUOTATION

No. : QT-09292

MSIG INS (S) PTE LTD
MOTOR CLAIMS DEPT
16 RAFFLES QUAY
#24-01 HONG LEONG BLDG
SINGAPORE 048581

Your Ref. :
Our Ref :
C. C. :
Date : 01-02-2018
Page : 2 of 2

TEL : 6880 9644 FAX : 6225 6571

Description	Qty	U/ Price S\$	Amount S\$
-------------	-----	-----------------	---------------

6498.08

6378.08

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Total **5,817.92**

Yours faithfully,



Administrator

NGS TRADING

8B, 10 Ang Mo Kio Ind. Pk 2a #02-01 ANK AutoParts Singapore 568047
Tel: 64815721 Fax: 64815772 Email: evelyn@ngstrading@gmail.com
Reg No: 51106300L

QUOTATION

No. : QT-09292

MSIG INS (S) PTE LTD
MOTOR CLAIMS DEPT
16 RAFFLES QUAY
#24-01 HONG LEONG BLDG
SINGAPORE 048581

TEL : 6880 9644

FAX : 6225 6571

Your Ref. :
Our Ref. :
C.C. :
Date : 01-02-2018
Page : 1 of 2

Not Authorized
1/1 Sing B:
Revising After Point
3 day

Description	Qty	U/ Price	Amount
		S\$	S\$
ACCIDENT ON 27/01/2018 @19:30HRS ALONG FUNGGOL ROAD			
INVOVING SGT55588 & FX9567A CLAIMS AGAINST FX9567A			
REPLACEMENT PART:			
REAR BOOT LID	1	<i>R</i> 983.30	983.30
REAR BUMPER	1	<i>Bu</i> 815.90	815.90
REAR RETAINER LH REAR BUMPER	1	<i>Sen</i> 48.00	48.00
REAR BOOT LAMP LH	1	<i>CR</i> 442.10	442.10
REAR BUMPER REFLECTOR	1	<i>CR</i> 162.50	162.50
TAILLAMP LH ASSY	1	<i>CR</i> 478.70	478.70
EXHAUST	1	<i>R</i> 0.00	<i>700.20</i> 0.00
TOW COVER	1	<i>R</i> 48.00	48.00
EXHAUST HANGER	2	<i>Tn</i> 38.20	76.40
SubTotal			3,054.90
Less 20%	1	-610.98	-610.98
REAR BOOT LOGO 'BOYSSIEY' S.NETT	1	82.00	82.00
REVERSE SENSOR S.NETT	1	<i>4pas \$400</i> 280.00	280.00
PARKING CAMERA S.NETT	1	380.00	380.00
CLIPS S.NETT	8	<i>re</i> 4.00	32.00
TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT	1	1,200.00	1,200.00
STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL			
REPLACE DAMAGED PARTS REFIT INTO POSITION			
REMOVE/REPLACE EXHAUST REALIGN INTO POSITION			
TRANSFER REAR BOOT MECHANISM	1	150.00	150.00
SPRAY PAINTING ON REAR BOOT LID, REAR BUMPER, REAR FENDER LH, REAR END PANEL & ECT	1	1,200.00	1,200.00
CHECK WIRING/LIGHT PROPER FUNCTION		50.00	50.00

L/S \$3540

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 25 May 2018 9:32 AM
To: 'Evelyn Ng'
Cc: SUR
Subject: RE: SJT5558B for finalisation

Dear Evelyn,

WITHOUT PREJUDICE

Confirmed Repair Sum \$3200.00 @ 3working days.

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Evelyn Ng [mailto:evelynnngstrading@gmail.com]
Sent: Friday, 25 May 2018 9:20 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SJT5558B for finalisation

Hi Veron,

Kindly revise to \$3200.00 @3working days.

On 25 May 2018 at 08:23, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Evelyn,

WITHOUT PREJUDICE

Offer Lump Sum \$2900/- @3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 24 May 2018 11:37 AM

To: Evelyn Ng <evelynnngstrading@gmail.com>; SUR <sur@lkkauto.com>

Subject: RE: SJT5558B for finalisation

Dear Evelyn,

WITHOUT PREJUDICE

Offer Lump Sum \$2600/- @3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Evelyn Ng [mailto:evelynnngstrading@gmail.com]

Sent: Wednesday, 16 May 2018 4:43 PM

To: SUR <sur@lkkauto.com>

Subject: SJT5558B for finalisation

Hi Kenneth,

Please find attached photos before paint for your reference. Also, do find attached an estimated quotation, and for you to include Repairing of Rear Boot Lid, Labour & Spraypaint. Please also take note that Reverse Sensor is using 4pcs type kindly revise price.

Hope to get your response on the finalize amount as soon as possible.

Thank you,

NGS TRADING

Evelyn Ng HP96955547

Blk 10 Ang Mo Kio Ind Park 2a

#02-01 AMK AuotPoint

Singapore 568047

Tel: 64815727 Fax: 64815772

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Feb 2018		01 Feb 2018 11:31 Edit Adj Rpt	S\$3,391.04 Edit Estimates	S\$3,391.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUHAMMAD HUSSEIN MARICAN BIN ASN MARICAN , ID: S92215221								
Main Claimant:	SIZE CHONG SOON , ID: S2563054H								
Vehicle Reg. No.:	SJT5558B	Date of Loss:	27/01/2018 00:00 - :59 [101 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000183	Policy/Cover Note No.:	MSD/VMT/17-359717 Coverage: 24/02/2017 - 23/02/2018						
Vehicle Reg. No. (Insured):	FX9567A	Policy No. (Claimant):							
		Excess:							
Repairer:	NGS TRADING (HQ) Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64815727								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJT5558B (MSC/V/18-000183)
[FX9567A]**

TP

SZE CHONG SOON

Jan 27 2018 12:00AM

**[MUHAMMAD HUSSEIN MARICAN BIN ASN MARICAN]
NGS TRADING**

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page ☐	
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 11:05	Adjuster Immediate Advice	 Load HTML	☐
Photos/Images			3 per page ☐	
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/02/18 09:43	General View	 Load JPG	☐
2	02/02/18 09:43	General View	 Load JPG	☐
3	02/02/18 09:43	General View	 Load JPG	☐
4	02/02/18 09:43	General View	 Load JPG	☐
5	02/02/18 09:43	General View	 Load JPG	☐
6	02/02/18 09:43	General View	 Load JPG	☐
7	02/02/18 09:43	General View	 Load JPG	☐
8	02/02/18 09:43	General View	 Load JPG	☐
9	02/02/18 09:43	General View	 Load JPG	☐
10	02/02/18 09:43	General View	 Load JPG	☐
11	02/02/18 09:43	General View	 Load JPG	☐
12	02/02/18 09:43	General View	 Load JPG	☐
13	02/02/18 09:43	General View	 Load JPG	☐
14	02/02/18 09:43	General View	 Load JPG	☐
15	02/02/18 09:43	General View	 Load JPG	☐
16	24/05/18 11:26	Reinspection Photo	 Load JPG	☐
17	24/05/18 11:26	Reinspection Photo	 Load JPG	☐
Documentation			1 per page ☐	
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/18 11:32	Email frm TP - PRI	 Load PDF	☐
2	01/02/18 11:33	SJT5558B GIA Rpt	 Load PDF	☐

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002030/KVD3E2

Date: 30/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-359717
Claimant Vehicle No :	SJT5558B	Insured Vehicle No :	FX9567A
Date of Loss:	27/01/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000183

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT5558B	Engine No:	K24Z21300372
Make & Model:	HONDA ODYSSEY, 2.4 AT SR (A)	Chassis No:	JHMRB38509C200367
Reg. Date:	05/08/2009 (Man. Year: 2008)	Odometer:	177859 km
Colour:	Metallic Light Blue		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Maxxis 8 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 8 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,898.08	2,611.04	1,287.04	33.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	780.00	1,820.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,498.08	3,391.04	3,107.04	47.81

INSPECTION

Date of Assignment:	01/02/2018		
Date Inspected:	01/02/2018 Inspected At:	NGS TRADING (HQ)	
		Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK Autopoint	
		Singapore 568047	
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 AT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT5558B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	983.30 FL	*- FL
2	1		*REAR BUMPER	Buckled	815.90 FL	*815.90 FL
3	1		*REAR RETAINER LH, REAR BUMPER	Serviceable	48.00 FL	*- FL
4	1		*REAR BOOT LAMP LH	Cracked	442.10 FL	*442.10 FL
5	1		*REAR BUMPER REFLECTOR	Cracked	162.50 FL	*162.50 FL
6	1		*TAILLAMP LH ASSY	Cracked	478.70 FL	*478.70 FL
7	1		*EXHAUST	Bent	700.20 FL	*700.20 FL
8	1		*TOW COVER	Missing	48.00 FL	*48.00 FL
9	2		*EXHAUST HANGER	Torn	76.40 FL	*76.40 FL
10	1		*REAR BOOT LOGO ODYSSEY	Not Necessary	82.00 FS	*- FS
11	4		*REVERSE SENSOR	Shorted	400.00 FS	*400.00 FS
12	1		*PARKING CAMERA	Serviceable	380.00 FS	*- FS
13	8		*CLIPS	Necessary	32.00 FS	*32.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,649.10	3,155.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	751.02	544.76
Total Parts (\$\$)	3,898.08	2,611.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT / ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR / RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PARTS. REFIT INTO POSITION. REMOVE / REPLACE EXHAUST REALIGN INTO POSITION	New	1,200.00	280.00
2	TRANSFER REAR BOOT MECHANISM	New	150.00	0.00
3	SPRAY PAINTING ON REAR BOOT LID, REAR BUMPER, REAR FENDER LH, REAR END PANEL & ETC	New	1,200.00	480.00
4	CHECK WIRING / LIGHT PROPER FUNCTION	New	50.00	20.00
Gross Labour Cost (S\$)			2,600.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >