

ASS. REC. BY

REF. CS3/AIG/18002031/Wd302

* DAK 4 DAYS

Surveyor

Mehmen

ASSIGNMENT (Office)

From (Person)

Syed Yusoff

of

AIG

Date/Time

01/02/18 @ 12:09pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 53142

Insured:

SCW 7227K

at Workshop m/s:

Soon Lee Choon Auto

Tel:

64846217

of

BLK 5032 AMK Ind. Prk 2 # 01-283

Policy No:

2100506610

Claim No:

8120008321SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

02/02/2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

joey

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	VERY URGENT
	SJR 53142 - X	
	SCW 7227K - X	
	Dismantle Part: 13.02.2018	
	After repair: 14.02.2018	

ALG

File 02/02/18

STR 5314 Z 26 Jun 2009

Insurance Co.

TP WS TR RES CO RES EVALUATION

To inspect vehicle SJR 5314Z
at Address 1300 Lee Choon Auto
Blk 5032, Amk Ind Prk 2 # 01-283

Insured

Policy No

Damage

Sum Insured


Excess

Client's Record

Name of Van

Policy Condition

Remarks: The van had commenced its repair at the time of inspection.



Ball or Marker Value

CAD Accident Report Consistent? Yes or No

GA - PP Seen Consistent? Yes or No

Est. Repairs 7 days Pass: Yes or No

Est. Sum 3 Valid: Yes or No

CA REV + REP 24 HRS up

Date Person Contacted Vehicle IN/OUT

The U/C Chassis frame Body Structure affected by accident

Date Time Action Instruction

Track Treatment

Name Taptan Wisly 1797.
Color white

St. Reading 164612 T. Panel Insured (St. N. VA

Eng No

DNo 24520-0006198

Gen. Cont. Good (P) Poor Burnt

Steering (P) Jammed Leaked Burnt or

Brake (P) Jammed Leaked Burnt or

Mod. Nil (SR) STD A Rim or

Tyre Size = 205/60 R15
R 195/115 R15

BS/DUN EXNOVA GA FS LIZA MD CHTSU PR SUVI
NEW SAT Westlake (P) RHF
TOYO YOK (P) Westlake NEWTON (P) RHF
Westlake Chury NEWTON (P) RHF

R Ba 3 -- R Ba 4 --

L Ba 3 -- L Ba 4 --

DCA 29/1/2018 CC 2/2/2018

Surveyed at: At Home @ 1.59pm

Des. of Damages P. P. Pass OS NS U/C Roofed or

RECEIVED 1 MAR 2018

One Time Fee Report ☐ Prel. Report

26032018 ☐ Final Report

One Time Fee Report

Days Of Repair

Resurvey No. of Time

Survey Fee

Add Fee

Inter. Fee

Inter. Fee

Inter. Fee

Inter. Fee

Inter. Fee

Report Form PRS

Form 5.1.1.1

180
20
200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigner	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018		01 Feb 2018 12:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM TIAN BACK, ID: S0750620A, Tel: +6598387227		
Main Claimant:	DANIEL AND PARTNER SERVICES, Co. Reg. No.: 53363948D		
Vehicle Reg. No.:	SJR5314Z	Date of Loss:	29/01/2018 16:00 - :59
Claim Type:	TP / 8120008321SG	Policy/Cover Note No.:	2100506610 (Comprehensive) Coverage: 10/04/2017 - 09/04/2018
Vehicle Reg. No. (Insured):	SCW7227K	Policy No. (Claimant):	5096913124
	Excess:		
Repairer:	Soon Lee Choon Auto Services (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2, #01-283 SINGAPORE 569535, 569535 Ang Mo Kio - Tel: 64840217		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/02/2018]		
Driver/Custodian (Insured):	LIM TIAN BACK (68 / Male), NRIC: S0750620A, Tel: +6598387227		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)


There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done /
No results.									

Your password will expire in 10 days. [Click here to change it.](#)

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SCW7227K AND SJR5314Z ON 29/01/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 1/2/2018 12:12:35 PM
Attachments:  Fax3DF6.tif

Hi LKK,

Kindly assist to survey, vehicle in.

Case assigned to you in Merimen.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & COAdvocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Nedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)**Please reply to our Branch Office for this matter**

⇒ Branch Office:

11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igens.lim@mneduco.com.sg
serene.tan@mneduco.com.sgOur Reference : MN/IG/S5/1812206/st
Your Reference : SCW 7227KDate : 31st January 2018

BY FAX 6835-7416 ONLY

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Dear Sirs,

1. **NOTICE OF ACCIDENT** TO INSURERS AND PRE-REPAIR SURVEY **WITHIN 2 WORKING DAYS** PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 29/01/2018 INVOLVING VEHICLE NOS. SJR 5314Z & SCW 7227K ALONG ECP CHANGI.

We are instructed by DANIEL AND PARTNER SERVICES (owners of motor vehicle no. SJR 5314Z) and/or SOON LEE CHOON AUTO SERVICES PTE LTD (the motor workshop for SJR 5314Z) to notify you of a road traffic accident on 29/01/2018 at about 1810 HOURS along ECP CHANGI involving our client's vehicle registration number [SJR 5314Z] and [SCW 7227K] driven by you at the material time.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO - (Branch Office)

encl

c.c. 1) Lim Tian Back

(Vehicle : SCW 7227K)

- 2) SOON LEE CHOON AUTO SERVICES PTE LTD
Blk 5032 Ang Mo Kio Industrial Park 2
#01-283
Singapore 569535
Telephone : 9686-8855 (Ms Phyllis)

(Vehicle : SJR 5314Z)

(9) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shined (9) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (X)

Rear Portion

NAC	INC	Item	CON	ACQ	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	LH	OUT	✓
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	RUC	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	OUT	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	RUC	✓	
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Bu	✓	
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	OUT	✓	
1198	994651	Tailgate Rubber	DIS	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SJR5314 Z**

NAC	INC	Item	CON	ACQ	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	RUC	✓	
1219	993449	Rear LH Fender Protector	NBS	✓	
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	CRA	✓	
1224	993621	Rear LH Mudflap	DIS	✓	
1225	993933	Rear LH Wheel Rim	OUT	✓	
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre	OUT	✓	572
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	LH	OUT	✓
1250	992167	Fuel Lid	DIS	✓	
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 21

Assessor: _____

26/8/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 12:10
Date Of Accident	29/01/2018 16:10
Exact Location Of Accident	ECP CHANGI (12.5KM MARKING)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR5314Z
Insured/Policyholder	
Name Of Registered Owner	DANIEL AND PARTNER SERVICES
Co Reg No	NA 53363948D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93231587
Alternative Phone No	OFFICE-93231587

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096913124
Cover Note Number	

Driver

Name of Driver	ANG BOON PING, DANIEL (HONG WENBIN)
NRIC No	S8724377Z
Date Of Birth	15/08/1987
Occupation	OUTDOOR
Date Of Driving Pass	23/03/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93231587
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 51 MARINE TERRACE #07-175
Postcode	440051
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WAS TRAVELLING ON LANE 2 ALONG ECP CHANGI AND DUE TO ROAD WORKS AHEAD I SLOW DOWN MY VEHICLE. SOON AFTER SLOWING DOWN THE CAR BEHIND ME COLLIDED ONTO MY CAR.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCW7227K
Vehicle Make/Model/Colour	MERCEDES BENZ E250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM TIAN BACK
NRIC/Passport Number	S0750620A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was travelling on lane 2 along ECP Chagpi and due to road works ahead I slow down my vehicle. Soon after slowing down the car behind me collided onto my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018		01 Feb 2018 12:09 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	LIM TIAN BACK , ID: S0750620A, Tel: +6598387227		
Main Claimant:	DANIEL AND PARTNER SERVICES , Co. Reg. No.: 53363948D		
Vehicle Reg. No.:	SJR5314Z	Date of Loss:	29/01/2018 16:00 - :59
Claim Type:	TP / 8120008321SG	Policy/Cover Note No.:	2100506610 (Comprehensive) Coverage: 10/04/2017 - 09/04/2018
Vehicle Reg. No. (Insured):	SCW7227K	Policy No. (Claimant):	5096913124
	Excess:		
Repairer:	Soon Lee Choon Auto Services (HQ) BLK 5032 ANG MO KIO INDUSTRIAL PARK 2, #01-283 SINGAPORE 569535, 569535 Ang Mo Kio - Tel: 64840217		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 12/02/2018]		
Driver/Custodian (Insured):	LIM TIAN BACK (68 / Male) , NRIC: S0750620A, Tel: +6598387227		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)
























There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJR5314Z (8120008321SG)**
[SCW7227K]
TP
DANIEL AND PARTNER SERVICES
Jan 29 2018 4:00PM
[LIM TIAN BACK]
Soon Lee Choon Auto Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser <input type="button" value="v"/>		
Video												1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail	Print			
1	06/02/18 16:55	Video - Accident From:OD - Reg. No: SCW7227K, Claimant: LIM TIAN BACK											Load MP4				
Photos/Images												3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>			
No	Finalized On	Su Brothers' Motor Workshop (AMK)											Thumbnail	Print			
1	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
2	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
3	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
4	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
5	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
6	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
7	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
8	30/01/18 12:17	Accident Photo [Linked Accident Report Documents]											Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	23/03/18 17:09	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>			
2	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
3	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
4	23/03/18 17:09	Chassis Number											Load JPG	<input checked="" type="checkbox"/>			
5	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
6	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
7	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
8	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
9	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
10	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
11	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
12	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
13	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
14	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
15	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
16	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
17	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
18	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
19	23/03/18 17:09	General View											Load JPG	<input checked="" type="checkbox"/>			
20	23/03/18 17:09	General View											Load JPG				

					<input checked="" type="checkbox"/>
21	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
22	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
23	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
24	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
25	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
26	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
27	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
28	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
29	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
30	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
31	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
32	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
33	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
34	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
35	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
36	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
37	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
38	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
39	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
40	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
41	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
42	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
43	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
44	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
45	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
46	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
47	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
48	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
49	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
50	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
51	23/03/18 17:09	General View		Load JPG	<input checked="" type="checkbox"/>
52	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
60	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
61	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
65	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	23/03/18 17:10	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

70	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
71	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
72	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
73	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
74	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
75	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
76	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
77	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
78	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
79	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
80	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
81	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
82	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
83	23/03/18 17:13	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	12/03/18 16:32	color photos- part 1	1	Load PDF	
2	12/03/18 16:32	color photos- pt 2	1	Load PDF	
3	12/03/18 16:32	TP surveyor report	1	Load PDF	
No	Finalized On	Su Brothers' Motor Workshop (AMK)		Thumbnail	Print
1	30/01/18 12:16	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	30/01/18 12:16	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

				View	View in Browser
				1 per page	<input checked="" type="checkbox"/>
Assessment Reports					
No	Finalized On	Su Brothers' Motor Workshop (AMK)		Thumbnail	Print
1	30/01/18 12:19	Accident Statement	1	Load HTM	
				3 per page	<input checked="" type="checkbox"/>
Photos/Images					
No	Finalized On	Su Brothers' Motor Workshop (AMK)		Thumbnail	Print
1	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	30/01/18 12:17	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
Documentation					
No	Finalized On	Su Brothers' Motor Workshop (AMK)		Thumbnail	Print
1	30/01/18 12:16	Sketch Plan	1	Load TIF	
2	30/01/18 12:16	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18002031/WD3E2

Date: 27/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100506610
Claimant Vehicle No : SJR5314Z **Insured Vehicle No :** SCW7227K
 Date of Loss: 29/01/2018 Nature of Claim: TP Claim No: 8120008321SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR5314Z**
 Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 2ZR0423575
 Reg. Date: 26/06/2009 (Man. Year: 2009) Chassis No: ZGE200006198
 Colour: White Odometer: 164612 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Membat 3 mm Rear Left Side: West Lake 4 mm
 Front Right Side: West Lake 3 mm Rear Right Side: Neuton 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/02/2018
 Date Inspected: 02/02/2018 Inspected At: Soon Lee Choon Auto Services (HQ)
 BLK 5032 ANG MO KIO INDUSTRIAL
 PARK 2, #01-283 ,
 Singapore 569535
 Estimated Period of Repair: 7.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	0.00 F	*- F
2	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER LH	Cut	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR END PANEL	Buckled	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
7	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*- F
8	1		*TAILGATE	Buckled	0.00 F	*- F
9	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*TAILGATE LOCK	Cut	0.00 F	*- F
12	1		*TAILGATE RUBBER	Distorted	0.00 F	*- F
13	1		*REAR LH FENDER	Buckled	0.00 F	*- F
14	1		*REAR LH FENDER GLASS SEALANT	Necessary	0.00 F	*- F
15	1		*REAR LH FENDER INNER TRIM	* Check	0.00 F	*- F
16	1		*REAR LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
17	1		*REAR LH MUDFLAP	Distorted	0.00 F	*- F
18	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
19	1		*REAR LH TYRE (50%)	Cut	0.00 F	*- F
20	1		*REAR FENDER AIR GRILLE LH	Cut	0.00 F	*- F
21	1		*FUEL LID	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >