

22/03/2002

ASS. REC. BY:

REF: CS/EGI18002075/Kad307

Special Instruction:

Surveyor: KennethASSIGNMENT (Office)From (Person): Yee Pei Li

of

EGIDate/Time: 11/2/18 @ 3:32 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFV 80132

Insured:

XD 59164

at Workshop m/s

Lai Huat (Meng Kee)

Tel:

6453 8110of Blk 160 Sing Ming Drive # 04-01

Policy No:

Claim No:

XD 59164 / SE / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/01/2018

CA / REV / REP. / REV 24 HRS

Wp02/02/2018

H.O.D. Endorsement:

Date/Time: 5:25 pm @ 1/2/18

Person Contacted:

JennyVehicle: IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SFV 80132 - XXD 59164 - CS/EGI17020189/Urban2D.O.A.: 21/10/201705/2/18 @ 4:13 pm revised to Steven Lim by email.09/5/18 @ 8:23 pm Kenneth confirmed to email CS \$ 7650, 5 days, CPed to 24/11.10, 24%



REF: EGI

ASSIGNMENT

From _____ Date: 02/02/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect/Vehicle No: SFV 8013Z
at Workshop m/s: Lei Huch (Meng Kee)
of Blk 160 Sin Ming Drive # 04-01

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8 4/16

IDAO Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: 20 % G Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFV 8013Z Regn: 02 09

Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Volvo S60

1984

Colour: m. Gray

A/C Insured / Std / NI / NA

Se Reading: 148907

T Radio Insured / Std / NI / NA

Eng No: _____

O No: YVIRS494992734779

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front: _____

Rear: _____

R/Bal: 7 mm

R/Bal: 8 mm

L/Bal: 7 mm

L/Bal: 8 mm

D.O.A: 31/1/18

D.O.A: 2/2/18

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

5/2 File pass to Catherine

RECEIVED 19 OCT 2018

Date/Time File Pass to:

19/10 Request

☐
☐

: Preli. Report

: Final Report

Date/Time File Return to:

Days Of Repair: 5

Resurvey No. of Trips: 1

Survey Fee: 350

Transportation: _____

3 - P.O. _____

Finger: _____

Open: _____

Total: 350

Add Fee:

☐
☐
☐
☐

Stemmat: \$

Interfer: \$

Techn. Ins: \$

Referend: \$

Report Format: TP

Lump Sum: 7650



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18002075/Kqd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 02-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5916U	Veh. Inspected	SFV 8013Z
Policy No.		Coverage (\$)	0.00
Claim No.	XD5916U/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 1 February 2018 3:32 PM
To: 'admin-d@lkkauto.com'
Subject: OI : XD5916U / TP : SFV803Z/LKK / DOA : 31/01/18
Attachments: XD5916U - SAS.pdf; SFV8013Z - SAS.pdf; SFV8013Z - ESTIMATE.pdf; SFV8013Z - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LAI HUAT (MENG KEE) MOTOR PTE LTD,**

ADDRESS : BLK 160 SIN MING DRIVE
#04-01 SIN MING AUTOCITY
SINGAPORE 575722

PERSON TO CONTACT : JENNY @ 6453 8110

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 01.02.2018
Our Reference: XD 5916U/SE/pl
Your Reference: SFV 8013Z

Sent via Fax

or

Email

jenny.lim@laihuat.com.sg

To: LAI HUAT (MENG KEE) MOTOR PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SFV 8013Z
Insured's Vehicle: XD 5916U
Date Of Accident: 31.01.2018


We acknowledge receipt of your request for PRS on: 01.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto Consultants PL

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☐ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 5 February 2018 4:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); Admin-D (LKKAuto); 'Steve Lim'
Cc: SUR
Subject: RE: OI : XD5916U / TP : SFV803Z/LKK / DOA : 31/01/18
Attachments: CSEGI18002075Kqb.pdf

Dear Steven,

Enclosed herewith preliminary advice of SFV 8013Z.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Thursday, 1 February 2018 3:32 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: OI : XD5916U / TP : SFV803Z/LKK / DOA : 31/01/18

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LAI HUAT (MENG KEE) MOTOR PTE LTD,**

ADDRESS : BLK 160 SIN MING DRIVE
#04-01 SIN MING AUTOCITY
SINGAPORE 575722

PERSON TO CONTACT : JENNY @ 6453 8110

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: XD5916U/SE/pl

Date: 05th February 2018

Our Ref: CS/EG118002075/Kqd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFV 8013Z .


We thank you for the instruction on 01/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/02/2018 at the premises of M/s LAI HUAT MENG KEE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,061.10</u> .
Revised Estimate Amount	: S\$ <u>9,610.20</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorise repair.

Yours faithfully

KENNETH KONG
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 14:54
Date Of Accident	31/01/2018 11:30
Exact Location Of Accident	ALONG ORCHARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFV8013Z
Insured/Policyholder	
Name Of Registered Owner	DALJEET SINGH
NRIC No	S1083201B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96633479
Alternative Phone No	OTHERS-96633479

Vehicle Particulars

Manufacturer	VOLVO
Model	S60
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5054660566-05 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	DALJEET SINGH
NRIC No	S1083201B
Date Of Birth	20/05/1940
Occupation	INDOOR
Date Of Driving Pass	26/03/1958
Driving Experience	59 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96633479
Fax Number	
Contact Number	OTHERS-96633479
Email Address	NOEMAIL

Address	25 VANDA ROAD
Postcode	287785
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NIRMAL JIT KAUR GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD5916U
Vehicle Make/Model/Colour	MITSUBISHI FUSO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHOR YONG HING
NRIC/Passport Number	S1114025D
Contact Number	97386907
Address	COMPANY NAME: SOH KIM POO TRADING & TRANSPORT PL
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 31 JAN 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident happened this morning 31/01/2018 at 11:30am.

I was driving my car (A) SFV 8013Z along Orchard Road, traffic was heavy and all cars were moving slowly. A truck (B) XD 5916U was at my right trying to cut into my lane due to road closure ahead. I honk at him, but he still squeeze into my lane and hit onto the right side of my car. No injuries to both parties. We exchanged particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

31 JAN 2019

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:





REPUBLIC OF SINGAPORE DRIVING LICENCE

Licensee Number: **S1083201B**
 Name: **DALJEET SINGH**

Birth Date: **20 May 1940**
 Issue Date: **02 Dec 2003**




001023582K

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. **S1083201B**

Name: **DALJEET SINGH**

Race: **SIKH**
 Date of Birth: **20-05-1940** Sex: **M**
 Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
 26 Mar 1958

NP 428A



1335131

NRIC No: **S1083201B**

Blood Group: **A+** Date of Issue: **09-10-1993**

25 VANDA ROAD
 SINGAPORE 287785
 NRIC No: **S1083201B** Date: **08/09/2017**




Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5054660566-05

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : **SFV8013Z**
Chassis Number : YV1RS494992734779
2. Name of Policyholder : DALJEET SINGH
3. Effective Date of Insurance : 26 Aug 2017
4. Expiry Date of Insurance : 25 Aug 2018
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: DALJEET SINGH
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: STANDARD CHARTERED BANK
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : INSMART (INSURANCE) AGENCY PTE LTD (00000615165)
Date of Issue : 11 Aug 2017 13:48 hrs
Reprint : 11 Aug 2017 13:48 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3201B

Vehicle Details

Vehicle No.: SFV8013Z

Vehicle to be Exported: Yes

Intended De-registration Date: 31 Jan 2018

Vehicle Make: VOLVO

Vehicle Model: S60 2.0T AUTO

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: B5204T4357568

Chassis No.: YV1RS494992734779

Maximum Power Output: 132.0 kW (177 bhp)

Open Market Value: \$35,284.00

Original Registration Date: 26 Feb 2009

First Registration Date: 26 Feb 2009

Transfer Count: 1

Actual ARF Paid: \$35,284.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Feb 2019

PARF Rebate Amount: \$19,406.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$5,889.00

COE Rebate Amount: \$525.00

Total Rebate Amount: \$19,931.00

The information contained herein is correct as at 31 Jan 2018

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-016922

Date of Request: 31/01/2018

Your Ref No:

Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 31/01/2018
Enquiry By Jenny Lim Lai Foong
TP Vehicle No. XD5916U
Accident Date 31/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
XD5916U	ERGO Insurance Pte. Ltd.	16/07/2017-15/07/2018	6829 9199

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-016922

Date of Request: 31/01/2018

Your Ref No:

Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 31/01/2018
Enquiry By Jenny Lim Lai Foong
TP Vehicle No. XD5916U
Accident Date 31/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018487
Daljeet Singh

Page 1 of 1
Your ref. TP-XD 5916U ERGO
Job No. 69199
Our ref. 18.01.45
Payment
Date 1/2/2018

Attn

Vehicle No SFV 8013Z
Vehicle Model : Volvo S60
Accident on ... 31/1/2018

NOT Notified
11 Sep 8?
Resurvey After Paint 5 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear door RH	2,189.10		2,189.10
1.00	Pc	Rear door protector RH	316.70		316.70
1.00	Pc	Rear door weathertstrip RH	289.20		289.20
1.00	Pc	Front door RH	2,408.00		2,408.00
1.00	Pc	Front door protector RH	316.70		316.70
1.00	Pc	Front door weatherstrip RH	312.60		312.60
1.00	Pc	Front door wing mirror assy RH	1,605.70		1,605.70
1.00	Pc	Front fender RH	963.10		963.10
Labour & Misc:					
1.00		To check wheel alignment (computerised)	60.00		60.00
1.00		To dismantle and renew above parts	800.00		800.00
1.00		To spray paint	800.00		800.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

10,081.10
704.28
10,785.38

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Jenny Lim

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Sent: Wednesday, 9 May, 2018 8:23 AM
To: Jenny Lim
Subject: RE: Finalisation - SFV 8013Z / Volvo S60

L/Sump \$7650.00, 5days confirmed. Kenneth

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]
Sent: Thursday, 3 May, 2018 4:22 PM
To: Kenneth Kong (LKKAUTO)
Subject: Finalisation - SFV 8013Z / Volvo S60

Dear Sir

For your confirmation, please:

- Parts: \$8100.20
- L&P: \$1510.00

Sub-total: \$9610.20
LS -20%: (\$1922.04) = \$7688.16
Lump sum: \$7650.00 / 7 days

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG18002075/Kqd3e2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 24-10-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5916U	Veh. Inspected	SFV 8013Z
Policy No.		Coverage (\$)	0.00
Claim No.	XD5916U/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model	VOLVO S60 (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YV1RS494992734779	Colour	METALLIC GREY
Odometer	148907	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	7 mm
L/H Front Tyre	225/45 R17	PIRELLI	7 mm
R/H Rear Tyre	225/45 R17	PIRELLI	8 mm
L/H Rear Tyre	225/45 R17	PIRELLI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2018	Inspection Date	02/02/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 8013Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR RH (SN)	BENT	2,189.10	2,189.10
1	REAR DOOR PROTECTOR RH (SN)	BENT	316.70	316.70
1	REAR DOOR WEATHERSTRIP RH (SN) (50%)	NECESSARY	289.20	144.60
1	FRONT DOOR RH (SN)	DENTED / WARPED	2,408.00	2,408.00
1	FRONT DOOR PROTECTOR RH (SN)	DENTED	316.70	316.70
1	FRONT DOOR WEATHERSTRIP RH (SN) (50%)	NECESSARY	312.60	156.30
1	FRONT DOOR WING MIRROR ASSY RH (SN)	BROKEN	1,605.70	1,605.70
1	FRONT FENDER RH (SN)	BENT	963.10	963.10
			8,401.10	8,100.20
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT (COMPUTERISED).		60.00	60.00
	TO DISMANTLE AND RENEW ABOVE PARTS.		800.00	700.00
	TO SPRAY PAINT.		800.00	750.00
			1,660.00	1,510.00
	GRAND TOTAL		10,061.10	9,610.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,650.00

Report Ref No. CS/EGI18002075/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

