

22/03/2001

REF: CS3/MSG18002077/WD302

Range

Special Instructions:

ASS. REC. BY:

Surveyor

Mehmen

From (Person):

Wilson

Lionel Tan

ASSIGNMENT (Office)

of MSIG

Date/Time: 11/2/18 @ 2:32pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 91832

Insured:

SLB 8971S

at Workshop m/s

United SG Automobile

Tel:

9007 7556

of

53 Ubi Ave | #01-56

Policy No:

A2893937 QM Y

Claim No:

547913

Sum Insured:

Excess:

D.O.A. 27/01/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

5:15pm @ 11/2/18

Person Contacted:

Sean

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLT 91832 - X

SLB 8971S - X

Dismantle Part : 05/02/2018

After repair : 08/02/2018

REF: MSIG

## ASSIGNMENT

Date: 02/02/18

SLT 9183Z 18/9/2015

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLT 9183Z  
at Workshop No: United SG Automobile  
at 53 Ubi Ave 1 #01-56

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record):

Make of Vehicle:

(Policy Condition):

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR / Seen: Consistent?: Yes or No

Est. Repairs: days: Res: Yes or No

Cum. Sum: %: 3 Val: Yes or No

CA / REV / REP: 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Type: M/Cycle / Bus / Van / Lorry / Taxi / Pallet/Trailer

Truck / Trailer:

Make: Honda Mobilis, RS 1497

Color: Black - Insured: Std / N / NA

Go Reading: 46933

Eng No:

C No: MRHDD 48701P 000242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRIM / STD A/Rim or

Tyre Size: R: 185 / 65 R15

R: 185 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / R / SUMI

TOYO / YOKO or Dunlop

Front:

Rear:

R Bal: 4 R Bal: 4

L Bal: 4 L Bal: 4

DOA: 27/1/2018 DOA: 2/2/2018

Survey held at: At 14 Ave

Des. of Damages: Frt: Res: O/S N/S U/C Roof top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time / Action / Instruction

2/2/2018 No Accident Report Give  
→ chain collision.

Range \$7900 - \$8900

RECEIVED 9 APR 2018

Date/Time File Pass to:

09/04/2018



: Prelim. Report



: Final Report

Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transmission:

Fuel:

Oil:

Tire:

Wash:

Other:

Add Fee:

Ste. Mac:

Wash:

Tire:

Wash:

120

50

10

10

10

10

10

180

Report Format:

PR9

Cum. Sum: N/S

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		01 Feb 2018 14:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GAUWRI SKUMAR, ID: S8939183J, Tel: +6581985699		
Main Claimant:	TANG SOON THIAM, ID: S1703627J		
Vehicle Reg. No.:	SLT9183Z	Date of Loss:	27/01/2018 02:00 - :59
Claim Type:	TP / 547913	Policy/Cover Note No.:	A28939378QMY (Comprehensive) Coverage: 26/04/2017 - 25/04/2018
Vehicle Reg. No. (Insured):	SLB8971S	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/02/2018]		
Driver/Custodian (Insured):	GAUWRI SKUMAR (28 / Male), NRIC: S8939183J, Tel: +6581985699		
Adj Asg. Remarks:	Location - 53 UBI AVE 1 #01-56 PAYA UBI INDS PARK S(408934) Please contact MR SEAN LIAN @ 9007 7556 to arrange for survey .		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Iryani Amin

---

**From:** Jerone <jerone@chiaarul.com>  
**Sent:** Thursday, 1 February, 2018 1:42 PM  
**To:** Iryani Amin  
**Cc:** Lionel Tan  
**Subject:** RE: Our ref : M547913 ; Your ref : SLT9183Z(jr) & DOA : 27/01/2018

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Madam,

We noted on the contents of your email below.

As stated in our PRS Notice, our client's workshop details are as follows:

<b>Name:</b>	M/s United SG Automobile Pte Ltd
<b>Address:</b>	53 Ubi Avenue 1 #01 – 56, Paya Ubi Industrial Park Singapore 408934
<b>Contact Person:</b>	Mr. Sean Lian (H/p: 9007 7556)

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

**Mr. Jerone Lee**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Iryani Amin [mailto:iryani\_amin@sg.msig-asia.com]  
**Sent:** Thursday, 1 February, 2018 1:13 PM  
**To:** Jerone <jerone@chiaarul.com>  
**Cc:** Lionel Tan <lionel\_tan@sg.msig-asia.com>  
**Subject:** RE: Our ref : M547913 ; Your ref : SLT9183Z(jr) & DOA : 27/01/2018  
**Importance:** High

Dear Mr Jerone Lee ,

We refer to your list of surveyors submitted to us dated 01/02/2018

We regret to inform you that we are unable to accept your list of nominated Single Joint Experts( SJE)

We will proceed to appoint the following surveyor, **LKK AUTO CONSULTANTS PTE LTD** for your claim.

Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

**Kindly provide us the workshop name & address . Thank you**

Have a nice day

Iryani Binte Amin  
Admin Officer, Claims Services (Motor)  
Direct line +65 6594 2555 | Direct fax +65 6225 7402 | [iryani\\_amin@sg.msig-asia.com](mailto:iryani_amin@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



A member of **MS&AD** INSURANCE GROUP

**From:** Jerone [<mailto:jerone@chiaarul.com>]  
**Sent:** Thursday, 1 February, 2018 11:54 AM  
**To:** Iryani Amin <[iryani\\_amin@sg.msig-asia.com](mailto:iryani_amin@sg.msig-asia.com)>  
**Cc:** Lionel Tan <[lionel\\_tan@sg.msig-asia.com](mailto:lionel_tan@sg.msig-asia.com)>  
**Subject:** RE: Our ref : M547913 ; Your ref : SLT9183Z(jr) & DOA : 27/01/2018

O/Ref: SLT 9183Z (Jr)  
Y/Ref: M547913

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Madam,

We thank you for your email below.

Kindly be informed that our client is not agreeable to your list of surveyors and we hereby propose the following:

<u>Name of Surveyor</u>	<u>Company</u>
Winson Goh	WG Appraisal Services

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

**Mr. Jerone Lee**  
M/s Chia S Arul LLC  
151 Chin Swee Road  
#03-09 Manhattan House  
Singapore 169876  
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted,

lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Iryani Amin [[mailto:iryani\\_amin@sg.msig-asia.com](mailto:iryani_amin@sg.msig-asia.com)]  
**Sent:** Thursday, 1 February, 2018 11:14 AM  
**To:** [jerone@chiaarul.com](mailto:jerone@chiaarul.com)  
**Cc:** Lionel Tan <[lionel\\_tan@sg.msig-asia.com](mailto:lionel_tan@sg.msig-asia.com)>  
**Subject:** Our ref : M547913 ; Your ref : SLT9183Z(jr) & DOA : 27/01/2018  
**Importance:** High

Dear Mr Jerone Lee ,

We would like to appoint the following surveyor, **LKK AUTO CONSULTANTS PTE LTD** for your claim.

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You han
- 8) Gary Soon
- 9) Chow Bo Xiong
- 10) Benjamin Chua





In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol

Have a nice day

**Iryani Binte Amin**  
Admin Officer, Claims Services (Motor)  
Direct line +65 6594 2555 | Direct fax +65 6225 7402 | [iryani\\_amin@sg.msig-asia.com](mailto:iryani_amin@sg.msig-asia.com)



**MSIG Insurance (Singapore) Pte. Ltd.** 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of **MS&AD** INSURANCE GROUP

---

**From:** Muhd Ashik B Madi  
**Sent:** Thursday, 1 February, 2018 10:40 AM

To: Iryani Amin <iryani\_amin@sg.msig-asia.com>; Lionel Tan <lionel\_tan@sg.msig-asia.com>  
Cc: Fievel Foo <Fievel\_Foo@sg.msig-asia.com>; jerone@chiaarul.com  
Subject: FW: PRS Notice for SLT 9183Z & SLB89715

Dear Yani,

For your necessary action.

Thank you.

**Ashik Madi**

Executive, Claims Services (Motor)

Direct line +65 6594 2548 | Direct fax +65 6225 7402 | [ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

From: Jerone [<mailto:jerone@chiaarul.com>]

Sent: Thursday, 1 February, 2018 10:34 AM

To: Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

Cc: Muhd Ashik B Madi <[ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)>; Fievel Foo <[Fievel\\_Foo@sg.msig-asia.com](mailto:Fievel_Foo@sg.msig-asia.com)>

Subject: PRS Notice for SLT 9183Z

O/Ref: SLT 9183Z (Jr)

Y/Ref: TBA

Dear Sirs,

We refer to the above matter.

Kindly find the PRS Notice for your attention.

Please feel free to contact us should you have any queries thereof.

Yours faithfully,

**Mr. Jerone Lee**

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted,

lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/01/2018 12:12
Date Of Accident	27/01/2018 02:30
Exact Location Of Accident	SEBBAWANG RD TWDS CHONG PANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT9183Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TANG SOON THIAM
NRIC No	S1703627J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97647146
Alternative Phone No	OFFICE-97647146

### Vehicle Particulars

Manufacturer	HONDA
Model	MOBILIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA299423/1
Cover Note Number	

### Driver

Name of Driver	TANG SOON THIAM
NRIC No	S1703627J
Date Of Birth	11/11/1965
Occupation	INDOOR
Date Of Driving Pass	18/07/1990
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97647146
Fax Number	
Contact Number	OFFICE-97647146
Email Address	NOEMAIL

Address	14A GALISTAN AVENUE
Postcode	669692
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIAW SHIRLEY
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY CAR WAS STATIONARY ALONG SEMBAWANG ROAD TOWARDS CHONG PANG TRAFFIC LIGHT WHILE WAITING FOR THE RED LIGHT TRAFFIC TO TURN GREEN. SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR. THE IMPACT WAS SO BIG THAT IT CASUED MY VEHICLE TO MOVE FORWARD, HIT ON THE VEHICLE IN FRONT. I GET DOWN AND REALISED 3 VEHICLES WERE INVOLVED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT8064A
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLB8971S  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE C  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name TANG SOON THIAM  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLT9183Z  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

29/1/12 11.20 AM  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS STATIONARY ALONG SEMBAYANG RD TOWARDS CHONG PANG  
TRAFFIC LIGHT WHILE WAITING FOR THE TRAFFIC LIGHT TO TURN GREEN.  
SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR. THE IMPACT WAS SO BIG  
THAT IT CAUSED MY VEHICLE TO MOVE FORWARD & HIT ON THE VEHICLE IN  
FRONT. I GET DOWN & REALIZED 3 VEHICLE WAS INVOLVES.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		01 Feb 2018 14:32 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>GAUWRI SKUMAR</b> , ID: S8939183J, Tel: +6581985699									
Main Claimant: <b>TANG SOON THIAM</b> , ID: S1703627J									
Vehicle Reg. No.: <b>SLT9183Z</b>		Date of Loss: 27/01/2018 02:00 - :59 [29 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 547913</b>		Policy/Cover Note No.: A28939378QMY (Comprehensive) Coverage: 26/04/2017 - 25/04/2018							
Vehicle Reg. No. (Insured): <b>SLB8971S</b>		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: <b>United SG Automobile Pte Ltd (HQ)</b> 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Lionel Tan Tian Pei</b> - 6643 1307]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Teo Cheng Ming Wilson</b> ] ... [Imm.Advice due 02/02/2018]									
Driver/Custodian (Insured): GAUWRI SKUMAR (28 / Male), NRIC: S8939183J, Tel: +6581985699									
Adj Asg. Remarks: Location - 53 UBI AVE 1 #01-56 PAYA UBI INDS PARK S(408934) Please contact MR SEAN LIAN @ 9007 7556 to arrange for survey .									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLT9183Z (547913)  
[SLB8971S]  
TP  
TANG SOON THIAM  
Jan 27 2018 2:00AM  
[GAUWRI SKUMAR]  
United SG Automobile Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)



















































**View** [View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/18 11:25	<b>Accident Statement</b> <small>From: SC - Reg. No: SLB8971S, Claimant: GAUWRI SKUMAR</small>	Load HTM	
















































  



















































Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
32	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>
33	09/04/18 16:23	General View	Load JPG	<input checked="" type="checkbox"/>



















































































Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
71	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
72	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
73	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
74	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
75	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
76	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
77	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
78	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
79	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
80	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
81	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
82	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
83	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
85	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
86	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
87	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
88	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
89	09/04/18 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
90	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
138	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
160	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
161	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
162	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
163	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
164	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
165	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
166	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
167	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
168	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
169	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
170	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
171	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
172	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
173	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
174	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
175	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
176	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
177	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
178	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
179	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
180	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
181	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
182	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
183	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
184	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
185	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
186	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
187	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
188	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
189	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
190	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
191	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
192	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
193	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
194	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
195	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
196	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
197	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
198	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
199	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
200	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
201	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
202	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
203	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
204	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
205	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
206	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
207	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
208	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
209	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
210	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
211	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
212	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
213	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
214	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
215	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
216	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
217	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
218	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
219	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
220	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
221	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
222	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
223	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
224	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
225	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
226	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
227	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
228	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
229	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
230	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
231	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
232	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
233	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
234	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
235	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
236	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
237	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
238	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
239	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
240	09/04/18 16:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
241	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
242	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
243	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
244	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
245	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
246	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
247	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
248	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
249	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
250	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
251	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
252	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
253	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
254	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
255	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
256	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
257	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
258	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
259	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
260	09/04/18 16:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/18 11:25	TPD SLT9183Z GIA REPORT (2/3) From: SC - Reg. No: SLB89715, Claimant: GAUWRI SKUMAR	 Load PDF	
2	01/02/18 11:27	TPD SLT9183Z - SURVEY LETTER	 Load PDF	
3	01/02/18 14:33	TPD SLT9183Z - PRI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18002077/WD3E2

Date: 10/04/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28939378QMY

Claimant Vehicle No: SLT9183Z

Insured Vehicle No: SLB8971S

Date of Loss: 27/01/2018

Nature of Claim: TP

Claim No: 547913

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLT9183Z

Make &amp; Model: HONDA MOBILIO SV, 1.5 CVT (A)

Engine No: L15Z12101067

Reg. Date: 18/08/2015 (Man. Year: 2015)

Chassis No: MRHDD4870FP000242

Colour: Black

Odometer: 46933 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 01/02/2018

Date Inspected: 02/02/2018 Inspected At:

United SG Automobile Pte Ltd (HQ)  
53 Ubi Avenue 1, #01-56 Paya Ubi  
Industrial Park  
Singapore 408934

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,900.00 - \$8,900.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
<b>Parts:</b>	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT9183Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >