

22/05/2002

ASS. REC. BY:

REF: CS/MSG18002086/ A v d3 ⁷²

Special Instruction:

Surveyor:

Merimen

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSIG

Date/Time: 11/2/18 @ 12.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 5529A

Insured:

XD 7869J

at Workshop m/s

PH Auto Services

Tel:

9271 2214

of

1 Kaki Bkt Ave 6 # 01-107

Policy No:

A28624722MKF

Claim No:

547929

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

5.12pm 01/02/18

Person Contacted:

Chns

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GX5529A - NJA / INC10023012 / y

D.O.A: 1/10/2010

XD 7869J - CS/MSG17024132 / Kvd3

D.O.A: 18/12/2017

6/2/18

Informed Ashik pending workshop est by merimen

11/4/18

Adrian confirmed IS \$ 2500 (Red 10,986.19, 81%)

12/4/18

Send preli revised by merimen

Survivor

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:			
IDAC Accident Rpt:		Consistent?	Yes or No
GIA / PR Seen:		Consistent?	Yes or No
Est. Repairs:	days	Res.:	Yes or No
Lum Sum:	%	3 Val.:	Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: Gx5529A Yr Regn: 2004 July
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or Pick Up
Make: Nissan Double Cab c.c. 2664
Colour: silver A/C: Insured / Std / NI / NA
Sp. Reading: 380620 T/Radio: Insured / Std / NI / NA
Eng/No: JN1CH6D22Z0073313
C/No: JN1CH6D22Z0073313
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185R14C BS
R: 185R14C Thunderer

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front
R/Bal. 06 mm
L/Bal. 06 mm
D.O.A. _____
Survey held at PH
Des. of Damages : Frt / Rear / (O/S) / N/S / U/C / Rooftop or

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP MSL6.
	MV: 18K
	TV: 5.7K
	Next: 12.3K.
	RECEIVED 12 APR 2018

Date/Time: File Pass to?

☐: Prel. Report

13

☐: Final Report

Date/Time, File Return to?

2) 12/4 - typist

Report Format : merimen

Lump Sum / I.B.I: (\$) 2500/-

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$

☐ Interview (\$

Tech. Invs (\$)

☐ Weekend (\$

Survey Fee:

Transportation

$$S \rightarrow RS, \quad S$$

) Photos

Others

TOTAL

300

10

310

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/18002086/Ave/3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18002086/Avd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 02-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 7869J	Veh. Inspected	GX 5529A	
Policy No.	A28624722MKF	Coverage (\$)	0.00	
Claim No.	547929	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	02/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018	Inspection Date		
Survey held at	PH AUTO SERVICES 1 KAKI BUKIT AVE 6 #01-96 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Muhd Ashik B Madi	Date: 12 Apr 2018

Preliminary Advice

Insured Vehicle No	: XD7869J		
TP Vehicle No	: GX5529A	Accident Date	: 29/01/2018
Make	: NISSAN CABSTAR	Assignment Date	: 01/02/2018
Date of Inspection	: 05/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: PH AUTO SERVICES (HQ) 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,486.10
Revised Amount	:S\$	2,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2018		01 Feb 2018 12:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG FU CONSTRUCTION PTE LTD , Co. Reg. No.: 199003776H		
Main Claimant:	RENTZ , Co. Reg. No.: 53193294W		
Vehicle Reg. No.:	GX5529A	Date of Loss:	29/01/2018 08:00 - :59
Claim Type:	TP / 547929	Policy/Cover Note No.:	A28624722MKF (Comprehensive) Coverage: 28/10/2017 - 27/10/2018
Vehicle Reg. No. (Insured):	XD7869J	Policy No. (Claimant):	
		Excess:	
Repairer:	Ph Auto Services (HQ) 1 Kaki Bukit Avenue 6 #01-107 Autobay @ KB, 417883 Kaki Bukit - Tel: 92712214		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/02/2018]		
Driver/Custodian (Insured):	CHIA CHEE KHIANG (), NRIC: S7250479H, Tel: +6587208046		
Adj Asg. Remarks:	request Adrian Ling for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Eileen Ang

From: Pang Xiu Shi
Sent: Thursday, 1 February, 2018 11:41 AM
To: Eileen Ang
Cc: Muhd Ashik B Madi
Subject: FW: GX5529A & XD7869J DOA 29.01.2018
Attachments: file-6.jpeg; file1.jpeg; file-5.jpeg

Hi Eileen,

For your next action please. Thank You!

Have a great week ahead!

Pang Xiu Shi
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2586 | Direct fax +65 6225 7402 | xiushi_pang@sg.msigg-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Thursday, 1 February, 2018 11:32 AM
To: Pang Xiu Shi <xiushi_pang@sg.msigg-asia.com>
Subject: GX5529A & XD7869J DOA 29.01.2018

Dear Xiushi,

Enclosed is our client's report & scene photos.

The scene photos show that our client's car was stopped in his own lane due to in front car stopped. (can see in scene photo the front car stopped)

Your insured lorry too big & squeeze, cut into our lane & caused accident.

Please advise your OIC & claim, liability.

Please let us have your 10 name list of surveyor to survey our client's car no : GX5529A

Regards,
Chris Chan Pick Yuen
PH AUTO SERVICES
1 KAKI BUKIT AVENUE 6
01-107 AUTOBAY @KB
SINGAPORE 417883
HP: 92712214

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

View Sent Message

This mail is associated with :

***GX5529A (547929)**
[XD7869J]

TP

RENTZ

Jan 29 2018 8:00AM

[HONG FU CONSTRUCTION PTE LTD]
Ph Auto Services

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **06/02/2018 11:10 AM.**
To MSI_ASHIK
Subject TP SURVEY GX 5529A

Dear Ashik,

Please be informed that we have inspected the vehicle GX 5529A on 5/2/2018 .

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.



ANNOUNCING Roadlink Auto Pte Ltd as sgCarMart Premium Dealer 2018



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Year COE Renewal, Toyota Estima 2.4A.



\$6800 Downpayment Monthly,
From \$938 Onwards. Lowest
3.68% P.A. 0% Car Financing.
GV Credit Pte Ltd StarAd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

8 vehicles

nissan pick

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	nissan pick		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan Double-Cab Pickup (COE till 02/2022)	\$28,800	\$7,080 /yr	17-Nov-2000	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
	Rebate Of Minimum \$6236 On Lifespan Expiry. Well Maintained.							DIRECT OWNER	
	Posted: 04-Feb-2018 Tags: 2000 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
	Nissan Double-Cab Pickup (COE till 04/2022)	\$30,800	\$7,310 /yr	24-Apr-2002	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
	Guarantee COE Rebate Of At Least \$3200 At The End Of 2022. Actual Depreciation Of \$6700/Yr Only! Most Reliable And Durable Double Cab Pickup. Excellent Engine, Interior, Alcon. Well Maintained Leather...								
	Posted: 26-Jan-2018 Tags: 2002 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
	Nissan Double-Cab Pickup (COE till 02/2022)	\$26,900	\$6,620 /yr	23-Aug-2002	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
								DIRECT OWNER	
	Posted: 20-Jan-2018 Tags: 2002 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
	Nissan Double-Cab Pickup (COE till 04/2022)	\$32,800	\$7,750 /yr	03-Apr-2003	2,664 cc	395,900 km	Truck	Available	
	Fuel Type: Diesel								
	Think One Automobile & Trading								
	Posted: 18-Dec-2017 Tags: 2003 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
<div>Car Buying</div> <div>Car Selling</div> <div>Car Aftermarket</div> <div>Car Ownership</div> <div>On The Move</div> <div>Lifestyle</div>									
	Nissan Double-Cab Pickup (New 5-yr COE)	\$37,800	\$7,560 /yr	12-Jan-2004	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
	1 Owner. Durable Nissan Double Cabin Pickup With Silent Powerful TD27 Engine. New Paintwork And Upholstery Just Done. New 5 Years COE Extended Till March 2023.							PREMIERED	
	Posted: 09-Jan-2018 Tags: 2004 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
	Nissan Double-Cab Pickup (COE till 06/2019)	\$18,800	\$14,240 /yr	03-Jun-2004	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
	1 Owner Only. Double Cab Pick-up. Comes With Rear Aluminium Checkered Plate. New Paintwork And Upholstery. Can Renew Another 5 Year COE After Current COE Expires.								
	Posted: 28-Jan-2018 Tags: 2004 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan								
	Nissan Double-Cab Pickup (COE till 03/2020)	\$36,800	\$17,510 /yr	14-Mar-2005	2,664 cc	-	Truck	Available	
	Fuel Type: Diesel								
	Company Which Do Not Carry Heavy Stuffs. Well Maintained By Owner With No Repair Needed. Hurry Before It's Gone. Best Price For The Best Pick								

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3294W
Vehicle Details	
Vehicle No.:	GX5529A
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Feb 2018
Vehicle Make:	NISSAN
Vehicle Model:	P/UP D/CAB
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	TD27737149
Chassis No.:	JN1CHGD22Z0073313
Maximum Power Output:	-
Open Market Value:	\$19,639.00
Original Registration Date:	02 Jul 2004
First Registration Date:	02 Jul 2004
Transfer Count:	3
Actual ARF Paid:	\$21,603.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$5,729.00
Total Rebate Amount:	\$5,729.00
Message	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 3294W

Vehicle Details

Vehicle No.: GX5529A

Vehicle to be Exported: Yes

Intended De-registration Date: 05 Feb 2018

Vehicle Make: NISSAN

Vehicle Model: P/UP D/CAB

Primary Colour: Silver

Manufacturing Year: 2004

Engine No.: TD27737149

Chassis No.: JN1CHGD22Z0073313

Maximum Power Output: -

Open Market Value: \$19,639.00

Original Registration Date: 02 Jul 2004

First Registration Date: 02 Jul 2004

Transfer Count: 3

Actual ARF Paid: \$21,603.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 01 Jul 2019
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$20,383.00
COE Rebate Amount: \$5,729.00
Total Rebate Amount: \$5,729.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 05 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/01/2018 08:40
 Date Of Accident 29/01/2018 08:30
 Exact Location Of Accident CLEMENTI AVE 6
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GX5529A
Insured/Policyholder
 Name Of Registered Owner RENTZ
 Co Reg No 53193294W
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-90223258
 Alternative Phone No OFFICE-90223258

Vehicle Particulars

Manufacturer NISSAN
 Model CABSTAR-2.0 (M)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number 5072303359-02
 Cover Note Number

Driver

Name of Driver YEO KOK GUAN
 NRIC No S8512885Z
 Date Of Birth 15/04/1985
 Occupation OUTDOOR
 Date Of Driving Pass 18/05/2005
 Driving Experience 12 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90223258
 Fax Number
 Contact Number OFFICE-90223258
 EMail Address NOEMAIL

Address 431 CLEMENTI AVE 3
#01-320
Postcode S120431
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : -
GENDER: : FEMALE
Passenger 2 NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD7869J
Vehicle Make/Model/Colour TRUCK
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

30 JAN 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/01/18, 05:47pm

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Along Clementi Avenue 6 at traffic light junction near the bus stop.

While waiting stationary at the traffic light junction on the left lane. Driver of truck (XD7869J) driving on the middle lane got too close and scraped the right back of my vehicle (GK5529A) causing a tear of approximately 1/2 meter and damages on the right light.

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/01/18 08:45am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IDAC: BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

30 JAN 2018

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Sheet1
PH AUTO SERVICES

BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883
Tel : (65) 69664526 HP: 92712214 Fax: (65) 67476918

RENTZ

Bik 3020A Ubi Road 1
01-33
Singapore 408717

05th FEBRUARY 2018

Accident date: 29th JANUARY 2018

Estimated repair cost for vehicle no: GX5529A NISSAN

S/n	Qty	Items	U/price	Amount
1	2	Rear boot lid side lock-RH	\$183.20	\$366.40
2	1	Rear boot lid		\$1,688.40
3	1	Rear center lower crossmember		\$650.00
4	1	Rear Bumper		\$950.00
5	1	rear side RH tail gate		\$2,800.00
6	1	Rear side RH tail gate aluminium cover		\$1,209.50

Subtotal :- \$7,664.30

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear Boot Lid Top Side Hinge-RH	\$183.20	\$366.40
2	1	Rear boot lid lower side hinge -RH	\$201.30	\$201.30
3	1	rear step panel		\$450.00
4	1	Rear end panel		\$1,150.00
5	1	Rear tail lamp-RH		\$255.00
6	1	Rear tail lamp panel-RH	\$181.10	\$181.10

Subtotal :- \$2,603.80

S/n	Qty	Items/S/Nett	U/price	Amount
1	1	Rear boot lid 70 km/h logo		\$30.00
1	1 SET	rear reverse sensor		\$300.00
2	1	Rear boot lid lower nissan logo		\$108.00

Subtotal :- \$438.00

Labour charges

To remove & re-fix RH side panel &
rear aluminium cover

~~\$300.00~~ 120

To Check Wiring System

1050

~~\$80.00~~ 30

Panel beating

~~\$1,200.00~~ 600

Spray painting

~~\$1,200.00~~ 300

Subtotal :- \$2,780.00

Total:- \$13,486.10

total 312862
4/5: 2.5K
05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002086/AVD3N2

Date: 13/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28624722MKF
Claimant Vehicle No :	GX5529A	Insured Vehicle No :	XD7869J
Date of Loss:	29/01/2018	Nature of Claim:	TP
		Claim No:	547929

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX5529A	Engine No:	TD27737149
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Chassis No:	JN1CHGD22Z0073313
Reg. Date:	02/07/2004 (Man. Year: 2004)	Odometer:	380620 km
Colour:	Silver		
Engine Capacity:	2664 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14C	Rear Tyre Size:	185 R14C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Thunderer 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Thunderer 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,706.10	2,078.62	8,627.48	80.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,050.00	1,730.00	62.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,486.10	3,128.62	10,357.48	76.80
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	13,486.10	2,500.00	10,986.10	81.46

INSPECTION

Date of Assignment:	01/02/2018	
Date Inspected:	05/02/2018 Inspected At:	Ph Auto Services (HQ) 1 Kaki Bukit Avenue 6 #01-107 Autobay @ KB Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Apr 2018)
Parts:	N/A NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX5529A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	2	*REAR BOOT LID SIDE LOCK-RH	Not Necessary	366.40 F	*- FL
2	1	*REAR BOOT LID	Not Necessary	1,688.40 F	*- FL
3	1	*REAR CENTER LOWER CROSSMEMBER	Not Necessary	650.00 F	*- FL
4	1	*REAR BUMPER	Dented	950.00 F	*791.60 FL
5	1	*REAR SIDE RH TAIL GATE	Dented	2,800.00 F	*1,850.00 FL
6	1	*REAR SIDE RH TAIL GATE ALUMINIUM COVER	Not Necessary	1,209.50 F	*- FL
7	2	*REAR BOOT LID TOP SIDE HINGE-RH	Not Necessary	366.40 F	*- FN
8	1	*REAR BOOT LID LOWER SIDE HINGE-RH	Not Necessary	201.30 F	*- FN
9	1	*REAR STEP PANEL	Not Necessary	450.00 F	*- FN
10	1	*REAR END PANEL	Not Necessary	1,150.00 F	*- FN
11	1	*REAR TAIL LAMP-RH	Cracked	255.00 F	*255.00 FN
12	1	*REAR TAIL LAMP PANEL-RH	Not Necessary	181.10 F	*- FN
13	1	*REAR BOOT LID 70 KM/H LOGO	Not Necessary	30.00 FS	*- FS
14	1	*SET REAR REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
15	1	*REAR BOOT LID LOWER NISSAN LOGO	Not Necessary	108.00 FS	*- FS
				Sub Total (\$\$)	10,706.10 2,896.60
				- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00 792.48
				- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 25.50
				Total Parts (\$\$)	10,706.10 2,078.62

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RE-FIX RH SIDE PANEL & REAR ALUMINIUM COVER	New	300.00	120.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	PANEL BEATING	New	1,200.00	600.00
4	SPRAY PAINTING	New	1,200.00	300.00
Gross Labour Cost (S\$)			2,780.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >