

(08/11/13) , wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est/ Repairs:

13

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G BE 46604

Yr Regn:

12/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C

2982

Colour:

yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

77925

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 201 5019304

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-12.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/1/18

D.O.I.

2/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 32536

7pm 11 m/s.

Ajay inc

act 27444

L/S & 18.00 (Red to 16.04.30, 47.1)

Date/Time, File Pass to?

☐

Preli. Report

1) 16/5 Typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

13

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Acknowledged by Repairer

Signature:

Date:

24x15

170 + 360

50

50

80

174

884

Ref. No :	CSTP18002096/1446 ⁿ²		Res. Date:	2/2/18	Date Received:	
Veh. No :	GBE 460Y		SP:		WKSP:	<i>[Signature]</i>
C/No :						
Action/Instruction:						
1. File	2. Submit Photo?	YES / NO				
3. Indicate Res. Date On Photo Page?	YES / NO		Message:			
If No, due to	a) No authorisation	b) Days of repair				
others:						
			<i>[Signature]</i>			
Final Re-inspection	or	Progress Photos	Inspected By:			

MY1218015238 / Yaw Tee Automobile Tech Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 31/01/2018 13:15
 SUBMITTED BY: Ton Lei Ming

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report accurately the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 31/01/2018 13:15
 Date Of Accident 30/01/2018 10:30
 Exact Location Of Accident AYE TOWARDS CTE BEFORE CLEMENTI AVE 2 EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE4650Y
 Insured/Policyholder
 Name Of Registered Owner S&H EXPRESS
 Co Reg No 53271677M
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-83387296
 Alternative Phone No OFFICE-83387296
 Vehicle Particulars
 Manufacturer TOYOTA
 Model HIACE
 Exact Purpose for which vehicle was being used at time of accident WORK USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE
 Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5095913586
 Cover Note Number
 Driver
 Name of Driver AHMAD SHAIRUL BIN MAWI
 NRIC No S86077151
 Date Of Birth 23/03/1986
 Occupation OUTDOOR
 Date Of Driving Pass 20/02/2013
 Driving Experience 4 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83387296
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address APT BLK 107A CANBERRA STREET #02-561
 Postcode 751107
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD3820K
 Vehicle Make/Model/Colour NISSAN LORRY BLUE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver DONG JIANZHOU
 NRIC/Passport Number G2723151P
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	G3F5886Y
Vehicle Make/Model/Colour	TOYOTA VAN YELLOW
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ABDUL MUN'IM BIN MANSOR
NRIC/Passport Number	S9225999D
Contact Number	83634492
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	AHMAD SHAIRUL BIN MAWI
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	GBE4650Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when required.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

S&H EXPRESS
1830 RIVERVALE CRESCENT
#05-215 SINGAPORE (544167)
TEL: 8338 7296
CO. REG. 832716771

Policyholder's Signature

Date & Time: 31/1/18, 12pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 31/1/18, 12pm


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Report to Police Report

DECLARATION
I/We hereby declare that the particulars are true in every respect.
TEL: 8338 7256
CO. REG. 53271677

Policyholder's Signature
Date & Time: 31/1/18, 12pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/1/18, 12pm

Reporting Centre Personnel's Signature
Name:
NRJC/FIN No.:

GIAMAC SketchPlan_v3



SINGAPORE POLICE FORCE



T/20180131/2026

1 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No, T/20180131/2026

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/01/2018 10:57	Vide Report No.:	Station Diary No.: 47
--	------------------	--------------------------

Informant's Particulars

Name of Informant: AHMAD SHAIRUL BIN MAWI			Address: APT BLK 107A CANBERRA STREET #02-561 SINGAPORE 751107		
ID Type / ID No.: NRIC NO / S86077151			Contact No.: Home/Office: Mobile: 83387296		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 23/03/1986	Type of Informant: Driver		
Race: Boyanesese			Language:		Institution / School Name:
Occupation: Postal/Courier service supervisor			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 30/01/2018 10:30	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE towards CTE before Clementi Ave 2 exit Lane 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD3820K	Lorry	NISSAN		Blue	Slightly Damaged	0
GBE4650Y	Van	TOYOTA		Yellow	Slightly Damaged	0
GBF5886Y	Van	TOYOTA		Yellow	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180131/2026

2 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No, T/20180131/2026

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	DONG JIANZHOU	ID No.	G2723151P
Related Vehicle	GBD3820K (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	AHMAD SHAIRUL BIN MAWI	ID No.	S8607715I
Related Vehicle	GBE4650Y (Van)	Contact No.	83387296
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	09	Degree of Injury	Slight
Driver			
Name	ABDUL MUN'IM BIN MANSOR	ID No.	S9225999D
Related Vehicle	GBF5886Y (Van)	Contact No.	83634492
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 30/1/18 at about 1030hrs, I was driving my van, GBE4650Y, a yellow Toyota, along AYE towards CTE, in lane 2. When the traffic turned heavy, I slowed to a stop in lane 2, behind my colleague's van, GBF5886Y, a yellow Toyota. While I was stationary, I suddenly felt an impact from my rear. My vehicle was pushed forward and as a result, my van hit my colleague's van in the rear.

I alighted and met my colleague Abdul Mun'im Bin Mansor HP: 83634492 who informed that he was not hurt. We also met with the driver of the blue lorry behind me, GBD3820K, whom also alighted and appeared uninjured. Only the 3 mentioned Singapore-registered vehicles were involved in this accident.



**SINGAPORE
POLICE FORCE**



T/20180131/2026

3 of 4

Police Station Of Origin:

Yishun North N.P.C

31 Yishun Central SINGAPORE 768827

Tel No: 1800-8529999

Report No, T/20180131/2026

CONTINUATION OF REPORT

No other property was damaged. As we all did not require immediate medical attention, we exchanged particulars and an Auxiliary Police Officer came and advised us to move to a safer location. We later drove off to a nearby carpark escorted by the officer. Once at the carpark, I lodged a report through the NTUC Orange Force rider who was there and called for a tow truck to tow my van to a workshop. My colleague and the lorry driver drove off from the location.

No traffic police nor ambulance came to scene. I later went to Change Hospital and was given 9 days MC. There is an in-vehicle camera in my van which was recording at the time of the incident. I did not get the lorry driver's contact number. This is the first time I met the lorry driver.



**SINGAPORE
POLICE FORCE**



T/20180131/2026

4 of 4

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

Report No. T/20180131/2026

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt SZE WEIJIE, WILSON 	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 31/01/2018 10:57
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BINTE BOHARI Contact No.: 65476219	Classification Of Case:
Authentication Stamp NP168 	 Signature: Singapore Police Force

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1677M
Vehicle Details	
Vehicle No.:	GBE4650Y
Vehicle to be Exported:	No
Intended De-registration Date:	02 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 M
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2553845
Chassis No.:	KDH2015019304
Maximum Power Output:	-
Open Market Value:	\$30,383.00
Original Registration Date:	18 Dec 2015
First Registration Date:	18 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$1,520.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,349.00
COE Rebate Amount:	\$32,556.00
Total Rebate Amount:	\$32,556.00

The information contained herein is correct as at 02 Feb 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 Nissan Qashqai 1.2A DIG-T Premium @ \$95800 Only



CNY Promotion, 5 Yrs Unlimited
Mileage Warranty, Free Solar
Film, Call Now!!!
Global Carz Pte Ltd StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted


20 results/page

5 vehicles

Toyota Hiace

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace		Any	Any	2015	Any	Any	Any	Available
	Toyota Hiace		\$64,800	\$8,460 /yr	01-Oct-2015	2,982 cc	-	Van	Available
Fuel Type: Diesel Last Call Before We Rent Out, Price Dropped, Fire Sales, View To Offer, Brand New Condition, Still Under Agent Warranty, Mileage Only 65305Km With Agent Record, View Now!									
Posted: 29-Jan-2018 Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota Hiace Commuter		\$95,800	\$12,120 /yr	28-Dec-2015	2,982 cc	-	Bus	Available
Fuel Type: Diesel Please Call To Arrange For Viewing, Thanks.									
Posted: 15-Jan-2018 Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota Hiace		\$62,800	\$8,020 /yr	02-Dec-2015	2,982 cc	38,500 km	Van	Available
Fuel Type: Diesel One Owner Only! 100% Accident Free. Lowest Depreciation In The Market. Well Maintained With Low Mileage Done! Call For A Viewing Appointment Now.									
Posted: 18-Dec-2017 Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
	Toyota Hiace		\$63,800	\$8,270 /yr	19-Oct-2015	2,982 cc	52,000 km	Van	Available
Fuel Type: Diesel Full Bodykit, Spoiler With Brake Light, CF Bonnet, CF Front Grills, Piano Black Dashboard Panels, Dual Projector Headlamp, BMW Tail Lights, CF Do Or Handles, Merc Retractable Side Mirrors, 17" Lenso S...									
Posted: 11-Dec-2017 Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									
<div> <div>Car Buying</div> <div>Car Ownership</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Aftermarket</div> <div>Lifestyle</div> </div>									
	Toyota Hiace		\$64,800	\$8,200 /yr	29-Dec-2015	2,982 cc	-	Van	Available
Fuel Type: Diesel Accident Free. Very Good Condition, 100% Loan Available, Low Interest, High Trade In Welcome. Call For Viewing.									
Posted: 08-Dec-2017 Tags: 2015 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota									



Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Compare



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-51/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwei2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

not Afford
 2/5 @ 18,000
 13 day.

GRE46507

	Rear windscreen	SW	1255.10	✓
	Rear windscreen moulding	nc	110.10	✓
	Tailgate	W/Sat	1969.30	✓
	Tailgate outer handle	gord	248.50	✓
	Tailgate inner lock	W/SM	359.20	✓
	Tailgate lock striker	twl	66.50	✓
	Tailgate weatherstrip	twl	387.30	✓
	Tailgate inner trim board	11	480.00	X
1set	Tailgate inner trim board clips	11	45.00	X
	Rear end panel outer	body	506.10	✓
	Rear end panel inner	body	936.20	✓
	Rear end panel top plate	But	269.50	✓
	tail lamp filter panel nls	body	345.10	✓
	Rear exhaust	R	971.10	X
	Tailgate rear logo	nc	60.50	✓
	Tailgate 'hvac' emblem	nc	66.20	✓
	Rear spare tyre carrier	11	392.30	X
	Rear Lender	R	1419.70	X
	tail lamp lower garnish nls	twl	169.30	✓
	front bumper beam top	but	166.20	✓
	front bumper reinforcement	but	380.40	✓
2py	headlamp assy 'H10' @ 2950	one	2900.00	✓ 4900
	Bonnet	R	1050.00	X
2py	Bonnet hinges @ 115.00	but	230.00	✓
	Bonnet lock	twl	28.90	✓
	front support panel	R	348.80	X
	Air con condenser	11	1431.10	X
	Radiator assy	11	2110.20	X
			21672.40	21822.40
		less 25%	16254.30	

12574.2



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

S. Nott GRC 4650Y

	front bumper sport	one	3200.00	2600
	front bumper centre grille	two	280.00	✓
2pc	front corner panels f.b.e @600	1/scene	1200.00	170
	wiper panel top f.b.e	material/one	480.00	✓
	front licence plate w/holder	set	50.00	40
	Bonnet 'DHL' logo	one	180.00	100
	Rear bumper sport	one	3200.00	2600
	Rear exhaust chrome pipe	set	200.00	100
2pc	taillamps sport a b f d	one	1360.00	✓
	Rear windscreen sealant	one	50.00	40
	Rear windscreen solar film	one	180.00	150
1set	Rear reverse camera	short	380.00	300
1set	Rear video cam	shs/mis	500.00	✓
1set	Tailgate corporate sticker	one	180.00	✓
	Tailgate top spoiler	one	600.00	X
	To check wiring		80.00	-30
	To dismantle & replacing rear windscreen		150.00	-120
	To dismantle & replacing rear reverse camera		100.00	-50
	To dismantle & refix garnish upholstery		150.00	-80
	To dismantle & refix tailgate mechanism		150.00	-60
	To dismantle & refix rear exhaust	11	100.00	X
	To spray rust proofing		180.00	100
	To mount vehicle on car o-liner	11	380.00	X
	labour for panel beating, cut, weld, straighten & replacing parts		2000.00	1500
	To putty & spray painting		2500.00	1800
	TOTAL			34084.30
				34196.80

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18002096/Utbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 22-05-2018



ON BEHALF OF S & H EXPRESS

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GBE 4650Y
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	02/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDH2015019304	Colour	YELLOW
Odometer	77975	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/01/2018	Inspection Date	02/02/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4650Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN	BROKEN	1,255.10	1,255.10
1	REAR WINDSCREEN MOULDING	NECESSARY	110.10	110.10
1	TAILGATE	DENTED / BENT	1,969.30	1,969.30
1	TAILGATE OUTER HANDLE	GRAZED	248.50	248.50
1	TAILGATE INNER LOCK	DENTED / JAMMED	359.00	359.00
1	TAILGATE LOCK STRIKER	TWISTED	66.50	66.50
1	TAILGATE WEATHERSTRIP	TWISTED	387.30	387.30
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	480.00	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	45.00	-
1	REAR END PANEL OUTER	BADLY DENTED	566.10	566.10
1	REAR END PANEL INNER	BADLY DENTED / BENT	936.20	936.20
1	REAR END PANEL TOP PLATE	BENT	269.50	269.50
1	TAILLAMP FILTER PANEL N/S	BADLY DENTED	345.10	345.10
1	REAR EXHAUST	TO REPAIR SEE LABOUR	971.10	-
1	TAILGATE REAR LOGO	NECESSARY	60.50	60.50
1	TAILGATE "HIACE" EMBLEM	NECESSARY	66.20	66.20
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	392.30	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,419.70	-
1	TAILLAMP LOWER GARNISH N/S	TWISTED	169.30	169.30
1	FRONT BUMPER BEAM TOP	BENT	166.20	166.20
1	FRONT BUMPER REINFORCEMENT	BENT	380.40	380.40
2	HEADLAMP ASSY "HID" @\$2950.00	CRACKED	5,900.00	4,900.00
1	BONNET	TO REPAIR SEE LABOUR	1,050.00	-
2	BONNET HINGES @\$115.00	BENT	230.00	230.00
1	BONNET LOCK	TWISTED	88.90	88.90
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	348.80	-
1	AIR CON CONDENSER	NOT NECESSARY	1,431.10	-
1	RADIATOR ASSY	NOT NECESSARY	2,110.20	-
	LESS 25% DISCOUNT		-5,455.60	-3,143.55
			16,366.80	9,430.65

Report Ref No. CS/TP18002096/Utbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER SPORT (SN)	CRACKED	3,200.00	2,600.00
1	FRONT BUMPER CENTRE GRILLE (SN)	TORN	280.00	280.00
2	FRONT CORNER PANELS FIBRE @\$600.00 (SN)	N/S CRACKED	1,200.00	600.00
1	WIPER PANEL TOP FIBRE (SN)	WARPED / CRACKED	480.00	480.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	BONNET "DHL" LOGO (SN)	NECESSARY	180.00	100.00
1	REAR BUMPER SPORT (SN)	CRACKED	3,200.00	2,600.00
1	REAR EXHAUST CHROME PIPE (SN)	BENT	200.00	100.00
2	TAILLAMPS SPORT @\$680.00 (SN)	CRACKED	1,360.00	1,360.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	180.00	150.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	380.00	300.00
1	SET REAR VIDEO CAM (SN)	BROKEN / MISSING	500.00	500.00
1	SET TAILGATE CORPORATE STICKER (SN)	NECESSARY	180.00	180.00
1	TAILGATE TOP SPOILER (SN)	TO REPAIR SEE LABOUR	600.00	-
			12,040.00	9,330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR REVERSE CAMERA.		100.00	50.00
	TO DISMANTLE & REFIX GARNISH UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		150.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		180.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,REAR FENDER,BONNET,FRONT SUPPORT PANEL AND TAILGATE TOP SPOILER.		2,000.00	1,500.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,800.00
			5,790.00	3,740.00
	GRAND TOTAL		34,196.80	22,500.65

Report Ref No. CS/TP18002096/Utbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,000.00
---	--	--	-----------

Report Ref No. CS/TP18002096/Utbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.