



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 BMW 650 I GRAND COUPE (SKS5922B)

Date of Loss

January 30, 2018

Time of Loss

8.20

Loss Description

SKS5922B (INSD) C/W UNKNOWN (TP)

Comment

Workshop Details

Total Rebate Amount

95123

Nett Loss Amount

\$60,877.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

04/10/2018



Days of work completion *

67



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKS5922B

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

09/27/2012



Mileage

42785

Age of Vehicle

5

Driver Details

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2011

ASSESSMENT INFO...

2011

CATEGORY

Driver Name

FNOL INFORMATI...

BUCKLEY NELSON RICHARD

CATEGORY Make

POLICY INFORMAT... BMW

ASSESSMENT INFO... B.M.W.

CATEGORY Model

POLICY INFORMAT... 650 I GRAND COUPE

ASSESSMENT INFO... 650I AT ABS D/AB 2DR SR LED DSC N/A

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WBALX32010C952041

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... March 28, 1972

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 45

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 21120053N63B44A

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 23

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATION... 235 ARCADIA ROAD, #08-07 THE ARCADIA, 289843, Singapore

POST SURVEY INFORMATION

CATEGORY Address type

FNOL INFORMATION... Residential

POST SURVEY INFORMATION

CATEGORY Gender

FNOL INFORMATION... Male

POST SURVEY INFORMATION

CATEGORY Marital status

FNOL INFORMATION... Married

POST SURVEY INFORMATION

CATEGORY Identification #

FNOL INFORMATION... G6101418M

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/05/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

4500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

285/30R20

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

285/30R20

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			RIGHT UPPER			Serviceable	0	0	0	0	0	Deny
☐		2	1			ROCKER PANEL			Buckled	2317.48				2317.48	Review
☐		3	2			REINFORCEMEN			Necessary	46.74				93.48	Review
☐		4	2			REINFORCEMEN			Necessary	46.74				93.48	Review
☐		5	2			REINFORCEMEN			Necessary	46.74				93.48	Review
☐		6	1			DOOR			Bent	2422.98				2422.98	Review
☐		7	1			RIGHT LOWER			Serviceable	0	0	0	0	0	Deny
☐		8	1			DOOR BRAKE			Serviceable	0	0	0	0	0	Deny
☐		9	1			SEAL, DOOR B			Necessary	24.42				24.42	Review
☐		10	1			REAR WINDOW			Necessary	1026.15				1026.15	Review
☐		11	1			WINDOW GUIDE			Serviceable	0	0	0	0	0	Deny
☐		12	1			INNER RIGHT			Necessary	265.72				265.72	Review
☐		13	1			SEAL, DOOR S			Necessary	111.68				111.68	Review
☐		14	1			DUCT COVER,			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		15	1			DUST COVER			Serviceable	0	0	0	0	0	Deny
		16	1			B011514 WINDOW LIFTE			Serviceable	0	0	0	0	0	Deny
		17	1			COVER, SIDE			Necessary	248				248	Review
		18	1			C010759E VELCRO FAST - 10PCS			Necessary	8.55				8.55	Review
		19	1			SIDE WINDOW			Necessary	381.86				381.86	Review
		20	1			NOISE INSULA			Necessary	72.54				72.54	Review
		21	1			SOUND INSULA			Necessary	101.99				101.99	Review
		22	1			CRASHPAD, DO			Serviceable	0	0	0	0	0	Deny
		23	1			CRASHPAD, DO			Serviceable	0	0	0	0	0	Deny
		24	1			DOOR WEATHER			Necessary	227.53				227.53	Review
		25	1			A060451 DRIVE FOR WI			Serviceable	0	0	0	0	0	Deny
		26	1			C020101B BLIND RIVET - 19PCS			Necessary	9.93				9.93	Review
		27	1			C040218A BLOT			Necessary	0.53				0.53	Review
		28	1			R-OFFICE ADHESIVE K5			Necessary	267.48				267.48	Review
		29	1			C020218B RIVET N5 - 11 PCS			Necessary	5.75				5.75	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		30	1			B020244 ADHESIVE K5A			Necessary	112.44				112.44	Review
		31	1			B020246 CLEANER R1			Necessary	22.66				22.66	Review
		32	1			R-OFFICE REPAIR KIT			Necessary	124.98				124.98	Review
		33	1			PUNCH RIVET - 23PCS			Necessary	12.02				12.02	Review
		34	1			R-OFFICE SEAM SEALAN			Necessary	32.11				32.11	Review
		35	1			SILL COVER PRIME R			Cut	498.52				498.52	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTED BODY PARTS	6000	0	0	Reviewing		1
		2		VEHICLE DIAGNOSIS - CARRYING OUT THE ABL AND DELETE FAULT CODE	625	0	0	Reviewing		1
		3		CHECK AND SECURE WIRING AND ELECTRICAL SYSTEM	500	0	0	Reviewing		1
		4		PAINTING RIGHT DOOR	900	0	0	Reviewing		1
		5		PAINTING RIGHT SIDE PANEL	900	0	0	Reviewing		1
		6		PAINTING RIGHT SIDE SKIRT	600	0	0	Reviewing		1
		7		SET VEHICLE BENCH	1200	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$15,499.51

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$10,725.00	\$10,725.00
Spare Parts	\$8,575.76	\$8,575.76
Miscellaneous	\$698.75	\$698.75
Excess	-\$4,500.00	-\$4,500.00

Submit for Review