



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 30/08/2019

Survey Details:

Date of loss	19.01.2018
Date of appointment	02.02.2018
Date of survey	05.02.2018
Location of survey	SMRT Automotive Services PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	SG5516J
Make and Model	Volvo B9TL (9364cc)
Date of registration	26.10.2017
Excess	
Market Value/ Book Value	(est)
Parf/COE Rebate	(est)
Nett Value/ ERV	(est)

Repair details:

Initial Estimate	\$ 7,737.65
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 5,980.65
Check items (estimate)	NIL
Labour	\$ 1,360.00
Supplementary	NIL
Total	\$ 7,340.65
Lump Sum(if applicable)	-

Number of days for repair	<u>2</u>
----------------------------------	-----------------



Remarks:

TP snapshots suggest that OID had veered near to TP, while TP had keeping within its own lane, leading to the collision

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,340.65	
Loss of use	\$ 600.00	(2days x \$300.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA/GIA search fees	\$ 7.00	
Others	NIL	
Proposed Total	\$ 7,947.65	