

ASS. REC. BY

REF CS3/CTI18002138 / Nd354

range &amp; days

Surveyor

Wilson

ASSIGNMENT (Office)

From (Person):

Menimen Janyan Tay

of

CTI

Date/Time

2/2/2018 @ 4:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE3563D

Insured:

SKL53D

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

2 Kaki Bkt # 01-17/18

Policy No:

DMPCSN1678311801

Claim No:

SNM18D00615C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/01/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

4:04pm @ 2/2/18

Person Contacted:

Melody

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLE3563D - NA / AIG18002047 / r3

D.O.A : 31/01/2018

SKL53D - NA / AIG18002047 / r3

D.O.A : 31/01/2018

Dismantle Part : 05/02/2018

After repair: 07/02/2018

WYLLT PRS

CTH

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/INV:  
To inspect Vehicle No: SLE 356.3 D  
at Workshop mis: NSI  
of \_\_\_\_\_  
Insured \_\_\_\_\_  
Policy No \_\_\_\_\_  
Claims No \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Ven: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	OS

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SLE 356.3 D Yr Regn: 16/12/2011  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mini Cooper cc 1598  
Colour: white AC Insured / Std / NI / NA  
Sp. Reading: 113448 T. Radio: Insured / Std / NI / NA  
Eng No \_\_\_\_\_  
C/No: WMWZB32060WL84625  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size F: 205/55 R17  
R: 205/55 R17  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal: 4 mm R/Bal: 4 mm  
L/Bal: 4 mm L/Bal: 4 mm  
D.O.A: 31/1/18 D.O.I: 2/2/2018  
Survey held at: As above  
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
2/2/2018 No Accident Report Given - no Car  
Range \$5900 - \$6900  
4 Days Repairs

RECEIVED 1 JAN 2018

Date/Time File Path to: ☐ : Preli. Report  
10042018 ☐ : Final Report

Days Of Repair:  
Resurvey No. of Trip:

Report Format: PRS  
Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp: (\$)  
☐ Interview: (\$)  
☐ Tech. Insp: (\$)  
☐ Weekend: (\$)

Survey Fee  
Transportation  
1. \$ - \$  
2. Phone  
3. Other

9/4/2018

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		02 Feb 2018 16:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	GOH WEE HONG, ID: S1694439D		[Created by insurer]	
Main Claimant:	LIM SIEW CHENG, ID: S73110311			
Vehicle Reg. No.:	SLE3563D			
Claim Type:	TP / SNM18D00615C02		Date of Loss:	31/01/2018 17:00 - :59
Vehicle Reg. No. (Insured):	SKL53D		Policy/Cover Note No.:	DMPCSN1678311801
			Policy No. (Claimant):	
			Excess:	S\$0.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2018]			
Adj Asg. Remarks:	Please conduct survey, check consistency of the damages on without prejudice basis. Kindly let us have your recommended repair amount if there is no estimate provided during pre repair.			

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Friday, 2 February 2018 3:35 PM  
**To:** assignments  
**Subject:** FW: OUR REF: PRS/SNM18D00615C02/3 & YR REF: SLE3563D -TO CONDUCT PRE REPAIR SURVEY -SLE3563D  
**Attachments:** 02022018153032.pdf

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Chin Hui Xin [mailto:[huixin@n51.com.sg](mailto:huixin@n51.com.sg)]

**Sent:** Friday, 2 February 2018 3:32 PM

**To:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Cc:** Jowyn Tay <[jowyn.tay@sg.cntaiping.com](mailto:jowyn.tay@sg.cntaiping.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>

**Subject:** Re: OUR REF: PRS/SNM18D00615C02/3 & YR REF: SLE3563D -TO CONDUCT PRE REPAIR SURVEY -SLE3563D

Dear Sir / Madam,

Please see attached.

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



On Fri, Feb 2, 2018 at 3:26 PM, Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)> wrote:

Without Prejudice

Dear Melody,

We refer to your email on even date.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Calvin/ Marcus,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer:*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Chin Hui Xin [<mailto:huixin@n51.com.sg>]

**Sent:** Friday, 2 February, 2018 3:14 PM

**To:** Angie Foo

**Cc:** Jowyn Tay

**Subject:** Re: OUR REF: PRS/SNM18D00615C02/3 & YR REF: SLE3563D -TO CONDUCT PRE REPAIR SURVEY -SLE3563D

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



On Fri, Feb 2, 2018 at 3:05 PM, Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)> wrote:

WITHOUT PREJUDICE

Dear Melody,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)

Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer:*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Chin Hui Xin [mailto:[huixin@n51.com.sg](mailto:huixin@n51.com.sg)]

**Sent:** Thursday, 1 February, 2018 4:59 PM

**To:** Claims Dept of CTI

**Subject:** SLE3563D & SKL53D - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,



Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

TWINCAR Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: SLE 3563 D  
Your ref: SKL 53 D

02 February 2018

CHINA TAIPING INSURANCE (S) PTE LTD

BY EMAIL [angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com) ONLY

105 CECIL STREET

#18-00 / #19-00 THE OCTAGON

SINGAPORE 069534

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : LIM SIEW CHENG

VEHICLE NUMBER : SLE 3563 D

YOUR INSURED VEHICLE NUMBER : SKL 53 D

ACCIDENT ON 31 Jan 2018 ALONG LORONG 2 TOA PAYOH SLIP ROAD INTO PIE (CHANGI)  
AT ABOUT 17:15 HOURS

We refer to your email dated **02 Feb 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**TWINCAR AUTOMOTIVE PTE LTD**

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

Contact Person:

**6842 0051 / 6744 0510 (Melody)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

#### FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!  
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

<b>Vehicle No.</b>	SLE 25630	Model / Make	Mitsubishi Canter
Date of Accident	31/1/18		
Time of Accident	5.15pm	HRS	
Location of Accident	Lorong 2 Tanjong Pagar Sijil Rd (No P/E Change)		
Exact purpose use during accident	Pre use		
<b>Name of Owner</b>	Lim Siew Chong		
Telephone No.	H/P: 90235855	Home:	Office: 90235857 (husband)
NRIC	S7311031Z		
Address	B1C52, Hong K Telok Kurau, #04-04, S U25780		
Claim type	OD	(THIRD PARTY)	REPORTING ONLY
Insurance Company	AIG		
Type of Coverage	(Comprehensive)	Third Party	Third Party / Fire / Theft
Policy No.	2100482102-01		

<b>Name of Driver</b>	(As Above) If No,		
NRIC		Any Passengers: 01 (female) 12yrs	
Date of birth	23/3/1973		
Occupation	Outdoor	/	(Indoor)
Driving License Pass Date	24/12/1994		
Gender	(Male) / (Female)		
Contact No.	H/P:	Home:	Office:
Address			
Driver have any own vehicle	No,	If yes, Reg No.	
Relationship	Employee,	If no, state	
Weather condition	Clear	(Raining)	Other
Road Surface	Dry	(Wet)	Other
Any Injuries	(No,	If Yes, Who?	
Name And Contact No.			
Name And Contact No.			
Police Report	No,	If Yes, Where?	

<b>Vehicle B No.</b>	SEL 530	Any Passengers:	—
Name of Driver	Goh Nee Hung	Contact No.:	96223998
<b>Vehicle C No.</b>		Any Passengers:	
<b>Vehicle D No.</b>		Any Passengers:	
<b>Vehicle E no.</b>		Any Passengers:	
<b>Vehicle F No.</b>		Any Passengers:	
<b>Vehicle G No.</b>		Any Passengers:	
Witness Name		Witness Contact:	
<b>Accident Portion</b>	Rear Portion		
<b>Camera Recorder</b>	(Yes / No)		
<b>Email Address</b>	Kimlimsc @ hotmail. com		

<b>PARTICULAR WORKSHOP</b>	Tanaka Automotive SPC
<b>CONTACT NO.</b>	6842 0051 / 6744 0510
<b>CONTACT PERSON</b>	Xuan
<b>FAX NO</b>	6741 0510
<b>WORKSHOP EMAIL ADDRESS</b>	sales @ n51. com. sg

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN


A - SLE 25630

B - SKL 530

Lor 2  
Tua Payoh  
Cnr Pet  
into  
PIE (change)



PIE (change)



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Lor 2 Tua Payoh Sry road and into PIE (change). I stopped as to give way to incoming traffic. As of the sudden, veh (B) came from the rear and collided directly onto the rear portion of my vehicle.

A - SLE 35630

B - SKL 530

*[Signature]*

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		02 Feb 2018 16:09 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>GOH WEE HONG</b> , ID: S1694439D		
Main Claimant:	<b>LIM SIEW CHENG</b> , ID: S7311031I		
Vehicle Reg. No.:	<b>SLE3563D</b>	Date of Loss:	31/01/2018 17:00 - :59 [73 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D00615C02</b>	Policy/Cover Note No.:	DMPCSN1678311801
Vehicle Reg. No. (Insured):	<b>SKL53D</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Twincar Automotive Pte Ltd (Kaki Bukit)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Jowyn Tay</b> - 6389 6174]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Teo Cheng Ming Wilson</b> ] ... [Final Rpt due 13/02/2018]		
Adj Asg. Remarks:	Please conduct survey, check consistency of the damages on without prejudice basis. Kindly let us have your recommended repair amount if there is no estimate provided during pre repair.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLE3563D (SNM18D00615C02)**  
**[SKL53D]**

**TP**

**LIM SIEW CHENG**

**Jan 31 2018 5:00PM**

**[GOH WEE HONG]**

**Twincar Automotive Pte Ltd**

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

**View** [View in Browser](#) ▼

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No.	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	02/02/18 16:11	<b>INSURED SAS REPORT SKL53D</b>		Load PDF
2	02/02/18 16:11	<b>THIRD PARTY SLE3563D -FROM TWINCAR AUTO -PRS LTR</b>		Load PDF
3	02/02/18 16:11	<b>THIRD PARTY SAS REPORT SLE3563D</b>		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	10/04/18 16:44	<b>LKKPhotosIn6-1</b>		Load PDF
2	10/04/18 16:44	<b>LKKPhotosIn6-2</b>		Load PDF
3	10/04/18 16:44	<b>LKKPhotosIn6-3</b>		Load PDF

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18002138/WD3S2  
Date: 16/04/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1678311801  
Claimant Vehicle No: SLE3563D Insured Vehicle No: SKL53D  
Date of Loss: 31/01/2018 Nature of Claim: TP Claim No: SNM18D00615C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLE3563D Engine No: A530I983N16B16A  
Make & Model: MINI COOPER S, 1.6 COUNTRYMAN (A) Chassis No: WMWZB32060WL89625  
Reg. Date: 16/12/2011 (Man. Year: 2011) Odometer: 113448 km  
Colour: White  
Engine Capacity: 1598 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55R17 Rear Tyre Size: 205/55R17  
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm  
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 02/02/2018  
Date Inspected: 02/02/2018 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB  
Singapore 417921  
Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/16/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,900.00 - \$6,900.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
<b>Parts:</b>	144	MINI COOPER S 1.6 COUNTRYMAN (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE3563D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >