Surveyor REF: III 2140 || Veg3 , ②.

ASSIGNMENT

From: Date: 13/2/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 4873 R

at Workshop m/s Esteem performance

of Blk 5033, AMK Ind. Prk 2 #01-259

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record) 10 am owner waiting

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 4873R Yr Regn: 06 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: NIS (A) NV350 c.c.: 2488

Colour: White / Blue A/C: Insured / Std / NI / NA

Sp.Reading: 70122 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC24267 0006646

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoder / Jammed / Leaked / Burnt or

Brake: Inoder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15 x8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	22/1/18	D.O.I.	13/2/18

Survey held at ✓

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
14/2	File pass to Cashier

Date/Time. File Pass to?

1) ☐ : Preli. Report

☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insc ($ ☐ Interview ($ ☐ Tech Invs ($ ☐ Weekend ($

Report Format :

Lump Sum / I.B.I: ($

Survey Fee

Transportation

Photos

Others

TOTAL