SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	03/02/2018 07:27
Date Of Accident	02/02/2018 15:05
Exact Location Of Accident	JURONG EAST ST 21 X C/P ENTRANCE NEAR LAMP POST 3:
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHB3374X
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	140
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	
Driver	
Name of Driver	CHOY CHONG WENG
NRIC No	S1178301E
Date Of Birth	10/10/1955
Occupation	OUTDOOR
Date Of Driving Pass	03/01/1977
Driving Experience	41 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	CWCHOY@HOTMAIL.COM

Address

746 05-726 WOODLANDS CIRCLE

Postcode

730746

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

GENDER:

: FEMALE

Passenger 2

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes. Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SJK1430J

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Page 2 of 15

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

FRT

Sketch Plan Pg. 1



ACCIDENT STATEMENT SHB 3374 X

This afternoon(02/02/2018), it was drizzling when I travelled on Jurong East Street 21 ferrying 2 female passengers on the way to Ng Teng Fong Hospital.

As seen in the video footage, when an SMRT taxi(SHC4604X) stopped in front before turning right into the carpark driveway and as I followed suit, I felt a sudden impact after car B(SJK 14305), a Toyota, banged into the rear of my taxi. The accident took place near lamp post No 32.

I then alighted to take photos at the scene.

The impact inflicted damage to the rear left portion of my taxi.

I noticed the front of car B sustained dents and its front plate number fell onto the road following the accident.


No report of injury at the time of accident.

I affirmed the above-statement is true and correct.

Driver name : Choy Chong Weng


NRIC NO : S 1178301E 02/02/2018 Date:







17. 67. 4





. 1.79



