

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.02.2018

REPAIR ESTIMATE

Time: 16:08:09

Page: 1/2

AXA - 4sum

(Fri)

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305113070
REGN NO : SHB6697U
MILEAGE : 0000000000
MAKE : MERCEDES BENZ
MODEL : VIANO CDI 2.2L
DATE OF REGN : 24.10.2013
DATE/TIME IN : 02.02.2018 13:20
ACCIDENT DATE : 01.02.2018

1614

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0203-0579-G	REAR BUMPER	1	1,372.00	20.00	1,097.60	1,372.00
0002 04-01-0203-2044-G	REAR BUMPER RH	1	473.60	20.00	378.88	
0003 04-01-0203-2047-G	TAIL LAMP RH	1	322.00	20.00	257.60	X
0004 04-01-0203-0072-G	REARBUMPER REFLECTOR RH	1	33.00	20.00	26.40	X
0005 04-01-0203-2049-G	TAILLAMP LOWER GARNISH RH	1	35.70	20.00	28.56	X repair
0006 28-01-0203-2001-G	TYPE DESIGNATION-2.2	1	39.00	20.00	31.20	
0007 28-01-0203-2002-G	TYPE DESIGNATION-CDI	1	39.00	20.00	31.20	
0008 28-01-0203-2003-G	TYPE DESIGNATION-VIANO	1	39.00	20.00	31.20	
0009 28-01-0203-2000-G	TAILGATE MERCEDES STAR	1	29.00	20.00	23.20	
0010 28-01-0299-2011-G	TAILGATE MAXICAB STICKER	1	40.00	2.00	40.00	
0011 09-01-0299-2005-A	REVERSE SENSOR	1	288.00	0.20	288.00	

SUB-TOTAL : 2,233.84

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.02.2018

REPAIR ESTIMATE

Time: 16:08:09

Page: 2

(Fri)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305113070
 REGN NO : SHB6697U
 MILEAGE : 0000000000
 MAKE : MERCEDES BEN
 MODEL : VIANO CDI 2.2L
 DATE OF REGN : 24.10.2013
 DATE/TIME IN : 02.02.2018 13:20
 ACCIDENT DATE : 01.02.2018

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0000 L	PANEL BEATING	860.00	600
0001 23-502	SPRAYPAINT ON AFFECTED AREA	800.00	720
0002 17-01	CHECK ALL LIGHTING	50.00	X
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	X
0004 L	R/I REVERSE SENSOR	120.00	20
0005 20-05	REAR BUMPER MAT	50.00	—
		SUB-TOTAL : 1,920.00	
		TOTAL : 4,153.84	

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Kelvin (Clerk)
 5/2/18 1020h
 3 days
 L/S
 After Reps - photo