

INS. CASE OWNER:

Surveyor:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :\$

Is driver the owner?

(YES / ☒ NO)

Nature of Accident :

If NO, Driver Name / Age : MYO THINA SIE

Driver Tel No. :

(V/L-YES / NO)



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

CC 4 ASM AXA1800

ASSIGNMENT

DOI:

Date / Time :

Registered in Merimen:

LKK:

IDAC:

X62

9/7/18

5/2/18

GX 9390E

GOODMAN ENVIRONMENTAL PLU

HP:

D.O.A : 07/07/18

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

58M008EL 129377

P1546847

HUSAN

Juru Buntok DR 1 BENTAN
ENST DR.OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability :

%

Final ? Yes / No

SLT 2940B

Date/ Time		STAGE	DATE / PIC
27-2-18	W/OID & OIC MS. YU, CONFIRMED	Non-Reporting ltr (1st):	NA
@ 9:15	4W'S AGREED TO SETTLE &	Non-Reporting ltr (2nd):	
	AWARE NCD ISSUE.	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	JUY 27-2-18
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup):	<input checked="" type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$S	() days	Reduction: %
FINAL SETTLEMENT		Date/Time: 27-8-18	Confirm with: MARJ
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.: 27
Repair Cost:	\$S 1,845.22		
Loss of Rental (LOR):	\$S	() days	
Loss of Use (LOU):	\$S 180	(60 x 3) days	
Loss of Income (LOI):	\$S	() x days	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search:	\$S 2. x		
Medical:	\$S -		
Disbursement:	\$S -	(e.g. Tow/ Independent)	
Legal Cost:	\$S -		
Total:	\$S 2,027.22	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S 2,027.22	Name 1:	CYCLE & CARRIAGE-FULCO MOTOR DEALER
Payee 2: (Strike if N.A.)	\$S x	Name 2:	x
Payee 3: (Strike if N.A.)	\$S	Name 3:	x



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M008EL
Our ref: CC4/ASM18002266/Gjb3

Date: 08.02.2018

The Motor Claims Department
M/s AXA INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLT2940B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.02.2018 at the premises of M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,148.10
Revised Estimate Amount	: S\$	1,724.50
"Check" Items Amount	: S\$	1,121.40
Total (Including Check Items)	: S\$	2,845.90
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser



CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE



CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr CHAN KOK FEI Blk 277d Compassvale Link #15-300 Singapore 544277	Cust No/Name /Mr Chan Kok Fei Reg No/Reg Date SLT2940B / 25/10/2017 Date In/Mileage 05/02/2018/ 0 Chassis No KNAFX411MJ5747171 Engine No G4FGHH682349 Make/Model KIA/CERATO K3 1.6 A EX BWY Colour/Trim 4SS / WK
Contact No Mobile: 87979916	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00001	Cash	05/02/2018/ 13:13	DS	218- Y. Marslen	51919			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	SUNDRY						NNX 35.00	
	C & C LOGO							
S	MIPNT88088						/ 280.00	
	TO SUPPLY AND REPLACE REVERSE SENSOR							
S	MIPNT88088						60. 80.00	
	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT88088						600 2400.00	
	TO REPLACE REAR BUMPER, REINFORCEMENT, ETC							
	-TO REPAIR REAR END PANEL							
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS						420 1680.00	
S	MIPNT98088							
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							
P	KS 86611 A7 800	COVER - REAR BUMPER	X	NN	1.00	688.00	10.00	619.20
M	KS 86695 A7 800	COVER - REAR BUMPER	/	re	1.00	347.00	10.00	/ 312.30
P	KS 86631 A7 800	BEAM - REAR BUMPER	X	NN	1.00	318.00	10.00	286.20
M	KS 86641 A7 800	LH STAY - REAR BUMPER	X	NN	1.00	120.00	10.00	108.00
P	KS 86642 A7 800	RH STAY - REAR BUMPER	X	NN	1.00	120.00	10.00	108.00
M	KS 86613 A7 001	LH BRACKET - REAR BU	/	acc	1.00	29.00	10.00	/ 26.10
M	KS 86614 A7 001	RH BRACKET - REAR BU	/	acc	1.00	29.00	10.00	/ 26.10
P	KS 86310 A7 050	LOGO ASSY - KIA SUB	X		1.00	37.00	10.00	33.30
M	KS 86311 A7 030	EMBLEM - CERATO	X		1.00	35.00	10.00	31.50
M	SSKM1060	EMBLEM K3	X	NN	1.00	36.00	10.00	32.40
M	KS 87321 A7 000	WEATHERSTRIP - TRUNK	X	NN	1.00	100.00	10.00	90.00
Z	NOTES							
	ACCIDENT ON 03/02/2018 ALONG BUANGKOK E DR TRAFFIC JUNCTION							1724.5
	OWNER CLAIMING THIRD PARTY							
	REQUIRED REPLACEMENT CAR							
	TP : GX9390E TP INS : AXA							

3 Days .

before paint photos - / after repair photos

Long Qian - 8288082

Confirm & accepted by

Authorized signatory and company stamp

Parts	1,673.10
Labour	0.00
Standard Menu	0.00
Specialist Job	4,440.00
Others (Lub, etc)	0.00
Sundry	35.00
Total (w/o GST)	6,148.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18002266/Gjb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 05-02-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GX 9390E	Veh. Inspected	SLT 2940B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/02/2018	Inspection Date	07/02/2018
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Joy Irene (LKKAUTO)

From: Mars Ler <mars.ler@ccfulco.com.sg>
Sent: Monday, 27 August 2018 11:00 AM
To: Joy Irene (LKKAUTO); Chris Bulaclac
Cc: Admin A
Subject: RE: Accident On 03/02/2018 Involving Our Insured SLT2940B And Your Insured GX9390E - CAS201802052476536

Dear Joy ,

We would like to confirm accepted the offer amount .

Thank You,

Best regards

Mars Ler
B & P Service Advisor
Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3 Singapore 408650
D/D 65949163 H/P 91792566

-----Original Message-----

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Monday, 27 August, 2018 10:55 AM
To: Mars Ler; Chris Bulaclac
Cc: Admin A
Subject: RE: Accident On 03/02/2018 Involving Our Insured SLT2940B And Your Insured GX9390E - CAS201802052476536

WITHOUT PREJUDICE

Dear Sirs,

On without prejudice basis and without admission of liability, we offer settlement as follows:

Repair cost	\$1,845.22
Loss of use	\$ 180.00 \$60 x 3 days
LTA search fees	\$ 2.00
Total	\$2,027.22

Kindly confirm acceptance.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

X

LETTER OF DISCHARGE

We, CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD (workshop), hereby agreed and confirmed that we are authorized by the owner of motor vehicle SLT2940B to accept the sum of \$ _____ (inclusive of Inte alia, damages, interests, loss of use, costs and disbursements) from M/s _____ the authorized surveyors of M/s AXA Insurance Singapore Pte Ltd, the Third Party's insurers, on this matter.

This acceptance is in full and final settlement of any claim made against GX9390E pursuant to the road accident which occurred along BUANGKOK E DR TRAFFIC JUNCTION on 03/02/2018.

We CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD (workshop) are further authorized by the said owner that this settlement is reached on a strictly without prejudice basis on the part of M/s AXA Insurance Singapore Pte Ltd. And or their insured or other person or persons arising out of this said accident.

In consideration of the said payment by the said M/s AXA Insurance Singapore Pte Ltd, we, the said authorized workshop, shall fully discharge them from any further claim whatsoever in respect of the said accident.

We also declare that we are authorized by the said owner to receive the said settlement sum and hereby undertake to indemnify M/s AXA Insurance Pte Ltd, against any claim made or which may be made in respect of this matter.



For and on behalf of the owner of
(
(workshop stamp and authorized signature)

For and on behalf of M/s AXA
Insurance Singapore Pte Ltd



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE
330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

REPAIRER : CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - EUNOS LINK SERVICE CENTRE

MOTOR VEHICLE CLAIM DISCHARGE VOUCHER

ATTN: AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower
Singapore 068811

OWNER	: CHAN KOK FEI	VEHICLE NO	: <u>SLT2940B</u>
VEHICLE MODEL	: <u>KIA/K3</u>	THIRD PARTY #	: <u>GX9390E</u>
ACCIDENT DATE	: <u>03/02/2018</u>	WIP NO	: <u>51919</u>

I/WE CERTIFY THAT THE VEHICLE HAS BEEN FULLY REPAIRED TO MY ENTIRE SATISFACTION AND THE PAYMENT OF CLAIMABLE REPAIRER'S CHARGES ARE UNDER THE POLICY WILL BE DEEMED IN FULL AND THE FINAL SETTLEMENT OF MY CLAIMS.

OWNER/INSURED SIGNATURE

DATE :

TIME :

X

LETTER OF AUTHORITY

ACCIDENT INVOLVING SLT2940B AND GX9390E ON 3/2/2018
Own Vehicle's Number Other Vehicle's Number Date Of Accident

Along BUANGKOK E DR TRAFFIC JUNCTION
Accident Location

BY THE LETTER OF AUTHORITY, I/We CHAN KOK FEI
Name of Policy Holder & NRIC/Passport/Fin #

Of BLK 277D COMPASSVALE LINK #15-300 SINGAPORE 544277
Address of Policy Holder

Owner of Vehicle Registration Number SLT2940B hereby authorize **Cycle & Carriage-Fulco Motor**
Own Vehicle Number

Dealer Pte Ltd. to act for me with respect to my claim for repair cost and Car Rental and/or Loss of Use ("claim")

for my vehicle SLT2940B that was damaged.
Own Vehicle Number

I further Authorized **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** To settle my above mentioned claim in a manner that they deem fit and **Cycle & Carriage-Fulco Motor Dealer Pte Ltd.** Is further Authorize to Signed on my behalf & receive payment further to settlement cheque/s of my claim with payment being made in favour of **Cycle & Carriage-Fulco Motor Dealer Pte Ltd** I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis in so far as the driver/owner/insurers of the vehicle/s is concerned.

Dated this 3 Day of FEBRUARY (Month) 2018 (Year)


CHAN KOK FEI

Signed By Claimant/Policy Holder





Signed by " The Workshop"

<< **Re:RE: FOR QUANTUM APPROVAL**

Type

🔗 Question

Message

Hi LKK, please proceed as per mandate. Thank you.

Reply



Our Ref : SLT2940B
Your Ref : GX9390E

A.R. REGISTERED

14 JUN, 2018

AXA INSURANCE SINGAPORE PTE LTD
AXA TOWER
8 SHENTON WAY # 27-01
SINGAPORE 068811
Attention: Motor Claims

Dear Sir/Madam,

**Repair Services Rendered to Vehicle Reg. No.SLT2940B – Accident on 03/02/2018
Along BUANGKOK E DR TRAFFIC JUNCTION.**

We are pleased to enclose our invoice number **77379214** dated 30/05/2018 amounting as follows:

Cost of Repair	S\$ 1845.22
Loss of Use 03dayXS\$80.00/DAY	S\$ 240.00
LTA Search Fee	S\$ 2.00
Grand Total	S\$ 2087.22

In addition, attached are the supporting documents of repair services rendered to the abovementioned vehicle.

Please acknowledge receipt of the same.

Take Notice, the agreed settlement and acceptance for this case is subject to the understanding that we must receive your payment for the agreed sum within 30 days herein. Failing to, the above-mentioned agreed settlement and acceptance is considered void and nil and we will proceed to forward this case to our solicitors to proceed accordingly without further notices to you. To avoid unnecessary legal fees, kindly let us have your payment as stipulated above

Thank you.

Yours sincerely



Cycle & Carriage –Fulco Motor Dealer Pte Ltd
Eunos Service Centre

Encs.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 27 February 2018 9:26 AM
To: 'lingyu@goodmanenv.com.sg'
Cc: 'gmepl@singnet.com.sg'
Subject: ACCIDENT INVOLVING GX 9390E AND SLT 2940B ALONG JUNCTION OF BUANGKOK DRIVE ON 03.02.2018

GOODMAN ENVIRONMENTAL PTE LTD
Policy Holder

ATTENTION : Ms. Ling Yu (HR Dept)

Dear Madam,

OUR REF : CC4/ASM18002266/Gjb3
YOUR REF : GX 9390E

ACCIDENT INVOLVING GX 9390E AND SLT 2940B ALONG JUNCTION OF BUANGKOK DRIVE ON 03.02.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s CYCLE & CARRIAGE, acting on behalf of the owner of SLT 2940B against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SLT 2940B. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact the undersigned.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT

I/We, CHAN KOK FEI (the third party claimant") of BLK 277D COMPASSVALE LINK #15-300 SINGAPORE 544277 (address), owner of SLT2940B (vehicle no.) hereby authorize CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLT2940B that was damaged pursuant to the accident which occurred on 03/02/2018 (date) along BUANGKOK E DR TRAFFIC JUNCTION (location) involving vehicle no/s GX9390E ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 03 (day) of FEBRUARY (month) 2018 (year)



Signed by "the third party claimant"
(with company stamp if applicable)



Signed by "the workshop"
(with company stamp)



redefining / insurance

CLAIM REF : 58M0085L
INSURED : GOODMAN ENVIRONMENTAL PTE LTD.

DISCHARGE VOUCHER

We/I [CHAN KOK FEI] NRIC NO. S1157936A) hereby agree to accept the sum of dollars [TWO THOUSAND TWENTY SEVEN AND LEVTS TWENTY TWO ONLY] (S\$ 2,027.22) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [GX9390E] as a result of an accident along [BUANGKOK E DR TRAFFIC JUNCTION] on [GX9390E] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SLT2940B].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [GX9390E] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [GX9390E].

Dated this 27 day of AUG 2018

Claimant's Signature :

NRIC no./ Company Stamp :

1157936 A

Occupation/ Business :

Address :

BLK 277D COMPASSVALE LINK #15-300 SINGAPORE 544277

Telephone No. :


Witness's Name :

LER YEONG CHERNG

Witness's Signature :

Witness's NRIC No. :





CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**TAX INVOICE**

Co Reg No : 199707303Z

GST Reg No : 19-9707303-Z

Invoice Name & Address	Owner Name & Vehicle Info	
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name	/Mr Chan Kok Fei
	Reg No/Reg Date	SLT2940B / 25/10/2017
	Date In/Mileage	05/02/2018/ 5700
	Chassis/Package	KNAFX411MJ5747171 /FS1F
	Engine No	G4FGHH682349
	Make/Model	KIA/CERATO K3 1.6 A EX BWY
	Colour/Trim	4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
F0000008	Credit	30/05/2018/ 08:49	DS	323 / ChrisBulaciac	51919	77379214

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO SUPPLY AND REPLACE REVERSE SENSOR				280.00
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60.00
S MIPNT88088 TO REPLACE REAR BUMPER,REINFORCEMENT,ETC -TO REPAIR REAR END PANEL STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				600.00
S MIPNT98088 SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				420.00
X KS 86695 A7 800 COVER - REAR BUMPER,	1.00	347.00	10.00	312.30
X KS 86613 A7 001 LH BRACKET - REAR BU	1.00	29.00	10.00	26.10
X KS 86614 A7 001 RH BRACKET - REAR BU	1.00	29.00	10.00	26.10
Z NOTES ACCIDENT ON 03/02/2018 ALONG BUANGKOK E DR TRAFFIC JUNCTION OWNER CLAIMING THIRD PARTY LOSS OF USE TP : GX9390E TP INS : AXA				F.O.C.

Parts	364.50	Nett	1,724.50
Labour	0.00	7% GST on	120.72
Standard Menu	0.00		
Specialist Job	1,360.00	Total Payable	1,845.22
Others(Lub,etc)	0.00	Paid	0.00
Sundry	0.00	Total Due	1,845.22
Total(w/o GST)	1,724.50	Balance B/FWD	97,949.71
		Total Payable or C/FWD	99,794.93

Any dispute to the invoice must be made within 3 days.
 Cheques should be crossed and made payable to CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD - (SERVICE)
 This is a computer generated document, no signature is required.

Third Party Insurer Enquiry

Our Ref No: GR-18-019098

Date of Request: 05/02/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 05/02/2018

Enquiry By Mars Ler Yeong Cherng

TP Vehicle No. GX9390E

Accident Date 03/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GX9390E	AXA Insurance Pte Ltd	05/11/2017-04/11/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-019098

Date of Request: 05/02/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 05/02/2018

Enquiry By Mars Ler Yeong Cherng

TP Vehicle No. GX9390E

Accident Date 03/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Service Request Details

Claim	5844081EL	Actions
Reference	CCA/ASMT18002266/CB342 	Next Step: Wait for Approve Invoice
Loss Date	3 February 2018	Add Evidence
Request Date	21 August 2018	

Vehicle Information	
Incident Vehicle Registration #	SLT29408
Make	TP4D KIA
Model	FORTE K3
Service Address	
Primary Contact/Insured	
GOODMAN ENVIRONMENTAL PTE LTD 59 WOOLLAHED INDUSTRIAL PK EZ, NORDIX, 757476, Singapore	

Claim Handler	ANG Richard	richard_angbs@aaa.com.sg
---------------	-------------	--------------------------

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes	
<div> <div>Document Type</div> <div>Document SubType</div> </div> <div> <div>Upload Document</div> </div>							
<div> <div>LibInvoice1_CD.pdf</div> </div>		<div> <div>Invoice</div> </div>		<div> <div>Surveyor/ Assessor expense</div> </div>		<div> <div>LKK AUTO CONSULTANTS PTE LTD (19)</div> </div>	<div> <div>DATE UPLOADED</div> <div>20 September 2018</div> </div>

EDIT	SIR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR HLR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	2		TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	600	0	0	Approve		
	3		TO REPLACE REAR BUMPER REINFORCEMENT ETC TO REPAIR REAR END PANEL STRAIGHTEN/REFORM ALONG ON REAR ACCIDENT AFFECTED AREAS	6000	0	0	Approve		
	4		SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	420	0	0	Approve		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Milestones	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	------------	---------

Acknowledgements

Parts & Labour

Taxes & Ratio

Vehicle Condition

Vehicle & Driver Details

General & Workshop Details

Summary

Add	Remove	Change	Control Add
-----	--------	--------	-------------

Aggressive	Cherry	Blackberry All
------------	--------	----------------

15 October 2014

EDIT	INVT NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR:3 DAYS	Approve			

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Claim Amount	
Claim Amount		\$1,724.50												\$1,724.50	
CATEGORY	ESTIMATE	REVISED AMOUNT													
Spare Parts	\$364.50	\$364.50													
Labour	\$1,360.00	\$1,360.00													

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GX 9390E (Insd veh)	Model:	TPVD KIA FORTE K3
	SLT 2940B (TP veh)		
Date of Accident:	03/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,578.47
Final Repair Cost	:	\$	1,845.22
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	2,027.22

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	27
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	CYCLE & CARRIAGE.FULCO MOTOR DEALER PTE LTD	\$ 2,027.22

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

20/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))