

22/03/2012

ASS. REC. BY:

REF: CS3/MSG18002299/Gd3<sup>sr</sup>

Special Instructions:

Surveyor:

Menimen

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 5/2/18 @ 2:24pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 5360P

Insured:

SKC 5832L

at Workshop m/s

V.2 Automotive

Tel:

of

1 Kaki Bkt Ave 6 #02-02

Policy No:

29004870SMA

Claim No:

518524

Sum Insured:

Excess:

Make of Veh:

D.O.A

02/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp'

H.O.D. Endorsement:

Date/Time:

535pm @ 5/2/18

Person Contacted:

Ah huan

Vehicle: IN/OUT

Date/Time

Action/Instruction (x) Estimate

SKK 5360 - CC4/AxAL7004783/Kpg3q2

D.O.A: 5/3/17

SKC 5832L - CS3/ALG13022924/8b3y

D.O.A: 29/11/13

Dismantle: 6/2/2018

After repair: 9/2/2018

PRS xac.

MSIG.

9870E

SKK 5360P

30 Jul 2013

G

Subaru Forester 1998

Black

115519

IF/SIGK 85 DG 003358

G

G

G

G

235/50 R18

11

G

SS DUN EXNOVA GR FS LIZA MID OHTSU PR SUM

TOYO/YOKO

Front

RBa

6

LBa

6

CCA

Survey report

W/S

05-02-18

5:50pm

Des of Damages Rt Rear OS NS UC Backed in

N/S FA

The UIC / Chassis frame Body Structure affected due to collision

\* Repair Estimate : S\$3500 - 4500

\* 4 days

RECEIVED 03 MAY 2018

See This Report

☐

Prelim Report

See This Report

☐

Final Report

Days Of Repair

4

Resurvey No. of This

2

Add Fee

☐

Sketches

☐

Photocopy

☐

Repair

☐

As per

Report Format

PRS

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 14:24 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WONG SOO HUAT, ID: S1782467H		
Main Claimant:	LEE ENG HONG, ID: S7619870E		
Vehicle Reg. No.:	SKK5360P	Date of Loss:	02/02/2018 00:00 - :59
Claim Type:	TP / 548524	Policy/Cover Note No.:	29004870SMA Coverage: 12/09/2017 - 11/09/2018
Vehicle Reg. No. (Insured):	SKC5832L	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	V.z Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #02-02, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/02/2018]		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

5-38pm

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/02/2018 17:16
Date Of Accident	02/02/2018 08:50
Exact Location Of Accident	TPE(PIE) BEFORE LOYANG AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK5360P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE ENG HONG
NRIC No	S7619870E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92207250
Alternative Phone No	OTHERS-92207250

### Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA051587/1
Cover Note Number	

### Driver

Name of Driver	LEE ENG HONG
NRIC No	S7619870E
Date Of Birth	07/07/1976
Occupation	INDOOR
Date Of Driving Pass	18/03/2003
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92207250
Fax Number	
Contact Number	OTHERS-92207250
Email Address	NOEMAIL

Address 59 RIVERINA CRESCENT

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : AH HUAT  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKC5832L

Vehicle Make/Model/Colour HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Suhaimi  
NRIC/FIN No.: S8901951

## Sketch Plan #2

### SKETCH PLAN




### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was travelling along TPE PTE before Loyang Avenue. During the time of accident, there were accidents vehicle obstructing lane 2. The traffic was heavy and I was driving at a slow speed at lane 1. Suddenly I felt an impact at the left side of my vehicle as vehicle B tried to forcefully cut into my lane. That resulted my left side of the vehicle to be damaged. I then wanted to get down of my vehicle to access the scene but vehicle B hurried away immediately. Both vehicle B and my vehicle were then directed to the shoulder lane. A passerby, S9600741H, Tong Ji Sheng, approached me and informed me that he is willing to be an eye witness as he was at the accident scene too. He then left me his contact at 97725108.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

 02 FEB 2010  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Suhaimi  
NRIC/FIN No.: 98079915

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9870E
Vehicle Details	
Vehicle No.:	SKK5360P
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT AWD CVT
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	FA20G904228
Chassis No.:	JF15JGK85DG003358
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$20,443.00
Original Registration Date:	30 Jul 2013
First Registration Date:	30 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$20,621.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jul 2023
PARF Rebate Amount:	\$15,465.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jul 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$76,389.00
COE Rebate Amount:	\$41,849.00
Total Rebate Amount:	\$57,314.00

The information contained herein is correct as at 06 Feb 2018

OK



## ▶ Forester Used Vehicle List (2 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Subaru Forester 2.0XT	\$76,800	\$12,960 /yr	25-Mar-2013	1,998 cc	73,400 km	Dynamic Motoring	Available

8k Drive Away! New Model Forester XT In The Market For A Steal! It's Spacious Cabin And Great Engine Performance, This Model Is Much Sought After By Families. Immaculate Condition. Regular Serviced & ...

Office No. - 63866020

Dickson - 82888567 | Adrian - 88123478 | Loraine - 81683373 | Jacky - 97477375

Subaru Forester 2.0XT	\$82,900	\$13,290 /yr	05-Aug-2013	1,998 cc	76,800 km	Prime Motor & Leasing	Available
-----------------------	----------	--------------	-------------	----------	-----------	-----------------------	-----------

Elegant Blue, "XT" Model With 237 Bhp, Serviced By Agent, With Panoramic Sunroof, All Wheel Drive, Accident Free, One Owner Only, Very Well Maintained, Flexible In-house Loan Packages Available.

Office No. - 64440088

Pauline - 97810269 | Andy - 91086443 | Dennis - 91182773

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Feb 2018		05 Feb 2018 14:24 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>WONG SOO HUAT</b> , ID: S1782467H		
Main Claimant:	<b>LEE ENG HONG</b> , ID: S7619870E		
Vehicle Reg. No.:	<b>SKK5360P</b>	Date of Loss:	02/02/2018 00:00 - :59 [54 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 548524</b>	Policy/Cover Note No.:	29004870SMA Coverage: 12/09/2017 - 11/09/2018
Vehicle Reg. No. (Insured):	<b>SKC5832L</b>	Policy No. (Claimant):	
		Excess:	\$500.00
Repairer:	<b>V.z Automotive Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6 #02-02, 417883 Kaki Bukit - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 06/02/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKK5360P (548524)**

**[SKC5832L]**

**TP**

**LEE ENG HONG**


















**Feb 2 2018 12:00AM**


**[WONG SOO HUAT]**

**V.z Automotive Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/02/18 10:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/02/18 10:27	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
16	27/02/18 10:27	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
17	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
18	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
37	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
38	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
39	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
40	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
41	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
42	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
43	27/02/18 10:28	Photographs of Damaged Parts	 Load JPG	✓
44	27/02/18 10:28	Photo After Spray	 Load JPG	✓
45	27/02/18 10:28	Photo After Spray	 Load JPG	✓
46	27/02/18 10:28	Photo After Spray	 Load JPG	✓
47	27/02/18 10:28	Photo After Spray	 Load JPG	✓
48	27/02/18 10:28	Photo After Spray	 Load JPG	✓
49	27/02/18 10:28	Photo After Spray	 Load JPG	✓
50	27/02/18 10:28	Photo After Spray	 Load JPG	✓
51	27/02/18 10:28	Photo After Spray	 Load JPG	✓
52	27/02/18 10:28	Photo After Spray	 Load JPG	✓
53	27/02/18 10:28	Photo After Spray	 Load JPG	✓
54	27/02/18 10:28	Photo After Spray	 Load JPG	✓
55	27/02/18 10:28	Photo After Spray	 Load JPG	✓
56	27/02/18 10:28	Photo After Spray	 Load JPG	✓
57	27/02/18 10:28	Photo After Spray	 Load JPG	✓
58	27/02/18 10:28	Photo After Spray	 Load JPG	✓
59	27/02/18 10:28	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/02/18 14:22	PRI	 Load PDF	
2	05/02/18 14:22	EMAIL to TP reject their list of SJE	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18002299/GD3S2

Date: 09/05/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29004870SMA

Claimant Vehicle No : SKK5360P

Insured Vehicle No : SKC5832L

Date of Loss: 02/02/2018

Nature of Claim: TP

Claim No: 548524

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKK5360P

Make &amp; Model: SUBARU FORESTER, 2.0 XT AWD CVT (A)

Engine No: FA20G904228

Reg. Date: 30/07/2013 (Man. Year: 2012)

Chassis No: JF1SJGK85DG003358

Colour: Black

Odometer: 115519 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/50R18

Rear Tyre Size: 235/50R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 05/02/2018

Inspected At:

V.z Automotive Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6 #02-02  
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/9/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 09 May 2018)

**Parts:** M1-SUV      SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKK5360P)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >