

12/02/2018

ASS. REC. BY:

REF: CS/ICS18002301/Avd3m Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

mesmm

Lionel Chua

of

EC/CS

Date/Time:

5/2/18 @ 4.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

WPK 8988

Insured:

SJW 9567 H

at Workshop m/s:

MG solution

Tel:

9188 6931

of

23 Kaki Bukit Ave 4 #02-03B

Policy No:

Claim No:

DMP4180019H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/2/18

6/2/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:22pm @ 5/2/18

Person Contacted:

Ms. Heng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

WPK 8988 - X

SJW 9567H - X

26/4/18

Adrian confirmed LS \$4500 (Red 4468.55, 50%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: WPK8988 Yr Regn: 2006 / SeptType: M.Cari / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Innova c.c. 1998Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 240208 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PNI111N4008403807Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/65R15R: 205/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/02/18Survey held at: MG SolutionDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ECICS

RECEIVED 27 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 26/4 - typistDays Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

TP

Lump Sum / I.B.I: (\$

4500 k)

250

10

260

Survey Department Check List (Case Handler)

Reference No. : CS/1CS/8002301/Arv3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 26/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Monday, 5 February 2018 4:01 PM
To: mg3solution@gmail.com; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: ECICS Claims; SUR
Subject: RE: PRI for WPK8988
Attachments: PRI for WPK8988.pdf

Without Prejudice

Our claim no. DMPU1800019H

Thank you for your email.

We will appoint LKK for the Survey and please furnish us a copy of repair quotation/estimate to show the detail of each item parts and the colour photographs of the damaged vehicle to evaluate transparency on the pre-repair survey of this claim.

Aside to LKK,
Please assist to arrange for TP Survey.

Thank you.

Regards,
Lionel Chua
DID: +65 6303 0167
FAX: +65 6338 9267
ECICS LIMITED
Email: claims@ecics.com.sg

follow us on  facebook follow us on  twitter visit our website ecics.com.sg 

From: Jia Mu [mailto:mg3solution@gmail.com]
Sent: Monday, 5 February, 2018 12:47 PM
To: ECICS Claims
Subject: PRI for WPK8988

Dear person in charge,

Please refer to the attached file and arrange for pre-inspection.

We request survey name list below:

ADRIAN LING WAI PING	LKK AUTO CONSULTANTS PTE LTD
----------------------	------------------------------

Thanks,

Best Regards,
JACK Li

MG Solution Pte Ltd

No 23 Kaki Bukit Avenue 4

Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

		
--	---	---

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
Co. Reg. No. : 201427944N

Date : 5/2/18

vehicle in a
WPK 8988

To : ECICS LIMITED
Tel : 6337 4779
Fax : 6338 9267
Email : claims@ecics.com.sg

By Fax & Email

Attn: Motor Claims Department

Dear Sir,

Re: Accident involving motor vehicle Nos. WPK 8988 and SW 9567 H along
Dunearn Rd towards Newton Rd in between on 3/2/18
Barker Rd.

We are instructed by CHAN WOO LIM (Name of Claimant) to notify
you of a road traffic accident on the above mentioned. A copy of the Singapore Accident
Statement / Traffic Police Report filed is enclosed.

As a result of the accident, our client's / customer's vehicle has been damaged. Before our client
/ we proceed to repair the damaged vehicle, please let us know within **2 working days** of your
receipt of this notice whether you or your insurer would like to conduct a **Pre- Repair Survey** of
the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we
shall proceed to repair the vehicle without further reference to you.

Thank you,

Yours faithfully,



MS. HENG YOKE HONG
HP: 9188 6931

FOR SURVEYOR

Please initial here after completion of pre-repair
inspection. Thank you.

Appointed Surveyor: _____
(Name & Signature)

Date & Time of Inspection: _____

JABATAN PENGANGKUTAN JALAN MALAYSIA
PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **WPK8988**

No. Siri A **4313274**

Nama Pemunya : **NATION STRENGTH SDN BHD**
Berdaftar

717706-A
[SKT]

Alamat : **LOT 785, JALAN KOTA TINGGI (6 KM) KULAI**
81000 KULAI JOHOR D.T.

No. Enjin : **1TR6275549**
No. Casis : **PN111NV4008403807**
Buatan : **TOYOTA**
Nama Model : **INNOVA 2.0 E (A)**
Keupayaan Enjin : **1998 S.P**
Bahan Bakar : **PETROL**
Warna : **PERAK**
Kelas Kegunaan : **PERSENDIRIAN-MOTOKAR SYARIKAT**
Jenis Badan : **MOTOKAR PELBAGAI UTILITI**
Tahun Dibuat : **2006**
Tarikh Pendaftaran : **14/09/2006**
Status Pemunya : **SYARIKAT/PERTUBUHAN**
Muatan Tempatan : **8**
Duduk : **8**
Kadar Lesen : **6 bulan 12 bulan**
Kenderaan Motor : **RM492.90 RM985.80**

B.D.M/B.G.K : -
B.T.T. : -
Berat Kerb : -
B.T.M. : -
B.G.1 : -
B.G.2 : -
B.G.3 : -
B.G.4 : -
B.G.5 : -
B.G.6 : -
B.G.7 : -
B.G.8 : -
B.G.9 : -
B.G.10 : -
B.G.11 : -
B.G.12 : -



Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan
oleh Pengarah JPJ Negeri **JPJ CAW. BDR. SRI PERMAISURI**

PEMASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

HAK MILIK DITUNTUT OLEH : **PUBLIC BANK BERHAD** NO SIRI SURAT : **B404875**

NOTA PENTING

- Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
- Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
- Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
- Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
- Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
- Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
- Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

BAYARAN-BAYARAN

1	106071 14092006 15:01:11 031400 N 15-34360 SNORAIN 00647 CK 0 00647 WPK8988 13/09/2006 2153002RM*****500.00 2353070RM*****50.00 RM*****550.00	11	205050 07/09/2015 12:22:52 VEL02502 N DJD 054435 1 0 WPK8988 13/09/2016 2204000RM*****758.00 RM*****758.00
2	106071 14092006 15:01:58 035600 N 15-34361 SNORAIN 00649 CK 0 00649 WPK8988 13/09/2007 2204000RM*****985.80 RM*****985.80	12	0101011 11/11/2015 09:12:10 VEL04002 N IMAH333 007479 1 0 WPK8988 13/09/2016 2361000RM*****100.00 RM*****100.00
3	2 09023 11092007 15:14:14 052300 D/L N 02-10869 MEGA 08902 TU 0 08902 WPK8988 13092008 2204000 RM*****758.00 RM*****758.00	13	
4	2 09023 11092008 16:05:53 052300 D/L N 02-50597 AESHAH 03761 TU 0 03761 WPK8988 13092009 2204000 RM*****758.00 RM*****758.00	14	
5	2 09023 01092009 15:27:37 052300 D/L N 03-13168 JALILAH 09791 TU 0 09791 WPK8988 13092010 2204000 RM*****758.00 RM*****758.00	15	
6	2 09023 07092010 08:33:14 052300 D/L N 05-15090 QAYYUM 07110 TU 0 07110 WPK8988 13092011 2204000 RM*****758.00 RM*****758.00	16	
7	2 09023 09092011 16:10:51 052300 D/L N 02-54291 FIZI 03690 TU 0 03690 WPK8988 13092012 2204000 RM*****758.00 RM*****758.00	17	
8	2 05050 10092012 12:09:07 052300 D/L N 05-62649 ZAM 03091 TU 0 03091 WPK8988 13092013 2204000 RM*****758.00 RM*****758.00	18	
9	206029 10/09/2013 08:45:50 VEL02502 N IRA 002476 1 0 WPK8988 13/09/2014 2204000RM*****758.00 RM*****758.00	19	
10	206029 27/08/2014 12:57:26 VEL02502 N HARLINA 035588 1 0 WPK8988 13/09/2015 2204000RM*****758.00 RM*****758.00	20	

PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

1	CHAN WOOLIM 17 JALAN BERLIAN 8, TAMAN NORA, ULU TIRAM, 81800 JOHOR JOHOR	No. K.P./Def. Niaga/Sykt 771204016473 MAL 11112015	Tandatangan Pemunya Bendafar
2		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Bendafar
3		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Bendafar
4		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Bendafar
5		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Bendafar
6		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Bendafar

REKOD-REKOD PEMERIKSAAN

5	9
6	10
7	11
8	12

press to Adrian



RTD CODE : 13

ORIGINAL COPY

THE SCHEDULE

JADUAL

STAMP DUTY PAID
 DUTI SETEM DIBAYAR

M.X.1		PRIVATE CAR EXCLUDING GOODS	
INSURED PEMUNYA	CHAN WOOL LIM		Date of Issue/Time Tarikh Dikeluarkan/Waktu
ADDRESS ALAMAT	NO. 17 JALAN BERLIAN 8, TAMAN NORA, 81800 ULU TIRAM, JOHOR		E-Cover Note No. No. Nota Perlindungan
			AEJB0247856
			Account No. No. Akaun
			JB03667
			Premium
			1327.10
PERIOD OF INSURANCE TEMPCH INSURANS	(a) From 14-03-2017 (both dates inclusive) Dan To 13-03-2018 (termasuk kedua-dua tarikh) Hingga (b) Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium. Sebarang tempoh selanjutnya di mana Anda hendaklah membayar, dan Kami hendaklah bersetuju menerima premium pembaharuan.	Loading	0.00
		NCD	55.00 %
		2422180903170214	729.91
		Extra Coverage	
		LLP	67.80
		LLCP	7.50
		WINDSCREEN RM1,200.00	180.90
OCCUPATION/TYPE OF BUSINESS PERNIAGAAN/PEKERJAAN	OTHERS		GROSS PREM
			852.49
HIRE PURCHASE OWNERS/EMPLOYER'S LOAN SEWA BELI/PINJAMAN MAJIKAN			GST
			6.00 %
PARTICULARS OF VEHICLE BUTIR-BUTIR KENDERAAN	EXCESS LEBIHAN	0.00	STAMP DUTY
			10.00
Make and Type of Body / Badan dan Jenis Badan TOYOTA INNOVA 2.0E A/T	Registration No./Trailer No. / No. Pendaftaran/No. Treiler WPK8988		TOTAL DUE
			913.64
			AMOUNT PAYABLE
			(ROUNDED)
			913.65
Engine/Motor No. No. Enjin/Motor	Engine C.C./Horse Power/Tonnage/Watt Cc Enjin/Kuasa Kuda/Ten/Watt		Act. AKA
1TR6275549	1998.00 CC		61.97
Chassis No. No. Chasis	Seating Capacity Muatan Tempat Duduk	Year of Manufacture Tahun Dibuat	Sum Insured Jumlah Dinsuranskan
PN111NV4008403807	8	2006	39,000.00
NRIC No./Bus. Regn. No No. Kad Pengenalan/No. Pendaftaran Perniagaan	Telephone No. No. Telefon	Regn. Card No. No. Kad Pendaftaran	Type of Cover Jenis Perlindungan
771204016473	6016-78224951	A4313274	COMPREHENSIVE
This Policy is subject to the following endorsements as printed in this Policy or added thereon or attached thereto:- Polisi ini adalah tertakluk kepada pengendorsesan yang telah dicetak atau ditambah atau dimasukkan kedalamnya. ENDT.1 - EXCESS ALL CLAIMS ENDT.100 - LEGAL LIABILITY TO PASSENGER ENDT.113 - REFERENCE TO MOTOR VEHICLE MARKET VALUATION SYSTEM ENDT.72 - LEGAL LIABILITY OF PASSENGERS FOR NEGLIGENT ACTS ENDT.87 - AGREED VALUE CLAUSE ENDT.89 - COVER FOR WINDSCREENS, WINDOWS AND SUNROOF ENDT.W.1 - WARRANTY NO 1			
NAMED DRIVERS 1. THE POLICYHOLDER 2. CHAN WOOL LIANG			
LOGGING COMPLAINTS & GRIEVANCES IF YOU HAVE ANY COMPLAINTS OF UNFAIR MARKET PRACTICES BY THE COMPANY, YOU MAY CALL OR WRITE TO : 1. COMPLAINT UNIT ALLIANZ GENERAL INSURANCE COMPANY (MALAYSIA) GROUND FLOOR, BLOCK 2A, PLAZA SENTRAL, JALAN STESSEN SENTRAL 5, KUALA LUMPUR SENTRAL, 50470 KUALA LUMPUR TOLL FREE: 1-300-88-1028 TELNO : 03-2264 0520 FAX NO: 03-2264 0602 EMAIL: customer.service@allianz.com.my 2. OMBUDSMAN FOR FINANCIAL SERVICES ("OFS") (Formerly known as Financial Mediation Bureau) LEVEL 14, MAIN BLOCK, MENARA TAKAFUL MALAYSIA NO. 4, JALAN SULTAN SULAIMAN 50000 KUALA LUMPUR TELNO: +603-2272 2811 FAX NO: +603-2272 1577 EMAIL: enquiry@ofs.org.my 3. PENGARAH LAMAN INFORMASI NASIHAT DAN KHIDMAT (LINK) BANK NEGARA MALAYSIA GROUND FLOOR BLOCK C JALAN DATO' ONN 50480 KUALA LUMPUR TOLL FREE : 1-300-88-6466 FAX NO: 03-2174 1515 EMAIL: bnmatelelink@bnm.gov.my			
Geographical Area : Malaysia, Republic of Singapore and Negara Brunei Darussalam, Kawasan Geografi : Malaysia, Republik of Singapura dan Negara Brunei Darussalam Limitations as to User Authorised Driver : As described in the Certificate of Insurance. Had Penggunaan / Pemandu Yang Diben Kuasa : Seperti yang tercatat dalam Sijil Insurans		Issued By / Dikeluarkan oleh LW RISK MANAGEMENT AGENCY / JB03667-01 6-1, SUSUR 3, JALAN TUN ABDUL RAZAK 80200, JOHOR BAHRU TEL: 607-2236991 FAX: 607-2222661	
Please ensure All accidents are reported to the Police within 24 hours Pastikan semua kemalangan hendaklah dilaporkan kepada pihak Polis dalam masa 24 jam Issued In lieu of and Cancelling/Replacing Cover Note/Policy No. - Dikeluarkan Sebagai Pembatalan/Penggantian/No. Nota Perlindungan/ No. Polisi - Date of Signature of Proposal & Declaration Tarikh Tandatangan Cadangan dan Akaun		09-03-2017 Authorised Signature	

Important Notice : Policy print out can be obtained from our branch offices located nationwide or from your servicing agents.
 Kenyataan Penting : Cetakan polisi boleh diperolehi daripada pejabat cawangan kami di seluruh negara ataupun daripada ejen Allianz Anda.
 ALPHA-1 703667-000444274-2

RTD CODE : 13

CERTIFICATE OF INSURANCE SIJIL INSURANS

ORIGINAL COPY
SALINAN ASAL

M.X.1

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES 1959 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS & COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE)
MOTOR VEHICLES (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

CERTIFICATE NO. AEJB0247856
No. Sijil

NCD 55.00%
Diskaun Tanpa Tuntutan

1. Index Mark and Registration Number of Vehicle : WPK8988 1998.00 CC TOYOTA INNOVA 2.0E A/T
Tanda Indeks Dan Nombor Pendaftaran Kenderaan
2. Name of Policyholder : CHAN WOOLIM
Nama Pemegang Polisi
3. Effective date of the Commencement of Insurance for the purposes for the Regulations, Ordinance or Enactment : 14-03-2017
Tarikh efektif permulaan insuran untuk kegunaan Ordinan
4. Date of Expiry of the Insurance : 13-03-2018
Tarikh Luput Insuran
5. Persons or Classes of Persons entitled to drive
Orang atau Kelas Pihak Yang Dibenarkan Memandu
a) THE POLICYHOLDER b) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OF REGULATIONS IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use* Had Penggunaan
Use only for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the motor trade.

Digunakan hanya untuk tujuan sosial, domestik dan persiaran dan untuk perniagaan Pemegang Polisi.
Polisi ini tidak melindungi kegunaan untuk sewaan atau ganjaran, perlumbaan, mengkadar kelajuan, ujian kebolehppercayaan, ujian kelajuan, membawa barangan selain daripada sampel yang berkaitan dengan apa-apa pekerjaan atau perniagaan.

This Certificate is not transferable to a new owner of the Vehicle.

If for any reason the insurance is terminated during its currency this Certificate must be returned to the Company or if this Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the compulsory Insurance Legislation.

This Certificate must be returned if the insurance is suspended during its currency.

IMPORTANT

If you are involved in an accident causing injury to any person or damage to any property or other vehicle you must:

- (a) Try to obtain names and address of any witness to the accident.
- (b) Report to the Company immediately.
- (c) Refer to the Company immediately all communications received from the Police Authorities.
- (d) Sent to the Company immediately all letters from Third Parties unanswered.
- (e) Not pay money to any Party involved in the accident without the Company's written permission.

* Limitations rendered inoperative by Section 95 of the Road Transport Act, 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.

Had yang tidak beroperasi oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Bermotor (Gantrugi dan Risiko Pihak Ketiga) (Cap 189) Republik Singapura atau Seksyen 7 Akta Singapura atau Seksyen 7 Akta Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam adalah tidak termasuk di bawah tajuk ini.

I/We certify that the Policy to which the Certificate is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Saya/kami bersetuju bahawa Polisi di mana Sijil ini dikeluarkan tertakluk di bawah proviso Bahagian IV Akta Pengangkutan Jalan 1987, (Malaysia) Akta Kenderaan Bermotor (Risiko Pihak Ketiga & Gantrugi) (Cap 189) Republik Singapura dan Akta Kenderaan Bermotor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam.

Agent Code : JB03667
Kod Ejen

ALLIANZ GENERAL INSURANCE COMPANY (MALAYSIA) BERHAD (735426-V)



Authorised Signature

ALPHA-1703667-000444274-2

KAD PENGENALAN
MALAYSIA
IDENTITY CARD

771204-01-6473

MyKad

771204-01-6473


CHAN WOOLIM

NO 17
JALAN BERLIAN 8
TAMAN NORA
81800 ULU TIRAM
JOHOR

WARGANEGARA
LELAKI

WPK 8988
OWNER & DRIVER





KETUA PENGARAH
PENDAFTARAN NEGARA
771204-01-6473-02-01
(A3905509)

Touch
ngo

80K
chip

SN: 0000107000



LESEN MEMANDU
DRIVING LICENCE



MALAYSIA

CHAN WOOLIM



Bergengaman / Autocorrelity No. / Pendaftaran / Identity No.
MALAYSIA 771204016473

Kelas / Class

D

Tamgah / Validity

13/07/2015 - 04/12/2020

Alamat / Address

17 JALAN BERLIAN 8,
TAMAN NORA,
ULU TIRAM,
81800 JOHOR
JOHOR



WPK S988
OWNER & DRIVER

JPJL6

08392178

- A. Kenderaan Orang Gigit (Motorcycle) STM tidak melebihi 450 kg
- A1. Kenderaan Orang Gigit (Motor Cycle) unladen weight not exceeding 450 kg
- A1. Kenderaan Orang Gigit (Motor Cycle) STM tidak melebihi 450 kg
- A1. Kenderaan Orang Gigit (Motor Cycle) unladen weight not exceeding 450 kg
- B. Motor Cycle melebihi 500 cc
- B1. Motor Cycle tidak melebihi 500 cc
- B1. Motor Cycle not exceeding 500 cc
- B1. Motor Cycle not exceeding 500 cc
- B1. Motor Cycle not exceeding 500 cc
- C. Motor Cycle Tiga Roda
- C1. Motor Cycle Tiga Roda STM tidak melebihi 500 kg
- C1. Motor Cycle Tiga Roda STM not exceeding 500 kg
- C1. Motor Cycle Tiga Roda STM not exceeding 500 kg
- C1. Motor Cycle Tiga Roda STM not exceeding 500 kg
- D. Motor Cycle STM tidak melebihi 500 kg
- D1. Motor Cycle STM tidak melebihi 500 kg
- D1. Motor Cycle STM not exceeding 500 kg
- D1. Motor Cycle STM not exceeding 500 kg
- D1. Motor Cycle STM not exceeding 500 kg
- E. Motor Cycle STM tidak melebihi 500 kg
- E1. Motor Cycle STM tidak melebihi 500 kg
- E1. Motor Cycle STM not exceeding 500 kg
- E1. Motor Cycle STM not exceeding 500 kg
- E1. Motor Cycle STM not exceeding 500 kg

- F. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- F1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- F1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- F1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- G. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- G1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- G1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- G1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- H. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- H1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- H1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- H1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- I. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- I1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- I1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- I1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- J. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- J1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- J1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg
- J1. Traktor/Gerans / Tractor / Engine (Berat) STM tidak melebihi 5000 kg

209078 rgoOgRmc



Ketua Pengarah Pengangkutan Jalan



**SINGAPORE
POLICE FORCE**



T/20180203/2141

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

1 of 3

Report No. T/20180203/2141

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/02/2018 16:59		Vide Report No.:		Station Diary No.: 32	
Informant's Particulars					
Name of Informant: CHAN WOOLIM			Address: NO 17 JALAN BERLIAN 8 TAMAN NORA 81800 ULU TIRAM JOHOR		
ID Type / ID No.: NEW MALAYSIAN IC / 771204016473			Contact No.: Home/Office: Mobile: 93481599		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 40	Date of Birth: 04/12/1977	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: PROPERTY AGENT			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 03/02/2018 12:40	Type of Location: Straight Road
Location: Along Road 1 DUNEARN ROAD TOWARDS NEWTON ROAD IN BETWEEN BARKER ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJW9567H	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Seriously Damaged	0
WPK8988	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180203/2141

2 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20180203/2141

CONTINUATION OF REPORT

Driver			
Name	TUN MYINT OO	ID No.	S2743052Z
Related Vehicle	SJW9567H (Car)	Contact No.	81355650
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHAN WOOLIM	ID No.	771204016473
Related Vehicle	WPK8988 (Car)	Contact No.	93481599
Hospital/Clinic	GREEN CROSS MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	03/02/2018	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

On 3/2/18 at about 1240hrs, I was driving along Dunearn rd towards Newton Rd in between barker rd. I was travelling on the center lane when the vehicle in front of me stopped, I also slowed down and stopped. There was very heavy traffic then. Suddenly, there was a huge impact from my rear. The vehicle behind me SJW9567H, had hit onto the rear of my vehicle WPK8988. My rear bumper was dented whereas the other party vehicle had much more serious damages. No traffic police nor ambulance came down to scene. I am lodging this report for insurance claims.



**SINGAPORE
POLICE FORCE**



T/20180203/2141

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

3 of 3

Report No. T/20180203/2141

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 LIM JIA HUI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AE17 / SINGAPORE
SSI KASMAWATI BTE SAMIAN
Contact No.: 65476179

Authentication Stamp

NP168

SIGNATURE

Signature Of Informant:

Date/Time:

03/02/2018 16:59

Classification Of Case:

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: NTUC INCOME INSURANCE	DATE	: 02/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: WPK8988	Veron	
MODEL	: TOYOTA INNOVA 2.0E		
CHASSIS NO		PX1111NV4008403807	
<u>ACCIDENT DETAILS</u>		DATE	: 3-Feb-18
		TIME	: 12:40HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Perked</i>	1	\$ 1,588.30	\$ 1,588.30
2	TAIL GATE LOGO <i>Per</i>	1	\$ 72.00	\$ 72.00
3	TAIL GATE EMBLEM 'TOYOTA' <i>Per</i>	1	\$ 85.00	\$ 85.00
4	TAIL GATE EMBLEM 'INNOVA' <i>Per</i>	1	\$ 85.00	\$ 85.00
5	TAIL GATE EMBLEM '2.0' <i>Per</i>	1	\$ 85.00	\$ 85.00
6	TAIL GATE EMBLEM 'E' <i>Per</i>	1	\$ 85.00	\$ 85.00
7	TAIL GATE TOP LOCK <i>Perked</i>	1	\$ 280.00	\$ 280.00
8	TAIL GATE LOWER CATCH <i>Per</i>	1	\$ 62.00	\$ 62.00
9	TAILGATE WEATHER STRIP <i>Per</i>	1	\$ 266.00	\$ 266.00
10	TAILGATE WINDSCREEN MOULDING <i>Per</i>	1	\$ 122.00	\$ 122.00
11	REAR BUMPER <i>Perked</i>	1	\$ 688.30	\$ 688.30
12	REAR BUMPER SIDE RETAINER <i>Per</i>	2	\$ 72.00	\$ 144.00
13	TAILLAMP RH <i>Perked</i>	1	\$ 366.00	\$ 366.00
14	REAR END PANEL <i>Perked</i>	1	\$ 760.00	\$ 760.00
15	REAR EXHAUST PIPE <i>Per</i>	1	\$ 930.00	\$ 930.00

45323

3389.22

TOTAL PRICE \$ 5,618.60

LESS 25% \$ 1,404.65

SUB TOTAL PRICE \$ 4,213.95

1043
45
40
55
46
60
4
680
695

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>not new</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE SEALANT <i>not new</i>	1	\$ 60.00	\$ 60.00
3	TAILGATE WINDSCREEN SEALANT <i>2pc</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
5	TAILGATE STICKER <i>new</i>	1	\$ 300.00	\$ 300.00
6	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 35.00	\$ 35.00
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
9	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00

SSO

TOTAL \$ 965.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	700	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	WIRING CHECK	\$ 150.00	30	
4	TUFF COAT	\$ 200.00	X	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 180.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	50	
7	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	100	
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80	
9	TRANSFER TAILGATE MECHANISM	\$ 180.00	80	

TOTAL

\$3,790.00

1700

ESTIMATE REPORT

hence notify the Repairer of the following:

TOTAL PARTS COST \$ 5,178.95

- To display damaged part(s) during resurvey
- Parts prices are on a "Without Prejudice" basis

TOTAL LABOUR COST \$ 3,790.00

- Third party survey is on a "Without Prejudice" basis

TOTAL REPAIR COST \$ 8,968.95

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

APPROVED DETAILS

EXCESS :

Adrian Lij
t/s 06/02/18
06 days

total: 5649.22
t/s: 4.51C

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18002301/AVD3N2

Date: 04/05/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	WPK8988	Insured Vehicle No :	SJW9567H
Date of Loss:	03/02/2018	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	WPK8988	Engine No:	1TR6275549
Make & Model:	TOYOTA INNOVA, 2.0 (A)	Chassis No:	PN111NV4008403807
Reg. Date:	14/09/2006 (Man. Year: 2006)	Odometer:	240208 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,178.95	3,949.22	1,229.73	23.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,700.00	2,090.00	55.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,968.95	5,649.22	3,319.73	37.01
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	8,968.95	4,500.00	4,468.95	49.83
+ GST 7.00/7.00% (S\$)	627.83	315.00	312.83	49.83
Nett Amount (S\$)	9,596.78	4,815.00	4,781.78	49.83

INSPECTION

Date of Assignment:	05/02/2018	
Date Inspected:	06/02/2018 Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2018)
Parts:	M1-MPV	TOYOTA INNOVA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WPK8988)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,588.30 FL	*1,043.00 FL
2	1		*TAIL GATE LOGO	Necessary	72.00 FL	*45.00 FL
3	1		*TAIL GATE EMBLEM TOYOTA	Necessary	85.00 FL	*40.00 FL
4	1		*TAIL GATE EMBLEM INNOVA	Necessary	85.00 FL	*55.00 FL
5	1		*TAIL GATE EMBLEM 2.0	Necessary	85.00 FL	*48.00 FL
6	1		*TAIL GATE EMBLEM E	Necessary	85.00 FL	*60.00 FL
7	1		*TAIL GATE TOP LOCK	Damaged	280.00 FL	*280.00 FL
8	1		*TAIL GATE LOWER CATCH	Not Necessary	62.00 FL	*- FL
9	1		*TAILGATE WEATHER STRIP	Cut	266.00 FL	*266.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING	Necessary	122.00 FL	*122.00 FL
11	1		*REAR BUMPER	Deformed	688.30 FL	*688.30 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	144.00 FL	*144.00 FL
13	1		*TAILLAMP RH	Cracked	366.00 FL	*366.00 FL
14	1		*REAR END PANEL	Dented	760.00 FL	*680.00 FL
15	1		*REAR EXHAUST PIPE	Bent	930.00 FL	*695.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*TAIL GATE SEALANT	Not Necessary	60.00 FS	*- FS
18	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
19	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
20	1		*TAILGATE STICKER	Necessary	300.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
22	1		*SET TAIL LAMP CLIP	Not Necessary	35.00 FS	*- FS
23	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
24	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,583.60	5,082.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,404.65	1,133.08
Total Parts (\$\$)	5,178.95	3,949.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,400.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	600.00
3	WIRING CHECK	New	150.00	30.00
4	TUFF COAT	New	200.00	-
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	New	180.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	180.00	50.00
7	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	100.00
8	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
9	TRANSFER TAILGATE MECHANISM	New	180.00	80.00
Gross Labour Cost (S\$)			3,790.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >