

23/03/2001

Condition

ASS. REQ. BY:

REF: CS/FCI18002305/Agg302

Special Instruction:

Surveyor:

(WS)

Adnan

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

5/2/18 @ 4:21 pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGQ 1366R

Insured:

SH 95884

at Workshop m/s

New Hock Teck

Tel:

67 47 92 41

of

1 Kaki Bukit Ave 6, Blk C # 01-13 Autobay

Policy No:

D-180880936 MFSH

Claim No:

D18001059MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A.

04/02/2018

CA / REV / REP. / REV 24 HRS

w/p

6/2/18

H.O.D. Endorsement:

Date/Time:

5:42pm 06/2/18

Person Contacted:

Sukyi

Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction	Estimate
	SGQ 1366R - CCE / LPC16011603 / Agg302	D.O.A.: 19/6/16
	SH 95884 - CS / FCI17022206 / b	D.O.A.: 12/11/17
07/2/18 @ 2:13pm	Informed Eileen, we are pending estimate from repairer.	
08/3/18 @ 1:24pm	revised to Eileen Lee by email.	
	US \$5600, 7 days (Red \$1050.00, 6472)	

Page: Date: **6/2/18** Vehicle: **SGQ1366R** Page: **2007 Jun.**

Estimated Cost: Type: **Wagon** (M/D/S/L/B/S/Van/Long/Taxi/Prime/Motor Truck/Trailer)

OD/TP/VS/TF/RES/OD/RES/EVA/INV/MV
To inspect vehicle No: **SGQ1366R**
at Workshop No: **New Hock Teck**
of **1kaki Blot Ave 6 Blk C # 01-43**
Insured: Make: **Nissan Sylphy** 1498
Colour: **white** A/C: Insured: Std. A: NA
St. Reading: **148525** T. Radio: Insured: Std. A: NA

Eng. No: **JN1BAAG-1120101037**
D.No: **JN1BAAG-1120101037**
Gen. Cond: **Good** (Good/Fair/Poor/Burnt)

Steering: Inorder (Inorder/Jammed/Leaked/Burnt or
Brake: Inorder (Inorder/Jammed/Leaked/Burnt or

Mod.: Nil (S/Rim) (STD A/Rim) or
Tyre Size: F: **195/65R15**
R: **195/65R15**

BS/DUN/EXNOVA/GY/RS/LIZA/MIO/OHTSU/PIR/SUMI
TOYO (TOYO) or

Ball or Market Value: Front: Rear:
R.Bal: **06** P.Bal: **06**
L.Bal: **06** L.Bal: **06**
D.O.A: **06/02/18**
Surveyed at: **NHT.**

Des. of Damages: Frnt: **Yes** (Yes/No) OS: N.S. L.O. Rocthod or
The U.C. / Chassis/frame Body Structure affected due to collision

Date: Time: Action: Instruction: **TP 1st Cap.**

*Note: MV: **28K**
PV: **198K**
Nett: **8.2K**

RECEIVED 6 JUN 2018

Date/Time: Pre Pass: ☐ : Preli. Report
Days Of Repair: **7**
Resurvey No. of Trip: **1**

Date/Time: Pre Pass: ☐ : Final Report
Add Fee: ☐ Site Insp: \$
☐ Transp: \$
☐ Test: \$
☐ Fee: \$

Report Format: **TP**
L.H. No. Sign: **5600**


6x15=90
156+90
50
50
14
059
12/3/18
474

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002305/Aqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9588U	Veh. Inspected	SGQ 1366R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001059MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/02/2018	Inspection Date	06/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: CR/FZ118002304/And3
 Policy Type: OD / TP / TP RES / TL / EVA

SGA/1366R

Case Handler

Typist

Admin (Nivitha): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	<input checked="" type="checkbox"/>			
C	Customer Code	<input checked="" type="checkbox"/>			
N	Assign From	<input checked="" type="checkbox"/>			
C	Assign Date	<input checked="" type="checkbox"/>			
C	Veh No (Inspected)	<input checked="" type="checkbox"/>			
C	Veh No (Insured)	<input checked="" type="checkbox"/>			
C	D.O.A	<input checked="" type="checkbox"/>			
C	Policy No	<input checked="" type="checkbox"/>			
C	Claim No	<input checked="" type="checkbox"/>			
C	Insurance Authorisation (CA /REV/REP)	<input checked="" type="checkbox"/>			
C	Report Type	<input checked="" type="checkbox"/>			
C	Weekend Charges	<input checked="" type="checkbox"/>			
N	Survey held at/Repairer	<input checked="" type="checkbox"/>			
C	Excess				

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	<input checked="" type="checkbox"/>			
C	Regn Month/Year	<input checked="" type="checkbox"/>			
N	Vehicle Type	<input checked="" type="checkbox"/>			
N	Make & Model	<input checked="" type="checkbox"/>			
C	Engine Capacity. (C.C)	<input checked="" type="checkbox"/>			
N	Colour	<input checked="" type="checkbox"/>			
C	Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>			
C	Chassis No	<input checked="" type="checkbox"/>			
N	General Condition	<input checked="" type="checkbox"/>			
N	Steering	<input checked="" type="checkbox"/>			
N	Brake	<input checked="" type="checkbox"/>			
N	Modification (Modi)	<input checked="" type="checkbox"/>			
C	Tyre Size	<input checked="" type="checkbox"/>			
N	Tyre Make	<input checked="" type="checkbox"/>			
C	Tyre Balance	<input checked="" type="checkbox"/>			
C	Date of Inspection	<input checked="" type="checkbox"/>			
N	Survey held	<input checked="" type="checkbox"/>			
N	Des.of Damages	<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>			
---	--------------------------------------	-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	<input checked="" type="checkbox"/>			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	<input checked="" type="checkbox"/>			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	<input checked="" type="checkbox"/>			
---	-------------------------	-------------------------------------	--	--	--

Check By: [Signature] 08/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-02-2018	Our Ref No. D18001059MFSH
Accident Date	04-02-2018	Claim Type. Third Party
Insured Vehicle	SH9588U	Third Party Vehicle. SGQ1366R
Survey Location	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUKIT	
Contact Person.	REENA/SUKYI	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NEW HOCK TECK MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234655)



PRI Documents



Close



PRI Header Details

Claim No	D18001059MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & NEW HOC
Workshop Name	NEW HOCK TECK MOTOR PTE LTD (Contact Person : REENA/SUKYI)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUI Mobile: 0 , Phone: 67479241 , Fax: 67417276 EmailId: ADMIN@NHTMOTOR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9588U	TP Vehicle No	SGQ1366R
PRI Recieved Date	05-02-2018 05:21:31 PM	Surveyor Appointed Date	05-02-2018 04:20:01 PM	Surveyor Accept Date	05-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 8 March 2018 2:29 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001059MFSH/1
Attachments: CSFC118002305Aqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SGQ 1366R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)

Sent: Wednesday, 7 February 2018 2:13 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001059MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SGQ 1366R on 06/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Monday, 5 February 2018 4:26 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001059MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001059MFSH

Date: 08 March 2018

Our Ref: CS/FCI18002305/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGQ 1366R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/02/2018 at the premises of M/s NEW HOCK TECK, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,650.20</u>
Revised Estimate Amount	: S\$ <u>5,600.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 7 February 2018 2:13 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001059MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SGQ 1366R on 06/02/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 5 February 2018 4:26 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001059MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 5 February 2018 4:20 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001059MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1337D

Vehicle Details

Vehicle No.: SGQ1366R
Vehicle to be Exported: Yes
Intended De-registration Date: 06 Feb 2018
Vehicle Make: NISSAN
Vehicle Model: SYLPHY 1.5 4AT
Primary Colour: White
Manufacturing Year: 2006
Engine No.: HR15054216A
Chassis No.: JN1BAAG11Z0101037
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$17,161.00
Original Registration Date: 06 Jan 2007
First Registration Date: 06 Jan 2007
Transfer Count: 0
Actual ARF Paid: \$18,878.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Jan 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,323.00
COE Rebate Amount: \$19,822.00
Total Rebate Amount: \$19,822.00

Message

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1337D

Vehicle Details

Vehicle No.: SGQ1366R

Vehicle to be Exported: Yes

Intended De-registration Date: 05 Feb 2018

Vehicle Make: NISSAN

Vehicle Model: SYLPHY 1.5 4AT

Primary Colour: White

Manufacturing Year: 2006

Engine No.: HR15054216A

Chassis No.: JN1BAAG11Z0101037

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$17,161.00

Original Registration Date: 06 Jan 2007

First Registration Date: 06 Jan 2007

Transfer Count: 0

Actual ARF Paid: \$18,878.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Jan 2022

COE Category: A - Car (1600cc & below)


COE Period(Years):	5
PQP Paid:	\$25,323.00
COE Rebate Amount:	\$19,836.00
Total Rebate Amount:	\$19,836.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Feb 2018

OK



ANNOUNCING Cosmo Automobiles
as sgCarMart Premium Dealer for the 3rd Consecutive Year


C O S M O

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Mar 2012, Audi A4 1.8 TFSI @ \$71,888 - CNY Deal!



Agent Maintained. Condition As Good As New. Handle With Care. No Insurance.
Tradeit.Com Pte Ltd



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

4 vehicles

Sylphy

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Sylphy		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan	Sylphy 1.5A (COE till 05/2021)	\$32,800	N.A	25-May-2006	1,498 cc	-	Sedan	Available
1 Owner Only. End Of COE Still Get Back \$4557 Rebate From LTA (Proof In Photos). Cheapest And Lowest Depreciation, Mechanic Owner! Tan Chong Unit, Low Depreciation Of \$7k Per Year.									
Posted: 20-Dec-2017 Tags: 2006 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A (COE till 04/2021)	\$26,899	\$8,330 /yr	26-May-2006	1,498 cc	-	Sedan	Available
We Are The Coe Specialists, No Gimmicks, Honest Dealing. No Repairs Needed. High Loan With \$3000 Down Payment Drive Away! 100% Approval Buy With Trust & Confidence Only. Special Paint. New Leather.									
Posted: 29-Jan-2018 Tags: 2006 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A (COE till 01/2027)	\$54,933	\$6,110 /yr	31-Jan-2007	1,498 cc	-	Sedan	Available
Consignment Unit. COE Paid \$50645 Till Jan 2027, New SLV Nice Number 2787. Viewing And Test Drive Is Available. Price Negotiable.									
Posted: 13-Jan-2018 Tags: 2007 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									
	Nissan	Sylphy 1.5A (New 5-yr COE)	\$33,800	\$6,760 /yr	01-Feb-2008	1,498 cc	129,000 km	Sedan	Available
Well Maintain Car. Excellent Interior And Exterior Condition. Reliable And Spacious. View To Believe. Bank Loan And In House Loan Available. \$0 Down Payment Available. Call Now To Make A Appointment.									
Posted: 18-Jan-2018 Tags: 2008 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Sylphy, Sylphy Singapore, used Sylphy Singapore, used Sylphy, used vehicles Singapore or even buy used Sylphy Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Product
- Article
- Forum

- About Us
- Careers
- Contact Us
- Sitemap

MSME18017827 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 05/02/2018 16:31
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/02/2018 16:31
Date Of Accident	04/02/2018 15:45
Exact Location Of Accident	CLEMENTI ROAD TWDS CHURCH OF HOLY CROSS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ1366R
Insured/Policyholder	
Name Of Registered Owner	LOW CHOY SUM
NRIC No	S0001337D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91339377
Alternative Phone No	OFFICE-91339377
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5025671555-10
Cover Note Number	
Driver	
Name of Driver	LOW CHOY SUM
NRIC No	S0001337D
Date Of Birth	06/12/1947
Occupation	INDOOR
Date Of Driving Pass	12/01/1976
Driving Experience	42 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91339377
Fax Number	
Contact Number	OFFICE-91339377
Email Address	NOEMAIL

Address 3 JALAN PARI DEDAP
 Postcode 488606
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : CHEW CHING LEONG
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS ON THE THIRD LANE FROM THE RIGHT OUT OF 4 LANES. TRAFFIC LIGHT TURNED GREEN. JUST AS I ABOUT TO MOVE OFF, I SUDDENLY FELT AN IMPACT FROM BEHIND. VEHICLE B HAD HIT ONTO MY VEHICLE AND CAUSED DAMAGES. AFTER THE ACCIDENT, I ALIGHTED AND REALISED IT WAS A 4 CARS CHAIN COLLISION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SH9588U
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category TAXI
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJM6668Y
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	YN6596M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE D
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

		A: SGQ1366R B: SH 9588U C: SJM 6668Y D: YN 6596M.
		Clement Rd towards Church Hill Cross

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was on the third lane from the right out of four lanes.

Traffic light turned green, just as I was about to

move off, I suddenly felt an impact from behind.

Vehicle "B" had hit into my vehicle and caused

damage.

After the accident, I aligned and realised it was

a four car chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

was on the third lane from the right out of four lanes
Traffic light turned green. Just as I was about to
move off, I suddenly felt an impact from behind.
Vehicle "B" had hit into my vehicle and caused
damage.
After the accident, I aligned and realised it was
a four car chain collision.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

LOW CHOY SUM

06/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.

Xiao Chen.

JX18AAG1120101037

Accident date: 04/02/2018

Estimated repair cost for vehicle no: SGQ1366R NISSAN SYLPHY 1.5 A '07

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Boot Lid Buckled		\$850.90 ✓
2	1	Rear Bumper Deboned		\$652.70 ✓
3	2	Rear Bumper Bracket LH Dented	\$65.10	\$130.20 65.10
4	2	Rear Bumper Side Retainer New	\$81.70	\$163.40 70.40
5	1	Rear End Panel Dented		\$591.80 ✓
6	2	Rear Fender Inner Trim Board New	\$342.20	\$684.40 +
7	1	Rear Spare Tyre Panel Repair		\$771.40 +
8	1	Rear Spare Tyre Panel Top Cover Deboned		\$615.20 ✓
9	1	Rear Windscreen Moulding New		\$130.10 +
10	1	Rear L/H Fender Repair		\$1,148.40 +
11	1	Rear L/H Fender Glass Assy New		\$563.30 +
2		Taillamp Panel Bent	197.90	395.80
			Subtotal:-	\$6,301.80

3241.9

2269.33

S/N	QTY	ITEMS / NETT	U/PRICE	AMOUNT
12	2	Rear Boot Lid Hinge <i>Not New</i>	\$75.90	\$151.80 ✓
13	1	Rear Boot Lid Emblem Logo <i>2 new</i>		\$35.20 ✓
14	1	Rear Boot Lid Sylphy logo <i>2 new</i>		\$68.70 ✓
15	1	Rear Boot Lid Centre Top Moulding <i>2</i>		\$321.00 ✓
16	4	Rear Boot Lid Centre Top Moulding Clip <i>2 new</i>	\$6.50	\$26.00 ✓
17	1	Rear Boot Lid Lower Chrome Moulding		\$173.80 ✓
18	4	Rear Boot Lid Lower Chrome Moulding Clip	\$6.50	\$26.00 ✓
19	2	Rear Boot Lid Side Reflector <i>at</i>	\$155.10	\$310.20 ✓
20	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$97.00 ✓
21	1	Rear Boot Lid Inner Rubber <i>at</i>		\$79.20 ✓
22	8	Rear Boot Lid Inner Trim Board Clip <i>2 new</i>	\$6.50	\$52.00 ✓
23	2	Rear Tail Lamp <i>1 ruled</i>	\$230.20	\$460.40 ✓
24	4	Rear Tail Lamp Clip <i>1 new</i>	\$8.00	\$32.00 ✓
25	2	Rear Bumper Side Reflector <i>Not new</i>	\$41.20	\$82.40 ✓
26	1	Rear Bumper Centre Chrome Moulding <i>New</i>		\$156.70 ✓
27	1	Rear End Panel Top Garnish <i>Damaged</i>		\$203.00 167.80 ✓
28	1	Rear End Panel Lock Sensor <i>Damaged</i>		\$139.00 ✓
29	16	Rear Fender Inner Trim Board Clip <i>2 new</i>	\$6.50	\$104.00 ✓
30	1	Rear Exhaust <i>Best</i>		\$568.70 ✓
31	1	Rear Centre Exhaust <i>2</i>		\$488.60 ✓
32	2	Rear Exhaust Mounting <i>2 new</i>	\$56.80	\$113.60 ✓
33	1	Rear Exhaust Aluminium Cover		\$94.00 ✓

Subtotal:- \$3,783.30
 2114.90
 1903.41

S/N	QTY	ITEMS / SPECIAL NETT	U/PRICE	AMOUNT
34	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$350.00 200 ✓
35	1	Rear Bumper Inner Sponge <i>Damaged</i>		\$85.10 ✓
36	1	Rear Spare Tyre Panel & End Panel Sealant <i>New</i>		\$450.00 60 ✓

345.10

Subtotal:- \$885.10

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 20
To remove & refit rear windscreen	\$120.00 X
Gum	\$50.00 X
Towing fee	\$100.00 X
To check wiring	\$100.00 30
Tuff kote	\$150.00 40
Panel beating	\$1,800.00 1000
Spray painting	\$1,600.00 1200

Subtotal:- \$4,680.00

Total:- \$15,650.20

total 6997.84

H/S: 5.6K

0 Days

5.6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002305/Aqd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-03-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SH 9588U	Veh. Inspected	SGQ 1366R
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001059MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	05/02/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JN1BAAG11Z0101037	Colour	WHITE
Odometer	148525	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/02/2018	Inspection Date	06/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGQ 1366R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	850.90	850.90
1	REAR BUMPER	DEFORMED	652.70	652.70
2	REAR BUMPER BRACKET @\$65.10	N/S DENTED	130.20	65.10
2	REAR BUMPER SIDE RETAINER @\$81.70	NECESSARY	163.40	70.40
1	REAR END PANEL	DENTED	591.80	591.80
2	REAR FENDER INNER TRIM BOARD @\$342.20	NOT NECESSARY	684.40	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	771.40	-
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	615.20	615.20
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	130.10	-
1	REAR L/H FENDER	TO REPAIR SEE LABOUR	1,148.40	-
1	REAR L/H FENDER GLASS ASSY	NOT NECESSARY	563.30	-
2	TAILLAMP PANEL @\$197.90		395.80	395.80
	LESS 30% DISCOUNT		-	-972.57
			6,697.60	2,269.33
NETT ITEMS				
2	REAR BOOT LID HINGE @\$75.90 (N)	NOT NECESSARY	151.80	-
1	REAR BOOT LID EMBLEM LOGO (N)	NECESSARY	35.20	35.20
1	REAR BOOT LID SYLPHY LOGO (N)	NECESSARY	68.70	68.70
1	REAR BOOT LID CENTRE TOP MOULDING (N)	NOT NECESSARY	321.00	-
4	REAR BOOT LID CENTRE TOP MOULDING CLIP @\$6.50 (N)	NOT NECESSARY	26.00	-
1	REAR BOOT LID LOWER CHROME MOULDING (N)	NOT NECESSARY	173.80	-
4	REAR BOOT LID LOWER CHROME MOULDING CLIP @\$6.50 (N)	NOT NECESSARY	26.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$155.10 (N)	CUT	310.20	310.20
1	REAR BOOT LID INNER LOCK (N)	DAMAGED	97.00	97.00
1	REAR BOOT LID INNER RUBBER (N)	CUT	79.20	79.20
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50 (N)	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$230.20 (N)	CRACKED	460.40	460.40
4	REAR TAIL LAMP CLIP @\$8.00 (N)	NECESSARY	32.00	32.00

Report Ref No. CS/FCI18002305/Aqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimated Repair Cost (S)	Insurance Allowance (S)
2	REAR BUMPER SIDE REFLECTOR @\$41.20 (N)	NOT NECESSARY	82.40	-
1	REAR BUMPER CENTRE CHROME MOULDING (N)	NECESSARY	156.70	156.70
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	203.00	167.80
1	REAR END PANEL LOCK SENSOR (N)	DAMAGED	139.00	139.00
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50 (N)	NOT NECESSARY	104.00	-
1	REAR EXHAUST (N)	BENT	568.70	568.70
1	REAR CENTRE EXHAUST (N)	NOT NECESSARY	488.60	-
2	REAR EXHAUST MOUNTING @\$56.80 (N)	NOT NECESSARY	113.60	-
1	REAR EXHAUST ALUMINIUM COVER (N)	NOT NECESSARY	94.00	-
	LESS 10% DISCOUNT		-	-211.49
			3,783.30	1,903.41
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR BUMPER INNER SPONGE (SN)	DEFORMED	85.10	85.10
1	REAR SPARE TYRE PANEL & END PANEL SEALANT (SN)	NECESSARY	450.00	60.00
			885.10	345.10
	LABOUR			
	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	GUM.	NOT NECESSARY	50.00	-
	TOWING FEE.	NOT NECESSARY	100.00	-
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	40.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL AND REAR L/H FENDER.		1,800.00	1,000.00
	SPRAY PAINTING.		1,600.00	1,200.00
			4,680.00	2,480.00
	GRAND TOTAL		16,046.00	6,997.84

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,800.00
---	--	--	-----------------

Report Ref No. CS/FCI18002305/Aqd3e2



Report Ref No. CS/FCI18002305/Aqd3e2

MARKET VALUE: \$28,000.00 (EST)-PAPER VALUE: \$19,800.00=NETT VALUE: \$8,200.00

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar, with a stylized flourish.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.