

ASS. REC. EN

REF: CS3/MSG17024465/R/vb-102

Special Information

Menmen

Rasut

ASSIGNMENT (Office)

From (Person):

Monica Chung

MSIG

Date/Time

06/02/2018

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCV4455T

Insured:

EQ 7788R

at Workshop m/s

Yap Lee Motor

Tel:

6844 1555

of 1 kaki Blk Ave 6 #01-26 Autobay

Policy No: A80433216 AVW

Claim No: 542335

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A. 19/12/17

CA / REV / REP. / REV 24 HRS

wup

H.O.D. Endorsement:

Date/Time:

12:42pm @ 27/12/17


Person Contacted:

Ms. Shirley

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Do Not Amend
	SCV4455T-NA INCL600789/d2	D.O.A: 01/02/2016
	EQ 7788R-CV1/VAL17003392/CV	D.O.A: 20/02/2017
	Dismantle Part: 28.12.2017	
	After repair: 29.12.2017	

26/11/18 954am Email to Monica Chung thru Menmen.

21/12/18 submit L/S \$2500, 4 days  
Red: \$3100, 55%.


19/1/2018

RECEIVED 17/12/2017

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SCV 4455 T

at Workshop no's YAP LEE MOTORS

of PULI, KAKI PARKIN RD 6 # 01-76 A.B

Insured: MSLH

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:		
IDAC Accident Rpt:	Consistent?: Yes or No	
GIA / FR Seen:	Consistent?: Yes or No	
Est. Repairs:	days	Res.: Yes or No
Lum Sum:	%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time	Action / Instruction
-------------	----------------------

Veh No: SCV 4455T      Yr Regn: 2016 Jan 29  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Audi A5 Sportback 2.0A cc  
Colour: Black A.C.: Insured / Std / NI / NA  
Sp.Reading: 17063 T.Radio: Insured / Std / NI / NA  
Eng/No:

C/No: WAUZZZ8T9BA 093417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40ZR18  
R: 18

BS/DUN/EXNOVA/GY/FS/LIZA/MIS/OHTSU/PIR/SUMI/  
TOYO/YOKO or

Front

R/Bal. 6 0000

L/Bal. 12/20

D.O.A. 4 12 17

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

ESTIMATE RANGE OF RATE -

26/04/18 Repn range ~~1.2K~~ \$1.2K to \$1.5K. wtu 2 days 2

Date/Time: File Pass to:

☐: Preli. Report

☐ : Final Report

DataTime: File Return 102

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Fee: \$

10/15/2015

1-20-00

\_\_\_\_\_

Survey Fee:

Transcreator

— 100 —

250

١٠٠٠

### Report Format :

Lump Sum / I.B.I.: 63

180
-----



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17024465/R1vb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 06-02-2018	
			Code : MSG	
<b>1. Policy Particulars - THIRD PARTY CLAIM</b>				
Insured Veh.	EQ 7788R	Veh. Inspected	SCV 4455T	
Policy No.	A80433216AVW	Coverage (\$)	0.00	
Claim No.	542335	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	06/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	19/12/2017	Inspection Date	06/02/2018	
Survey held at	YAP LEE MOTOR BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Catherine Chong (LKK Auto)

---

**From:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Sent:** Tuesday, 6 February, 2018 10:35 AM  
**To:** Catherine Chong (LKK Auto); ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: PRE-REPAIR SURVEY - EQ7788R(OI) / SCV4455T ON 19/12/2017 Our Ref: 542335

Dear Catherine,

We have sent back case for paper adjustment survey.

Regards,

**Monica Chung**  
Assistant Executive, Claims Services (Motor)  
Direct line +65 6594 2552 | Direct fax +65 6225 7402 | [monica\\_chung@sg.msig-asia.com](mailto:monica_chung@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, January 25, 2018 6:18 PM  
**To:** Monica Chung <Monica\_Chung@sg.msig-asia.com>; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: PRE-REPAIR SURVEY - EQ7788R(OI) / SCV4455T ON 19/12/2017 Our Ref: 542335

Dear Monica,

Thank you for your email.

We will submit report to you shortly.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Monica Chung [mailto:Monica\_Chung@sg.msig-asia.com]  
**Sent:** Thursday, 25 January, 2018 4:22 PM  
**To:** Nivitha (LKK Auto) <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** FW: PRE-REPAIR SURVEY - EQ7788R(OI) / SCV4455T ON 19/12/2017 Our Ref: 542335

Dear both,

Please submit preliminary advice/survey report as we have received letter of demand.

Thanks.

Regards,

**Monica Chung**

Assistant Executive, Claims Services (Motor)

Direct line +65 6594 2552 | Direct fax +65 6225 7402 | [monica\\_chung@sg.msig-asia.com](mailto:monica_chung@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

**From:** Rashitha Binte Shahuthuman

**Sent:** Friday, December 22, 2017 3:18 PM

**To:** 'Ong & Shan LLC' <[ongshanllc@gmail.com](mailto:ongshanllc@gmail.com)>; 'Nivitha (LKK Auto)' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** Monica Chung <[Monica\\_Chung@sg.msig-asia.com](mailto:Monica_Chung@sg.msig-asia.com)>; Rashitha Binte Shahuthuman <[rashitha\\_shahuthuman@sg.msig-asia.com](mailto:rashitha_shahuthuman@sg.msig-asia.com)>

**Subject:** RE: PRE-REPAIR SURVEY - EQ7788R(OI) / SCV4455T ON 19/12/2017

**OUR REF – TBA**

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to your list of surveyors .

We regret to inform you that we are unable to accept your list of nominated Single Join Experts( SJE). We will proceed to appoint a surveyor from M/s LKK Auto Consultants Pte Ltd for your client's claim.

Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

Dear LKK,


We will grant rights to you in merimen. Fyna.

*Rashitha*

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | [Rashitha\\_shahuthuman@sg.msig-asia.com](mailto:Rashitha_shahuthuman@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg/) | Follow us on 

A member of **MS&AD** INSURANCE GROUP

**From:** Ong & Shan LLC [<mailto:ongshanllc@gmail.com>]  
**Sent:** Friday, 22 December, 2017 2:45 PM  
**To:** Rashitha Binte Shahuthuman <[rashitha\\_shahuthuman@sg.msig-asia.com](mailto:rashitha_shahuthuman@sg.msig-asia.com)>  
**Subject:** Re: PRE-REPAIR SURVEY - EQ7788R(OI) / SCV4455T ON 19/12/2017

Dear Sirs,

We refer to the above matter and your letter of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Andrew How
2. Dixon Yeo
3. Alan Kim

Name of workshop : M/s Yap Lee Motor  
Address : 1 Kaki Bukit Ave 6 #01-26 Singapore 417883  
Contact person : Ms. Shirley/ Jace  
Telephone no : 6-844-1555  
Fax no : 6-844-1311

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single Joint Expert".

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

Warmest Regards,

CM Chen  
M/s Ong & Shan LLC  
Block 184 Toa Payoh Central  
#02-364 Singapore 310184

Tel: 6224 9847 Fax : 6254 7261  
Email: [ongshanllc@gmail.com](mailto:ongshanllc@gmail.com)

On Fri, Dec 22, 2017 at 2:41 PM, Rashitha Binte Shahuthuman <[rashitha\\_shahuthuman@sg.msiga.com](mailto:rashitha_shahuthuman@sg.msiga.com)> wrote:

WITHOUT PREJUDICE

Dear Sirs,

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

*Rashitha*

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha\_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Dec 2017		26 Dec 2017 14:23 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

<b>Insured:</b>	SITI AISHAH BTE JAFFAR, ID: S1806066C	<a href="#">[Created by insurer]</a>	
<b>Main Claimant:</b>	TAY KAY SOCK GERLAD, ID: S1470106J		
<b>Vehicle Reg. No.:</b>	SCV4455T	<b>Date of Loss:</b>	19/12/2017 18:00 - :59
<b>Claim Type:</b>	TP / 542335	<b>Policy/Cover Note No.:</b>	A80433216AVW (Comprehensive) Coverage: 29/05/2017 - 28/05/2018
<b>Vehicle Reg. No. (Insured):</b>	EQ7788R	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pel Zhen - 6594 2552]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/02/2018]		
<b>Driver/Custodian (Insured):</b>	SYED MOHAMED BIN ZUMRI AL-KHAIRID (), NRIC: S1583411J, Tel: +6597669996		

### ASSOCIATED MAIL RECEIVED

- MSIG\_SG (06/02/2018): Report Send Back Alerts - SCV4455T (TP)

[View All](#)
[Compose Case Mail](#)


### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
No results.						<a href="#">Assigned By</a>	<a href="#">Completed On</a>	<a href="#">Created On</a>	<a href="#">Done?</a>

# YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883  
Tel : 6844 1555 Fax: 6844 1311 Email : yap\_lee\_motor@singnet.com.sg

Owner : Mr Tay Kay Sock Gerald  
Address : 11 West Coast Walk  
#11-24  
Singapore 127161

Date: 22-Jan-18

Veh No: **SCV 4455 T**

Model: Audi Sportback 2.0A

## Final Repair Bill

<u>Serial No</u>	<u>Description</u>	<u>Amount</u>
1	Lump sum repair costs	\$ 5,600.00

Grand total: \$ 5,600.00



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 2014044340

## INVOICE

Mr Tay Kay Sock Gerled  
C/o. 1 Kaki Bukit Ave 6  
#01-26 Autobay  
Singapore 417883

Invoice No. : HA/1801-32

Date : 17/01/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 448.00
SGD Dollar : Four Hundred Forty Eight Dollars Only.	
Our Reference : PAS/TP/0431217	
Vehicle No. : SCV4455T	
Make & Model : Audi A5 Sportback	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0431217

Date of Report : 17/01/2018

To : Mr Tay Kay Sock Gerled  
C/o. 1 Kaki Bukit Ave 6  
#01-26 Autobay  
Singapore 417883

Date of Assignment : 27/12/2017  
Report requested by : Mr Tay Kay Sock Gerled  
Date of Accident : 19/12/2017  
Date of Inspection : 27/12/2017  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SCV4455T  
Make & Model : Audi A5 Sportback  
Date of Registration : 29/01/2016  
Colour : Met. Black

Engine Capacity (cc) : 1984cc  
Mileage (km) : 17062km  
Chassis / Frame No. : WAUZZZ8T9BA093417  
Engine No. : CDN212210

### TYRE CONDITION

Front LH : 6 mm  
Make : Michelin

Front RH : 6 mm  
Make : Michelin

Rear LH : 6 mm  
Make : Michelin

Rear RH : 6 mm  
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Yap Lee Motor  
1, Kaki Bukit Ave 6, Blk B, #01-26, Autobay @ Kaki Bukit, Singapore 417883

### ASSESSMENT

Repairer's Estimate : \$ 8,073.55  
Revised Amount : \$ 7,036.55  
Less Excess : \$ -  
Recommended Reserve : \$ 5,600.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SCV4455T

Report No. : PAS/TP/0431217

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Yap Lee Motor, 1, Kaki Bukit Ave 6, Blk B, #01-26, Autobay @ Kaki Bukit, Singapore 417883.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear RH portion.

### DAMAGES

The boot lid, rear bumper, rear end panel, RHR chassis members, RHR fender, rear exhaust muffler, RH taillamp, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7,036.55.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,600.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SCV4455T

Report No. : PAS/TP/0431217

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Rr bumper	Dented	\$ 1,392.00	\$ 1,392.00
2	1 pc	Rr bumper lower garnish	Dented/Deformed	\$ 315.00	\$ 315.00
3	2 pcs	Rr bumper reverse RH	Dented/Damaged	\$ 536.00	\$ 265.00
4	2 pcs	Rr bumper guide R/L	Necessary	\$ 72.00	\$ 72.00
5	1 pc	Rr bumper reinforcement	Dented	\$ 455.00	\$ 455.00
6	2 pcs	Rr bumper bracket R/L	RH Dented	\$ 378.00	\$ 189.00
7	1 pc	Rr taillamp RH	Cracked	\$ 815.00	\$ 815.00
8	1 pc	Rr end panel	Dented/Distorted	\$ 678.00	\$ 678.00
9	1 pc	Rr end panel garnish	Dented/Deformed	\$ 174.00	\$ 174.00
10	1 pc	Rr exhaust muffler RH	Dented/Bent	\$ 894.00	\$ 894.00
				\$ 5,709.00	\$ 5,249.00
Less Discount : 5%				\$ 285.45	\$ 262.45
List Parts Sub-Total :				\$ 5,423.55	\$ 4,986.55
Parts Total :				\$ 5,423.55	\$ 4,986.55



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SCV4455T

Report No. : PAS/TP/0431217

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 80.00	\$ 50.00 X
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00 X
3	To straighten, repair, realign center exhaust pipe and replace exhaust muffler.	\$ 120.00	\$ <del>80.00</del> 60
4	To remove, replace and/or transfer rear reverse sensors & reset control unit.	\$ 220.00	\$ <del>180.00</del> 80
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 770.00 300
6	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 800.00 250
7	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 50.00 X
Labour Total :		\$ 2,650.00	\$ 2,050.00 690
Total (Parts & Labour) :		\$ 8,073.55	\$ 7,036.55

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 5,600.00

Under normal circumstances, the repairs should be completed within a reasonable period of 7 Working Days.

48 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

2470.95  
690.00  
3160.95  
208  
2528.76

415-2,500.00  
4 days

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/12/2017 16:17
Date Of Accident	19/12/2017 18:40
Exact Location Of Accident	CLEMENTI ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCV4455T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY KAY SOCK GERLAD
NRIC No	S1470106J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96649007
Alternative Phone No	OFFICE-96649007

### Vehicle Particulars

Manufacturer	AUDI
Model	A5

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700388

Cover Note Number

### Driver

Name of Driver	TAY KAY SOCK GERLAD
NRIC No	S1470106J
Date Of Birth	31/03/1961
Occupation	INDOOR
Date Of Driving Pass	22/08/1983
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96649007
Fax Number	
Contact Number	OFFICE-96649007
EMail Address	NOEMAIL



Address	11 WEST COAST WALK #11-24
Postcode	127161
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEHICLE IN FRONT SLOW DOWN. I FOLLOW TO SLOW DOWN AND STOP. BUT VEHICLE B ON MY REAR CANNOT STOP IN TIME AND HIT ONTO MY REAR RIGHT PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EQ7788R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle in front slow down, I follow to slow  
down and stop, but vehicle B on my  
rear cannot stop in time and hit onto  
my rear <sup>right</sup> portion

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

YAP LEE

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Dec 2017		26 Dec 2017 14:23 <a href="#">Edit Adj Rpt</a>	<b>S\$2,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	SITI AISHAH BTE JAFFAR, ID: S1806066C								
Main Claimant:	TAY KAY SOCK GERLAD, ID: S1470106J								
Vehicle Reg. No.:	SCV4455T	Date of Loss:	19/12/2017 18:00 - :59						
Claim Type:	TP / 542335	Policy/Cover Note No.:	A80433216AVW (Comprehensive) Coverage: 29/05/2017 - 28/05/2018						
Vehicle Reg. No. (Insured):	EQ7788R	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/02/2018]								
Driver/Custodian (Insured):	SYED MOHAMED BIN ZUMRI AL-KHAIRID (), NRIC: S1583411J, Tel: +6597669996								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (06/02/2018): Report Send Back Alerts - SCV4455T (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SCV4455T (542335)**  
**[EQ7788R]**  
**TP**  
**TAY KAY SOCK GERLAD**  
**Dec 19 2017 6:00PM**  
**[SITI AISHAH BTE JAFFAR]**  
**Yap Lee Motor**



[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

**View** [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 14:26	<b>Accident Statement</b> From: SC - Reg. No: EQ7788R, Claimant: SITI AISHAH BTE JAFFAR	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/01/18 09:49	<b>Odometer Reading</b>	Load JPG	<input checked="" type="checkbox"/>
2	26/01/18 09:49	<b>Chassis Number</b>	Load JPG	<input checked="" type="checkbox"/>
3	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	26/01/18 09:49	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
28	26/01/18 09:50	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
29	26/01/18 09:50	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>
30	26/01/18 09:50	<b>Photographs of Damaged Parts</b>	Load JPG	<input checked="" type="checkbox"/>

31	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
34	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
35	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
36	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
37	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
38	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
51	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
52	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
53	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	26/01/18 09:50	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
60	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
61	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
62	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
63	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
64	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
65	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
66	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
67	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
68	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
69	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
70	26/01/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/12/17 14:24	PRE REPAIR SURVEY REQUEST FROM TP LAWYER / TP GIA REPORT		Load PDF
2	26/12/17 14:25	WE REJECT TP SURVEYORS & APPOINT LKK TO BE THE SJE		Load PDF
3	05/02/18 14:54	FRB / TP SURVEY REPORT		Load PDF
4	05/02/18 14:54	TP SURVEY PHOTOS		Load PDF
5	05/02/18 14:54	TP SURVEY PHOTOS		Load PDF
6	06/02/18 10:33	SCV4455T		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

1	22/02/18 08:45	PHOTO		Load PDF	
2	22/02/18 08:45	Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG17024465/R1VBE2-1  
**Date:** 22/02/2018

**REFERENCE**

<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	A80433216AVW
<b>Claimant Vehicle No :</b>	SCV4455T	<b>Insured Vehicle No :</b>	EQ7788R
<b>Date of Loss:</b>	19/12/2017	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	542335

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	<b>SCV4455T</b>	<b>Engine No:</b>	CDN212210
<b>Make &amp; Model:</b>	AUDI A5, 2.0 SPORTBACK (A)	<b>Chassis No:</b>	WAUZZZ8T9BA093417
<b>Reg. Date:</b>	29/01/2016 (Man. Year: 2011)	<b>Odometer:</b>	17063 km
<b>Colour:</b>	Black		
<b>Engine Capacity:</b>	1984 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	Steering (Serviceable):	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	245/40Z R18	<b>Rear Tyre Size:</b>	245/40Z R18
<b>Front Left Side:</b>	Michelin 6 mm	<b>Rear Left Side:</b>	Michelin 6 mm
<b>Front Right Side:</b>	Michelin 6 mm	<b>Rear Right Side:</b>	Michelin 6 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,423.55	2,470.95	2,952.60	54.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	690.00	1,960.00	73.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,073.55</b>	<b>3,160.95</b>	<b>4,912.60</b>	<b>60.85</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>8,073.55</b>	<b>2,500.00</b>	<b>5,573.55</b>	<b>69.03</b>

**INSPECTION**

<b>Date of Assignment:</b>	26/12/2017	<b>Yap Lee Motor (HQ)</b>
<b>Date Inspected:</b>	28/12/2017	<b>Inspected At:</b>
		1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit
		Singapore 417883
<b>Estimated Period of Repair:</b>	4.0 days	

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

**NOTE:** This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2018)
<b>Parts:</b> 143	AUDI A5 2.0 SPORTBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SCV4455T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Dented	1,392.00 FL	*1,392.00 FL
2	1		*RR BUMPER LOWER GARNISH	Dented / Deformed	315.00 FL	*315.00 FL
3	1		*RR BUMPER REVERSE RH	Dented / Damaged - 1pc only	536.00 FL	*265.00 FL
4	2		*RR BUMPER GUIDE R/L	Serviceable	72.00 FL	*- FL
5	1		*RR BUMPER REINFORCEMENT	Dented	455.00 FL	*455.00 FL
6	2		*RR BUMPER BRACKET R/L	Serviceable	378.00 FL	*- FL
7	1		*RR TAILLAMP RH	Serviceable	815.00 FL	*- FL
8	1		*RR END PANEL	Serviceable	678.00 FL	*- FL
9	1		*RR END PANEL GARNISH	Dented / Deformed	174.00 FL	*174.00 FL
10	1		*RR EXHAUST MUFFLER RH	Repair	894.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,709.00</b>	<b>2,601.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (S\$)</b>	285.45	130.05
<b>Total Parts (S\$)</b>	<b>5,423.55</b>	<b>2,470.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	80.00	0.00
2	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	150.00	0.00
3	TO STRAIGHTEN, REPAIR, REALIGN CENTER EXHAUST PIPE AND REPLACE EXHAUST MUFFLER	New	120.00	60.00
4	TO REMOVE, REPLACE AND / OR TRANSFER REAR REVERSE SENSORS & RESET CONTROL UNIT	New	220.00	80.00
5	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	300.00
6	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	250.00
7	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,650.00</b>	<b>690.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >