

Surveyor

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

PA 41377

Policy No:

5083736033-01

01/09/2017

Claims No:

M1/0980389-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMB58935

Yr Regn:

11/11/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Man A95

cc 10518

Colour:

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

131320

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WM AA 95 Z E 8 9 7003046

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 275/70R22.5

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirella

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

26/1/18

D.O.I.

1/2/18

Survey held at:

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMB 58935 - x

PA 41377 - Q1 / TPD 14011737 / D

PA: 10.10.2012

Final Est \$2698.20 (Red \$ 617.80, 19%)

RECEIVED 21 MAY 2017

Date/Time, File Pass to?

11/1/15

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$



: Preli. Report



: Final Report

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos:

Others:

TOTAL

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002316/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 06-02-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 4137T	Veh. Inspected	SMB 5893S
Policy No.	5083736033-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/01/2018	Inspection Date	01/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0939315-003	SMRT BUSES LTD	SMB 1472A	SKJ 7179P	29/03/2017
2	MT/0995090-001	SMRT BUSES LTD	SMB 342Z	PC 8808D	14/09/2017
3	MT/0980389-002	SMRT BUSES LTD	SMB 5893S	PA 4137T	26/01/2018
4	MT/0939257-002	SMRT BUSES LTD	SMB 1582R	PA 8425K	25/03/2017
5	MT/0987666-002	SMRT BUSES LTD	SMB 1484R	SHB 8685R	27/2/2018
6	MT/0990787-002	SMRT BUSES LTD	SMB 1473Y	SIK 5147B	16/4/2018
7	MT/0985497-002	SMRT BUSES LTD	SMB 1515K	SGK454H	9/3/2018
8	MT/0989067-002	SMRT BUSES LTD	SMB 61J	SIH 4630U	2/4/2018
9	MT/0991323-002	SMRT BUSES LTD	SG 1721J	EN 59Z	20/4/2018

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5083736033-01	SENTOSA DEVELOPMENT CORPORATION	T08GB0048K	GFT	Third Party	PA4137T	PA4137T	01/09/2017	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2292D

Vehicle Details

Vehicle No.: SMB5893S

Vehicle to be Exported: No

Intended De-registration Date: 06 Feb 2018

Vehicle Make: MAN

Vehicle Model: A95

Primary Colour: Multi-Colour

Manufacturing Year: 2015

Engine No.: 50342170624215

Chassis No.: WMAA95ZZ8G7003046

Maximum Power Output: -

Open Market Value: \$438,406.00

Original Registration Date: 11 Nov 2015

First Registration Date: 11 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 06 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2018 13:35
Date Of Accident	26/01/2018 18:20
Exact Location Of Accident	HARBOURFRONT INTERCHANGE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB5893S
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64823888
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	BUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	
Driver	
Name of Driver	LIU XUEPING
NRIC No	G2531691L
Date Of Birth	17/06/1974
Occupation	OUTDOOR
Date Of Driving Pass	27/10/2014
Driving Experience	3 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I had stationary the bus at layover area and went to toilet, when I return back realized a private bus PA 4137T had collided onto my bus.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA4137T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver JUPRI BIN HUSSEIN

NRIC/Passport Number

Contact Number 81388653

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

Bus | 01 | 14 | 1043.

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurer companies.
 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded to the Director of the Police Traffic Department and the General Insurance Association of Singapore (GIA) for archiving and their copies of this report will for free be made available upon application of interested parties.

By the submission of this report to the Insurer, the Policyholder agrees to the following conditions:

1. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

刘学军


SKETCH PLAN

Harbour front Interchange

P SM27



PA 4137T



DESCRIBE CIRCUMSTANCES OF THE INCIDENT

pls refer to BIA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

刘学军

Driver's Signature
(If driver is not the policyholder)
Date & Time:


105

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB5893S
Ref. No : BUS/01/18/1043
Reg. Date : 30/01/2018
Vehicle Type : DOUBLE DECK
Make : A95MAN
Model : MAN A95
Name of Driver : Liu Xueping
Type of Accident : SIDE SWIPE
Date / Time of Accident : 26/01/2018 06:20:00 PM
Accident Reported Date / Time : 29/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB5893S - LEFT REAR WINDOW GLASS PANEL WEBBED
PA4137T(TP) - INSURED WITH NTUC
Prepared Date : 30/01/2018 01:20:39 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sebastian 1/2/2017
- Part by post repair
- Photo Before & After Paint

9003621

Sebastian Yang @ lkkauto.com

12/2/18

Chassis No :

Work Shop :

Summary of Repair Estimates

Total Labour Charges

Total Spray Painting Charges

Total Material Charges

Other Charges

TOTAL

Lum Sum Total

No. of Repair Days

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

Mileage

Repair Completed Date / Time :

Adjusted by Surveyor, if applicable

Quotation from ARC
: 1,060.00
: 878.00
: 1,346.40
: 210.00
: **3,494.40**
: **0.00**
: **3.00**

01/01/1500 12:00:00 AM

01/02/2018 12:14:41 PM



Prepared / Adjusted Date

Remarks

Prepared Date : 01/02/2018 12:05:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Quotation Date :

Invoice Amount :

Invoice No :

Invoice Date :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	0.00 - 795
Total Labour	1,060.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	878.00	0.00 600
Total Spray Painting & Panel Beating	878.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL LHS MID	210.00	0.00 ✓ NEC
Total Other Costs	210.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
			Side Glass L11(MAN A95)	1	1748.00	10.00	673.20	Replace	Replace	No ✓ CNE
		99	EMERGENCY EXIT STICKER	1	175.00	0.00	75.00	Replace	Replace	No ✓ NEC
TOTAL MATERIALS								748.20	748.20	
TOTAL MATERIALS(Discounted)								1,346.40	1,346.40	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB5893S
 Ref. No : BUS/01/18/1043
 Reg. Date : 11/11/2015
 Vehicle Type : DOUBLE DECK
 Make : A95MAN
 Model : MAN A95
 Name of Driver : Liu Xueping
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 28/01/2018 06:20:00 PM
 Accident Reported Date / Time : 29/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094436
 Special Instruction to ARC, if any :

SMB5893S - LEFT REAR WINDOW GLASS PANEL WEBBED
 PA4137T(TP) - INSURED WITH NTUC

Prepared Date : 30/01/2018 01:20:39 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA95ZZ8G7003046

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	795.00
Total Spray Painting Charges	: 878.00	600.00
Total Material Charges	: 1,093.20	1,093.20
Other Charges	: 210.00	210.00
TOTAL	: 3,241.20	2,698.20
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00 ✓
Prepared / Adjusted By	:	SEBASTIAN LKK
Arc / Surveyor Sign Off Date	: 01/02/2018 12:14:41 PM	04/05/2018 06:37:02 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/02/2018 12:05:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	795.00 ✓
Total Labour	1,060.00	795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	878.00	600.00 ✓
Total Spray Painting & Panel Beating	878.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PIXEL STENCIL LHS MID	210.00	210.00 ✓ NEL
Total Other Costs	210.00	210.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
G20.05.01.12			SIDE GLASS L11 (A95MAN)	1	748.00	10.00	673.20	Replace	Replace ✓	No CRK
		99	EMERGENCY EXIT STICKER	1	75.00	0.00	75.00	Replace	Replace ✓	No NEC
	COMMO N	4006313	PRIMER	1	80.00	0.00	80.00	Replace	Replace ✓	No NEC
	COMMO N	4006314	SEALANT SIKAFLEX	5	37.00	0.00	185.00	Replace	Replace ✓	No NEC
		4006315	ACTIVATOR	1	80.00	0.00	80.00	Replace	Replace ✓	No NEC
TOTAL MATERIALS							1,093.20	1,093.20		
TOTAL MATERIALS(Discounted)							1,093.20	1,093.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	COMMO N	PRIMER	1	80.00	0.00	80.00	Replace	Replace	No
	COMMO N	SEALANT SIKAFLEX	5	37.00	0.00	185.00	Replace	Replace	No
		ACTIVATOR	1	80.00	0.00	80.00	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						345.00			

1093.2
+ 1605.0
2698.2

Part by Part : \$2698.20

Sebastian
17/5/18

3316



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18002316/Sqbn2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 23-05-2018	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PA 4137T	Veh. Inspected	SMB 5893S
Policy No.	5083736033-01	Coverage (\$)	0.00
Claim No.	MT/0980389-002	Excess (\$)	0.00
Assign From		Assign Date	01/02/2018
2. Vehicle Particulars & Condition			
Make & Model	MAN A95	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA95ZZ8G7003046	Colour	MULTI
Odometer	131320	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/01/2018	Inspection Date	01/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 5893S

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 33333

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE GLASS L11 (A95MAN)	CRACKED	748.00	748.00
	LESS 10% DISCOUNT		-	-74.80
			748.00	673.20
<u>SPECIAL NETT ITEMS</u>				
1	EMERGENCY EXIT STICKER (SN)	NECESSARY	75.00	75.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
5	SEALANT SIKAFLEX @\$37.00 (SN)	NECESSARY	185.00	185.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	PIXEL STENCIL LHS MID (SN)	NECESSARY	210.00	210.00
			630.00	630.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		1,060.00	795.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		878.00	600.00
			1,938.00	1,395.00
GRAND TOTAL			3,316.00	2,698.20
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,698.20

Report Ref No. NS/INC18002316/Sqbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.