

ASS. REC. BY:

REF: CS/MSG18002338/Uvd3n2 Special Instructions

Surveyor  
Merimen

Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 6/2/18 @ 10:09am

Estimated Cost:

Bill to:

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS3869K

Insured:

FBK 3012P

at Workshop m/s

Imperium Automotive

Tel:

9748

of

Policy No:

MSD/VMFT/17-983378

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 02/02/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

11:08am 6/2/18

Person Contacted:

John

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKS3869K - NA/AG18002274/K9

D.O.A: 2/2/18

FBK 3012P - NA/AG18002274/K9

D.O.A: 2/2/18

7/2/18

Informed Irene pending workshop est by merimen

8/2/18

Send preli revised by merimen

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKS3869K*at Workshop m/s *1 myr*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA PR Seen: *10* Consistent? : Yes or NoEst. Repairs: *3* days Res.: Yes or NoLum Sum: *1.31* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *SKS3869K* Yr Regn: *4 15*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA*Make: *mit outlander* c.c. *2360*Colour: *Red* A/C: Insured / Std / NI / NASp. Reading: *70894* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JMYXTG F3WFT001723*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: *225/55R18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

*continental*

Front

Rear

R/Bal. *7* mmR/Bal. *7* mmL/Bal. *7* mmL/Bal. *7* mmD.O.A. *2/2/18*D.O.I. *6/2/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rear*

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction *27/1/18* *Continent* *final* *2984.90* *with shown* *(Red 3869.30, 569)*

RECEIVED 12 FEB 2018

12/2/2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *3*

1)

☐ : Final ReportResurvey No. of Trip: *1*

Date/Time, File Return to?

2) *12/2- typist*Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: *men, men*Lump Sum / I.B.I. (\$) *2984.90*

210

# Survey Department Check List (Case Handler)

Reference No. : CS | MSG | 800 2338 | Urd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (**

): Case handler to make sure all Information created by the assignment team are ACCURATE.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (**

): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON

Case Handler

8/2/18  
Date

\*C: Critical \*N: Non-Critical

21/05/201



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18002338/Uvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 06-02-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBK 3012P	Veh. Inspected	SKS 3869K
Policy No.	MSD/VMFT/17-983378	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	06/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	02/02/2018	Inspection Date	06/02/2018
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2018		06 Feb 2018 10:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM CHOON CHEOW, ID: S1590786Z		
Main Claimant:	LIM TIAM SOON, ID: S2576397A		
Vehicle Reg. No.:	SKS3869K	Date of Loss:	02/02/2018 18:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMFT/17-983378 (TP, Fire & Theft) Coverage: 22/06/2017 - 21/06/2018
Vehicle Reg. No. (Insured):	FBK3012P	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Imperium Automotive (HQ) 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB SINGAPORE 417800, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/02/2018]		
Driver/Custodian (Insured):	LIM CHOON CHEOW ( / Male), NRIC: S1590786Z		
Adj Asg. Remarks:	Please assign to Marcus Chua		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 08 Feb 2018
<b><u>Preliminary Advice</u></b>	

Insured Vehicle No	: FBK3012P	Accident Date	: 02/02/2018
TP Vehicle No	: SKS3869K	Assignment Date	: 06/02/2018
Make	: MITSUBISHI OUTLANDER	Est. Duration of Repair	: 3.00
Date of Inspection	: 06/02/2018		
Inspection At	: IMPREMIUM AUTOMOTIVE (HQ) 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY@KB SINGAPORE 417800 SINGAPORE 417800		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,854.20
Revised Amount	:S\$	2,984.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,984.90
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## View Sent Message

This mail is associated with :

**\*SKS3869K (MSC/V/18-000202)**  
**[FBK3012P]**

TP  
LIM TIAM SOON  
Feb 2 2018 6:00PM  
[LIM CHOON CHEOW]  
Imperium Automotive

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **07/02/2018 16:37 PM.**  
**To** MSI\_ITAN  
**Subject** TP SURVEY SKS 3869K

Dear Irene,

Please be informed that we have inspected the vehicle SKS 3869K on 6/2/2018 .

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/02/2018 17:21
Date Of Accident	02/02/2018 18:05
Exact Location Of Accident	PIE TWDS CHANGI BEFORE LORNIE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS3869K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM TIAM SOON
NRIC No	S2576397A
Email Address	LIM62@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-91298106
Alternative Phone No	OTHERS-91298106

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100408485-02000
Cover Note Number	

### Driver

Name of Driver	LIM TIAM SOON
NRIC No	S2576397A
Date Of Birth	11/10/1965
Occupation	INDOOR
Date Of Driving Pass	03/05/1990
Driving Experience	27 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91298106
Fax Number	
Contact Number	OTHERS-91298106
EMail Address	LIM62@SINGNET.COM.SG



Address	77 JURONG WEST CENTRAL 3 #10-29
Postcode	648338
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ONG GEE LEE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180202/7020

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK3012P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	LIM CHOON CHEOW
NRIC/Passport Number	S1590786Z
Contact Number	97469697
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## SKETCH PLAN


### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

PIR TOWARD  
Changi Before  
Lornie Road



(A) SKS3869K  
(B) FBK3012P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls Refer to the Attached  
T/20180202/7020

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20180202/7020

1 of 4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180202/7020

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/02/2018 23:00	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: LIM TIAM SOON			Address: 77 JURONG WEST CENTRAL 3 #10-29 SINGAPORE 648338		
ID Type / ID No.: NRIC NO / S2576397A			Contact No.: Home/Office: Mobile: 91298106		
Nationality: SINGAPORE CITIZEN			Email: tsli@chevron.com		
Sex: Male	Age: 52	Date of Birth: 11/10/1965	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: OPERATIONS OFFICER (EXCEPT TRANSPORT OPERATIONS)			Driving Licence Information: Class: 2,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/02/2018 18:05	Type of Location: Straight Road
Location:  PAN ISLAND EXPRESSWAY  Along the PIE towards Changi, before Lornie Road				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBK3012P	Motorcycle		2 wheels in front, rear 1 wheel	Grey		0
SKS3869K	Car	MITSUBISHI	Outlander	Red	Slightly Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20180202/7020

2 of 4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180202/7020

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKS3869K	AIG ASIA PACIFIC INSURANCE PTE. LTD.			

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Rider				
Name	Lim Choon Cheow	ID No.	S1590786Z	
Related Vehicle	FBK3012P (Motorcycle)	Contact No.	97469697	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3,4,5 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	
Driver				
Name	LIM TIAM SOON	ID No.	S2576397A	
Related Vehicle	SKS3869K (Car)	Contact No.	91298106	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2,3 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Passenger				
Name	Ong Gee Lee	ID No.	S2624927I	
Related Vehicle	SKS3869K (Car)	Contact No.	98321896	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	





**SINGAPORE  
POLICE FORCE**



T/20180202/7020

3 of 4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180202/7020

**CONTINUATION OF REPORT**

Brief Details.

I was travelling along the PIE towards Changi direction, the traffic flow was heavy, all vehicles were moving very slow. I was at the outer line, following front car slowly. It was drizzling and the road surface was wet.

Suddenly I heard a loud sound from behind of my moving vehicle. I stopped the vehicle and went down to check. I saw one motorist laying on the floor. He was riding alone. A white car behind the motorist was stopped too. The driver came down together with me to check the injury, he was conscious and we pull him up. His right arm looked like injured as he continue rubbing on it. We continue asked him does he alright, required to activate ambulance? This incident take place near the lamp post 1347/1A, however I keyed in the lamp post no it shows invalid.

After few minutes, he felt better, he said no required ambulance. Three of us lift up the bike together and move it to side of the road. His bike is 3 wheels type, 2 in front and 1 behind.

Soon, the white car owner left the scene.

The motorist and me exchange particular and snap some photos on both vehicles.

My car rear end right side(towards center) found dented his motor bike looks like still in good condition, many so scratches and front end.

He informed to claim his insurance company. Later, he ride his bike and move away from the location.

I managed to get white car owner particular, his name is Alumugam, HP no 94240504. He was the witness as he mentioned the motorist cut in from left in front of his car and skit, bang into my car rear right end.

The motorist rider particular is Lim Choon Cheow, I/C No: S1590786Z, HP no 97469697.



**SINGAPORE  
POLICE FORCE**



T/20180202/7020

4 of 4

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20180202/7020

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
02/02/2018 23:00

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6397A
Vehicle Details	
Vehicle No.:	SKS3869K
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	4B12PG7127
Chassis No.:	JMYXTGF3WFZ001723
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2025
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$71,921.00
COE Rebate Amount:	\$50,922.00
<b>Total Rebate Amount:</b>	<b>\$64,408.00</b>

The information contained herein is correct as at 06 Feb 2018

# IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800  
Tel: 9478 9940 Fax: 6346 7213

Vehicle No: SKS 3869K

Model: Mitsubishi Outlander

not allowed  
6/11/18  
take photo before party.  
3dy.  
P/P \$ 2984.90

## QTY

## List Price:

1	Rear tailgate
1	Rear tailgate emblem "Mitsubishi" Logo
1	Rear tailgate emblem "C&C"
1	Rear tailgate emblem "Outlander"
1	Rear tailgate emblem "Mivec"
1	Rear tailgate lock
1	Rear tailgate w/strip
1	Rear bumper
1	Rear bumper lower extension
1	Rear bumper reflector - RH
1	Rear bumper reflector holder - RH
2	Rear bumper side retainer - LH/RH @ 19.00
1	Rear end panel
1	Rear end panel garnish
2	Rear end panel bracket - LH/RH @ 79.00
1	Rear exhaust pipe
2	Rear exhaust moulding - LH/RH @ 27.00

Less 10%

1761  
10%  
1584.90

## Prices \$

11	1049.00	X
11	65.00	X
11	38.00	X
11	52.00	X
11	40.00	X
11	428.00	X
11	224.00	X
20	983.00	—
20	597.00	—
cm	186.00	—
cm	129.00	—
11	38.00	X
2	335.00	X
11	174.00	X
11	158.00	X
11	538.00	X
11	54.00	X
	5088.00	
	(508.80)	
Subtotal	4579.20	

## Special Nett Items:

1 set	Rear bumper reverse sensor
1 set	Rear bumper clip 350

Subtotal	280.00	200
	55.00	✓
Subtotal	335.00	

## Labour Charges:

Panel beating, cut, weld, remove and replacing above parts
To respray painting and etc
To checking rear wiring
To refix reverse sensor
To remove, replace rear exhaust box
To respray undercoating

800.00	480
800.00	600
80.00	20
80.00	50
11 80.00	X
11 100.00	X
Subtotal	1940.00

## ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 6854.20

2984.90

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:  
Page 1 of 1  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002338/UVD3N2

Date: 13/02/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-983378
Claimant Vehicle No :	SKS3869K	Insured Vehicle No :	FBK3012P
Date of Loss:	02/02/2018	Nature of Claim:	TP
		Claim No:	MSCV/18-000202

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKS3869K	Engine No:	4B12PG7127
Make & Model:	MITSUBISHI OUTLANDER, 2.4 2.4 CVT AWD S/R FACE (A)	Chassis No:	JMYXTGF3WZF001723
Reg. Date:	13/04/2015 (Man. Year: 2015)	Odometer:	70894 km
Colour:	Red		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,914.20	1,834.90	3,079.30	62.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,150.00	790.00	40.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>6,854.20</b>	<b>2,984.90</b>	<b>3,869.30</b>	<b>56.45</b>

## INSPECTION

Date of Assignment: 06/02/2018

Date Inspected: 06/02/2018 Inspected At:

Imperium Automotive (HQ)  
25 KAKI BUKIT ROAD 4 #01-49  
SYNERGY@KB SINGAPORE 417800  
Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2018)
<b>Parts:</b>	M1-SUV	mitsubishi OUTLANDER 2.4 2.4 CVT AWD S/R FACE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKS3869K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	1,049.00 FL	*- FL
2	1		*REAR TAILGATE EMBLEM MITSUBISHI LOGO	Not Necessary	65.00 FL	*- FL
3	1		*REAR TAILGATE EMBLEM C&C	Not Necessary	38.00 FL	*- FL
4	1		*REAR TAILGATE EMBLEM OUTLANDER	Not Necessary	52.00 FL	*- FL
5	1		*REAR TAILGATE EMBLEM MIVEC	Not Necessary	40.00 FL	*- FL
6	1		*REAR TAILGATE LOCK	Not Necessary	428.00 FL	*- FL
7	1		*REAR TAILGATE W/STRIP	Not Necessary	224.00 FL	*- FL
8	1		*REAR BUMPER	Dented	983.00 FL	*983.00 FL
9	1		*REAR BUMPER LOWER EXTENSION	Dented	597.00 FL	*487.00 FL
10	1		*REAR BUMPER REFLECTOR-RH	Cracked	186.00 FL	*162.00 FL
11	1		*REAR BUMPER REFLECTOR HOLDER-RH	Cracked	129.00 FL	*129.00 FL
12	2		*REAR BUMPER SIDE RETAINER-LH/RH	Not Necessary	38.00 FL	*- FL
13	1		*REAR END PANEL	Repair	335.00 FL	*- FL
14	1		*REAR END PANEL GARNISH	Not Necessary	174.00 FL	*- FL
15	2		*REAR END PANEL BRACKET-LH/RH	Not Necessary	158.00 FL	*- FL
16	1		*REAR EXHAUST PIPE	Not Necessary	538.00 FL	*- FL
17	2		*REAR EXHAUST MOUNTING-LH/RH	Not Necessary	54.00 FL	*- FL
18	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	55.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,423.00</b>	<b>2,011.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>508.80</b>	<b>176.10</b>
<b>Total Parts (S\$)</b>	<b>4,914.20</b>	<b>1,834.90</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	800.00	480.00
2	TO RESPRAY PAINTING AND ETC	New	800.00	600.00
3	TO CHECKING REAR WIRING	New	80.00	20.00
4	TO REFIX REVERSE SENSOR	New	80.00	50.00
5	TO REMOVE,REPLACE REAR EXHAUST BOX	New	80.00	-
6	TO RESPRAY UNDERCOATING	New	100.00	-
Gross Labour Cost (S\$)			1,940.00	1,150.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;