

ASS. REC. BY

REF: CS/CRT#180023 11/9rd3er

Special Instruction

Surveyor
Menimen

GA
Sharon Hun

ASSIGNMENT (Office)

of CTI

Date/Time 6/2/18 @ 10:03am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: SLT 33694

To Inspect Vehicle No: SLD1884X

Tel: 6384 4404

at Workshop m/s: Ethicarz

of 56 Layney Way #04-04

Policy No: DMPCSN 3090671700

Claim No: SNM18D00635 C02

Sum Insured:

Excess:

D.O.A. 02/02/18

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 11:09am @ 6/2/18 Person Contacted: John

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD1884X-X
	SLT 33694-X
	Confirm LIs \$5100 @ 7 days (Red: \$10,369.09, 671.)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		06 Feb 2018 10:03 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	WIN MIN HTOO , ID: S8682269E		
Main Claimant:	JJ SAFEJOURNEY , Co. Reg. No.: 53355093M		
Vehicle Reg. No.:	SLD1884X	Date of Loss:	02/02/2018 09:00 - :59
Claim Type:	TP / SNM18D00635C02	Policy/Cover Note No.:	DMPCSN3090071700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT3369U	Policy No. (Claimant):	5087725492 COMP
		Excess:	\$0.00
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/02/2018]		
Driver/Custodian (Insured):	WIN MIN HTOO (31 / Male), NRIC: S8682269E		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Ethicarz Pte. Ltd.

56 Loyang Way, Loyang Enterprise Building

#04-04 Singapore 508775

Tel: +65 6384 4404 Fax: +65 6384 0444

E-mail: claims@ethicarz.sg

Biz Reg.: 201729003E

02 February 2018

CHINA TAIPING INSURANCE (S) PTE LTD

3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Dear Sirs

**ACCIDENT INVOLVING SLD1884X & SLT3369U ALONG ECP TOWARDS CHANGI
(BEFORE EXIT 1) AT ABOUT 0900 HOURS.**

**(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING
DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We are instructed by JJ SAFE JOURNEY to notify you of a road traffic accident on 2 February 2018 at about 0900/Hours at/along ECP TOWARDS CHANGI (BEFORE EXIT 1) involving our client's vehicle registration number SLD1884X and vehicle registration number SLT3369U driven by you/your insured at the material time. A copy of the Singapore accident statement filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline. We shall proceed to repair the vehicle without further reference to you.

Yours Faithfully

John Ong

Person-In-Charge

HP : 6384 4404



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002341/Grd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 06-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLT 3369U	Veh. Inspected	SLD 1884X
Policy No.	DMPCSN3090071700	Coverage (\$)	0.00
Claim No.	SNM18D00635C02	Excess (\$)	0.00
Assign From	MERIMEN (SHARON HAN)	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/02/2018	Inspection Date	06/02/2018
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

<p>A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.</p>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2018 11:53
Date Of Accident	02/02/2018 09:00
Exact Location Of Accident	ECP TOWARDS CHANGI (BEFORE EXIT 1)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1884X
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	JJ SAFEJOURNEY
Co Reg No	53355093M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81186089

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087725492 COMP
Cover Note Number	

Driver

Name of Driver	GAO JUNJIE
NRIC No	S8278563I
Date Of Birth	29/09/1982
Occupation	INDOOR
Date Of Driving Pass	18/03/2014
Driving Experience	3 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81186089
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 408 CHOA CHU KANG AVE 3 #10-313
 Postcode 680408
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - OWN COMPANY
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : MS KIRAN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLT3369U
 Vehicle Make/Model/Colour BMW 218I COUPE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLC8708G
Vehicle Make/Model/Colour	HONDA VEZEL 1.5X CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law or administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

- 2 FEB 2018

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A was travelling along the stated venue. All vehicles in front were slowing down before the exit, I slow down as well. Suddenly I felt an impact and realize vehicle B has hit onto my rear portion. when I alight from my vehicle I then realize I was involve in a chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy No:
Date & Time:



Gao Jimpce

Driver's Signature
(if driver is not the policyholder)
Date & Time: - 2 FEB 2018

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details		
Vehicle No. :	SLD1884X	
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car	
Vehicle Attachment 1 :	No Attachment	
Vehicle Scheme :	Normal	
Vehicle Make :	TOYOTA	
Vehicle Model :	COROLLA ALTIS CLASSIC 1.6 CVT	
Chassis No. :	MR053REH104551118	
Propellant :	Petrol	
Engine No. :	1ZRY292524	
Engine Capacity :	1598 cc	
Maximum Power Output :	90.0 kW (120 bhp)	
Maximum Laden Weight :	1640 kg	
Unladen Weight :	1205 kg	
Year Of Manufacture :	2016	
Original Registration Date :	07 Jun 2016	
Lifespan Expiry Date :	-	
COE Category :	A - Car up to 1600cc & 97kW (130bhp)	
Quota Premium :	\$47,020.00	
COE Expiry Date :	06 Jun 2026	
Road Tax Expiry Date :	06 Jun 2018	
PARF Eligibility Expiry Date :	06 Jun 2026	
Inspection Due Date :	06 Jun 2019	
Intended Transfer Date :	07 Feb 2018	
CO2 Emission :	151.00 (g/km)	
CEV/VES Rebate Utilised Amount :	-	
CO Emission :	-	
HC Emission :	-	
NOx Emission :	-	
PM Emission :	-	
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.		
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.		
Amount Payable		
Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: kelvinwo@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

TYRE:

CHASSIS NUM:

SLD1884X
TOYOTA ALTIS
MR053REH104551118

ATTN:			
QTY	DESCRIPTION - PARTS		PRICE
	BOOTLID / Buc		\$ 937.08
	BOOTLID LOCK / BT		\$ 441.84
	BOOTLID WEATHERSTRIP / Twi		\$ 268.08
	BOOTLID HINGE L+R X NN		\$ 269.70
	BOOTLID LAMP L+R X PH X NN		\$ 621.36
	BOOTLID CENTER CHROME MOULDING / ee		\$ 344.28
	BOOTLID LOGO /		\$ 104.85
	BOOTLID EMBLEM - COROLLA /		\$ 104.85
	BOOTLID EMBLEM - ALTIS /		\$ 104.85
	BOOTLID INNER TRIM X		\$ 542.28
	BOOTLID INNER TRIM CLIPS X NN		\$ 50.00
	NUMBER PLATE LAMP L+R X		\$ 269.70
	REAR BUMPER / ee		\$ 584.16
	REAR BUMPER CLIPS / mcl (SN)		\$ 50.00
	REAR BUMPER SIDE RETAINER L+R / mcl		\$ 251.04
	REAR BUMPER BRACKET L+R X NN		\$ 297.60
	REAR BUMPER REINFORCEMENT / BT		\$ 463.92
	REAR BUMPER REFLECTOR L+R X NN		\$ 299.70
	REAR END PANEL / Buc		\$ 779.04
	REAR END PANEL TOP GARNISH / ee		\$ 322.68
	REAR END PANEL TOP GARNISH CLIPS / mcl (SN)		\$ 50.00
	SPARE WHEEL PANEL X NN		\$ 1,187.88
	SPARE WHEEL PANEL BOARD / ee		\$ 395.88
	SPARE WHEEL PANEL QUARTER SPONGE L+R X NN		\$ 388.90
	SPARE WHEEL SPONGE X NN		\$ 253.90
	REAR FENDER INNER TRIM L+R / Twi		\$ 1,174.08
	REAR FENDER INNER TRIM CLIPS L+R / mcl (SN)		\$ 100.00
	REAR FENDER COWLING L+R X		\$ 379.76
	REAR FENDER COWLING CLIPS L+R X NN		\$ 100.00
	AIR DUCT X		\$ 233.40
	TAILLAMP L+R / CPA		\$ 788.88
	TAILLAMP PANEL L+R X NN		\$ 485.76
	TAILLAMP CLIPS L+R / mcl (SN)		\$ 20.00
	REAR FENDER L+R X Repair		REPAIR
	Spare wheel Bracket / BT		
		SUBTOTAL	\$ 12,665.45
		LESS 25%	\$ 3,166.36
		PARTS TOTAL	\$ 9,499.09

755.90
258.2
184.70
X
310.68
/ ee
59.90
51.70
49.17
X
X
X
486.55
30.00
65
X
374.50
X
590.00
(56.1)
35.00
X
145
X
X
723.20
20.00
X
X
755.0
X
/

5303.88 SN: 105
-5%: 3977.91

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2018		06 Feb 2018 10:03 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	WIN MIN HTOO, ID: S8682269E								
Main Claimant:	JJ SAFEJOURNEY, Co. Reg. No.: 53355093M								
Vehicle Reg. No.:	SLD1884X	Date of Loss: 02/02/2018 09:00 - :59 [19 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM18D00635C02	Policy/Cover Note No.: DMPCSN3090071700 (Comprehensive)							
Vehicle Reg. No. (Insured):	SLT3369U	Policy No. (Claimant): 5087725492 COMP							
		Excess: S\$0.00							
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/02/2018]								
Driver/Custodian (Insured):	WIN MIN HTOO (31 / Male), NRIC: S8682269E								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD1884X (SNM18D00635C02)
 [SLT3369U]
 TP
JJ SAFEJOURNEY
 Feb 2 2018 9:00AM
 [WIN MIN HTOO]
 Ethicarz Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Video			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail Print
1	02/02/18 12:03	Video - Accident [Linked Accident Report Documents]	Load MP4
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail Print
1	02/02/18 12:03	Accident Statement	Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail Print
1	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
2	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
3	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
4	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
5	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
6	02/02/18 12:03	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
2	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
3	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
4	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
5	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
6	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
7	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
8	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
9	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
10	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
11	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
12	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
13	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
14	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
15	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
16	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
17	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
18	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
19	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
20	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>
21	12/09/18 11:19	General View	Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
22	12/09/18 11:19	General View	Load JPG	<input checked="" type="checkbox"/>
23	12/09/18 11:19	General View	Load JPG	<input checked="" type="checkbox"/>
24	12/09/18 11:19	General View	Load JPG	<input checked="" type="checkbox"/>
25	12/09/18 11:19	General View	Load JPG	<input checked="" type="checkbox"/>
26	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	12/09/18 11:20	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
Documentation				
China Taiping Insurance (Singapore) Pte. Ltd. (HQ)			1 per page	<input checked="" type="checkbox"/>
1	06/02/18 10:02	PRS	Load PDF	
2	06/02/18 10:03	OI GIA REPORT	Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	02/02/18 12:02	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
2	02/02/18 12:02	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>	Load TIF	

Linked Accident Report Documents

Video			View in Browser	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print	
1	02/02/18 12:03	Video - Accident	Load MP4		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print	
1	02/02/18 12:03	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print	
1	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
2	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
3	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
4	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
5	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
6	02/02/18 12:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print	
1	02/02/18 12:02	Sketch Plan	Load TIF		
2	02/02/18 12:02	Sketch Plan #2	Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118002341/GRD3E2

Date: 14/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3090071700	
Claimant Vehicle No: SLD1884X	Insured Vehicle No: SLT3369U	
Date of Loss: 02/02/2018	Nature of Claim: TP	Claim No: SNM18D00635C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD1884X		
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No: 1ZRY292524	
Reg. Date: 07/06/2016 (Man. Year: 2016)	Chassis No: MR053REH104551118	
Colour: Silver	Odometer: 43533 km	
Engine Capacity: 1598 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/55 R16	Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 7 mm	Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm	Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,594.09	4,322.91	6,271.18	59.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	2,050.00	2,830.00	57.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,474.09	6,372.91	9,101.18	58.82
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	15,474.09	5,100.00	10,374.09	67.04
+ GST 7.00/7.00% (S\$)	1,083.19	357.00	726.19	67.04
Nett Amount (S\$)	16,557.28	5,457.00	11,100.28	67.04

INSPECTION

Date of Assignment: 06/02/2018		
Date Inspected: 06/02/2018 Inspected At:		Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING Singapore 508775

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD1884X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	937.08 FL	*755.90 FL
2	1		*BOOTLID LOCK	Bent	441.84 FL	*258.20 FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	268.08 FL	*184.70 FL
4	1		*BOOTLID HINGE L+R	Not Necessary	269.70 FL	*- FL
5	1		*BOOTLID LAMP L+R	N/S Deformed/O/SNot Necessary	621.36 FL	*310.68 FL
6	1		*BOOTLID CENTER CHROME MOULDING	Deformed	344.28 FL	*344.28 FL
7	1		*BOOTLID LOGO	Necessary	104.85 FL	*59.90 FL
8	1		*BOOTLID EMBLEM - COROLLA	Necessary	104.85 FL	*51.70 FL
9	1		*BOOTLID EMBLEM - ALTIS	Necessary	104.85 FL	*49.17 FL
10	1		*BOOTLID INNER TRIM	Not Necessary	542.28 FL	*- FL
11	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FL	*- FL
12	1		*NUMBER PLATE LAMP L+R	Not Necessary	269.70 FL	*- FL
13	1		*REAR BUMPER	Deformed	584.16 FL	*486.55 FL
14	1		*REAR BUMPER CLIPS	Necessary	37.50 FS	*30.00 FS
15	1		*REAR BUMPER SIDE RETAINER L+R	Necessary	251.04 FL	*65.00 FL
16	1		*REAR BUMPER BRACKET L+R	Not Necessary	297.60 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	463.92 FL	*374.50 FL
18	1		*REAR BUMPER REFLECTOR L+R	Not Necessary	299.70 FL	*- FL
19	1		*REAR END PANEL	Buckled	779.04 FL	*590.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	322.68 FL	*150.10 FL
21	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	37.50 FS	*35.00 FS
22	1		*SPARE WHEEL PANEL	Not Necessary	1,187.88 FL	*- FL
23	1		*SPARE WHEEL PANEL BOARD	Deformed	395.88 FL	*145.00 FL
24	1		*SPARE WHEEL SPONGE	Not Necessary	253.90 FL	*- FL
25	1		*REAR FENDER INNER TRIM L+R	Torn	1,174.08 FL	*723.20 FL
26	1		*REAR FENDER INNER TRIM CLIPS L+R	Necessary	75.00 FS	*20.00 FS
27	1		*REAR FENDER COWLING L+R	Not Necessary	379.76 FL	*- FL
28	1		*REAR FENDER COWLING CLIPS L+R	Not Necessary	100.00 FL	*- FL
29	1		*AIR DUCT	Not Necessary	233.40 FL	*- FL
30	1		*TAILLAMP L+R	Cracked	788.88 FL	*755.00 FL
31	1		*TAILLAMP PANEL L+R	Not Necessary	485.76 FL	*- FL
32	1		*TAILLAMP CLIPS L+R	Necessary	20.00 FS	*20.00 FS
33	1		*REAR FENDER L+R (NPA)	Repair	0.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
35	1		*REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
36	1		*REVERSE CAM	Not Necessary	400.00 FS	*- FS
37	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*SPARE WHEEL INSULATOR	Not Necessary	150.00 FS	*- FS
40	1		*SPARE WHEEL PANEL QUARTER SPONGE L+R	Not Necessary	388.90 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,705.45	5,648.88
- List Item Discount on L Items 25.00/25.00% (\$)	3,111.36	1,325.97
Total Parts (\$)	10,594.09	4,322.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK & REALIGN	New	1,800.00	1,000.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,800.00	800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	180.00	80.00
4	TO RNR REAR BOOT MECHANISM	New	200.00	40.00
5	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	New	200.00	60.00
6	TO RNR REVERSE SENSOR & CHECK FUNCTION	New	150.00	40.00
7	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	150.00	0.00
8	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	New	100.00	30.00
9	TO DO WATER LEAK TEST	New	100.00	0.00
10	TO RNR REAR LUGGAGE COMPARTMENT	New	200.00	0.00
Gross Labour Cost (S\$)			4,880.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >